

ASS. REC. BY:

REF: CS/TP19012475/KHFB3 n2

Special Instruction:

*Wurman*

Surveyor: Kalvin

ASSIGNMENT (Office)

From (Person):

Narulhaida Binte  
Mond

TMIS

Date/Time:

15/7/19

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SH136720K

Insured:

SLP 7627U

at Workshop m/s

Comfort Delgro Eng'g

Tel:

of

59 Loyang Drive S(68969)

Policy No:

MIK000577

Claim No:

TP / M1905295

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13/7/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

*rup'*

H.O.D. Endorsement:

Date/Time:

15.7.19 5.00 p.m

Person Contacted:

Jumadi

Vehicle (IN) OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SH136720K CC3/DAI15007708/HI ja 3g2 OOA = 5/5/15
	SLP 7627U X

108/1113

REF:

Surveyor: Kevin

**ASSIGNMENT**

Veh No: SHB 6720K Yr Regn: 24 Apr 2018

From: \_\_\_\_\_ Date: \_\_\_\_\_

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/Tr / Prime Mover /

Estimated Cost: \_\_\_\_\_

Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Make: Mercedes Benz V/Ch 0 C.C. 2143

To Inspected Vehicle No: \_\_\_\_\_

Colour: White A/C: Insured / Std / NI / NA

at Workshop m/s \_\_\_\_\_

Sp. Reading: 659593 T/Radio: Insured / Std / NI / NA

of \_\_\_\_\_

Eng/No: \_\_\_\_\_

Insured: \_\_\_\_\_

C/No: WDF 639817-23858667

Policy No: \_\_\_\_\_

Gen. Cond: Good / Scr / Poor / Burnt

Claims No: \_\_\_\_\_

Steering: In order / Scr / Jammed / Leaked / Burnt or

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Brake: In order / Scr / Jammed / Leaked / Burnt or

(Client's Record)

Modi: Nil / S/Rim / STD / Scr / Rim or

Make of Veh: \_\_\_\_\_

Tyre Size: F: 225 / 60R16c

(Policy Condition)

N/S	O/S

R: \_\_\_\_\_

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Bal. or Market Value: \_\_\_\_\_

Front 7 mm Rear 7 mm

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

R/Bal. 7 mm

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

L/Bal. 7 mm

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

D.O.A. 13/7/19 D.O.I. 15/7/19

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Survey held at CPAE (Loyens)

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or o/s front

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>23/7/19</u>	<u>Contract u/s \$1450 / 2 days. (Red: 2729.40 : 65%) To K2 U2</u>

RECEIVED 25 JUL 2019

Date/Time, File Pass to?

: Prel. Report  
 : Final Report

Days Of Repair: 2

1) 247 Typist

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

Transportation:

S + RS, \$

Photos

250
11
261

Add Fee:

: Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

2)

0

TP  
14501

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Jul 2019 Sendback Est	15 Jul 2019 11:57 S\$4,179.40	15 Jul 2019 16:12 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS**

Insured:	LION CITY RENTALS PTE LTD, Co. Reg. No.: 201504621K		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHB6720K	Date of Loss:	13/07/2019 00:00 - :59 [62 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1905295	Policy/Cover Note No.:	MK000577 (Third Party Only) Coverage: 25/06/2019 - 24/02/2020
Vehicle Reg. No. (Insured):	SLP7627U	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Nurulhaida Binte Mohd Seain]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/07/2019]		
Driver/Custodian (Insured):	WONG BAN LONG (42) , NRIC: S1113037B Email:		
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT		

**ASSOCIATED MAIL RECEIVED** View All Compose Case Mail

There are no mail for this case.

---

**ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/07/2019 10:41
Date Of Accident	13/07/2019 01:15
Exact Location Of Accident	TANJONG PAGAR ROAD TWDS SOUTH BRIDGE ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB6720K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	VIANO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	NG KIAN CHUAN
NRIC No	S7419555E
Date Of Birth	23/06/1974
Occupation	OUTDOOR
Date Of Driving Pass	28/04/1994
Driving Experience	25 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91003531
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	815 TAMPINES AVENUE 4 12-241
Postcode	520815
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

SEE ATTACH.

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO


### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP7627U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG BAN LONG
NRIC/Passport Number	S1113037B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	LEFT FRT
No. Of Passenger (Including Driver)	

SKETCH PLAN

A = SHB 6720K  
 B = SLP 7627U

Tanjung Pagar  
 Road - was  
 Earth Bridge  
 Road



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/7/19 at about 01:15 hrs, I was driving straight at above said location without pax. Shortly Veh B overtaking my taxi from behind then cut into my path. Due to this, Veh B it left front portion grazed onto the right front portion of my taxi. Both of us then alighted to take photo and exchange particulars. No injury at the point of accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
 CO. REG. NO. 199303821R

13/7/19

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

AMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:









Driver's Signature  
(If driver is not the policyholder)  
Date & Time:








13/7/19

Reporting Centre Personnel's Signature  
Name: **Loke Wei Yiang**  
NRIC/FIN No.:









Team: ARC Repair TP(CLSO)1

**JOB CARD**

Sales Order:

JG NO: 305311042


TOMER COMFORT TRANSPORTATION PTE LTD 7010045 TOMER NO: 383 SIN MING DRIVE SINGAPORE SINGAPORE 575717 65508755 (R) (P)	REGN NO:	SHB6720K	MILEAGE
	MAKE:	MERCEDES BENZ	FUEL
	MODEL:	VIANO CDI 2.2L	DATE/TIME IN
	YR OF MANU:	24.04.2014	TARGET DATE
	CHASSIS CODE:	WDF63981323858667	COMPLETION DATE/TIME

*Tokio Marine*

JOB DESCRIPTION

Accident Date: 13.07.2019  
 NATURE: 3P 13.07.2019

S/NO                      LABOR CODE                      DESCRIPTION



CHECKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: SHB6720K

LKE

*Calvin*

Vehicle No.: SHB6720K

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

**CITY CAB PTE LTD**  
**REPAIR ESTIMATE\***

VEHICLE NO : SHB 6720K

MAKE :

MODEL : MERCEDES BENZ VIANO

DATE 15/7/2019 9:54

*Lee Kahwin*  
*Lee* *Toto Marine*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper, FRT <i>x repair</i>			\$ 1,920.00
	Bumper Bracket, FRT/RH <i>x 1/2</i>			\$ 66.00
	Front Wheel Rim(RH) <i>1 head</i>			\$ 1,512.00
	<i>Front RH fender x repair</i>			
	<b>SUB TOTAL</b>			<b>\$ 3,498.00</b>
	<b>LESS 20%</b>			<b>\$ 699.60</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 2,798.40</b>
	<b>Labour Charge</b>			
	Panel Beating-Repair Fender			\$ <sup>200</sup> <del>600.00</del>
	Spray Painting Charge			\$ <sup>400</sup> <del>600.00</del>
	Tuff Kote			\$ <del>x 50.00</del>
	FRT Wheel Alignment			\$ <del>x 120.00</del>
	<i>Marine Fee</i>			\$ <del>11 -</del>
	<b>TOTAL LABOUR</b>			<b>\$ 1,370.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 4,168.40</b>

*Kahwin Lee*  
*15/7/19 10:30h*  
*207h*  
*U/S*  
*After Repair photo*

I hereby acknowledge and agree to finance notify  
 the insurance company for the following:  
 • Panel Beating and Spray Painting  
 • Tuff Kote  
 • FRT Wheel Alignment  
 • Labour Charge  
 • Marine Fee  
 • Without Prejudice basis  
 • Subject to the surveyor's approval and  
 • Final approval from Insurance Company  
 Acknowledged by Repairer:  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)

59 Loyang Drive  
 Singapore 508969  
 Tel: 6214 8300

**TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)**  
**CTPL**

Singapore

**PARTICULARS OF CLAIM**

<b>Claim Type:</b>	THIRD PARTY	<b>Ref. No:</b>	
<b>Policy No:</b>		<b>Date of Loss:</b>	13/07/2019
<b>Vehicle Reg. No.:</b>	SHB6720K	<b>Driveable?</b>	YES
<b>Party At Fault:</b>	UNKNOWN		
<b>Make/Model:</b>	MERCEDES-BENZ VIANO, 2.2 D CDI (W639) (A)	<b>Vehicle Reg. Date:</b>	24/04/2014
<b>Vehicle Colour:</b>	WHITE	<b>Gen Condition:</b>	GOOD
<b>Engine No:</b>	65194031542791	<b>Chassis No:</b>	WDF63981323858667
<b>Odometer:</b>	0 KM		
<b>Paint Type:</b>			
<b>List Item Discount:</b>	20.00 %		
<b>Total Loss?</b>	<b>NO</b>		
<b>Est. Duration of Repair (day)</b>	3		
<b>Present Location:</b>	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	2,798.40
Miscellaneous Items	11.00
Labour	1,370.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>4,179.40</b>
<b>+ GST 7.00% (S\$)</b>	<b>292.56</b>
<b>Nett Amount (S\$)</b>	<b>4,471.96</b>

**This claim is handled by: LIM KWOK ENG**

*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 15 Jul 2019)  
**Parts:** M1-MPV      MERCEDES-BENZ VIANO 2.2 D CDI (W639) (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** ComfortDelGro Engineering Pte Ltd/SHB6720K/15/07/2019 11:57  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER	20.00	0.00	*1,920.00 FL R
2	1		*FRT BUMPER BRACKET RH	20.00	0.00	*66.00 FL SV <
3	1		*FRT WHEEL RIM RH	20.00	0.00	*1,512.00 FL Gra
<b>Sub Total (S\$)</b>						<b>3,498.00</b>
<b>- List Item Discount on L Items (S\$)</b>						699.60
<b>Total Parts (S\$)</b>						<b>2,798.40</b>

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHB6720K/15/07/2019 11:57. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
<b>Sub Total (S\$)</b>			<b>11.00</b>

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING - Repair Fender	New	600.00
2	SPRAY PAINTING CHARGE	New	600.00
3	TUFF KOTE	New	50.00
4	FRT WHEEL ALIGNMENT	New	120.00
<b>Gross Labour Cost (S\$)</b>			<b>1,370.00</b>

ComfortDelGro Engineering Pte Ltd/SHB6720K/15/07/2019 11:57. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

# COMFORTDELGRO ENGINEERING

Our Job Ref No 305311042  
Date : 20.07.19

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK Fax : \_\_\_\_\_  
Attn : Mr KALVIN ANG  
Vehicle Reg No. SHB6720K CTPL 13.07.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SLP7627U
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \_\_\_\_\_
  - (b) Labour Charges \_\_\_\_\_
  - Total for Part-By-Part Repair Cost** \_\_\_\_\_
  - (c.) Lumpsum Repair (if applicable) \_\_\_\_\_
  - Total for Lumpsum repair cost after Less: 20% \$1,450.00
  - Final Lumpsum Repair cost** \$1,450.00


3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM KWOK ENG  
Tel : 62148316  
Fax : 65468156

Signature :   
Name : Kalvin  
Date : 23/7/19

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_  
\_\_\_\_\_

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19012475/K1TF3N2  
Date: 29/07/2019**REFERENCE**

<b>Handling Insurer:</b>	Tokio Marine Insurance Singapore Ltd	<b>Policy No:</b>	MK000577
<b>Claimant Vehicle No :</b>	SHB6720K	<b>Insured Vehicle No :</b>	SLP7627U
<b>Date of Loss:</b>	13/07/2019	<b>Nature of Claim:</b>	TP
		<b>Claim No:</b>	M1905295

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

<b>Reg No:</b>	SHB6720K	<b>Engine No:</b>	65194031542791
<b>Make &amp; Model:</b>	MERCEDES-BENZ VIANO, 2.2 D CDI (W639) (A)	<b>Chassis No:</b>	WDF63981323858667
<b>Reg. Date:</b>	24/04/2014 (Man. Year: 2013)	<b>Odometer:</b>	659593 km
<b>Colour:</b>	White		
<b>Engine Capacity:</b>	2143 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

<b>General Condition:</b>	Good	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>	Good

**CONDITION OF TYRES**

<b>Front Tyre Size:</b>	225/60R16C	<b>Rear Tyre Size:</b>	225/60R16C
<b>Front Left Side:</b>	Hankook 7 mm	<b>Rear Left Side:</b>	Hankook 7 mm
<b>Front Right Side:</b>	Hankook 7 mm	<b>Rear Right Side:</b>	Hankook 7 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %	
Parts	2,798.40	1,209.60	1,588.80	56.78	
Miscellaneous Items	11.00	11.00	0.00	0.00	
Labour	1,370.00	600.00	770.00	56.20	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>4,179.40</b>	<b>1,820.60</b>	<b>2,358.80</b>	<b>56.44</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>1,450.00</b>			
	(S\$)	4,179.40	1,450.00	2,729.40	65.31
<b>+ GST 7.00/7.00% (S\$)</b>	292.56	101.50	191.06	65.31	
<b>Nett Amount (S\$)</b>	<b>4,471.96</b>	<b>1,551.50</b>	<b>2,920.46</b>	<b>65.31</b>	

**INSPECTION**

<b>Date of Assignment:</b>	15/07/2019	<b>Present Location:</b>	ComfortDelGro Engineering Pte Ltd (Loyang)
<b>Date Inspected:</b>	15/07/2019	<b>Inspected At:</b>	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
<b>Estimated Period of Repair:</b>	2.0 days		

Adjuster: KALVIN ANG WEI KUN

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2019)
<b>Parts:</b> M1-MPV	MERCEDES-BENZ VIANO 2.2 D CDI (W639) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB6720K)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Repair	1,920.00 FL	*- FL
2	1		*FRT BUMPER BRACKET RH	Serviceable	66.00 FL	*- FL
3	1		*FRT WHEEL RIM RH	Grazed	1,512.00 FL	*1,512.00 FL
4	1		*FRONT RH FENDER (NPA)	Repair	-	*- FL
<b>Sub Total (S\$)</b>					<b>3,498.00</b>	<b>1,512.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>					699.60	302.40
<b>Total Parts (S\$)</b>					<b>2,798.40</b>	<b>1,209.60</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (S\$)</b>			<b>11.00</b>	<b>11.00</b>

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING - Repair Fender	New	600.00	200.00
2	SPRAY PAINTING CHARGE	New	600.00	400.00
3	TUFF KOTE	New	50.00	0.00
4	FRT WHEEL ALIGNMENT	New	120.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,370.00</b>	<b>600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >