

ASS. REC. BY:

REF:

CS/CS19012522/KV362

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Crystabelle Pan of ECICE Date/Time: 16/7/2019

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJW 3744C Insured: SKG 3155A

at Workshop in/s Cheng Hoe Tel: 67556142

of BLC 1019 Yishun Ind Pk #01-274

Policy No: Claim No: DMPL 1900180 H

5/8/19 @ 1209p

Sum Insured: Excess:

crystabelle

Make of Veh: (Client's Record) D.O.A. 8/7/2019.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 16/7 Person Contacted: Vehicle IN / OUT

Date/Time	Action/Instruction
	Isahang? ✓
	SJW 3744C X
	SKG 3155A X.
5/8/19	@ 319pm Efeeds will check

AGS. REC. BY:

REF: 1051

Kenneth


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s Cheng Hoo
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: STW 3744C Yr Regn: 03, 10
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Traller or _____
 Make: Chevrolet Cruze c.c. 1598
 Colour: M. Red A/C: Insured / Std / NI / NA
 Sp. Reading: 114850 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KL1TAB961AK 818457
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: NII / S/Rlm / STD A/Rlm or
 Tyre Size: Westlake 205/80R16
 F: _____
 R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 811K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 03 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook
 Front R/Bal. 8 mm - Rear R/Bal. 6 mm
 L/Bal. 8 mm L/Bal. 6 mm
 D.O.A. 8/7/19 D.O.I. 16/7/19
 Survey held at _____
 Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
1	File pass to EM not ready
318	61 Lump @ 2000 Carmin (Red 826.80, 2990)

RECEIVED 05 AUG 2019

Date/Time, File Pass to? : Prell. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) 5/8 - typist
 Report Format: merimen
 Lump Sum / I.B.I: (\$) 2000/2
 Days Of Repair: 3
 Resurvey No. of Trip: 2
 Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech Invs (\$))
 : Weekend (\$))
 Survey Fee: _____
 Transportation: _____
 S - RS, SI _____
 Fixturs _____
 Others _____
 TOTAL 361

Nivitha (LKK Auto)

From: Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle_Tan@ecics.com.sg>
Sent: Tuesday, 16 July 2019 10:06 AM
To: assignments
Cc: Cheng Hoe Motor Pte Ltd (Yishun-June)
Subject: RE: Repair Survey (Single Joint Expert) - SJW3744C, doa 08/07/2019 (Yr insured SKG3155A)

Dear LKK

Refer to below email and arrange survey.

Best regards

Crystabelle Tan

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email crystabelle_tan@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunus Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]
Sent: Monday, 15 July, 2019 7:53 PM
To: Crystabelle Tan Gek Peng (ECICS, Claims)
Subject: Re: Repair Survey (Single Joint Expert) - SJW3744C, doa 08/07/2019 (Yr insured SKG3155A)

Hi Crystabelle,

Our selection as below :-

1. LKK

Pls assist to arrange for survey.

Thank you.

Rgds

June Phua

Cheng Hoe Motor Pte Ltd

Tel :67556142

Fax : 67557719

Veh lu - KSC

From: Crystabelle Tan Gek Peng (ECICS, Claims)
Sent: Monday, July 15, 2019 4:40 PM
To: Efeeda (Cheng Hoe -Yishun)
Subject: RE: Repair Survey (Single Joint Expert) - SJW3744C, doa 08/07/2019 (Yr insured SKG3155A)

Without Prejudice

Dear Efeeda

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Best regards

Crystabelle Tan

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email crystabelle_tan@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Efeeda (Cheng Hoe -Yishun) [<mailto:chmotor@singnet.com.sg>]

Sent: Monday, 15 July, 2019 1:27 PM

To: ECICS Claims

Cc: Chmotor

Subject: Repair Survey (Single Joint Expert) - SJW3744C, doa 08/07/2019 (Yr insured SKG3155A)

Dear Sir,

OUR CLIENT – SJW3744C
DOA : 08/07/2019
YR INSURED : SKG3155A

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards
Efeeda
Cheng Hoe Motor Pte Ltd
Tel :67556142

Fax : 67557719

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

> Back to OneMotoring

SJW 3744 C
TP/ECICS

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6035F
Vehicle Details	
Vehicle No.:	SJW3744C
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jul 2019
Vehicle Make:	CHEVROLET
Vehicle Model:	CRUZE 1.6L AUTO ABS D/AB 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2010
Engine No.:	F16D35447821
Chassis No.:	KL1JA6961AK618457
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,674.00
Original Registration Date:	19 Mar 2010
First Registration Date:	19 Mar 2010
Transfer Count:	2
Actual ARF Paid:	\$12,674.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Mar 2020
PARF Rebate Amount:	\$6,337.00
Intended COE Rebate Details	
COE Expiry Date:	18 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,802.00
COE Rebate Amount:	\$1,437.00
Total Rebate Amount:	\$7,774.00

The information contained herein is correct as at 09 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/07/2019 10:21
Date Of Accident	08/07/2019 08:25
Exact Location Of Accident	CENTRAL EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW3744C
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	KOH JOO MENG EUGENE (XU YUMING EUGENE)
NRIC No	S7516035F
Email Address	EUGENEKOH_75@YAHOO.COM
Mobile Phone No	(LOCAL) +65-92368816
Alternative Phone No	OTHERS-92368816

Vehicle Particulars

Manufacturer	CHEVROLET
Model	CRUZE 1.6L AUTO ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3059761800
Cover Note Number	07/09/18 - 18/09/19

Driver

Name of Driver	KOH JOO MENG EUGENE (XU YUMING EUGENE)
NRIC No	S7516035F
Date Of Birth	27/05/1975
Occupation	INDOOR
Date Of Driving Pass	28/02/1995
Driving Experience	24 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92368816
Fax Number	
Contact Number	OTHERS-92368816
EEmail Address	EUGENEKOH_75@YAHOO.COM

Address 11 CANBERRA DRIVE #07-22
 Postcode 768071
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLOUDY
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4
 Passenger 1 NAME: : GRABHITCH PASSENGER
 GENDER: : FEMALE
 Passenger 2 NAME: : GRABHITCH PASSENGER
 GENDER: : FEMALE
 Passenger 3 NAME: : RUTTANAKORN KUMSAWAD (FRIEND)
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name 10 UBI AVENUE 3
 Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: RETRIEVING
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKG3155A
 Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	HONG SHUFEN
NRIC/Passport Number	S8135635A
Contact Number	98458333
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	KOH JOO MENG EUGENE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJW3744C
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	RUTTANAKORN KUMSAWAD
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJW3744C
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

VEHICLE NO.: SIW 3744C
INSURER : China Taiping
DATE & TIME: 8/7/19 8:25am

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time: 09/07/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

(YS) ong 9/7/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



[Signature]

09/07/2019



**SINGAPORE
POLICE FORCE**



T/20190708/7015

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20190708/7015

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/07/2019 18:43		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: KOH JOO MENG EUGENE			Address: 11 CANBERRA DRIVE #07-22 SINGAPORE 768071		
ID Type / ID No.: NRIC NO / S7516035F			Contact No.: Home/Office:		Mobile: 92368816
Nationality: SINGAPORE CITIZEN			Email: eugenekoh_75@yahoo.com		
Sex: Male	Age: 44	Date of Birth: 27/05/1975	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: Sales and marketing manager		Driving Licence Information: Class: 3		Date of Expiry: 21/02/2003	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 08/07/2019 08:25	Type of Location: Straight Road
Location: CENTRAL EXPRESSWAY				
Weather: Cloudy		Road Surface: Dry		Road Speed Limit: 60 Km/h
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJW3744C	Car	CHEVROLET	CRUZE+1.6 L+AUTO+AB S+D/AB+2W D+4DR	Red		0
SKG3155A	Car	TOYOTA	TOYOTA WISH	Grey		0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJW3744C	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSN30597618 00	07/09/2018	18/09/2019



**SINGAPORE
POLICE FORCE**



T/20190708/7015

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20190708/7015

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
KOH CHEE SENG, KEVIN
Contact No.: 65472073

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
08/07/2019 18:43

Classification Of Case:

Authentication Stamp

NP168



Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	RUTTANAKORN KUMSAWAD	ID No.	S8788189Z
Related Vehicle	SJW3744C (Car)	Contact No.	96428872
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	KOH JOO MENG EUGENE	ID No.	S7516035F
Related Vehicle	SJW3744C (Car)	Contact No.	92368816
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: 21/02/2003
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

I was travelling along the slip road of CTE to PIE just before the ERP Gantry outside St Andrew's School. Traffic was the usual heavy morning peak hours traffic. I came to a stop behind a car as we were queuing to enter PIE when a dary grey Toyota Wish, License Plate SKG3155A driven by a Ms Hong Shufen, NRIC S8135635A collided into the rear of my car.

There were 3 other passengers in my car. 2 of them were my GrabHitch passengers. They seemed fine after the accident but i'm not too sure.

My other passenger, Ms Ruttanakorn Kumsawad of NRIC S8788189Z and myself, Eugene Koh Joo Meng of NRIC S7516035F suffered injuries to our back and neck and I was given 3 days Medical Leave.

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : ECICS LIMITED
 10 EUNOS ROAD 8
 SINGAPORE POST CENTRE, 09-04A
 SINGAPORE 408600

TEL: 63374779 FAX: 63389267
 ATTN: Motor Claim Department

WS Ref: TP/ECICS
 Claim Type: Third Party
 Accident Date: 08/07/2019
 TP Veh Reg No: SKG3155A

Not Notified
11 Day 8?
Missing After Paint
3 day

Estimate No: ES1991751/YISHUN
Date: 15 Jul 2019
Policy No: DMPCSN3059761800
Veh Reg No: SJW3744C
Make/Model: CHEVROLET CRUZE
 1.6L AUTO ABS D/AB
 2WD 4DR
Chassis No: KL1JA6961AK618457
Engine No: F16D35447821
Reg. Date: 19/03/2010

Estimate Repair Cost to Vehicle No :SJW3744C

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER	1,151.00	1 PC	1,151.00	✓
2 REAR BUMPER REINFORCEMENT	560.00	1 PC	560.00	✓
3 REAR BUMPER TOW COVER	7.00	1 PC	7.00	✓
4 REAR BOOT LOCK SWITCH	190.00	1 PC	190.00	✓
5 REVERSE SENSORS	172.00	2 PCS	344.00	✓
			2,252.00	
		Less 10%	225.20	2,026.80
Labour				
6 PANEL BEATING	400.00	1 LA	400.00	300
7 PUTTY & RESPRAY	400.00	1 LA	400.00	360
			800.00	800.00
			Total	S\$ 2,826.80
			Add GST @ 7%	197.88
			Total Amount Payable	S\$ 3,024.68

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SJW3744 C

TP/ECICS

M/S : ECICS LIMITED
 10 EUNOS ROAD 8
 SINGAPORE POST CENTRE, 09-04A
 SINGAPORE 408600

TEL: 63374779 FAX: 63389267
 ATTN: Motor Claim Department

Estimate No: ES1991751/YISHUN
Date: 15 Jul 2019
Policy No: DMPCSN3059761800
Veh Reg No: SJW3744C
Make/Model: CHEVROLET CRUZE
 1.6L AUTO ABS D/AB
 2WD 4DR

WS Ref: TP/ECICS
 Claim Type: Third Party
 Accident Date: 08/07/2019
 TP Veh Reg No: SKG3155A

Not Notified
 1/1/19 @ ?
 Recovery After Paint
 3 days

Chassis No: KL1JA6961AK618457
Engine No: F16D35447821
Reg. Date: 19/03/2010

Estimate Repair Cost to Vehicle No :SJW3744C

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER	1,151.00	1 PC	1,151.00	✓
2 REAR BUMPER REINFORCEMENT	560.00	1 PC	560.00	✓
3 REAR BUMPER TOW COVER	7.00	1 PC	7.00	✓
4 REAR END PANEL	806.00	1 PC	806.00	✗
5 REAR END PANEL INNER TOP GARNISH	55.00	1 PC	55.00	✗
6 REAR BOOT INNER LOCK	91.00	1 PC	91.00	✗
7 REVERSE SENSORS	172.00	2 PCS	344.00	✓
			3,014.00	
		Less 10%	301.40	2,712.60
Labour				
8 PANEL BEATING	400.00	1 LA	400.00	300
9 PUTTY & RESPRAY	400.00	1 LA	400.00	360
			800.00	800.00
			Total	S\$ 3,512.60
			Add GST @ 7%	245.88
			Total Amount Payable	S\$ 3,758.48

For Cheng Hoe Motor Pte Ltd



 AUTHORIZED SIGNATURE

Attne Kennedi
Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : ECICS LIMITED
 10 EUNOS ROAD 8
 SINGAPORE POST CENTRE, 09-04A
 SINGAPORE 408600
TEL: 63374779 **FAX:** 63389267
ATTN: Motor Claim Department

Estimate No: ES1991751/YISHUN
Date: 15 Jul 2019
Policy No: DMPCSN3059761800
Veh Reg No: SJW3744C
Make/Model: CHEVROLET CRUZE
 1.6L AUTO ABS D/AB
 2WD 4DR
Chassis No: KL1JA6961AK618457
Engine No: F16D35447821
Reg. Date: 19/03/2010

WS Ref: TP/ECICS
Claim Type: Third Party
Accident Date: 08/07/2019
TP Veh Reg No: SKG3155A

Not withair
61 Lyr B?
Respray After Paint
3 day

Estimate Repair Cost to Vehicle No :SJW3744C

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER	1,151.00	1 PC	<i>Bu</i> 1,151.00	<i>✓</i>
2 REAR BUMPER REINFORCEMENT	560.00	1 PC	<i>Bu</i> 560.00	<i>✓</i>
3 REAR BUMPER TOW COVER	7.00	1 PC	<i>nd</i> 7.00	<i>✓</i>
4 REAR BOOT LOCK SWITCH	190.00	1 PC	<i>su</i> 190.00	<i>X</i>
5 REVERSE SENSORS	172.00	2 PCS	<i>stan</i> 344.00	<i>✓</i>
			2,252.00	
		Less 10%	225.20	2,026.80
Labour				
6 PANEL BEATING	400.00	1 LA	400.00	<i>300</i>
7 PUTTY & RESPRAY	400.00	1 LA	400.00	<i>360</i>
			800.00	800.00
			Total	S\$ 2,826.80
			Add GST @ 7%	197.88
			Total Amount Payable	S\$ 3,024.68

Parts #2062
206.20

#1855.80
660

#2515.80
(/s \$2000)

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Veron Chen (LKKAuto)

From: Efeeda (Cheng Hoe -Yishun) <chmotor@singnet.com.sg>
Sent: Friday, 2 August 2019 2:57 PM
To: Veron Chen (LKKAuto)
Subject: SJW3744C DOA :08/07/2019 TP/ECICS
Attachments: S-chmys19080214540.pdf; _MG_2434.JPG; _MG_2436.JPG; _MG_2437.JPG; _MG_2438.JPG; _MG_2439.JPG; _MG_2440.JPG; _MG_2441.JPG; _MG_2944.JPG; _MG_2945.JPG; _MG_2946.JPG; _MG_2947.JPG; _MG_2948.JPG; S-chmys19080214540.pdf

Hi Veron,

Attached please find the photos and finalization list submit for your reference.

Kindly let us have your confirmation on the final sum – **S\$2000 / 3DAYS** via email.

We look forward to receiving your early confirmation.

Thanks & Rdgs
Efeeda
Cheng Hoe Motor Pte Ltd

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Aug 2019 10:25 Edit Reg		16 Jul 2019 00:00 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	0, Co. Reg. No.: 0, Email: EMAIL@EMAIL.COM								
Main Claimant:	KOH JOO MENG EUGENE(XU YUMING EUGENE), ID: S7516035F								
Vehicle Reg. No.:	SJW3744C	Date of Loss:	08/07/2019 08:00 - :59 [111 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / DMPC1900180H/CT		Policy/Cover Note No.:						
Vehicle Reg. No. (Insured):	SKG3155A	Policy No. (Claimant):							
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Crystabelle Tan - 6303 0190]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 26/07/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJW3744C (DMPC1900180H/CT)
[SKG3155A]
TP
KOH JOO MENG EUGENE(XU YUMING EUGENE)
Jul 8 2019 8:00AM
[0]
Cheng Hoe Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
2	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
3	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
4	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
5	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
6	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
7	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
8	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
9	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
10	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
11	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
12	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
13	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
14	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
15	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
16	05/08/19 12:10	General View		Load JPG	<input checked="" type="checkbox"/>						
17	05/08/19 12:12	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
18	05/08/19 12:12	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
19	05/08/19 12:12	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
20	05/08/19 12:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
21	05/08/19 12:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
22	05/08/19 12:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS19012522/KVF3E2

Date: 28/08/2019

REFERENCE

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : SJW3744C **Insured Vehicle No :** SKG3155A
 Date of Loss: 08/07/2019 Nature of Claim: TP Claim No: DMPC1900180H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJW3744C**
 Make & Model: CHEVROLET CRUZE, 1.6 (A) Engine No: F16D35447821
 Reg. Date: 19/03/2010 (Man. Year: 2010) Chassis No: KL1JA6961AK618457
 Colour: Metallic Red Odometer: 114850 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
 Front Left Side: West Lake 8 mm Rear Left Side: Hankook 6 mm
 Front Right Side: West Lake 8 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,026.80	1,855.80	171.00	8.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	660.00	140.00	17.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,826.80	2,515.80	311.00	11.00
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	2,826.80	2,000.00	826.80	29.25
+ GST 7.00/7.00% (S\$)	197.88	140.00	57.88	29.25
Nett Amount (S\$)	3,024.68	2,140.00	884.68	29.25

INSPECTION

Date of Assignment: 16/07/2019
 Date Inspected: 16/07/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Aug 2019)
Parts: 143	CHEVROLET CRUZE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW3744C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Buckled	1,151.00 FL	*1,151.00 FL	
2	1		*REAR BUMPER REINFORCEMENT	Buckled	560.00 FL	*560.00 FL	
3	1		*REAR BUMPER TOW COVER	Dented	7.00 FL	*7.00 FL	
4	1		*REAR BOOT LOCK SWITCH	Serviceable	190.00 FL	*- FL	
5	2		*REVERSE SENSORS	Shorted	344.00 FL	*344.00 FL	
					Sub Total (S\$)	2,252.00	2,062.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	225.20	206.20
					Total Parts (S\$)	2,026.80	1,855.80

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	300.00
2	PUTTY & RESPRAY	New	400.00	360.00
Gross Labour Cost (\$\$)			800.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >