

ASS. REC. BY:

REF:

CS3/CT119012528/Gct302

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person):

Tan Kah Long

of

CTI

Date/Time:

16.7.19 12.21 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMA 3358P

Insured:

GBF 3104J

at Workshop m/s

Green Star Spray Painting

Tel:

65463092

of

Blk 3011 Bedok North Ave 4 # 01-2004

Policy No:

DM CVSN 30561118000

Claim No:

SNM 19D203293102

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12.7.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

* PRS *

H.O.D. Endorsement:

Date/Time:

16.7.19 1.17 p.m

Person Contacted:

Jane

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SMA 3358P X

GBF 3104J X

ASS. FILE BY

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMA 3358P

at Workshop m/s Green Star 65463092

of Blk 301 Bedok Nth Ave 4 #01-2004

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMA 3358P

Yr Regn:

29 Nov 2016

Type: M / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

c.c

1.5 1498

Colour

Green

A/C:

Insured / Std / NI / NA

Sp. Reading

63648

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRH FC 1660 GT 000349

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235 / 40 ZR18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

16-07-19

*Survey held at

w/s

5:15pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$3000

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

3 + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Report Format:

PRE.

Lump Sum / L&L (\$

150

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jul 2019		16 Jul 2019 12:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer]																								
Insured:																								
Main Claimant: LOH KIM LIAN , ID: S0798064G																								
Vehicle Reg. No.: SMA3358P Date of Loss: 12/07/2019 14:00 - :59																								
Claim Type: TP / SNM19D203293C02 Policy/Cover Note No.: DMCVSN30561118000																								
Vehicle Reg. No. (Insured): GBF3104J Policy No. (Claimant): 1900021585																								
Excess: S\$350.00																								
Repairer: GREEN STAR SPRAY PAINTING (HQ) BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E, 489977 Bedok - Tel:																								
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]																								
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000																								
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/07/2019]																								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail																								
There are no mail for this case.																								
<div> ALL ASSOCIATED TASKS </div> <div> View All Search Tasks Create New Task Complete </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Tuesday, 16 July 2019 12:15 PM
To: jiamin.mak@alt.sg; assignments
Cc: jerdine.wang@alt.sg; vincent@alt.sg; allister@alt.sg; sales@greenstarsp.com
Subject: RE: OUR REF : SNM19D203293/TANKL - RE: PRI - SMA 3358 P

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Jiamin,

We refer to your email of 16.07.2019.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: jiamin.mak@alt.sg [mailto:jiamin.mak@alt.sg]
Sent: Tuesday, 16 July, 2019 12:12 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Cc: jerdine.wang@alt.sg; vincent@alt.sg; allister@alt.sg; sales@greenstarsp.com
Subject: RE: OUR REF : SNM19D203293/TANKL - RE: PRI - SMA 3358 P

Dear Sir,

We refer to your email dated 16 July 2019.

We have our client's instructions to reject your proposal on your Single Joint Expert.

We propose to use the motor surveyor(s) named in the list below to conduct the joint pre-repair survey as a Single Joint Expert:

- WG Appraisal Services

Kindly let us hear from you within 2 working days as per the new NIMA protocol failing which we will proceed with the necessary.

Thank you.

Best Regards,

Jiamin

For and on behalf of
Allister Lim

**ALLISTER LIM & THRUMURGAN
ADVOCATES & SOLICITORS**

111 North Bridge Road
#11-04 Peninsula Plaza
Singapore 179098
Telephone : 6422 2187
Facsimile : 6438 1211

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at mail@alt.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Tuesday, July 16, 2019 12:00 PM
To: jiamin.mak@alt.sg
Cc: jerdine.wang@alt.sg; vincent@alt.sg; allister@alt.sg; sales@greenstarsp.com
Subject: RE: OUR REF : SNM19D203293/TANKL - RE: PRI - SMA 3358 P

Without Prejudice

Dear Jiamin,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
LOW SAR HUEI
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN

XING QUO QIANG
KENNETH KONG
HONG FOOK CHOY
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Tuesday, 16 July, 2019 10:50 AM

To: jiamin.mak@alt.sg; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Cc: jerdine.wang@alt.sg; vincent@alt.sg; allister@alt.sg; Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>; sales@greenstarsp.com

Subject: OUR REF : SNM19D203293/TANKL - RE: PRI - SMA 3358 P

Dear All,

Please note that officer in charge is Kah Leong – 63896193.

Dear Kah Leong,

Please conduct PRS for SMA3358P.

Thank you

Lim Shu Min

Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896156 | F: (65) 62247175

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: jiamin.mak@alt.sg [mailto:jiamin.mak@alt.sg]
Sent: Monday, 15 July, 2019 5:17 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: jerdine.wang@alt.sg; vincent@alt.sg; allister@alt.sg; Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>; sales@greenstarsp.com
Subject: PRI - SMA 3358 P

Your Ref: GBF 3104 J

Our Ref: AL.INS.2019.SMA3358P

15 July 2019

**CHINA TAIPING INSURANCE (SINGAPORE)
COMPANY LTD**
3 Anson Road
#16-00 Sringleaf Tower
Singapore 079909

BY EMAIL ONLY

Dear Sirs,

ACCIDENT INVOLVING SMA 3358 P & GBF 3104 J ALONG CARPARK ENTRANCE OF ALBERT COMPLEX ON 12 JULY 2019 AT ABOUT 1410 HOURS

We act for the owner of vehicle no. SMA 3358 P.

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop:-

GREEN STAR SPRAY PAINTING
Blk 3011 Bedok North Avenue 4
#01-2004 Bedok Industrial Park E
Singapore 489977
Person In-Charge: Jane
Mobile Number: 6546 3092

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Please contact our staff, Jerdine / Jiamin at 6422 2187 or email us at jiamin.mak@alt.sg / jerdine.wang@alt.sg for future correspondences.

Best Regards,

For and on behalf of
Allister Lim

**ALLISTER LIM & THRUMURGAN
ADVOCATES & SOLICITORS**

111 North Bridge Road
#11-04 Peninsula Plaza
Singapore 179098
Telephone : 6422 2187
Facsimile : 6438 1211

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at mail@alt.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	8064G
Vehicle No.:	SMA3358P
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.5 TURBO VTIS SR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B71627405
Chassis No.:	MRHFC1660GT000349
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$26,990.00
Original Registration Date:	29 Nov 2016
First Registration Date:	29 Nov 2016
Transfer Count:	1
Actual ARF Paid:	\$24,786.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2026
PARF Rebate Amount:	\$18,589.00
COE Expiry Date:	28 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,500.00
COE Rebate Amount:	\$41,621.00
Total Rebate Amount:	\$60,210.00

The information contained herein is correct as at 16 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 15/07/2019 14:12
 Date Of Accident 12/07/2019 14:10
 Exact Location Of Accident CARPARK ENTRANCE OF ALBERT COMPLEX
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMA3358P
Insured/Policyholder
 Name Of Registered Owner LOH KIM LIAN
 NRIC No S0798064G
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-90665883
 Alternative Phone No Others-90665883

Vehicle Particulars

Manufacturer HONDA
 Model CIVIC 1.5 TURBO VTIS SR
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 1900021585
 Cover Note Number

Driver

Name of Driver BENEDICT HO BOON LEE
 NRIC No S7935260H
 Date Of Birth 24/10/1979
 Occupation OUTDOOR
 Date Of Driving Pass 23/05/2017
 Driving Experience 2 YEARS AND 1 MONTH
 Gender MALE
 Mobile Number (LOCAL) +65-93835384

Fax Number

Contact Number

EMail Address

BENEDICT@HBLPRODUCTIONS.COM.SG

Address

BLK 510B YISHUN STREET 51
#13-585

Postcode

762510

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

CHILDREN

Vehicle Registration Number of Driver's Own
Vehicle-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-**General Information of the Accident**

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved
in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by
ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)
soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

VIDEO - GREENSTAR SPRAY PAINTING

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBF3104J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

• Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN**IMPORTANT NOTICE**



1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 15 07 19
02 15 PM

Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No.: 

SKETCH PLAN

ROAD

ON ALBERT COMPLEX

* STN LTM A
SQUARE

CARPARK ENTRANCE

SMA 3358P

(XX)

H11
B-1

GBF 3104

(SIGNAL ON AND TURNING
INTO CARPARK)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

① WAS TURNING INTO CARPARK ENTRANCE
OF OK ALBERT COMPLEX ON 12th JULY
ABOUT 2.13 PM

② SIGNAL WAS ON SHOWING ABOUT (LEFT TURN),
SLOWED DOWN TO TURN
HIT BY LORRY [GBF 3104] WHICH FAILED
TO BRACE / WAS FOLLOWING TOO CLOSELY.

Repair at workshop: GREENSTAR SPRAY
PAINTING.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 15th JULY
2.05 PM.

Reporting Centre Personnel's Signature
Name: Tan Kwee Choo
NRIC/FIN No.: 2084083A

CERTIFICATE OF INSURANCE






































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jul 2019		16 Jul 2019 12:21 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	LOH KIM LIAN , ID: S0798064G								
Vehicle Reg. No.:	SMA3358P	Date of Loss:	12/07/2019 14:00 - :59 [31 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203293C02	Policy/Cover Note No.:	DMCVSN30561118000						
Vehicle Reg. No. (Insured):	GBF3104J	Policy No. (Claimant):	1900021585						
		Excess:	S\$350.00						
Repairer:	GREEN STAR SPRAY PAINTING (HQ) BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E, 489977 Bedok - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents




*SMA3358P (SNM19D203293C02)
[GBF3104J]
TP
LOH KIM LIAN
Jul 12 2019 2:00PM
[-]
GREEN STAR SPRAY PAINTING

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/07/19 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
21	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
22	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
23	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	24/07/19 17:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	24/07/19 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	24/07/19 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	24/07/19 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	24/07/19 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	24/07/19 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	24/07/19 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	24/07/19 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	24/07/19 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	24/07/19 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	15/07/19 18:04	Accident Statement	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	15/07/19 17:20	SCENE PHOTO	 Load JPG	<input checked="" type="checkbox"/>
2	15/07/19 17:20	SCENE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
3	15/07/19 17:20	SCENE PHOTO	 Load JPG	<input checked="" type="checkbox"/>
4	15/07/19 18:04	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	15/07/19 18:04	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	15/07/19 18:04	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	15/07/19 18:04	CHASSIS NUMBER	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	15/07/19 17:30	Sketch Plan	 Load TIF	
2	15/07/19 17:30	CERTIFICATE OF INSURANCE	 Load TIF	
3	15/07/19 17:31	OWNER'S NRIC	 Load TIF	
4	15/07/19 17:31	DRIVER'S NRIC + DRIVING LICENCE	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19012528/GCF3E2

Date: 29/07/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30561118000

Claimant Vehicle
No : SMA3358PInsured Vehicle
No : GBF3104J

Date of Loss: 12/07/2019

Nature of Claim: TP

Claim
No: SNM19D203293C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMA3358P

Make & Model: HONDA CIVIC, 1.5 TURBO VTI-S SR (A)

Engine No: L15B71627405

Reg. Date: 29/11/2016 (Man. Year: 2016)

Chassis No: MRHFC1660GT000349

Colour: Green

Odometer: 63648 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40Z R18	Rear Tyre Size:	235/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/07/2019

Date Inspected: 16/07/2019 Inspected At:

GREEN STAR SPRAY PAINTING (HQ)
BLK 3011 BEDOK NORTH AVENUE 4
#01-2004 BEDOK INDUSTRIAL PARK E
Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2019)
Parts:	143	HONDA CIVIC 1.5 TURBO VTi-S SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA3358P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >