

22/03/2019

ASS. REC. BY:

REF:

CS3/111 19012535/Gcd307

Special Instruction:

Surveyor: GQ

## ASSIGNMENT (Office)

From (Person): Gabriel

of

HI

Date/Time:

16/7/2019

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKD 30655

Insured:

SHA 7534E

at Workshop in/s Platinum Werks

Tel:

8826 1413 Yu Sheng

of 53 Ubi Ave 1 #01-25

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/7/2019

CA / REV / REP. / REV 24 HRS

PRS

H.O.D. Endorsement:

Date/Time:

16/7

Person Contacted:

Yu Sheng

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction
	Delivered (X)
	SKD 30655 NA/INC19012448/24
	SHA 7534E CC4/ASM19001535/1C1 pg 3
	Dismantle: 18/7/2019 0634pm
	After repair: 23/7/2019 1215pm

ASS. REC. BY: PR

REF: III

# ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKD 3065 S

at Workshop m/s Platinum Werkz

of 53 Ubi Ave 1 #01-25

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

<input checked="" type="checkbox"/>	
N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKD 3065 S

Yr Regn:

Nov / 10

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Scirocco 1.4

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

112710

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVW ZZZ 138 BV001582

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40 ZR18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

16-07-19

Survey held at

w/s

2pm

Des. of Damages: ☒ Fr / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$1000 - \$2000

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

3 + PS. \$1

Photos

Others

TOTAL

120

11

131

Report Format: PRC

Lump Sum / L.R. \$

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Inv (\$)

☐ : Weekend (\$)

## Nivitha (LKK Auto)

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Tuesday, 16 July 2019 11:57 AM  
**To:** Wendy Jiang; 'sur@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Lua Siew Hui; Pooi Chin Han Daniel  
**Subject:** RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SKD3065S (Accident involving SKD3065S and SHA7534E on 13.07.2019)[1907-7367(PW)(PD)]  
**Attachments:** sha7534e\_20190716103414.pdf

Dear Sir / Mdm

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO. : SKD3065S  
III INSURED VEHICLE NO. : SHA7534E  
DATE OF LOSS : 13.07.19

We acknowledge receipt of your email.

**In compliance to Pre-Action Protocol for NIMA cases, we note that**

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSUTLANTS to conduct the pre-repair survey.

This claim is handled by **Daniel**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

**\*\*We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

**\*\*Surveyor kindly upload this assignment to Merimen.**

Thank You.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

Veh lu- XGQ

**From:** Wendy Jiang [mailto:wendy\_jiang@rssolomon.com]  
**Sent:** 16 July, 2019 11:12 AM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** Lua Siew Hui <lua\_siewhui@rssolomon.com>  
**Subject:** Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. SKD3065S (Accident involving SKD3065S and SHA7534E on 13.07.2019)[1907-7367(PW)(PD)]

Dear Gabriel,

We refer to your email of even date.

We write to inform that our client will be appointing his own Surveyors.

In this respect, please contact Mr. Yu Sheng of Platinum Werkz Pte Ltd at Mobile No. 8826 1413 for a pre-repair survey of our client's vehicle located at 53 Ubi Avenue 1 #01-25 Paya Ubi Industrial Park Singapore 408934.

Yours sincerely  
Wendy Jiang | Legal Executive

**R. S. Solomon LLC | 正氣律師事務所**

**Advocates & Solicitors**

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e [wendy\\_jiang@rssolomon.com](mailto:wendy_jiang@rssolomon.com) | w [www.rssolomon.com](http://www.rssolomon.com)

---

The contents of this email (including any attachment) are strictly confidential and may contain privileged information.

If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system.  
Thank you.

On Tue, Jul 16, 2019 at 10:49 AM Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*

**Gabriel Wee**



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling

and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4271
<b>Vehicle Details</b>	
Vehicle No.:	SKD30655
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jul 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SCIROCCO 1.4 TSI A
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	CAV204396
Chassis No.:	WVWZZZ13ZBV001582
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$22,768.00
Original Registration Date:	03 Nov 2010
First Registration Date:	03 Nov 2010
Transfer Count:	3
Actual ARF Paid:	\$22,768.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Nov 2020
PARF Rebate Amount:	\$12,522.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	02 Nov 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$27,389.00
COE Rebate Amount:	\$3,490.00
<b>Total Rebate Amount:</b>	<b>\$16,012.00</b>

The information contained herein is correct as at 24 Jul 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	15/07/2019 12:14
Date Of Accident	13/07/2019 16:35
Exact Location Of Accident	BLK 882 TAMPINES ST 84 CARPARK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKD3065S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YEO KAI JIE
NRIC No	S9211427I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97972658
Alternative Phone No	OFFICE-97972658
<b>Vehicle Particulars</b>	
Manufacturer	VOLKSWAGEN
Model	SCIROCCO 1.4 TSI A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106322968
Cover Note Number	
<b>Driver</b>	
Name of Driver	YEO KAI JIE
NRIC No	S9211427I
Date Of Birth	31/03/1992
Occupation	INDOOR
Date Of Driving Pass	06/01/2014
Driving Experience	5 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97972658
Fax Number	
Contact Number	OFFICE-97972658
Email Address	NOEMAIL



Address	BLK 882 TAMPINES STREET 84 #07-80
Postcode	521882
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA7534E
Vehicle Make/Model/Colour	HYUNDAI SONATA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	RAIMEI BIN RAHMAN
NRIC/Passport Number	S7328806A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Accident Sketch Plan


### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulations, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Person's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan

A - SKD 30655

B - SH 17534E

## SKETCH PLAN





## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On the stated date and time, my vehicle was parked  
 parked stationary. ~~Vehicle~~ Vehicle B reverse and hit  
 onto my front left of my vehicle.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/PIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jul 2019 09:34 <a href="#">Edit Reg</a>		16 Jul 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: -, Co. Reg. No.: -									
Main Claimant: <b>YEO KAI JIE</b> , ID: S9211427I									
Vehicle Reg. No.: <b>SKD3065S</b>		Date of Loss: 13/07/2019 16:00 - :59 [104 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP</b>		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): <b>SHA7534E</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Platinum Werkz Pte Ltd (HQ)</b> 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park, 408934 Ubi - Tel: 6741 610									
Handling Insurer: <b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Pooi Chin Han Daniel</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 02/08/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKD3065S

[SHA7534E]






































TP

YEO KAI JIE

Jul 13 2019 4:00PM

[-]

Platinum Werkz Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View In Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/07/19 17:34	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
22	24/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
23	24/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	24/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	24/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	24/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	24/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	24/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	24/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	24/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	24/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	24/07/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	24/07/19 17:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
34	24/07/19 17:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
35	24/07/19 17:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
36	24/07/19 17:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	24/07/19 17:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	24/07/19 17:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	24/07/19 17:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	24/07/19 17:34	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	25/07/19 08:36	Singapore Accident Statement	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19012535/GCF3E2

Date: 30/07/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SKD3065S

Insured Vehicle No : SHA7534E

Date of Loss: 13/07/2019

Nature of Claim:

TP

Claim No: N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKD3065S

Make &amp; Model: VOLKSWAGEN SCIROCCO, 1.4 TSI (A)

Engine No: CAV204396

Reg. Date: 03/11/2010 (Man. Year: 2010)

Chassis No: WWWZZZ13ZBV001582

Colour: White

Odometer: 112710 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/40Z R18

Rear Tyre Size: 225/40Z R18

Front Left Side: Achilles 6 mm

Rear Left Side: Achilles 6 mm

Front Right Side: Achilles 6 mm

Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 16/07/2019

Date Inspected: 16/07/2019 Inspected At:

Platinum Werkz Pte Ltd (HQ)  
53 Ubi Ave 1 01-25 Paya Ubi Industrial  
Park  
Singapore 408934

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.



## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 30 Jul 2019)

**Parts:** 144      VOLKSWAGEN SCIROCCO 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SKD3065S)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >