



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19012541/Kpa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:JAS TAN

Date : 13-05-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHF 637L	Veh. Inspected	SKL 1004P
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S9M01TZR	Excess (\$)	0.00
Assign From		Assign Date	16/07/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV350	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JN1UC4E26Z0000018	Colour	WHITE / RED
Odometer	214683	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15X8	MICHELIN	3 mm
L/H Front Tyre	195 R15X8	MICHELIN	3 mm
R/H Rear Tyre	195 R15X8	MICHELIN	4 mm
L/H Rear Tyre	195 R15X8	MICHELIN	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/07/2019	Inspection Date	16/07/2019
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------