

22/03/2002

ASS. REC. BY:

REF:

CS/TM119012547/K1+f302

Special Instruction:

Surveyor

Kalin

ASSIGNMENT (Office)

From (Person):

Munulhaida Bnp Mand

of

TM1

Date/Time:

16.7.19 14.55 p.m

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 4241D

Insured:

SLE 6728B

at Workshop m/s

Comfadelgro

Tel:

6214 8300

of

59 Ioyang Drive

Policy No:

MK 000582

Claim No:

M 1905341

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14.7.19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

16.7.19 3.16 p.m

Person Contacted:

Jumadi

Vehicle

(IN) OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 4241D NA/AWA16007435/104

SLE 6728B X

(08/11/13)

Surrey: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 42419 Yr Regn: 17 Mar 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Zing C.C. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 150682 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 1CMHC85/CVH4022835

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD Alloy or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fallin - Front Parati - Rear

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 14/7/19 D.O.I. 15/7/19Survey held at CPGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Req

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
19/7/19	Calculated PIP \$1168.12 / 24hrs. (Red: 659.36%)

RECEIVED 19 JUL 2019

Date/Time, File Pass to?

1) 19/7 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1Survey Fee: 250

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS _____☐ : Interview (\$ _____) Photos _____☐ : _____ Photos _____

11

261

TP

P/P 1168.12

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jul 2019 14:58 Sendback Est	15 Jul 2019 15:06 S\$1,838.12	16 Jul 2019 14:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	LION CITY RENTALS PTE LTD, Co. Reg. No.: 201504621K		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHD4241D	Date of Loss:	14/07/2019 16:00 - :59 [27 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1905341	Policy/Cover Note No.:	MK000582 (Third Party Only) Coverage: 25/06/2019 - 24/02/2020
Vehicle Reg. No. (Insured):	SLE6728B	Policy No. (Claimant):	
		Excess:	S\$1,600.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Nurulhaida Binte Mohd Seain]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

COMFORT DELGRO



Date/Time: 15.07.2019 13:27

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305311156

MER
COMFORT TRANSPORTATION PTE LTD
7010045
MER NO.
SS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

REGN NO.: SHD4241D	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ	DATE/TIME IN 14.07.2019 19:45
YR OF MANU 17.03.2017	TARGET DATE
CHASSIS CODE KMHC851CVHU022835	COMPLETION DATE/TIME


Tokio Marine

JNT CARD NO.

JOB DESCRIPTION

Accident Date: 14.07.2019
NATURE: 3P 14.07.2019/C

3/NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

lo.: SHD4241D

LKE

Vehicle No.: SHD4241D

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/07/2019 11:09
Date Of Accident	14/07/2019 16:25
Exact Location Of Accident	SENTOSA GATEWAY TWDS TELOK BLANGAH RD.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD4241D
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ HYBRID

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	LOW SOON POH
NRIC No	S1753738E
Date Of Birth	27/12/1966
Occupation	OUTDOOR
Date Of Driving Pass	03/03/1997
Driving Experience	22 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91251108
Fax Number	
Contact Number	
EEmail Address	DESHILAO@HOTMAIL.COM

Address	BLK 488A TAMPINES AVENUE 9 #09-164
Postcode	520488
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : - GENDER: : FEMALE
Passenger 2	NAME: : - GENDER: : FEMALE
Passenger 3	NAME: : - GENDER: : FEMALE
Passenger 4	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED * TYPE OF ACCIDENT :- HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE6728B
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

KOH KWEE HUAT

NRIC/Passport Number

S0044292E

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

RH FRONT

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

15/7/19
Jackson Heng
CSO

SKETCH PLAN

(A) SHD 4241D
(B) SLE 6728B



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14/7/2019 at about 1625 hrs, I vehicle A was driving my taxi along Sentosa gate way toward telok blangah Rd. While I was in the middle at the bend, Vehicle B was on my left hit vehicle A at bend Caused the damage. NO one was injured at that time.

DECLARATION






I declare the foregoing particulars are true in every respect.
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

15/7/19
Jackson Heng



COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4241D

DATE 15/7/2019 14:25

MAKE :

MODEL : HYUNDAI IONIQ

Date/Kalvin

Lee

Tokio Marine

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Wheel Hub Cap (LH) <i>hairs</i>			\$ 346.40	
	Rear Door (LH) X repair				
	Rear Fender (LH) X repair				
	Rear Bumper X repair				
	SUB TOTAL			\$ 346.40	
	LESS 20%			\$ 69.28	
	DISCOUNTED TOTAL			\$ 277.12	
	Rear Bumper Rubber Mat X			\$ 50.00	Nett
	Rear Door Comfort & Apps Sticker (LH)			\$ 80.00	Nett
				\$ 130.00	
	Labour Charge				
	Panel Beating-Repair Rear Bumper & Rear Fender			\$ 500.00 200	
	Spray Painting Charge			\$ 750.00 600	
	Tuff Kote			\$ 50.00 X	
	Rear Wheel Alignment			\$ 120.00 X	
	<i>Merina Fee</i>			\$ 11	
	TOTAL LABOUR			\$ 1,420.00	
	ESTIMATE TOTAL			\$ 1,827.12	
	<i>Kalvin 16/07/19</i>				
	<i>15/7/19 1505h.</i>				
	<i>2 Days</i>				
	<i>P/P</i>				
	<i>After Repair photo</i>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

COMFORTDELGRO ENGINEERING

Our Job Ref No 305311156
Date : 18.07.19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr KALVIN ANG
Vehicle Reg No. SHD4241D CTPL

Fax :


14.07.19


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE SLE6728B
2. The finalized amount shall be:

(a) Spare Parts after List discount	<u>\$357.12</u>
(b) Labour Charges	<u>\$811.00</u>
Total for Part-By-Part Repair Cost	<u>\$1,168.12</u>
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	<u> </u>
Final Lumpsum Repair cost	<u> </u>
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature : 
Name : Kalvin
Date : 19/7/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305311156
REGN NO : SHD4241D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ
DATE OF REGN : 17.03.2017
DATE/TIME IN : 14.07.2019 19:45
ACCIDENT DATE : 14.07.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 03-01-0104-2061-G	IONIQV1/3 CAP ASSY-WHEEL	1 L	346.40	20.00	277.12
0002 28-01-0103-2013-A	I40V3 APP LOGO REAR DOOR	1 N	80.00	2.00-	80.00

SUB-TOTAL : 357.12

JOB NATURE

0000 L	PANEL BEATING	200.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	600.00
0002 L	MERIMEN CHARGE	11.00

SUB-TOTAL : 811.00

TOTAL : 1,168.12

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :






























...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Jul 2019 14:58 Sendback Est	15 Jul 2019 15:06 S\$1,838.12	16 Jul 2019 14:55 Edit Adj Rpt	S\$1,168.12 Edit Estimates	S\$1,168.12 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	LION CITY RENTALS PTE LTD , Co. Reg. No.: 201504621K								
Main Claimant:	CTPL								
Vehicle Reg. No.:	SHD4241D	Date of Loss:	14/07/2019 16:00 - :59 [27 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M1905341	Policy/Cover Note No.:	MK000582 (Third Party Only) Coverage: 25/06/2019 - 24/02/2020						
Vehicle Reg. No. (Insured):	SLE6728B	Policy No. (Claimant):							
		Excess:	S\$1,600.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Nurulhaida Binte Mohd Seain]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 25/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHD4241D (M1905341)
[SLE6728B]
TP
CTPL
Jul 14 2019 4:00PM
[LION CITY RENTALS PTE LTD]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	15/07/19 15:06	Repairer Estimates	 Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	16/07/19 13:26	Accident Statement From:SC - Reg. No: SLE6728B, Claimant: LION CITY RENTALS PTE LTD	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
2	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
3	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
5	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
6	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
17	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
18	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
19	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
20	17/07/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
21	17/07/19 08:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
22	17/07/19 08:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	17/07/19 08:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	17/07/19 08:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	17/07/19 08:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	15/07/19 15:09	E-filed GIA report	 Load PDF	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	16/07/19 13:30	TP - SHD4241D SAS	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19012547/K1TF3E2

Date: 24/07/2019

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MK000582
Claimant Vehicle No : SHD4241D **Insured Vehicle No :** SLE6728B
 Date of Loss: 14/07/2019 Nature of Claim: TP Claim No: M1905341

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD4241D**
 Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEGU329722
 Reg. Date: 17/03/2017 (Man. Year: 2017) Chassis No: KMHC851CVHU022835
 Colour: Blue Odometer: 150682 km
 Engine Capacity: 1580 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Falken 7 mm Rear Left Side: Davanti 7 mm
 Front Right Side: Falken 7 mm Rear Right Side: Davanti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	407.12	357.12	50.00	12.28
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,420.00	800.00	620.00	43.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,838.12	1,168.12	670.00	36.45
+ GST 7.00/7.00% (S\$)	128.67	81.77	46.90	36.45
Nett Amount (S\$)	1,966.79	1,249.89	716.90	36.45

INSPECTION

Date of Assignment: 16/07/2019 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
 Date Inspected: 15/07/2019 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969
 Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2019)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD4241D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WHEEL HUB CAP LH	Grazed	346.40 FL	*346.40 FL
2	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 F	*- F
3	1		*REAR DOOR COMFORT & APPS STICKER LH	Necessary	80.00 F	*80.00 F
4	1		*REAR DOOR (LH) (NPA)	Repair	-	*- FL
5	1		*REAR FENDER (LH) (NPA)	Repair	-	*- FL
6	1		*REAR BUMPER (NPA)	Repair	-	*- FL
					Sub Total (S\$)	476.40 426.40
					- List Item Discount on L Items 20.00/20.00% (S\$)	69.28 69.28
					Total Parts (S\$)	407.12 357.12

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING - Rear Bumper & Rear Fender Lh	New	500.00	200.00
2	SPRAY PAINTING CHARGE	New	750.00	600.00
3	TUFF KOTE	New	50.00	0.00
4	REAR WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$)			1,420.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >