


INS. CASE OWNER: Sushe | CC 4 ^{RM} AXA1901 2553, U wb3 | LKK:
 IDAC:

Surveyor: marius | DOI: 10/1/19 | Date / Time: 16/1/19
 Registered in Merimen:

Pre-assign / CCU / FTE: SHD 460P

Insured Vehicle No.: Claim No.: SMO2TEC12682P
 Name of Insured: TRANSCAB SERVICES PTE LTD Policy No.:
 Insured Tel No.: HP: Make / Model:
 Excess Sec II :SS D.O.A: 8/1/19 Place of Accident:
 Is driver the owner? (YES / NO) Nature of Accident:
 If NO, Driver Name / Age: OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
 Driver Tel No.: (VL: YES / NO) Insured Liability: % Final? Yes / No



Date/ Time	STAGE	DATE / PIC
	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
<u>24/1/19</u>	Call OI:	<u>> 24/1/19</u>
	After call Itr to OI:	<u>UVA</u>
<u>28/1/19</u>	Documentation Check List:	Handler Typist
	Notification Itr (if non-pickup)	<input type="checkbox"/>
	After call Itr to OI	<input checked="" type="checkbox"/>
	Authorisation To Act	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:
 Repair Cost: \$S (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: 28/1/19 Confirm with: Susan Email Call
 Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 26
 Repair Cost: \$S 1650.00
 Loss of Rental (LOR): \$S (days)
 Loss of Use (LOU): \$S 400.00 (90 x 5 days)
 Loss of Income (LOI): \$S (5 x days)
 LOR only LOU only LOR + LOU LOR + LO [Tick only one]
 GIALTA Search: \$S 7.45
 Medical: \$S
 Disbursement: \$S (e.g. Tow/ Independent)
 Legal Cost: \$S

Total: \$S 2057.45 Global Sum \$S:

FINAL PAYMENT Date/Time: Confirm with: Email Call
 Payee 1: \$S 2057.45 Name 1: Lin's Brother Auto Engineering Workshop.
 Payee 2: (Strike if N.A.) \$S Name 2:
 Payee 3: (Strike if N.A.) \$S Name 3:

02/11/13 wef
ASS. REC. BY: MARIS

REF:

AXA

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: G RF 3539M
at Workshop m/s 10'S B30
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: G RF 3539M Yr Regn: 9/16
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or LM
Make: Toyota Hiace c.c. 2982
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 90485 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: KDH 2015021763
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195 R15
R: _____

(Policy Condition)
Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or MAXXIS
Front R/Bal. 6 mm Rear R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 8/7/19 D.O.I. 10/7/19

Bal. or Market Value: 48
IDAC Accident Rpt: _____ Consistent? : Yes or No
G/A PR Seen: 2 Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: 20 % 3 Val: Yes or No
CA / REV / REP. / 24 HRS 1196
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Lt O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
17/11/19 218/19 Confirm cl's \$1650.00 with 3 working days

12ed = \$4162.90
72.1

Date/Time, File Pass to? : Prel. Report
1) : Final Report
Date/Time, File Return to?
2) _____
Days Of Repair: _____
Resurvey No. of Trip: _____ Survey Fee: _____
Transportation: _____
Add Fee: : Site Insp (\$ _____) S + RS \$ _____
 : Interview (\$ _____) Photos
 : Tech. Invs (\$ _____) Others
 : Weekend (\$ _____)
Report Format : _____
Lump Sum / I.B.I. (\$) _____
TOTAL _____

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBG3539M190708

Estimate

Customer

Name: AXA Insurance Singapore Pte Ltd

Date: 15-07-19

Address: Motor Claims Department

Vehicle No: GBF3539M

8 Shenton Way #27-01

Model/Make: Toyota Hiace

AXA Tower

Singapore 068811

3.0 DX Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bonnet ^{TP}	\$ 853.30	
2	Head Lamp Rh holder one 781.40	\$ 930.70	
3	Grille	\$ 665.50	α
4	Grille Clip 1 set ^{1m}	\$ 30.00	SN α
5	Brake Master Pump ^{Re}	\$ 546.70	
6	Brake Air Tank ^{AA}	\$ 1,406.70	X
7	"Corporate" Advertisement & Artwork ^{Re}	\$ 180.00	805.00
	To remove, replace and transfer Brake Pump Labor Charge	\$ 300.00	40
	To check all wiring & electrical component for proper function	\$ 50.00	20
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 250.00	17x
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 300.00	200
	To putty & spray painting & including touch up paint on accident affected	\$ 250.00	200
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 50.00	30

Total Parts & Labour of estimate for damaged vehicle \$ 1,200.00

Total amount in Lump Sum Basis for repaired vehicle



SDLS:

M/s Liu's Brother Auto Engrg Wks

not allowed
 4/S \$1650.00
 telephone charges
 3 day.

P-2181.4
 50%
 P 1090.70
 S.V 80.00
 labor 490.00
 1660.70



5812-9

> Back to OneMotoring



Land Transport Authority
 10 Sin Ming Drive
 Singapore 575701
 GST Registration No. M4-0006529-2

Print Date/Time : 15 Jul 2019 / 11:05:31

Receipt Date/Time : 15 Jul 2019 / 11:05:31

Tax Invoice/Receipt

Receipt No. ITNET-00000-190715-000929

Previous Receipt No.

**S/N Item Description/
 Business Transaction Reference
 No.**

**Amount Before
 GST (\$\$)** **GST
 Amount (\$\$)** **Amount
 After GST (\$\$)**

Result of Insurance Enquiry - SHD460P
 As at 08 Jul 2019/08:00:00
 Insurance Co: AXA INSURANCE PTE LTD

1	Insurance Enquiry - SHD460P Enquiry Fee 20190715110329933296	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45

Paid By				
	xxxxxxxxxxxx4559	Credit Card Visa/MasterCard		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

SAVE \$\$ ON UR CAR INSURANCE RENEWAL

Compare 10+ Insurers **CLICK HERE >**

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Classic Offer! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan, Trade In Are Welcome, 100% Deposit Refund For Unapproved Loan, Classic Credit, StarAd

ABWIN ONE-STOP

Browse by Category

Back (1 2) Next >

Sort by Date Posted 20 results/page

31 vehicles

hiace

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

Search Selection

hiace		Any	Any	2016	Any	Any	Any	Available
-------	--	-----	-----	------	-----	-----	-----	-----------



Toyota Hiace 3.0M \$60,000 \$8,330 /yr 28-Sep-2016 2,982 cc - Van Available

Fuel Type: Diesel
Toyota Hiace High Roof Cargo Van With Low Mileage, Well Maintained Interior And Exterior, Front And Reverse Camera Included. Loan...
I-Deal Auto Trading Pte Ltd
Posted: 15-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 3.0M \$55,800 \$7,820 /yr 01-Sep-2016 2,982 cc - Van Available

Fuel Type: Diesel
\$3500 Drive Away! 100% Loan No Gemmick With Low Interest. High Trade In Private /commercial Vehicle. Monthly At \$852 Only. Come...
Car (5) Pte Ltd
Posted: 15-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 3.0M DX \$53,800 \$7,680 /yr 18-Jul-2016 2,982 cc 72,235 km Van Available

Fuel Type: Diesel
Toyota Hiace Manual Rear Aircon, 3 Days Delivery, Super Low Miles, No Need Repairs, \$0 Drive Away, Cash Rebate, High Loan With Lo...
ABWIN Bus Pte Ltd
Posted: 15-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 3.0M \$52,800 \$7,330 /yr 28-Sep-2016 2,982 cc 51,000 km Van Available

Fuel Type: Diesel
100% Loan At \$832 Monthly! Cheapest In Market! Guaranteed One Of The Best Condition! Original Tip Top Condition With No Repairs N...
Car (5) Pte Ltd
Posted: 15-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Camry takes on Volkswagen's Passat
The Toyota Camry offers more legroom for rear passengers, is sportier around corners and has more safety systems but the Volkswagen Passat is more affordable and feels more premium overall.
Find out more!



Toyota Hiace 3.0A DX \$55,800 \$8,250 /yr 21-Apr-2016 2,982 cc 70,500 km Van Available

Fuel Type: Diesel
1 Owner, Rare 5 Door, Toyota Hiace 3.0 Auto Transmission With Rear Aircon. Up To Full Loan Avail, Monthly At Only \$875. Powerful An...
Car (5) Pte Ltd
Posted: 15-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 3.0M DX \$51,800 \$7,340 /yr 04-Aug-2016 2,982 cc - Van Available

Fuel Type: Diesel
Look Here! Best Selling Van On Sale! Comes With Rear Aircon System. Very Good Condition. Wear And Tear Parts Been Replaced With...
ABWIN (1994) Pte Ltd
Posted: 15-Jul-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

Compare

◀ Service Request Details

Claim

S9M01TRC

Reference

None 

Loss Date

July 8, 2019

Report Date

Jul 15, 2019 4:09:00 PM

Request Date

July 16, 2019

Due Date

July 23, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: Susan

T: 9.57a.m

V: IN

G. ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

GBF3539M

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 1196N

Vehicle Details

Vehicle No.: GBF3539M

Vehicle to be Exported: No

Intended Deregistration Date: 16 Jul 2019

Vehicle Make: TOYOTA

Vehicle Model: HIACE DX 3.0 MANUAL

Primary Colour: Blue

Manufacturing Year: 2016

Engine No.: 1KD2604342

Chassis No.: KDH2015021763

Maximum Power Output: -

Open Market Value: \$30,644.00

Original Registration Date: 16 Sep 2016

First Registration Date: 16 Sep 2016

Transfer Count: 1

Actual ARF Paid: \$1,533.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 15 Sep 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$4,891.00

COE Rebate Amount: \$3,504.00

Total Rebate Amount: \$3,504.00

The information contained herein is correct as at 16 Jul 2019

OK

⏪ Re:TP MANDATE IA-S9M01TRC

Type

🗨 Question

Message

Approved. Please proceed. Thank you.

Reply

Our Ref: GBF3539M190708

Date: 25/07/2019

Your Ref:

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

Attn: Motor Claims Department

Dear Sir / Madam

TRAFFIC ACCIDENT ALONG Woodlands Train Station
INVOLVING GBF3539M **AND** SHD460P **ON** 08/07/2019

We/I, **Messers Goldbell Leasing Pte Ltd** (Nric / ROC No. **199001196N**), the registered owners of m/vehicle - GBF3539M at all material times of the above accident. Our/my vehicle was surveyed by " AXA " authorized appraiser and we/I based our/my claims on his recommendation for **S\$** 1,650-00 being the repair for 03 Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle - SHD460P when the same was involved in the aforesaid accident with our/my m/vehicle - GBF3539M.

We/I whereby you are the insurers of m/vehicle SHD460P and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle - GBF3539M has suffered loss and damage as follows:

(a) Cost of repairs	S\$	<u>1,650-00</u>
(b) LOU for pre-repair notice <u>02</u> days @ S\$ <u>80-00</u> [2982 cc]		<u>160-00</u>
(c) LOU Fee for <u>03</u> days @ S\$ <u>80-00</u> [2982 cc]		<u>240-00</u>
(d) GIA / LTA search fee		<u>7-45</u>
(e)		
Total Amount	S\$	<u>2,057-45</u>

We/I enclose herewith copies of the supporting documents for vehicle no. GBF3539M as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices and documents;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,


The owner of m/vehicle GBF3539M
Messers Goldbell Leasing Pte Ltd
cc. Liu's Bro Auto Engrg Ws

Suwanna (LKK Auto)

From: Suwanna (LKK Auto)
Sent: Friday, 26 July 2019 10:35 AM
To: 'claims@transcab.com.sg'
Cc: 'transcab_avaclaims@ava-ins.com'; Admin A; Vivian Lau (LKKAuto)
Subject: ACCIDENT INVOLVING SHD 460P AND GBF 3539M ALONG/AT WOODLANDS CHECKPOINT ON 08/07/2019

Dear Sir/ Mdm

OUR REF : CC4/ASM19012553/Uwb3 // S9M01TRC
YOUR REF : SHD 460P
ACCIDENT INVOLVING SHD 460P AND GBF 3539M ALONG/AT WOODLANDS CHECKPOINT ON 08/07/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a third party claim(s) from LIU'S BROTHER AUTO ENGINEERING WORKSHOP acting on behalf of the owner of GBF 3539M against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as it is opening the vehicle door and collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy. We also wish to inform you that Section II of the Motor Insurance Policy is attached, and capped, with an excess of 5,000 for third party claim settlements.

As Insurers, they shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to vivianlau@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Copy of the letter of authorization
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA Customer Care Centre.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact as at Ms. Vivian Lau (LKK Handler) 6841 8625 or vivianlau@lkkauto.com Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Best Regards,

Suwanna Te-Uttaruang | Admin support

LKK Auto Consultants Pte Ltd

Email Suwanna@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Authorization To Act

Attn: Motor Claims Department

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

I / We, Messers Goldbell Leasing Pte Ltd ("the third party claimant") of No. 18 Tuas Avenue 10 Singapore 639142 (address), owner of GBF3539M (vehicle no.) hereby authorize Liu's Brother Auto Engineering Workshop ("the workshop") to act for me / us with respect to my / our claim for repair costs and / or rental and / or loss of use ("claim") for my / our vehicle no. GBF3539M that was damaged pursuant to the accident which occurred on 08/07/2019 (date) along Woodlands Train Station (location) involving SHD460P ("the accident").

I / We further authorize the workshop to settle my / our above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my / our claim with payment cheque / s being made in favour of the workshop.

I / We further acknowledge that any settlement the workshop may reach on my / our behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle / s is concerned.

Dated this 07th day of August (month) 20 19 (year)

3rd Party Claimant:

Workshop:



Signature: _____

Signature: _____

Name: Goldbell Leasing Pte Ltd

Name: Liu's Brother Auto Engrg Workshop

Address: No. 18 Tuas Avenue 10

Address: 1 Kaki Bukit Avenue 6 #01-01

Singapore 639142

Singapore 417883

Nric/ROC No: 199001196N

ROB No: 53291793J



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SHD 460P (Insd veh)	Model: TOYOTA MIRLE
	GBF 3539M (TP veh)	
Date of Accident/ Time:	08/07/2019	

Repair Estimate:	S	5,859.00	
Final Repair Cost	S	1,650.00	
Loss of Use	S	400.00	05 days at S 80.00 per day
Rental (if any)	S		days at S per day
LTA / GIA Search Fee	S	7.45	
Others	S		
	S		
Final Settlement Sum	- S	2,057.45	

Payee Name : **Liu's Brother Auto Engineering Workshop**

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability 100 (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No, BOLA Scenario: No
 BOLA Liability: _____ (%) Assessed Liability (1): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks:

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and/or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp: Signature of Witness / Workshop stamp (if applicable): Name of Representative: **Liu's Brother Auto Engineering Workshop** Name of Witness: **Low Siew Yan (S1543134B)** Date: **- 8 AUG 2019** Date: **- 8 AUG 2019** ROB No. 53291793J

Signature of AXA's surveyor / Representative: Name of AXA's surveyor / Representative: **LKK** Date:

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417881
ROB No: 53291793J Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbro@gmail.com

Invoice/Ref No: GBG3539M190708

Final Bill

Customer

Name: AXA Insurance Singapore Pte Ltd

Date: 15-07-19

Address: Motor Claims Department

Vehicle No: GBF3539M

8 Shenton Way #27-01

Model/Make: Toyota Hiace

AXA Tower

Singapore 068811

3.0 DX Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bonnet	\$ 853.30	\$ -
2	Head Lamp Rh	\$ 930.70	\$ -
3	Grille	\$ 665.50	\$ -
4	Grille Clip 1 set	\$ 30.00	\$ -
5	Brake Master Pump	\$ 546.70	\$ -
6	Brake Air Tank	\$ 1,406.70	\$ -
7	"Corporate" Advertisement & Artwork	\$ 180.00	\$ -
	To remove, replace and transfer Brake Pump Labor Charge	\$ 300.00	\$ -
	To check all wiring & electrical component for proper function	\$ 50.00	\$ -
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 250.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 300.00	\$ -
	To putty & spray painting & including touch up paint on accident affect	\$ 250.00	\$ -
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 50.00	\$ -

Total Parts & Labour of estimate for damaged vehicle

\$ 1,200.00

Total amount in Lump Sum Basis for repaired vehicle

\$ 1,650.00



SDLS: One Thousand Six Hundred Fifty Only

M/s Liu's Brother Auto Engrg Wks

> Back to OneMotoring



Land Transport Authority
10 Sui Ming Drive
Singapore 575701
GST Registration No. : M4-0005529-2

Print Date/Time : 15 Jul 2019 / 11:05:31

Receipt Date/Time : 15 Jul 2019 / 11:05:31

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190715-000029

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHD460P As at 06 Jul 2019/08:00:00 Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - SHD460P Enquiry Fee 20190715110329933296	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx4559		Credit Card Visa/MasterCard	7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19012553/Uwb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:SASHE		Date : 03-09-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 460P	Veh. Inspected	GBF 3539M
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S9M01TRC	Excess (\$)	0.00
Assign From		Assign Date	16/07/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE(M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KDH2015021763	Colour	BLUE
Odometer	90495	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	MAXXIS	6 mm
L/H Front Tyre	195 R15	MAXXIS	6 mm
R/H Rear Tyre	195 R15	MAXXIS	6 mm
L/H Rear Tyre	195 R15	MAXXIS	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/07/2019	Inspection Date	16/07/2019
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 3539M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET (CONSISTENT)	DENTED	853.30	853.30
1	FRONT HEAD LAMP RH (CONSISTENT)	HOLDER CRACKED	930.70	781.40
1	FRONT GRILLE (CONSISTENT)	TO REPAIR SEE LABOUR	665.50	-
1	FRONT BRAKE MASTER PUMP (CONSISTENT)	DEFORMED	546.70	546.70
1	FRONT BRAKE AIR TANK (CONSISTENT)	NOT NECESSARY	1,406.70	-
	LESS 50% DISCOUNT		-	-1,090.70
			4,402.90	1,090.70
SPECIAL NETT ITEMS				
1	SET FRONT GRILLE CLIP (CONSISTENT) (SN)	NOT NECESSARY	30.00	-
1	FRONT 'CORPORATE' ADVERTISEMENT & ARTWORK (CONSISTENT) (SN)	NECESSARY	180.00	80.00
			210.00	80.00
LABOUR				
	TO REMOVE, REPLACE AND TRANSFER BRAKE PUMP LABOR CHARGE.		300.00	40.00
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		50.00	20.00
	TO REMOVE & REFIX AIR CON ,RE-FILL AIR CON GAS & TEST FOR LEAKAGES.	NOT NECESSARY	250.00	-
	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS.INCLUSIVE OF THE REPAIR OF FRONT GRILLE.		300.00	200.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED.		250.00	200.00
	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		50.00	30.00
			-	-
			-	-
			-	-
			1,200.00	490.00
GRAND TOTAL			5,812.90	1,660.70

Report Ref No. CC4/ASM19012553/Uwb3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,650.00
---	--	--	----------

Report Ref No. CC4/ASM19012553/Uwb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim: S9M01TBC
 Reference: CC8/ASM19012553/Uw63q2
 Loss Date: 8 July 2019
 Report Date: 15 Jul 2019 4:09:00 PM
 Request Date: 16 July 2019
 Due Date:

Vendor Name: LKX AUTO CONSULTANTS PTE LTD (TP)
 Type of Loss: Third Party Vehicle Damage
 Services: Pending verification - Direct Settlement

Actions

Next Step: Wait for Approve invoice

Next Step:

Vehicle Information

Incident Vehicle Registration #: G8F3539M
 Make: TPWD TOYOTA
 Model: HIACE DX 3.0 MANUAL
 Service Address: ...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD
 No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

GO Sashie
 sashie.goms@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type: Document SubType

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKXInvoice 1 (7).pdf	Invoice	Surveyor/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	5 September 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
LKKInspection (7).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
LKKAdjustment1a (5).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
WORKSHOP INVOICE.pdf	Invoice	Receipt	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
LETTER TO OL.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
MARKED ESTIMATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 August 2019
LKK Reinspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 August 2019
LKK Inspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 August 2019
TPNANDATE IA-GIF 33.39M.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 August 2019
TP-IA 3539.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2019
SHD-60P INSO GAI REPORT.PDF	Reports & Statement	GIA Report	DHAMAL Raghav	15 July 2019
TP-PRIFROM WORKSHOP WITH GIA REPORT.msx	Letters and Correspondence	Workshop	DHAMAL Raghav	15 July 2019