


Sketch Plan

AYE towards Tuas Before Buona Vista Exit

SKETCH PLAN



Vehicle A = SCM 9288S

Vehicle B = SGX 8838 M

Vehicle C = SKP 3330 M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle A (SCM 9288S) was travelling straight at the stated venue. As the front vehicle C (SKP 3330 M) stopped, I followed suit. Suddenly vehicle B (SGX 8838 M) hit hard onto my rear and result me to propel forward and hit onto vehicle C.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Location: ServicePlumhorn_VS

Driver's Signature

(If driver is not the policyholder)

Date & Time: 16/7/19

Reporting Centre Personnel's Signature

Name: Suhaila

NRIC# 24704 88040377A

Sketch Plan #2


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to revoke policy benefits.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service provider or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: **Suhaimi**
NIC/FIN No: **S8040377A**

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	251D
Vehicle Details	
Vehicle No.:	SLM92885
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Sep 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	P520439008
Chassis No.:	JM6BN22A8H0148834
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$19,206.00
Original Registration Date:	31 Mar 2017
First Registration Date:	31 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$14,206.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2027
PARF Rebate Amount:	\$10,654.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,765.00
COE Rebate Amount:	\$39,185.00
Total Rebate Amount:	\$49,839.00

The information contained herein is correct as at 04 Sep 2019

OK

TP Sampo
Veron

JM6BN22A8H0148834

ATTN:				
NO.	DESCRIPTION - PARTS	QTY	PRICE	ADJUSTED PRICE
1	REAR BOOT <i>Disparted</i>	1	✓ 1057.40	1057.40
2	REAR BOOT HINGE L+R <i>Self.</i>	2	✓ 290.60	290.60
3	REAR BOOT EMBLEM(MAZDA 3) <i>Free</i>	1	✓ 54	54
4	REAR BOOT EMBLEM(SKYACTIV)	1	✓ 64	64
5	REAR BOOT LAMP L+R <i>Cracked</i>	2	✓ 980	980 530
6	REAR BOOT LOGO <i>new</i>	1	✓ 75	75
7	REAR BOOT LAMP CLIP <i>new</i>	1 SET	✓ 30	30
8	REAR BOOT LOCK <i>Dented</i>	1	✓ 173	173
9	REAR BOOT LOCK SWITCH <i>Damaged</i>	1	✓ 133	133
10	REAR BOOT NO.PLATE LAMP L+R <i>new</i>	2	7. 73.	
11	REAR BOOT INSULATOR <i>Delaid</i>	1	✓ 132	132
12	REAR BOOT INSULATOR CLIP <i>new</i>	1	✓ 36	30
13	REAR BOOT WEATHERSTRIP <i>cut</i>	1	✓ 157	157
14	REAR BOOT REVERSE CAMERA <i>Damaged</i>	1	✓ 287	287
15	REAR BUMPER <i>Discolored</i>	1	✓ 1050	1050
16	REAR BUMPER RETAINER L+R <i>new</i>	2	✓ 74	74
17	REAR BUMPER BRACKET L+R <i>new</i>	2	✓ 50	50 x
18	REAR BUMPER CLIP <i>new</i>	1 SET	✓ 40	40
19	REAR BUMPER REINFORCEMENT <i>Best</i>	1	✓ 737	737 538
20	REAR BUMPER TOWING CAP L+R <i>Discolored</i>	2	✓ 36	36
21	REAR BUMPER RELECTOR L+R <i>LH cracked</i>	2	✓ 140	140 70
22	REAR BUMPER REVERSE SENSOR <i>Damaged</i>	4	✓ 300	300
23	TAIL LAMP L+R <i>LH cracked, RH cut</i>	2	✓ 1860	1860 1698
24	TAIL LAMP PANEL L+R <i>Dented</i>	2	✓ 800	800 622
25	TAIL LAMP CLIP L+R <i>new</i>	2	✓ 50	50
26	REAR FENDER L+R <i>LH Buckled, RH Repair</i>	2	✓ 2360	2360 1180
27	REAR FENDER COWLING L+R <i>new</i>	2	x 160	
28	REAR FENDER COWLING CLIP L+R <i>new</i>	1 SET	x 40	
29	REAR FENDER INNER TRIM L+R <i>Delaid</i>	2	✓ 600	600
30	REAR FENDER INNER TRIM CLIP L+R <i>new</i>	1 SET	✓ 30	30
31	REAR EXHAUST GASKET <i>new</i>	1	x 40	
32	REAR WINDSCREEN <i>new</i>	1	x 980	
33	REAR END PANEL <i>Discolored</i>	1	✓ 605	605