



Immediate Advice

To : AXA Insurance Pte Ltd

Date: 28/07/2019

Survey Details:

Date of loss	15-Jul-19
Date of appointment	17-Jul-19
Date of survey	17-Jul-19
Location of survey	COMFORTDELGRO ENGINEERING PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHC 2119T
Make and Model	HYUNDAI I40
Date of registration	20/12/2017
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$	2,173.54
------------------	----	----------

Proposed/Revised repair cost:

Parts	\$	852.58
Check items (estimate)		NIL
Labour	\$	490.00
Total	\$	1,342.58
Lump Sum(if applicable)	\$	-
Number of days for repair		2



Remarks:

*We are pending for OI LOA.
The total quantum is < \$5,000.00. We will proceed to negotiate
settlement with third party after received OI LOA.*

Mandate:

Liability(TP)	100%	
Proposed repair cost		
Loss of use		no. of days
Loss of rental		no. of days
Loss of income		no. of days
LTA search fees		
Others		
Proposed Total	TBA	

