

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/07/2019

### Survey Details:

Date of loss	15-Jul-19
Date of appointment	17-Jul-19
Date of survey	17-Jul-19
Location of survey	COMFORTDELGRO ENGINEERING PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SHC 2119T
Make and Model	HYUNDAI I40
Date of registration	20/12/2017
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

### Repair details:

Initial Estimate	\$	2,173.54
------------------	----	----------

### Proposed/Revised repair cost:

Parts	\$	852.58
Check items (estimate)	\$	610.96
Labour	\$	490.00
<b>Total</b>	<b>\$</b>	<b>1,953.54</b>
<b>Lump Sum(if applicable)</b>	<b>\$</b>	<b>-</b>
<b>Number of days for repair</b>		<b>2</b>



**Remarks:**

*We have not authorized repairs. We will seek mandate after our surveyor have verify the check items.*

**Mandate:**

<b>Liability(TP)</b>		<b>%</b>
Proposed repair cost		TBA
Loss of use		no. of days
Loss of rental		no. of days
Loss of income		no. of days
LTA search fees		
Others		
<b>Proposed Total</b>		<b>TBA</b>