

22/03/2002

ASS. REC. BY:

REF CS3/A1G 19012645/ FcF302 Special Instruction:

Surveyor RAWASSIGNMENT (Office)From (Person): Chin lei Ying of A1G Date/Time: 17.7.19 10.56 a.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLE 7450 U Insured: SLU 7512 Rat Workshop m/s motor Intelligence Tel: 62810087of 13 Kaki Bukit Rd 4 #01-20Policy No: 1700078236 Claim No: 366525043486

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 14.7.19  
(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 17.7.19 5.10 p.m Person Contacted: Zry Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SLE 7450 U - X</u>
	<u>SLU 7512 R - X</u>
	<u>Dismantle: 18/7/2019</u>
	<u>After repair: 22/7/2019</u>

urimn

REF:

A16

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLE 7450 U

at Workshop m/s Motor Intelligence.

of BKabi Bukit Rd 4 #01-20 Bartley Biz Centre

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No. SLE 7450 U Yr Regn: JUL / 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLKSWAGEN JETTA c.c 1390

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 41579 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZ16ZGM016292

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: 205/55 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.A. 14/07/2019

D.O.I. 17/7/2019

Survey held at Motor Intelligence

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair days: 3 days

MV: \$67000

PV: \$49191

NV: \$17000

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Report Format:

DAR

Lump Sum / I.B.I. (\$)

180

11

191

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jul 2019 <a href="#">Edit Reg</a>		17 Jul 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	LOO SOON TEAK (LU SHUNDE), ID: S7540366F		
Main Claimant:	LIM MEI LAN, ID: S1456140D		
Vehicle Reg. No.:	SLE7450U	Date of Loss:	14/07/2019 13:00 - :59
Claim Type:	TP / 3665250434SG	Policy/Cover Note No.:	1700078236 (Comprehensive)
Vehicle Reg. No. (Insured):	SLU7512R	Policy No. (Claimant):	
		Excess:	
Repairer:	Motor Intelligence Automo Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 26/07/2019]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AIG\_SG (18/07/2019): Request To Upload TP GIA Report

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VE...**

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fong, Andy-SY  
Sent: 7/17/2019 10:56:49 AM

Attachments:  2019.7.16-PRI letter to AIG for SLE7450U.PDF  2019.7.16-GIA report of our client SLE7450U.PDF

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** lua\_siewhui@rssolomon.com [mailto:lua\_siewhui@rssolomon.com]

**Sent:** Tuesday, July 16, 2019 2:34 PM

**To:** Hor, Yinrul; wendy\_jiang@rssolomon.com; natalie\_ng@rssolomon.com

**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin; lua\_siewhui@rssolomon.com

**Subject:** RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU7512R AND SLE7450U ON 14/07/2019

Dear Yinrul,

We refer to your email of even date.

We write to inform that our client will be appointing her own Surveyors.

In this respect, please arrange your surveyors to contact Ms. Ivy Pang of Motor Intelligence Automo Pte. Ltd. at tel no. 62810087 for a pre-repair survey of our client's vehicle located at 13 Kaki Bukit Road 4 #01-20 Bartley Biz Centre Singapore 417807.

Yours sincerely

Lua Siew Hui | Legal Executive

**R. S. Solomon LLC | 正氣律師事務所**

**Advocates & Solicitors**

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e [lua\\_siewhui@rssolomon.com](mailto:lua_siewhui@rssolomon.com) | w [www.rssolomon.com](http://www.rssolomon.com)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free

of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Our Ref. : RSS/1907-7370 (MI)(PD)  
Your Ref. :

W : Lua Siew Hui / Wendy Jiang

E : lua\_siewhui@rssolomon.com/wendy\_jiang@rssolomon.com

16 July 2019



R. S. SOLOMON LLC  
ADVOCATES & SOLICITORS

**AIG Asia Pacific Insurance Pte Ltd**

No. 78 Shenton Way

#07-16 Lippo Centre

Singapore 079120

Attn: Motor Claims Dept

**By Email: Yinrul.Hor@aig.com & PDX: 8181**

Dear Sirs,

**PRE-REPAIR SURVEY**

**ACCIDENT INVOLVING SLE7450U, SLU7512R & OTHERS ON 14<sup>TH</sup> JULY 2019 AT ABOUT 1300 HRS**

We act for the owner ("our Client") of vehicle no. SLE7450U.

2. We hereby notify you of a road traffic accident on **11<sup>th</sup> July 2019** at about **1300 hours** along Lane 2 of Seletar Expressway (Bukit Timah Expressway) involving our Client's vehicle and vehicle registration no. SLU7512R driven by your insured. A copy of our Client's Singapore Accident is enclosed.

3. As a result of the accident, our Client's vehicle has been damaged. Before our Client proceeds to repair the damaged vehicle, please let us know within 2 working days upon receipt of this notice whether you would intend to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our Client shall proceed to repair her vehicle without further reference to you.

Yours faithfully,

**R. S. SOLOMON LLC**

ADVOCATES & SOLICITORS

ENCL

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	140D
<b>Vehicle Details</b>	
Vehicle No.:	SLE7450U
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jul 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA GP 1.4 TSI 90 A/T TL 1632G5
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	CAXF83276
Chassis No.:	WVWZZZ16ZGM016292
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$16,700.00
Original Registration Date:	29 Jul 2016
First Registration Date:	29 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$16,700.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jul 2026
PARF Rebate Amount:	\$12,525.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	28 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,301.00
COE Rebate Amount:	\$36,666.00
<b>Total Rebate Amount:</b>	<b>\$49,191.00</b>

The information contained herein is correct as at 24 Jul 2019

DOA: 14/07/2019

OK

Remaining: 7 years 14 days (84.4 months)

Depn: \$8370 (yearly) \$697.5 (monthly)

PARF:  $\$16700 \times 50\% = \$8350$

$84.4 \text{ months} \times \$697.5 = \$58869$

$\$58869 + \$8350 = \$67219 \text{ (MV)}$



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Audi A4 1.4A TFSI S-tronic



Glacier White With Nougat  
Brown Seats, Elite Package  
Chrome Finish, Low Mileage  
Direct Owner StarAll



Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

14 vehicles

Volkswagen Jetta

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection								
	Volkswagen Jetta GP 1.4A TSI	\$66,988	\$8,530 /yr	25-May-2016	1,390 cc	-	Sedan	Available
Perfect Unit For Family And Your Daily Errands, Spacious Interior Fits Up To Five Comfortably, Offering A Nice Balance Of Ride Comfort And Confident Handling. Various Loan Packages Available, Simply Call Us Today For Viewing And Test Drive!								
Posted: 28-Jul-2019 Tags: 2016 Volkswagen Jetta, 2016 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen, Jetta, jetta, Used Volkswagen								
	Volkswagen Jetta GP 1.4A TSI	\$64,988	\$8,370 /yr	12-Apr-2016	1,390 cc	69,000 km	Sedan	Available
A Compact Sedan In The Volkswagen Model Range, Perfect Unit For Family And Your Daily Errands, Spacious Interior Cabin Space Fits Up To Five Comfortably, It Offering A Nice Balance Of Ride Comfort And Confident Handling, Full Agent Maintained With Parts Replaced, Hi...								
Karz Automobile								
Posted: 28-Jul-2019 Tags: 2016 Volkswagen Jetta, 2016 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen, Jetta, jetta, Used Volkswagen								
	Volkswagen Jetta 1.4A TSI Sportline	\$69,800	\$7,960 /yr	30-Nov-2016	1,390 cc	44,000 km	Sedan	Available
Well Maintained By Owner, Low Mileage, Warranty By Agent Till Nov 2019, Low Interest Rate At 2.28%, Buy With Peace Of Mind, Get To Know The Maintenance History From The Owner, Test Drive To Evaluate The Condition, View By Appointment Only, Consignment Unit,...								
Posted: 28-Jul-2019 Tags: 2016 Volkswagen Jetta, 2016 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen, Jetta, jetta, Used Volkswagen								
	Volkswagen Jetta 1.4A TSI Sportline	\$65,800	\$8,370 /yr	29-Jan-2016	1,390 cc	45,791 km	Sedan	Available
Cheapest Priced (Low \$8K Plus Depreciation) Yet With The Best Condition! Stylish Black Jetta 1.4A, Sportline Model. Agent Serviced With History, Last Done Jan 19. Amazing Low Mileage Done 45791km. 1 Owner. New Tyres/Paintwork. 100% Accident Free. Call Now!								
Lake View Credit Pte Ltd								
Posted: 27-Jul-2019 Tags: 2016 Volkswagen Jetta, 2016 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen, Jetta, jetta, Used Volkswagen								
	DVD Player 8" Monitor Screen with GPS							
Brand new DVD Player for Hyundai Elantra (2011). Comes with 1 year warranty, free installation, 8" Monitor Screen with GPS. Please call Advance Sound Auto @ 68730013 / 96718191 for any enquiries!								
Find out more!								
	Volkswagen Jetta 1.4A TSI	\$64,800	\$8,230 /yr	27-Jan-2016	1,390 cc	80,800 km	Sedan	Available
Unit Parked Under Shelter And Well Maintained. Renowned And Reliable. Comfortable Ride With Excellent Handling. Evaluation Welcomed, Buy With The Greatest Peace Of Mind. Multiple Loan Options Available. Viewing Is Strictly On Appointment Basis.								
Posted: 26-Jul-2019 Tags: 2016 Volkswagen Jetta, 2016 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen, Jetta, jetta, Used Volkswagen								
	Volkswagen Jetta GP 1.4A TSI	\$62,888	\$8,040 /yr	22-Apr-2016	1,390 cc	85,000 km	Sedan	Available
Low Interest, Full Service By Agent, In House Finance Options Available, Buy With Peace Of Mind, 1 Owner 100% Accident Free, All Trade In Are Welcome.								
Posted: 26-Jul-2019 Tags: 2016 Volkswagen Jetta, 2016 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen, Jetta, jetta, Used Volkswagen								
	Volkswagen Jetta GP 1.4A TSI Highline	\$72,000	\$8,610 /yr	24-Aug-2016	1,390 cc	19,500 km	Sedan	Available
w Mileage Done, I Use It For My Daily Commute From Home To Work And Back. My Working Place Only 2 Km From My Home. Ids Only To Church And Back. Underutilised That's Why The Low Mileage. Maintained And Serviced At VW Singapore Since Day O...								

\$8610  
↑  
\$8040



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/07/2019 13:02
Date Of Accident	14/07/2019 13:00
Exact Location Of Accident	ALONG LANE 2 OF SLE(BKE)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE7450U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM MEI LAN
NRIC No	S1456140D
Email Address	ZONGZHE32@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97376014
Alternative Phone No	OFFICE-97376014
<b>Vehicle Particulars</b>	
Manufacturer	VOLKSWAGEN
Model	JETTA-1.4 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28803043 AVW
Cover Note Number	
<b>Driver</b>	
Name of Driver	GARY CHIA ZONG ZHE
NRIC No	S9326375H
Date Of Birth	26/07/1993
Occupation	INDOOR
Date Of Driving Pass	11/04/2014
Driving Experience	5 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97376014
Fax Number	
Contact Number	
Email Address	ZONGZHE32@HOTMAIL.COM

Address	BLK 436D FERNVALE ROAD #11-150
Postcode	794436
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

MORE DETAILS PLEASE REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU7512R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LOO SOON TEAK
NRIC/Passport Number	S7540366F
Contact Number	86081065
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 15/7/2019  
1249 hrs.

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No

## Sketch Plan Pg. 2

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At around 1pm, 14 July 2019, I was travelling along Lane 2 of SLE (BKE) when the car in front came to a sudden halt due to upcoming Lane 1 closure.

I managed to brake in time, but was rear-ended by SLU7512, the car behind me. The impact was not insignificant as I lurched forward in my seat, will be seeing doctor.

I spoke to with the car owner of SLU7512 and he said that the collision was due to car SKT4589G hitting him from the back.

Third party details:

- Name - Loo Soon Teak
- NRIC - S7540366F
- Phone - 86081065

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: 15/7/2019, 1249 hrs.

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

Driving License



SLE7450U

A 82203043 Avw

# 2K

NCD 30%



97376014

zongzhe32@hotmail.com

# Identification Card

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)


EFFECTIVE DATE

Class 3 Motor Cars -- 3000kg with -- 7 passengers, exclusive of the driver, and other motor vehicles -- 2500kg 11 Apr 2011

Ref: 428A



1 2 5 4 9 8 17  
S932637511



Date of expiry  
20-01-2016

4221814  
AUT BLK 436U PENNYVALE ROAD  
#11-150  
SINGAPORE 101430

# MOTORCAR (Rear)

## Rear Portion

Vehicle No: SLE 7450U

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	/	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	cra	/	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	nel	1/6	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	015	1/2	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	cra	/	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	Shunt	DM	
1159	993327	Rear End Panel	DD	R	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
		REAR BUMPER LOWER COVER	cra	/	

No of Items:

Assessor:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jul 2019 <a href="#">Edit Reg</a>		17 Jul 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>







































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> [Created by adjuster]									
Insured:	<b>LOO SOON TEAK (LU SHUNDE)</b> , ID: S7540366F								
Main Claimant:	<b>LIM MEI LAN</b> , ID: S1456140D								
Vehicle Reg. No.:	<b>SLE7450U</b>	Date of Loss:	14/07/2019 13:00 - :59 [35 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 3665250434SG</b>	Policy/Cover Note No.:	1700078236 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLU7512R</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Motor Intelligence Automo Pte Ltd (HQ)</b> 13 KAKI BUKIT ROAD 4, #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Tan, Bennie-WZ</b> - 6419 1718] Bennie-WZ.Tan@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>PARASURAM SHANMUGAM</b> ] ... [Final Rpt due 26/07/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
<ul style="list-style-type: none"> <li>AIG_SG (18/07/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SLE7450U (3665250434SG)**  
**[SLU7512R]**  
**TP**  
**LIM MEI LAN**  
**Jul 14 2019 1:00PM**  
**[LOO SOON TEAK (LU SHUNDE)]**  
**Motor Intelligence Automo Pte Ltd**

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Video											1 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print	
1	25/07/19 11:38	OI Video - Accident (Rear)										Load MOV		
2	25/07/19 11:39	OI Video - Accident (Front)										Load MOV		
Photos/Images											3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
2	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
3	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
4	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
5	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
6	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
7	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
8	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
9	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
10	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
11	17/07/19 17:31	General View Left										Load JPG	<input checked="" type="checkbox"/>	
12	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
13	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
14	17/07/19 17:31	General View Left										Load JPG	<input checked="" type="checkbox"/>	
15	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
16	17/07/19 17:31	Odometer Reading										Load JPG	<input checked="" type="checkbox"/>	
17	17/07/19 17:31	Chassis Number										Load JPG	<input checked="" type="checkbox"/>	
18	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
19	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
20	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
21	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
22	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
23	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
24	17/07/19 17:31	General View										Load JPG	<input checked="" type="checkbox"/>	
25	26/07/19 14:48	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
26	26/07/19 14:48	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
27	26/07/19 14:48	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
28	26/07/19 14:48	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
29	26/07/19 14:48	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
30	26/07/19 14:48	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
31	26/07/19 14:48	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
32	26/07/19 14:48	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
33	26/07/19 14:48	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	26/07/19 14:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	26/07/19 14:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	26/07/19 14:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	26/07/19 14:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	26/07/19 14:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	26/07/19 14:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	26/07/19 14:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	26/07/19 14:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	26/07/19 14:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	26/07/19 14:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	26/07/19 14:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	26/07/19 14:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	26/07/19 14:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	26/07/19 14:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	26/07/19 14:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	26/07/19 14:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	18/07/19 09:15	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19012645/FCF3E2

Date: 31/07/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700078236  
**Claimant Vehicle No :** SLE7450U **Insured Vehicle No :** SLU7512R  
 Date of Loss: 14/07/2019 Nature of Claim: TP Claim No: 3665250434SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE7450U**  
 Make & Model: VOLKSWAGEN JETTA, 1.4 (A) Engine No: CAXF83276  
 Reg. Date: 29/07/2016 (Man. Year: 2015) Chassis No: WWZZZ16ZGM016292  
 Colour: Grey Odometer: 41579 km  
 Engine Capacity: 1390 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm  
 Front Right Side: Pirelli 4 mm Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 17/07/2019  
 Date Inspected: 17/07/2019 Inspected At: Motor Intelligence Automo Pte Ltd (HQ)  
 13 KAKI BUKIT ROAD 4, #01-20  
 BARTLEY BIZ CENTRE  
 Singapore 417807  
 Estimated Period of Repair: 3.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Cracked	0.00 F	*- F
3	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
5	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
6	1		*REVERSE SENSOR	Shorted / Damaged	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*REAR BUMPER LOWER COVER	Cracked	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >