

ASS. REC. BY:

REF: CS/II/9012668/EC307

Special Instruction:

Supervisor: Steve

ASSIGNMENT (Office)

From (Person):

McMinn Gabriel Wee

of

III

Date/Time:

17/7/19 @ 1:30pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FP9353S

Insured:

SHA 7072X

at Workshop m/s

Eng Soon Punting

Tel:

6760 6271

of

Blk 4 Yew Tee Ind. Est 343-J Woodlands Road

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

7/7/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:19am @ 18/7/19

Person Contacted:

Mr. Teo

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	FP9353S-CS/15108017321/Ur21
	SHA 7072X-CS/III 90122371/K/Ka3
	Dismantle: 23/7/2019 @ 4:45pm.

D.O.A: 10/6/2008

D.O.A: 10/7/2019

ASSIGNMENT

From _____ Date: _____
 Estimated Cost _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV _____
 To Inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FP 93535 Yr Regn: Feb 98
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Yamaha G.C. 133
 Colour: Red A/C Insured / Std / NI / NA
 Sp. Reading: 98179 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 Ci/No: 2MC-232893
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 2.50-18
 R: 2.50-18
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or VIVA

Front 5 mm Rear 5 mm
 R/Bal. mm L/Bal. mm
 D.O.A. 7/7/19 D.O.I. 18/7/19 103200
 Survey held at Eng Sam Paiting
 Des. of Damages: Frnt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time. File Pass to?

☐ : Preli. Report
☐ : Final Report

1) Date/Time. File Return to?
 2)

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

Transportation

☐ S + RS ☐ SI

☐ Photos

☐ Other

☐

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Report Format : PRE

Lump Sum / I.B.I: (\$

120

11

131

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified) Edit Reg		18 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:			
Main Claimant:	-		
Vehicle Reg. No.:	FP9353S	Date of Loss:	07/07/2019 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHA7072X	Policy No. (Claimant):	
		Excess:	
Repairer:	Eng Soon Painting Svc (HQ) BLK 4 YEW TEE IND EST 393J WOODLANDS ROAD, 677969 Woodlands - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 29/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 17 July 2019 1:30 PM
To: bonnie kwok; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Sherini Pillai
Subject: RE: PRI - Acc Inv: FP 9353 S & SHA 7072 X ON 7 JULY 2019

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : FP9353S
III INSURED VEHICLE NO. : SHA7072X
DATE OF LOSS : 07.07.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Sherini**.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: 17 July, 2019 10:05 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: PRI - Acc Inv: FP 9353 S & SHA 7072 X ON 7 JULY 2019

Dear Sir,

Our client disagrees to your list of surveyors.

Our client proposes their Single Joint Experts (SJE) as follows:-

Name of Surveyor

- 1 Fong Kok Heng Stanley
- 2 Ng Kong Beng Patrick
- 3 Lim Yong Tian
- 4 Danny Yap
- 5 Louis S C Ng Cae Amimi
- 6 Willy Goh
- 7 Francis Ng
- 8 Dennis Yap
- 9 Michael Yap
- 10 Philip Foo

Regards,
June

On Wed, 17 Jul 2019 at 09:07, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: 16 July, 2019 4:08 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: PRI - Acc Inv: FP 9353 S & SHA 7072 X ON 7 JULY 2019

Dear Sir,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle FP 9353 S at M/s Eng Soon Painting Services, Block 4 Yew Tee Ind Est 393-J Woodlands Road Singapore 677978. Contact number 6760 6271.

Regards,

June

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.



Virus-free. www.avg.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

--

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.
Registration No. 198703792-K

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	312B
Vehicle Details	
Vehicle No.:	FP9353S
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jul 2019
Vehicle Make:	YAMAHA
Vehicle Model:	RXZ
Primary Colour:	Blue
Manufacturing Year:	1998
Engine No.:	3BS232893
Chassis No.:	ZMC232893
Maximum Power Output:	-
Open Market Value:	\$3,092.00
Original Registration Date:	20 Feb 1998
First Registration Date:	20 Feb 1998
Transfer Count:	6
Actual ARF Paid:	\$464.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$5,910.00
COE Rebate Amount:	\$5,026.00
Total Rebate Amount:	\$5,026.00
Message	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit http://www.nea.gov.sg/mtcincentive or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 29 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/07/2019 14:14
Date Of Accident	07/07/2019 19:35
Exact Location Of Accident	BUKIT PANJANG RING ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FP9353S
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD FAIROZ BIN HAFAZUL
NRIC No	S9803312B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98308508
Alternative Phone No	OFFICE-98308508
Vehicle Particulars	
Manufacturer	YAMAHA
Model	RXZ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy or repair to your vehicle?	NO
No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Meet Policy	NO
Policy Number	5107653499
Cover Note Number	
Driver	
Name of Driver	MUHAMMAD FAIROZ BIN HAFAZUL
NRIC No	S9803312B
Date Of Birth	01/02/1998
Occupation	INDOOR
Date Of Driving Pass	12/12/2016
Driving Experience	2 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98308508
Fax Number	
Contact Number	OFFICE-98308508
Mail Address	NOEMAIL



Sketch Plan #2

Sketch Plan #2

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

RS
REPORT REFER TO
T/20190709/7000
POLICE



POLICE FORCE



T/20190709/7000

1 of 3

Report No. T/20190709/7000

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/07/2019 00:02	Vide Report No.: J/20190707/0120	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars

Name of Informant: MUHAMMAD FAIROZ BIN HAFAZUL			Address: APT BLK 472 CHOA CHU KANG AVENUE 3 #14-159 SINGAPORE 680472		
ID Type / ID No.: NRIC NO / S9803312B			Contact No.: Home/Office: Mobile: 98308508		
Nationality: SINGAPORE CITIZEN			Email: fairoz10@hotmail.com		
Sex: Male	Age: 21	Date of Birth: 01/02/1998	Type of Informant: Rider		
Race: Malay			Language: English		Institution / School Name:
Occupation: Student			Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 07/07/2019 19:35	Type of Location: Straight Road
Location: BUKIT PANJANG RING ROAD				
Weather: Clear	Road Surface: Dry	Road Speed Limit: 50 Km/h		
Traffic Flow: Two Way	Traffic Control: Traffic Light - Working	Traffic Volume: Light		
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FP9353S	Motorcycle	YAMAHA	RXZ	Blue		0
SHA7072X	Comfort Delgro Taxi			Blue	Slightly Damaged	2

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FP9353S	NTUC Income Insurance Co-Operative Limited	5107653499	19/02/2019	18/02/2020



SINGAPORE POLICE FORCE



T/20190709/7000

2 of 3

Report No. T/20190709/7000

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MUHAMMAD FAIROZ BIN HAFAZUL	ID No.	S9803312B
Related Vehicle	FP9353S (Motorcycle)	Contact No.	98308508
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On Sunday 07/07/2019, approximately at 1930hrs i was being hit by Comfort Delgro Taxi(SHA7072X) while i was working as a delivery rider. I was going straight on a two way lane to pick up my order at Hillion Mall when a taxi made a Uturn without giving me the right of way. Approximately around 30-40 meters away from the incident location, i was a traffic light, waiting for it to turn green. As it turned green, i slowly move off till the point where i saw this said taxi trying to make a Uturn. Upon seeing the said taxi, I slowed down. I was at the first lane and i tried to avoid any collision so i made an attempt to lane change to the left but by the time i tried slow down, he hit me from my right side. He then came out of his taxi to see what was going on. When i asked him why didn't he gave me the right of way, he mention that he didn't saw me even though i had my head light on. Inside the said taxi, there were 2 passengers boarding the taxi, and they tried to help me. One of the passengers then told to call for an ambulance, afraid that i might sustained any serious injuries. I called for ambulance and they arrived approximately 10 minutes later. Once they arrived, i was being brought to Ng Teng Fong General Hospital for further checks. I was not admitted to the hospital.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jul 2019 09:18 Edit Reg		17 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	FP9353S	Date of Loss:	07/07/2019 00:00 - :59 [256 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SHA7072X	Policy No. (Claimant):							
		Excess:							
Repairer:	Eng Soon Painting Svc (HQ) BLK 4 YEW TEE IND EST 393J WOODLANDS ROAD, 677969 Woodlands - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 29/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FP9353S
[SHA7072X]






































TP



















































-






























Jul 7 2019 12:00AM

[-]

Eng Soon Painting Svc

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
20	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
21	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
22	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
23	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
24	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
25	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
26	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
27	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
28	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
29	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
30	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
31	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
32	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
33	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
34	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
35	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
36	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
37	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
43	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
44	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
45	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
46	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
47	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
48	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
49	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
50	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
51	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
52	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
53	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
54	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
55	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
56	18/07/19 17:53	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
57	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
58	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
59	18/07/19 17:53	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
60	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
61	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
62	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
63	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
64	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
65	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
66	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
67	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
68	18/07/19 17:53	General View	 Load JPG	<input checked="" type="checkbox"/>
69	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
70	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
71	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
72	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
73	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
74	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
75	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
76	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
77	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
78	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
79	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
80	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
81	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
82	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
83	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
84	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
85	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
86	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
87	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
89	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
90	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
91	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
92	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
93	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
94	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
95	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
96	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
97	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
98	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
99	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
100	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
101	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
102	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
103	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
104	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
105	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
106	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
107	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
108	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
109	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
110	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
111	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
112	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
113	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
114	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
115	23/07/19 18:47	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	19/07/19 09:00	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19012668/ECD3E2

Date: 30/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : FP9353S

Insured Vehicle No : SHA7072X

Date of Loss: 07/07/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FP9353S

Make & Model: YAMAHA RXZ, 133cc (M)

Engine No: 3BS232893

Reg. Date: 20/02/1998 (Man. Year: 1998)

Chassis No: ZMC232893

Colour: Red

Odometer: 98179 km

Engine Capacity: 133 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 2.50-18 Rear Tyre Size: 2.50-18

Front Left Side: Viva 5 mm Rear Left Side: Viva 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 17/07/2019

Date Inspected: 18/07/2019 Inspected At:

Eng Soon Painting Svc (HQ)
BLK 4 YEW TEE IND EST 393J
WOODLANDS ROAD
Singapore 677969

Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Jul 2019)	
Parts:	N/A	YAMAHA RXZ 133cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FP9353S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >