

ASS. REC. BY:

REF: CS/CT119012675/UV1312

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Elaine Cheong of CT1 Date/Time: 18.7.19 13.45p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGP 5599P Insured: SJZ 9019H

at Workshop m/s JA Autorace Tel: 94513429

of 8 Kaki Bukit Ave 4 #02-37

Policy No: DMPCSN 3035 3619000 Claim No: SNM19b20334 302

Sum Insured: Excess:

Make of Veh: D.O.A. 16.7.19
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 18.7.19 2.08p.m Person Contacted: Jenny H.O.D. Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SGP 5599P X
	SJZ 9019H X

108/11/13 wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: SGP 5599P
 at Workshop m/s JA Arcade 11am
 of 5J29019H
 Insured: _____
 Policy No.: _____
 Claims No.: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SGP 5599P Yr Regn: 3 / 15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Peugeot 3008 C.C. 1560
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 104331 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: VF3049HDE S23955
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Insured / Jammed / Leaked / Burnt or
 Brake: Insured / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/50 ZR17
 R: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 58
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: 1 Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 2 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS LTA 37459
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kumho
 Front: 6 mm Rear: 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 16/7/19 D.O.I. 22/7/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
25/7/19 2/5 @ 3400 continued with Terry (Red 1827.17, 359)

RECEIVED 25 JUL 2019

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 1

Date/Time, File Return to?

2) 25/7 - typist

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS (\$ _____)
☐ : Interview (\$ _____) ☐ : Photos
☐ : Tech. Invs (\$ _____) ☐ : Others
☐ : Weekend (\$ _____)

Report Format: Meriman
 Lump Sum / I.B.I. (\$) 3400/2

Survey Fee:
 Transportation:

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jul 2019		18 Jul 2019 13:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: GOH PING PING SABRINA , ID: S7815310E									
Vehicle Reg. No.:		SGP5599P	Date of Loss:	16/07/2019 17:00 - :59					
Claim Type:		TP / SNM19D203343C02	Policy/Cover Note No.:	DMPCSN3035361900					
Vehicle Reg. No. (Insured):		SJZ9019H	Policy No. (Claimant):	GA261913					
			Excess:	S\$500.00					
Repairer: Ja Autocare Pte Ltd () 8 KAKI BUKIT AVE 4, #02-37 PREMIER@KAKI BUKIT, 415875 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/07/2019]									
Adj Asg. Remarks: TP workshop requested Mr Marcus to survey									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

SAVE \$\$ ON UR CAR

INSURANCE RENEWAL

Compare
10+ Insurers

CLICK HERE >

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Punchy 2011 MINI Cooper S At Only \$35,000.



Owner's Baby. Low Mileage.
Super Fun Torque-y Pocket
Rocket. Ideal For COE Renew
Direct Owner StarAd

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan



YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted

20 results/page

1 vehicles

3008

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	3008		Any	Any	2015	Any	Any	Any	Available


Peugeot 3008 Diesel 1.6A
e-HDi ETG

\$63,500

\$9,490 /yr

26-Aug-2015

1,560 cc

122,000 km

SUV

Available

Fuel Type: Diesel (Euro 5 Engine and Above)

Peugeot Best Selling Model! Full Tank For 900KM Usage, Make It One Of The Best Cost Effective Car To Own In Singapore. Spacious Leg...

Car Buyers Automotive Pte Ltd

Posted: 15-Jul-2019

Tags: 2015 Peugeot 3008, 2015 peugeot 3008, Peugeot 3008, peugeot 3008, Peugeot, 3008, Used Peugeot

Save this search criteria, to get email alerts whenever a match is found.

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used 3008, 3008 Singapore, used 3008 Singapore, used 3008, used vehicles Singapore or even buy used 3008 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	310E
Vehicle Details	
Vehicle No.:	SGP5599P
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jul 2019
Vehicle Make:	PEUGEOT
Vehicle Model:	3008 1.6 E-HDI ETG ACTIVE SUV
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	10JBFT0080751
Chassis No.:	VF30U9HD8ES239555
Maximum Power Output:	84.0 kW (112 bhp)
Open Market Value:	\$21,518.00
Original Registration Date:	06 Mar 2015
First Registration Date:	06 Mar 2015
Transfer Count:	1
Actual ARF Paid:	\$7,126.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Mar 2025
PARF Rebate Amount:	\$5,344.00
Intended COE Rebate Details	
COE Expiry Date:	05 Mar 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,199.00
COE Rebate Amount:	\$32,115.00
Total Rebate Amount:	\$37,459.00

The information contained herein is correct as at 22 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/07/2019 10:44
Date Of Accident	16/07/2019 17:20
Exact Location Of Accident	SELETAR EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGP5599P
Insured/Policyholder	
Name Of Registered Owner	GOH PING PING SABRINA
NRIC No	S7815310E
Email Address	SABRINAGOH55@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96901594
Alternative Phone No	OFFICE-96901594
Vehicle Particulars	
Manufacturer	PEUGEOT
Model	3008-1.6 D E-HDI ETG ACTIVE (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA261913
Cover Note Number	

Driver

Name of Driver	GOH PING PING SABRINA
NRIC No	S7815310E
Date Of Birth	04/06/1978
Occupation	INDOOR
Date Of Driving Pass	19/10/1999
Driving Experience	19 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96901594
Fax Number	
Contact Number	OFFICE-96901594
Email Address	SABRINAGOH55@GMAIL.COM

Address	BLK 126C EDGEDALE PLAINS #02-306
Postcode	823126
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS DIVISION HQ
Police Station Address	ROAD: 1 WOODLANDS STREET 12 , POSTCODE: 738622 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJZ9019H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

YL5557T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SGP5599P

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

△
A
△
B
△
C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRSC/FIN No.:



**SINGAPORE
POLICE FORCE**



L/20190716/7041

1 of 2

POLICE REPORT (NP299)

Report No. L/20190716/7041

Police Station Of Origin
Woodlands Division HQ
1 Woodlands Street 12 SINGAPORE 738622
Tel No:1800-4660000

Date/Time Report Made 16/07/2019 22:16	Vide Report No.		Station Diary No.	
Name Of Informant GOH PING PING, SABRINA	Address APT BLK 126C EDGEDALE PLAINS #02-306 SINGAPORE 823126			
ID Type / ID No. NRIC NO / S7815310E	Contact No. Home/Office: Mobile: 96901594			
Nationality SINGAPORE CITIZEN	Email Address sabinagoh55@gmail.com			
Occupation Military personnel	Sex Female	Age 41	Date of Birth 04/06/1978	Race Chinese
Institution/School Name	Language English			
Date/Time Of Incident 16/07/2019 17:20 - 16/07/2019 17:25	Location Of Incident SELETAR EXPRESSWAY			

Brief details.

I was travelling along SLE towards woodlands. As I was approaching the exit of Woodlands AVE 12, I stopped my vehicle due to the traffic ahead which was heavy and had come to a stop. I observed from my rear view mirror that the car behind me had also stopped. Shortly after that, I felt a impact from the rear of my vehicle. I noticed that a lorry had knocked into the car behind me causing the car behind me to hit the rear part of my car. After the accident, we alighted our vehicles to take pictures and exchange our particulars. My vehicle number is SGP5599P. The car behind me is SJZ9019H, driver details are, Raymond Lee Kien Going, S7919050J. The commercial lorry number is YL5557T, driver details are,

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 16/07/2019 22:16
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



**SINGAPORE
POLICE FORCE**



L/20190716/7041

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. L/20190716/7041

Aung Zaw Latt, S8087274G. The accident was also recorded by my in car dash cam. We were also assisted by a few EMAS traffic officers who happened to be at the vicinity, they had also took some pictures of the accident. A LTA traffic officer also arrived shortly. As my vehicle was able to move and there was no one seriously injured, we were advised to move our vehicles to the road shoulder. Following that, I checked that it was safe for my vehicle to be driven, we left the scene of accident.

While on my way back home, I felt unwell and consulted a doctor near my home. Doctor has given me 3 days of medical leave to monitor my condition.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 16/07/2019 22:16
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

8 Kaki Bukit Ave 4
#02-37 Premier @ Kaki Bukit
Singapore 415875
Tel : 94513429

China Taiping Insurance (s) Pte Ltd
3 Anson Road
#16-00 Springleaf tower
Singapore 079909

Date	17.07.2019
Vehicle no :	SGP 5599P
Model:	Peugeot 3008
DOA :	16.07.2019

not Affected
here
2/27/19
2/5 ~~\$~~ 3400 |
3 day.
to higher than before

- 01) Rear bumper
- 02) Rear bumper clips
- 03) Rear bumper reinforcement
- 04) Rear bumper lower pad
- 05) Rear bumper *top retainer*

652)

\$ 700	1,280.00	
\$ 80	80.00	
\$ 850	850.00	
\$ 450	450.80	
\$ 250	250.00	
\$	2,910.80	
\$	(291.08)	
\$	2,619.72	

06) Rear number plate with garnish
07) Reverse sensor *1 set*

\$ cre	75.00	40
\$ chub	320.00	200
\$	<u>395.00</u>	

- 08) To check wiring and replace sensor
- 09) to apply anti rust chemical
- 10) To knock out dent on affected areas and renew parts
- 11) To putty & respray painting

\$	100.00	50
\$	100.00	2
\$	600.00	400
\$	800.00	600
\$	1,600.00	

Sub Total	\$	4,614.72	5227.17
-----------	----	----------	---------

for JA AUTOCARE PTE LTD

$$P = 3391.30$$

$$\frac{10\%}{3052.17}$$

JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4

#02-37 Premier @ Kaki Bukit

Singapore 415875

Tel : 94513429

SUPPLEMENTARY

China Taiping Insurance (s) Pte Ltd
3 Anson Road
#16-00 Springleaf tower
Singapore 079909

Date 17.07.2019
Vehicle no : SGO 5599P
Model: Peugeot 3008
DOA : 16.07.2019

PARTS

01) Tail gate lower garnish

<i>Torn</i>	\$	680.50
	\$	680.50
Less 10%	\$	(68.50)
	\$	612.45

Sub Total	\$	612.45
-----------	----	--------

for JA AUTOCARE PTE LTD

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119012675/UVF3N2

Date: 29/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3035361900	
Claimant Vehicle No :	SGP5599P	Insured Vehicle No :	SJZ9019H	
Date of Loss:	16/07/2019	Nature of Claim:	TP	Claim No: SNM19D203343C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGP5599P		Engine No:	10JBFT0080751
Make & Model:	PEUGEOT 3008, 1.6 D e-HDi ETG Active (A)		Chassis No:	VF30U9HD8ES239555
Reg. Date:	06/03/2015 (Man. Year: 2014)		Odometer:	104331 km
Colour:	Black			
Engine Capacity:	1560 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 ZR17	Rear Tyre Size:	225/50 ZR17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,627.17	3,292.17	335.00	9.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	1,050.00	550.00	34.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,227.17	4,342.17	885.00	16.93
Approved Total (Overridden) (\$\$)		3,400.00		
Nett Amount (\$\$)	5,227.17	3,400.00	1,827.17	34.96

INSPECTION

Date of Assignment:	18/07/2019
Date Inspected:	22/07/2019 Inspected At:

Ja Autocare Pte Ltd
8 KAKI BUKIT AVE 4, #02-37
PREMIER@KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2019)
Parts:	M1-SUV	PEUGEOT 3008 1.6 D e-HDi ETG Active (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGP5599P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	1,280.00 FL	*1,280.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	80.00 FL	*80.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Dented	850.00 FL	*650.00 FL
4	1		*REAR BUMPER LOWER PAD	Deformed/Torn	450.80 FL	*450.80 FL
5	1		*REAR BUMPER TOP RETAINER	Cracked	250.00 FL	*250.00 FL
6	1		*TAIL GATE LOWER GARNISH	Torn	680.50 FL	*680.50 FL
7	1		*REAR NUMBER PLATE WITH GARNISH	Cracked	75.00 FS	*40.00 FS
8	1		*SET REVERSE SENSOR	Shorted	320.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,986.30	3,631.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	359.13	339.13
Total Parts (\$\$)	3,627.17	3,292.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND REPLACE SENSOR	New	100.00	50.00
2	TO APPLY ANTI RUST CHEMICAL	New	100.00	0.00
3	TO KNOCK OUT DENTS ON AFFECTED AREASAND RENEW PARTS	New	600.00	400.00
4	TO PUTTY & RESPRAY PAINTING	New	800.00	600.00
Gross Labour Cost (\$\$)			1,600.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >