

12/09/2001

ASS. REC. BY:

REF:

CS3/SMO19012680/Ncf3⁵²

Special Instruction:

SURVEYOR

Marcus

ASSIGNMENT (Office)

From (Person):

Gniah Pau Loong

of

Smo

Date/Time:

18.7.19 13.24pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGW 4792

Insured:

GBC 2219J

at Workshop m/s

Blumel Automotive

Tel:

67452088

of

1 Kaki Bukit Ave 6

Policy No:

DIB MTPC VE 002758

Claim No:

CMTD M03416

Sum Insured:

Excess:

Make of Veh:

D.O.A. 16.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time:

18.7.19 2.00p.m

Person Contacted:

Sally

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SGW 4792 CC4/AIG12013104/H1bfg2y DOA 29/6/12
	GBC 2219J CL7/AIG13007515/Cpa3q2=1
	Dismantle: 23/7/2019.
	After repair: 29/7/2019.

(08/11/23) wef

ASS. REC. BY: Marcus

REF:

SMU/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Dep bkw No settlement. PRS Typs 11/11/19
resury 29/7/19
4-5/k.

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

) \$ + RS, \$ SI

) Photos

) Others

)

Report Format: PRS.

Lump Sum / I.B.I. (\$

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jul 2019		18 Jul 2019 13:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SWISSWERKZ (S) PTE LTD, Co. Reg. No.: 200801506C								
Main Claimant:	DANNY BUAY ENG KIT, ID: S7806588E								
Vehicle Reg. No.:	SGW479Z	Date of Loss:	16/07/2019 09:00 - :59						
Claim Type:	TP / CMTD1903416	Policy/Cover Note No.:	D18MTPCVE002758 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBC2219J	Policy No. (Claimant):							
	Excess:								
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/07/2019]								
Driver/Custodian (Insured):	LUM CHEE FAI (), NRIC: S2584543I, Tel: +6596195972 Email:								
Adj Asg. Remarks:	WS: SALLY 67452088								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

17/07 2019 WED 10:51 FAX

001/004

MSME10093050 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 16/07/2019 15:27
 SUBMITTED BY: Chia Pak Ying

Marcus

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.

ACCIDENT STATEMENT	
Date Of Report	16/07/2019 15:27
Date Of Accident	16/07/2019 09:40
Exact Location Of Accident	JUNCTION OF HOUGANG AVE 3 & LOR AH SOO
Country/State Of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGW479Z
Insured/Policyholder	
Name Of Registered Owner	DANNY BUAY ENG KIT
NRIC No	S7806588E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83183183
Alternative Phone No	OFFICE-83183183
Vehicle Particulars	
Manufacturer	SUBARU
Model	WRX
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100373440-05
Cover Note Number	
Driver	
Name of Driver	DANNY BUAY ENG KIT
NRIC No	S7806588E
Date Of Birth	09/03/1978
Occupation	INDOOR
Date Of Driving Pass	26/07/2003
Driving Experience	15 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83183183
Fax Number	
Contact Number	OFFICE-83183183
Email Address	NOEMAIL

17/07 2019 WED 10:51 FAX

002/004

Address BLK 715 YISHUN ST 71 #09-276
 Postcode 760715
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 16/07/2019 AT ABOUT 9.37AM, I WAS DRIVING ALONG HOUGANG AVE 3 ON THE SECOND LANE WHEN SUDDENLY, A VAN B WHICH WAS ON THE THIRD LANE CAME INTO MY LANE AND HIT THE FRONT LH SIDE OF MY CAR A.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC2219J
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

17/07 2019 WED 10:51 FAX

0003/004


Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature

Date & Time: 16/7/19, 10:00am


 Driver's Signature

(If driver is not the policyholder)

Date & Time: 16/7/19, 10:10am

Reporting Centre Personnel's Signature

Name:


NRIC/FIN No.:

17/07 2019 WED 10:52 FAX

004/004

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/7/19 at about 9:30am, I was driving along Horgang Ave 3 on the 2nd lane when suddenly a van (B) which was on the 3rd lane came into my lane and hit the front L/H side of my car (A).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 16/7/19, 10:10am

GIARMC SketchPlanForm_V3

Driver's Signature
(If driver is not the policyholder)
Date & Time: 16/7/19, 10:10am

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	588E
Vehicle Details	
Vehicle No.:	SGW479Z
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jul 2019
Vehicle Make:	SUBARU
Vehicle Model:	2.5 WRX
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	EJ25D125745
Chassis No.:	JF1GDGKD37G071558
Maximum Power Output:	169.0 kW (226 bhp)
Open Market Value:	\$17,229.00
Original Registration Date:	29 Jun 2007
First Registration Date:	29 Jun 2007
Transfer Count:	2
Actual ARF Paid:	\$18,952.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jun 2027
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$54,088.00
COE Rebate Amount:	\$42,894.00
Total Rebate Amount:	\$42,894.00

The information contained herein is correct as at 23 Jul 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



WRX

Price Range ▼

Depreciation ▼

> 10 year(s) ▼

Vehicle Type ▼



Home » Used Cars » Axle Motors Pte Ltd » Subaru Impreza WRX 2.5M (COE till 04/2027)

Subaru Impreza WRX 2.5M (COE till 04/2027)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$51,800**Depreciation** ⓘ \$6,660 /yr**Reg Date** 11-Jun-2007
(7yrs 9mths 7days COE left)**Mileage** N.A.**Manufactured** ⓘ 2007**Road Tax** ⓘ \$2,100 /yr**Transmission** Manual**Dereg Value** ⓘ \$40,438 as of today (change)**OMV** ⓘ \$17,312**COE** ⓘ \$52,008**ARF** ⓘ \$19,044**Engine Cap** 2,457 cc**Power** 169.0 kW (226 bhp)**Curb Weight** ⓘ 1,405 kg**No. of Owners** ⓘ 4**Type of Vehicle** Sports Car**Features**

Hawkeye WRX 2.5M, Powerful Boxer 4, 16 Valve Dohc Turbocharged In All Wheel Drive. View specs of the Subaru Impreza WRX (2007-2011)

Accessories

LTA Approved Fujitsubo Rear Exhaust Muffler, TD05-18G Turbo, STI Intercooler, STI 6-speed Gearbox, STI Brembo Front & Rear Brakes, Blitz Air Intake.

Description

Gizzmo Boost Controller, Cusco REAR LSD, D2 Coil Overs With Camber Adjuster And Camber Bolts, Cusco Front And Rear Sway Bars, Exedy Clutch Changed In Feb 2019, Spare TD04 Turbo, All Receipts Of Parts Changed Available. Trade-Ins Welcomed. Viewing Strictly By Appointment Only.

Category

COE Car, Premium Ad Car

Status

Available

Compare



Shortlist

Corr

Report Error

M

Seller Information**Company****Axle**

» dea

» 19

Address

705 S

Searc

Location

Shun

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Jul 2019		18 Jul 2019 13:24 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SWISSWERKZ (S) PTE LTD, Co. Reg. No.: 200801506C		
Main Claimant:	DANNY BUAY ENG KIT, ID: S7806588E		
Vehicle Reg. No.:	SGW479Z	Date of Loss:	16/07/2019 09:00 - :59 [144 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1903416	Policy/Cover Note No.:	D18MTPCVE002758 (Comprehensive)
Vehicle Reg. No. (Insured):	GBC2219J	Policy No. (Claimant):	
		Excess:	
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 29/07/2019]		
Driver/Custodian (Insured):	LUM CHEE FAI (), NRIC: S2584543I, Tel: +6596195972 Email:		
Adj Asg. Remarks:	WS: SALLY 67452088		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGW479Z (CMTD1903416)**
[GBC2219J]
TP
DANNY BUAY ENG KIT
Jul 16 2019 9:00AM
[SWISSWERKZ (S) PTE LTD]
Bluwel Automotive Service Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View [View in Browser](#) ▼

Assessment Reports

No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
1	18/07/19 13:23	Accident Statement From: SC - Reg. No: GBC2219J, Claimant: SWISSWERKZ (S) PTE LTD	1	Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	29/07/19 11:56	General View	1	Load JPG	✓
2	29/07/19 11:56	General View	1	Load JPG	✓
3	29/07/19 11:56	General View	1	Load JPG	✓
4	29/07/19 11:56	General View	1	Load JPG	✓
5	29/07/19 11:56	General View	1	Load JPG	✓
6	29/07/19 11:56	General View	1	Load JPG	✓
7	29/07/19 11:56	General View	1	Load JPG	✓
8	29/07/19 11:56	General View	1	Load JPG	✓
9	29/07/19 11:56	General View	1	Load JPG	✓
10	29/07/19 11:56	General View	1	Load JPG	✓
11	29/07/19 11:56	General View	1	Load JPG	✓
12	29/07/19 11:56	General View	1	Load JPG	✓
13	29/07/19 11:56	General View	1	Load JPG	✓
14	29/07/19 11:56	General View	1	Load JPG	✓
15	29/07/19 11:56	General View	1	Load JPG	✓
16	29/07/19 11:56	General View	1	Load JPG	✓
17	29/07/19 11:56	General View	1	Load JPG	✓
18	29/07/19 11:56	General View	1	Load JPG	✓
19	29/07/19 11:56	General View	1	Load JPG	✓
20	29/07/19 11:56	General View	1	Load JPG	✓
21	29/07/19 11:56	General View	1	Load JPG	✓
22	29/07/19 11:56	General View	1	Load JPG	✓
23	29/07/19 11:56	General View	1	Load JPG	✓
24	29/07/19 11:56	General View	1	Load JPG	✓
25	29/07/19 11:56	General View	1	Load JPG	✓
26	29/07/19 11:56	General View	1	Load JPG	✓
27	29/07/19 11:56	General View	1	Load JPG	✓
28	29/07/19 11:56	General View	1	Load JPG	✓
29	29/07/19 11:56	General View	1	Load JPG	✓
30	29/07/19 11:57	Photographs of Damaged Parts	1	Load JPG	✓
31	29/07/19 11:57	Photographs of Damaged Parts	1	Load JPG	✓

Assessment Reports			1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
32	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
33	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
34	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
35	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
36	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
37	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
38	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
39	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
40	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
41	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
42	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
43	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
44	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
45	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
46	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
47	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
48	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
49	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
50	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
51	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
52	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
53	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
54	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
55	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
56	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
57	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
58	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
59	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
60	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
61	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
62	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
63	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
64	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
65	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
66	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
67	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
68	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
69	29/07/19 11:57	Photographs of Damaged Parts	 Load JPG	✓
70	29/07/19 18:12	After Repair Photo	 Load JPG	✓
71	29/07/19 18:12	After Repair Photo	 Load JPG	✓
72	29/07/19 18:12	After Repair Photo	 Load JPG	✓
73	29/07/19 18:12	After Repair Photo	 Load JPG	✓
74	29/07/19 18:12	After Repair Photo	 Load JPG	✓
75	29/07/19 18:12	After Repair Photo	 Load JPG	✓
76	29/07/19 18:12	After Repair Photo	 Load JPG	✓
77	29/07/19 18:12	After Repair Photo	 Load JPG	✓
78	29/07/19 18:12	After Repair Photo	 Load JPG	✓
79	29/07/19 18:12	After Repair Photo	 Load JPG	✓

Assessment Reports			1 per page ▾	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
Documentation			1 per page ▾	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	18/07/19 11:23	Pre-Repair Survey + GIA	 Load PDF	
2	18/07/19 13:24	Pre-Repair Survey - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19012680/UCF3S2

Date: 31/07/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPCVE002758
 Claimant Vehicle No: SGW479Z Insured Vehicle No: GBC2219J
 Date of Loss: 16/07/2019 Nature of Claim: TP Claim No: CMTD1903416

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGW479Z**
 Make & Model: SUBARU WRX, 2.0 AWD CVT (A) Engine No: EJ25D125745
 Reg. Date: 29/06/2007 (Man. Year: 2007) Chassis No: JF1GDGKD37G071558
 Colour: Grey Odometer: 258521 km
 Engine Capacity: 2457 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40ZR18 Rear Tyre Size: 225/40ZR18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/07/2019

Date Inspected: 22/07/2019 Inspected At:

Bluwel Automotive Service Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56
 Autobay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Jul 2019)

Parts: 143 SUBARU WRX 2.0 AWD CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGW479Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >