

ASS. REC. BY:

REF:

CS3 / CTI 19012690 / KAF302

Special Instruction:

Surveyor

Ram

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

18/7/19 @ 1:39pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 797G

Insured:

YM 9833P

at Workshop m/s

Zoom Autoworks

Tel:

94507920

of

15 kaki Bukit Road 4 #01-53

Policy No:

DMCVSN30014019000

Claim No:

SNM190203273602

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:14pm @ 18/7/19

Person Contacted:

elin

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLB 797G X

YM 9833P X

Dismantle: 22/7/2019

After repair: 24/7/2019

ASO. REC. BY:

RAM

REF:

CTI

PRS

ASSIGNMENT

From:

Date:

19/7/19

Estimated Cost:

OD / TP / NS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLB 797G

at Workshop m/s

Zoom Autowerks

of

15 Kaki Bukit Road 4 # 01-53

Insured:

Bentley Biz Centre

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Elin@94507920

After 10 am

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS 'up'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLB 797G

Yr Regn:

Oct

2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MADZA 3

c.c 1999

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

114728

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM6BL10F1A0110189

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/45 R17

R: 225/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MICY OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

5

mm

L/Bal.

4

mm

L/Bal.

5

mm

D.O.A.

09/07/19

D.O.I.

19/07/19

Survey held at

Zoom Autowerks

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair days: 5 days

Range: \$3000- \$4000

\$16,000

MV: \$7,000

PV: \$12,119

NV: \$18,887

23/7/2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 0

Survey Fee:

150

Transportation:

3 + RS, \$1

Photos

Others

TOTAL

150

Report Format:

PRS.

Lump Sum / LE J: %

Addl Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 18 July 2019 1:39 PM
To: Jenny
Cc: 'Ling Leong Hui'; Rachel Ling; 'Mdm Ling'; 'tcmg backup'; assignments
Subject: RE: OUR REF: SNM19D203273/CHONGBS - FW: PRE-REPAIR INSPECTION NOTICE FOR VEH SLB 797 G [Your ref: YM 9833 P]

SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK.

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Jenny [mailto:jenny@tcmg.com.sg]
Sent: Thursday, 18 July, 2019 11:42 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: 'Ling Leong Hui' <lhling@tcmg.com.sg>; Rachel Ling <jin@tcmg.com.sg>; 'Mdm Ling' <mdmling@tcmg.com.sg>; 'tcmg backup' <tcmg.backup@gmail.com>
Subject: RE: OUR REF: SNM19D203273/CHONGBS - FW: PRE-REPAIR INSPECTION NOTICE FOR VEH SLB 797 G [Your ref: YM 9833 P]
Importance: High

IMMEDIATE ATTENTION

WITHOUT PREJUDICE

Your ref: : SNM19D203273/CHONGBS
Our ref: TCMG/SLB797G/0719/ZAW

Dear Mr Chong

We refer to the above matter and to your mail of even date.

Our client is not agreeable to any of your appointed panel of surveyors as the Single Joint Expert.

Our client's panel of surveyors nominated as the Single Joint Expert is as attached.

(P/S : Please acknowledge receipt of this e-mail. Thank you.)

Regards

Jenny Tham
TOMMY CHOO, MARK GO LLC
151 Chin Swee Road
#14-15/16 Manhattan House
Singapore 169876
Tel: 6532 2455 - Fax: 6538 9850
Email Address: jenny@tcmg.com.sg

From: Chong Boon Sen [<mailto:boonsen.chong@sg.entaiping.com>]

Sent: 18 July 2019 11:16

To: jenny@tcmg.com.sg

Subject: RE: OUR REF: SNM19D203273/CHONGBS - FW: PRE-REPAIR INSPECTION NOTICE FOR VEH SLB 797 G [Your ref: YM 9833 P]

WITHOUT PREJUDICE

Dear Sir,

We refer to your email below.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Wednesday, 17 July, 2019 5:18 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>;
Chee So Chow <sochow.chee@sg.cntaiping.com>; jenny@tcmg.com.sg

Subject: OUR REF: SNM19D203273/CHONGBS - FW: PRE-REPAIR INSPECTION NOTICE FOR
VEH SLB 797 G [Your ref: YM 9833 P]

Importance: High

Dear Boon Sen,

Please conduct PRS for SLB797G.

Note : Officer in charge – Boon Sen 63896171.

Thanks,
shumin

From: Jenny [<mailto:jenny@tcmg.com.sg>]

Sent: Wednesday, July 17, 2019 5:08 PM

To: Claims Dept of CTI

Cc: zoomautowerks@gmail.com; 'Ling Leong Hui'; Rachel Ling; 'Mdm Ling'; 'tcmg backup'

Subject: PRE-REPAIR INSPECTION NOTICE FOR VEH SLB 797 G [Your ref: YM 9833 P]

Importance: High

IMMEDIATE ATTENTION

Dear Sirs

We refer to the above matter.

We attached herein copy of our Notice of Pre-Repair Inspection for your attention.

Thank you.

(P/S : Please acknowledge receipt of this e-mail. Thank you.)

Regards

Jenny Tham
TOMMY CHOO, MARK GO LLC
151 Chin Swee Road
#14-15/16 Manhattan House
Singapore 169876
Tel: 6532 2455 - Fax: 6538 9850
Email Address: jenny@tcmg.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	410M
Vehicle Details	
Vehicle No.:	SLB797G
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jul 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 2.0L HB
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	LF10794626
Chassis No.:	JM6BL10F1A0110189
Maximum Power Output:	108.0 kW (144 bhp)
Open Market Value:	\$23,197.00
Original Registration Date:	28 Oct 2009
First Registration Date:	28 Oct 2009
Transfer Count:	4
Actual ARF Paid:	\$23,197.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Oct 2019
PARF Rebate Amount:	\$11,598.00
Intended COE Rebate Details	
COE Expiry Date:	27 Oct 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$20,200.00
COE Rebate Amount:	\$521.00
Total Rebate Amount:	\$12,119.00

The information contained herein is correct as at 22 Jul 2019

DOA: 09/07/19

OK

COE: 27/10/19

COE remaining from DOA: 3 months 18 days (3.5 months)

Depri: \$9000 (yearly) \$750

3.5 months x \$750 = \$2625

\$2625 + \$11598 = \$14223



Mazda 3 1.6A (New 5-yr COE) **\$29,800** **\$5,950 /yr** 27-Jan-2010 1,598 cc - Sedan Available

Monthly \$600 Plus. Income \$3k And Above To Apply. Hurry Before It's Sold. Purchase From An Award Winning Dealership! Accident Free Quality Pre Owned With Low Mileage Done For Peace Of Mind. 100% Loan Approval With Our Flexible In House Financing Options. View...

88 Motor Trading

Posted: 12-Jul-2019 Tags: 2010 Mazda 3, 2010 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.6A Luxury **\$19,800** **\$9,700 /yr** 12-Jul-2010 1,598 cc 168,123 km Sedan Available

Evaluated By Vicom, Free 6 Months Maintenance And 1 Grooming.

Yong Lee Seng Motor

Posted: 10-Jul-2019 Tags: 2010 Mazda 3, 2010 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.6A Luxury (New 5-yr COE) **\$31,800** **\$6,350 /yr** 29-Jan-2010 1,598 cc 92,000 km Sedan Available

(100% Loan Available) Monthly \$430! Bank Interest Rate From 2.98%! Best Condition In The Market. Lowest Depreciation! Smooth Engine And Gear Box. Cash And Carry Or Loan With Low Interest Rate Available. Very Well Maintained By Previous Owner With No Repa...

Dynamic Motoring

Posted: 09-Jul-2019 Tags: 2010 Mazda 3, 2010 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda



Pimp Your Ride With Sports Rim

Sports rim do not just perk up the aggressive outlook of a car, it actually does improve performance with its lighter weight. Find yourself a beautiful set of rims from the list of tyre & rims retailers.

Find out more!



Mazda 3 2.0A Luxury **\$16,800** **\$9,090 /yr** 10-Feb-2010 1,999 cc 118,000 km Sedan Available

Guaranteed Accident Free, High OMV \$24K, Beautiful Leather Interior, Extremely Well Maintained, Wear & Tear Parts Fully Replaced, Guaranteed Loan For Bad Credit/Ex Bankruptcy, View After Lunch Till 11PM Daily, Please Call To Arrange Viewing.

Posted: 26-Jun-2019 Tags: 2010 Mazda 3, 2010 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used mazda 3, mazda 3 Singapore, used mazda 3 Singapore, used mazda 3, used vehicles Singapore or even buy used mazda 3 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/07/2019 17:27
Date Of Accident	09/07/2019 21:40
Exact Location Of Accident	ALONG BUKIT TIMAH RD BEFORE CAVANAGH RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLB797G
Insured/Policyholder	
Name Of Registered Owner	ZOOM CAR LEASING
Co Reg No	53349410M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94507920
Vehicle Particulars	
Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN048680
Cover Note Number	
Driver	
Name of Driver	TIONG KAI SIANG
NRIC No	S9449388I
Date Of Birth	31/12/1994
Occupation	OUTDOOR
Date Of Driving Pass	12/06/2015
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91172171
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 832 SIMS AVE #12-884
Postcode	400832
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE STATED DATE AND TIME, VEHICLE A (SLB797G) WAS STATIONARY ON THE STATED VENUE DUE TO RED LIGHT. SUDDNELY, VEHICLE B (YM9833P) HIT ONTO MY STATIONARY VEHICLE'S REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM9833P
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	82654649
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

ZOOM CAR
TEASING


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

vehicle B: YM9833P



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date & time, I, vehicle 'A'
SLB7974, was stationary on the stated venue due to
red light. Suddenly, vehicle 'B', YM 9833P, hit onto my
stationary vehicle's rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

**ZOOM CAR
LEASING**

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

LETTER OF UNDERTAKING

I/We, ZOOM CAR LEASING, the owner of vehicle no. SLB 7976

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14 (fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, _____

Signed and Acknowledge by:

**ZOOM CAR
LEASING**

Name and signature of policyholder

Company Stamp

10/07/2019
Date

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

Class 3 Motor Cars =< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg

EFFECTIVE DATE 12 Jun 2015

Licence No: S9449388

NP 428A

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S9449388I

Name TIONG KAI SIANG

张凯翔

RACE CHINESE

Date of birth 31-12-1994

Country of birth SINGAPORE

Sex M

4 5 2 2 4 1 2

NRIC No. S9449388I

Date of issue 14-01-2012

Address APT BLK 832 SIMS AVENUE #12-884 SINGAPORE 400832

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S9449388I

Name TIONG KAI SIANG

Birth Date: 31 Dec 1994

Issue Date: 12 Jun 2015

002438395H

AXA INSURANCE PTE LTD

8 Shenton Way, #24-01
 AXA Tower, Singapore 068811
 Customer Centre #01-21
 Tel 1800 8804888
 Website: www.axa.com.sg
 GST Registration Number : 199903512M
 customer.care@axa.com.sg

**Original**Agent Code: **15423**

Policy No.(if any):

New Business

SmartDrive Quote Ref:

MOTOR COVER NOTE**No. CN048680**

- The Motor Vehicle (Third Party Risks and Compensation) Act (Cap 189) - Republic of Singapore; or
- The Road Transport Act 1987 of Malaysia; or
- The Agreement between the Minister of Finance (Singapore) and the Motor Insurers' Bureau of Singapore dated 22 February 1975; or
- The Agreement between the Minister for Transport (Malaysia) and the Motor Insurers' Bureau of West Malaysia dated 30 March 1992;
- And any subsequent revisions to the above Acts and Agreements

The Insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule, is hereby HELD COVERED under the terms of the Company's usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE

THE COMPANY	AXA INSURANCE PTE LTD
INSURED	ZOOM CAR LEASING
INSURED BUSINESS REGISTRATION NO.	53349410M
MAKE AND DESCRIPTION OF VEHICLE	MAZDA MAZDA3 2.0L HB
VEHICLE REGISTRATION NO.	SLB797G
YEAR OF MANUFACTURE	2009
ENGINE NO.	LF10794626
CHASSIS NO.	JM6BL10F1A0110189
ENGINE CAPACITY/TONNAGE	1999 CC
COVER TYPE	THIRD PARTY ONLY
HIRE PURCHASE	NIL
VALUE (\$)	AS PER MARKET VALUE
PERIOD OF INSURANCE	FROM: 31/05/2019 TO: 30/05/2020
EXCESS (\$)	AS PER POLICY
AXA PREMIUM WORKSHOP?	NO

I/WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA).

AXA INSURANCE PTE LTD


 Authorised Signature

Issued by Pallavi BOSE on 12/06/2019 6:43 pm

Note: This Cover Note is only valid for 60 days from the date of issue unless replaced by the Certificate of Insurance issued by the Company.

- Premium for time on risk will be charged subject to minimum of S\$53.50 (inclusive of GST), if the policy is cancelled after the inception date.
- An administrative fee of S\$26.75 (inclusive of GST) will be charged :
 - Cover note issued and cancelled before inception.
 - Retaining the old registration number for a new vehicle insuring with AXA.

PREMIUM WARRANTY

For Individual Customers:

Please note that the premium in full should be paid before inception date shown above in order for the insurance cover to be valid.

For Non-Individual Customers:

Please note that where the period of cover is for more than 60 days, the premium in full should be paid within 60 days on inception / renewal / endorsement. For all other cases, the premium in full should be paid before inception.

MTR/CNOTE/01A03

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jul 2019		22 Jul 2019 08:46 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case
































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	ZOOM CAR LEASING , Co. Reg. No.: 53349410M								
Vehicle Reg. No.:	SLB797G	Date of Loss:	09/07/2019 21:00 - :59 [116 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203273C02	Policy/Cover Note No.:	DMCVSN30014019000						
Vehicle Reg. No. (Insured):	YM9833P	Policy No. (Claimant):	CN048680						
		Excess:	S\$0.00						
Repairer:	Zoom Auto Werks - Kaki Bukit (HQ) BLK 15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTRE, 417808 Kaki Bukit - Tel: 94507920								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 31/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									















































Claim Documents


***SLB797G (SNM19D203273C02)**
[YM9833P]

TP
ZOOM CAR LEASING
Jul 9 2019 9:00PM














[-]
Zoom Auto Werks - Kaki Bukit

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	10/07/19 17:35	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	10/07/19 17:35	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	10/07/19 17:35	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	10/07/19 17:35	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	10/07/19 17:35	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	10/07/19 17:35	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	10/07/19 17:35	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	10/07/19 17:35	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
2	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
3	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
4	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
5	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
6	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
7	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
8	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
9	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
10	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
11	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
12	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
13	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
14	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
15	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
16	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
17	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
18	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
19	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
20	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
21	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
22	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
23	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
24	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
25	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
26	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
27	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
28	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
29	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
30	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
31	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
32	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
33	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
34	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
35	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
36	26/07/19 14:02	General View	 Load JPG	<input checked="" type="checkbox"/>
37	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	26/07/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	26/07/19 14:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	26/07/19 14:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	26/07/19 14:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	10/07/19 17:35	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	10/07/19 17:35	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	10/07/19 17:35	Sketch Plan #3 [Linked Accident Report Documents]	 Load TIF	
4	10/07/19 17:35	Sketch Plan #4 [Linked Accident Report Documents]	 Load TIF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
5	10/07/19 17:35	Sketch Plan #5 [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser	1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print		
1	10/07/19 17:35	Accident Statement	 Load HTM			
Photos/Images			3 per page	<input checked="" type="checkbox"/>		
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print		
1	10/07/19 17:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
2	10/07/19 17:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
3	10/07/19 17:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
4	10/07/19 17:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
5	10/07/19 17:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
6	10/07/19 17:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
7	10/07/19 17:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
Documentation			1 per page	<input checked="" type="checkbox"/>		
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print		
1	10/07/19 17:35	Sketch Plan	 Load TIF			
2	10/07/19 17:35	Sketch Plan #2	 Load TIF			
3	10/07/19 17:35	Sketch Plan #3	 Load TIF			
4	10/07/19 17:35	Sketch Plan #4	 Load TIF			
5	10/07/19 17:35	Sketch Plan #5	 Load TIF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119012690/FCF3E2

Date: 31/07/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30014019000

Claimant Vehicle
No : SLB797GInsured Vehicle
No : YM9833P

Date of Loss: 09/07/2019

Nature of Claim: TP

Claim
No: SNM19D203273C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB797G

Make & Model: MAZDA 3, 2.0 (A)

Reg. Date: 28/10/2009 (Man. Year: 2009)

Colour: Blue

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: LF10794626

Chassis No: JM6BL10F1A0110189

Odometer: 114728 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Michelin 4 mm

Rear Left Side:

Michelin 5 mm

Front Right Side: Michelin 4 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/07/2019

Date Inspected: 19/07/2019 Inspected At:

Zoom Auto Werks - Kaki Bukit (HQ)
BLK 15 KAKI BUKIT ROAD 4, #01-53
BARTLEY BIZ CENTRE
Singapore 417808

Estimated Period of Repair: 5.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2019)
Parts:	144	MAZDA 3 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB797G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >