

INS. CASE OWNER:

CC 4 / EGI1901

2708, E1663.

LKK:

IDAC:

Surveyor:

STEVE

DOI:

17/5/10

Date / Time:

17/5/10

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

GBO 7072B.

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II : \$

D.O.A :

17/5/10

Place of Accident :

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SM 629E.



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time	STAGE	DATE / PIC
SM 629E - X	Non-Reporting ltr (1st):	
GBO 7072B - X	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☐ ☐
	Authorisation To Act:	☐ ☐
	Release Voucher:	☐ ☐
	Final Repair Bill:	☐ ☐
	Car Rental Invoice:	☐ ☐
	Towing Invoice:	☐ ☐
	LTA / GIA :	☐ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☐ ☐
	LOD	☐ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☐ ☐
	Others:	☐ ☐
PRELIMINARY ADVICE Date/Time:	Sent By:	Confirm by:
FINALIZATION Date/Time:	Confirm with:	Confirm by:
Repair Cost: \$	(days) Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time:	Confirm with	Email ☐ Call ☐
Final Liability: %	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost: \$		
Loss of Rental (LOR): \$	(days)	
Loss of Use (LOU): \$	(\$ x days)	
Loss of Income (LOI): \$	(\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐ [Tick only one]		
GIA/LTA Search \$		
Medical: \$		1) Claim status: Normal/Reject/Private Settle
Disbursement: \$	(e.g. Tow/ Independent)	2) Report Format:
Legal Cost \$		3) Survey fee:
Total: \$	Global Sum \$:	
FINAL PAYMENT Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1: \$	Name 1:	
Payee 2: (Strike if N.A.) \$	Name 2:	
Payee 3: (Strike if N.A.) \$	Name 3:	

Surveyor

Steve

REF: Ergo

ASSIGNMENT

From:

Date:

17.7.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLU 635R

at Workshop m/s

Vermogen

of

60 Jalan Lamy Huat

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLU 635R

Yr Regn:

7/7/11

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Jaguar XJ

c.c

5000

Colour:

Glam

A/C:

Insured / Std / NI / NA

Sp. Reading

87450

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

SAJAC 22FSBLV2047F

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45 R19

R:

18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

13/7/19

D.O.I.

17/7/19

Survey held at

Vermogen

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV - 83000

PV - 61,161

NV - 21,839

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$