

ASS. REC. BY:

REF:

CS3/CT119012717/G-327

Special Instruction:

Surveyor: Chao CheongASSIGNMENT (Office)

From (Person):

Aaine cheong

of

CTI

Date/Time:

18/7/19 3:06pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE2601J

Insured:

SLB9084X

at Workshop m/s

K&M Motor

Tel:

97538067

of

51 ubi Avenue 1 #03-18

Policy No:

OMPEN3014101900

Claim No:

SNMT19D203297C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

13/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:16pm 18/7/19

Person Contacted:

VickyVehicle: IN/OUT

Date/Time

Action/Instruction

Estimate (X)

SLE2601J NA/NC19012447/24 DOA=13/7/19SLB9084X NA/CT119012453/24 DOA= "Dismantle: 19/7/2019After repair: 24/7/2019

PRS  
62

REF:

CTI

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt.: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No.

Yr Regn:

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$ 4000 - \$ 5000

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format: PRO

Lump Sum / I.B.I.: (\$ )

Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

190

190

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                   | Adj Rpt | Adj Submitted | Ins Auth'ed | Status                               |
|------|-------------|---------------|--------------------------------|---------|---------------|-------------|--------------------------------------|
| Main | 17 Jul 2019 |               | 18 Jul 2019<br>16:43<br>Assign |         |               |             | <b>New Assignment</b><br>Cancel Case |

Main

Reference

Claim Details

Documents

Show All

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |  |                        |                        |
|-----------------------------|--|------------------------|------------------------|
| Insured:                    |  |                        |                        |
| Main Claimant:              | MD SYAHMEER BIN ROSMAN, ID: S9242050G  |                        |                        |
| Vehicle Reg. No.:           | SLE2601J   | Date of Loss:          | 13/07/2019 16:00 - :59 |
| Claim Type:                 | TP / SNM19D203297C02   | Policy/Cover Note No.: | DMPCSN3014101900       |
| Vehicle Reg. No. (Insured): | SLB9084X   | Policy No. (Claimant): | 5103565069             |
|                             |  | Excess:                | \$1,500.00             |
| Repairer:                   | K & M Motor Pte Ltd (HQ) 53 Ubi Ave 1 #01-19 Paya Ubi Industrial Park, 408934 Ubi - Tel: 66945965  |                        |                        |
| Handling Insurer:           | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong] |                        |                        |
| Claimant's Insurer:         | NTUC Income Insurance Co-operative Ltd (HQ) - Tel:   |                        |                        |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/07/2019]                  |                        |                        |

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Nivitha (LKK Auto)

---

**From:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Sent:** Thursday, 18 July 2019 3:06 PM  
**To:** wanting@lawrencelee.com.sg; assignments@lkkauto.com  
**Subject:** RE: OUR REF: SNM19D203297/CHEONGML - SLB9084X - PRS FOR SLE2601J FW: Fax Message NO.1376  
**Attachments:** OUR REF: SNM19D203297/CHEONGML - SLB9084X - PRS FOR SLE2601J FW: F....1376 (28.5 KB)

**WITHOUT PREJUDICE  
SAVE AS TO COSTS**

Dear Wanting,

We refer to your email of 17.07.19 and our telephone conversation a moment ago.

We noted that you are not agreeable to our proposed surveyors as SJE and we will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6224 7478 / 6224 7175

Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

-----Original Message-----

From: wanting@lawrencelee.com.sg [mailto:wanting@lawrencelee.com.sg]

Sent: Wednesday, 17 July, 2019 3:37 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: RE: OUR REF: SNM19D203297/CHEONGML - SLB9084X - PRS FOR SLE2601J FW: Fax Message NO.1376

Dear Elaine,

We refer to the above matter.

We note that to-date we have not received any response from you.

As such, our client's workshop will instruct their own surveyor and commence repair of our client's damaged vehicle.

Please instruct your own surveyor to conduct the pre-repair survey at K & M Motor Pte Ltd at 51 Ubi Avenue 1 #03-18 Paya Ubi Industrial Park Singapore 408933 (contact person: Vicki, mobile phone: 9753 8067) within the next two (2) working days excluding Saturday, Sunday and Public Holiday.

Regards,

Tay Wan Ting (wanting@lawrencelee.com.sg) Paralegal For and On Behalf of Lee Wee Peng Lawrence Lee & Co (UEN: 53159236K)  
133 New Bridge Road #13-05 Chinatown Point Singapore 059413 tel. 6533 3680 fax. 6533 3689 email. info@lawrencelee.com.sg

This email is confidential and may be subject to legal privilege. If you are not the intended recipient, please delete this email and its contents/attachments immediately.

-----Original Message-----

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Sent: Tuesday, 16 July 2019 11:33 AM

To: wanting@lawrencelee.com.sg; info@lawrencelee.com.sg; Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: OUR REF: SNM19D203297/CHEONGML - SLB9084X - PRS FOR SLE2601J FW: Fax Message NO.1376

Dear Elaine,

Please conduct PRS for SLE2601J.

Dear All,

Please be advise that the Officer in charge is Elaine, 63896530.

Thank you

Lim Shu Min  
Executive  
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896156 | F: (65) 62247175

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: FA-X5575C-19A

Sent: Monday, 15 July, 2019 3:12 PM  
To: FA-X5575C-16A-CL <FA-X5575C-16A-CL@sg.cntaiping.com>  
Subject: FW: Fax Message NO.1376

Maureen Ong  
HR & Administration Department

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6111 | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平狮城 Taiping SG

-----Original Message-----

From: FA-RC6004F-16A-FN@sg.cntaiping.com [mailto:FA-RC6004F-16A-FN@sg.cntaiping.com]  
Sent: Monday, 15 July, 2019 3:06 PM  
To: FA-X5575C-19A  
Subject: Fax Message NO.1376

This E-mail was sent from "RC6004F-16A-FN" (MP C6004ex).

Queries to: FA-RC6004F-16A-FN@sg.cntaiping.com

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## Nivitha (LKK Auto)

---

**From:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Sent:** Tuesday, 16 July 2019 11:33 AM  
**To:** wanting@lawrencelee.com.sg; info@lawrencelee.com.sg; Elaine Cheong; Alfred Toh; Chee So Chow  
**Subject:** OUR REF: SNM19D203297/CHEONGML - SLB9084X - PRS FOR SLE2601J FW: Fax Message NO.1376  
**Attachments:** 20190715150619765.pdf

Dear Elaine,

Please conduct PRS for SLE2601J.

Dear All,

Please be advise that the Officer in charge is Elaine, 63896530.

Thank you

Lim Shu Min  
Executive  
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896156 | F: (65) 62247175

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: FA-X5575C-19A  
Sent: Monday, 15 July, 2019 3:12 PM  
To: FA-X5575C-16A-CL <FA-X5575C-16A-CL@sg.cntaiping.com>  
Subject: FW: Fax Message NO.1376

Maureen Ong  
HR & Administration Department

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6111 | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平狮城 Taiping SG

-----Original Message-----

From: FA-RC6004F-16A-FN@sg.cntaiping.com [mailto:FA-RC6004F-16A-FN@sg.cntaiping.com]

Sent: Monday, 15 July, 2019 3:06 PM

To: FA-X5575C-19A

Subject: Fax Message NO.1376

This E-mail was sent from "RC6004F-16A-FN" (MP C6004ex).

Queries to: FA-RC6004F-16A-FN@sg.cntaiping.com



**LAWRENCE LEE & CO**

Advocates &amp; Solicitors

**李伟平律师楼**

UEN: 53159236K

133 New Bridge Road #13-05  
Chinatown Point Singapore 059413  
tel: 6533 3680 fax: 6533 3689  
email: info@lawrencelee.com.sg

Your ref: please advise  
Our ref: LWP/KMM/4286/19/wt

15 July 2019

China Taiping Insurance (Singapore) Pte Ltd

FAX: 6222 1033

Dear Sirs

**NOTICE OF ACCIDENT PURSUANT TO THE NIMA PROTOCOL  
ACCIDENT ALONG PIE TWDS TUAS ON 13.07.19  
INVOLVING SLE2601J & SLB9084X**

We are instructed by Mr Md Syahmeer Bin Rosman to notify you of the abovementioned road traffic accident involving our client's vehicle registration number SLE2601J and vehicle registration number SLB9084X owned and driven by your insured at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

We do hereby notify you that our client's damaged vehicle may be inspected at the workshop at K & M Motor Pte Ltd at 51 Ubi Avenue 1 #03-18 Paya Ubi Industrial Park Singapore 408933 (contact person: Vicki, mobile phone: 9753 8067).

*Kindly revert within two (2) working days by fax or by email to wanting@lawrencelee.com.sg.*

Yours faithfully



LEE WEE PENG LAWRENCE

Cc client

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                                      |
|-------------------------------|--------------------------------------|
| Owner ID Type:                | Singapore NRIC                       |
| Owner ID:                     | 050G                                 |
| Vehicle Details               |                                      |
| Vehicle No.:                  | SLE2601J                             |
| Vehicle to be Exported:       | No                                   |
| Intended Deregistration Date: | 19 Jul 2019                          |
| Vehicle Make:                 | HONDA                                |
| Vehicle Model:                | VEZEL 1.5X CVT                       |
| Primary Colour:               | Black                                |
| Manufacturing Year:           | 2015                                 |
| Engine No.:                   | L15B4031080                          |
| Chassis No.:                  | RU11111076                           |
| Maximum Power Output:         | 96.0 kW (128 bhp)                    |
| Open Market Value:            | \$19,772.00                          |
| Original Registration Date:   | 14 Jul 2016                          |
| First Registration Date:      | 14 Jul 2016                          |
| Transfer Count:               | 2                                    |
| Actual ARF Paid:              | \$9,772.00                           |
| Intended PARF Rebate Details  |                                      |
| PARF Eligibility:             | Yes                                  |
| PARF Eligibility Expiry Date: | 13 Jul 2026                          |
| PARF Rebate Amount:           | \$7,329.00                           |
| Intended COE Rebate Details   |                                      |
| COE Expiry Date:              | 13 Jul 2026                          |
| COE Category:                 | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):            | 10                                   |
| QP Paid:                      | \$46,009.00                          |
| COE Rebate Amount:            | \$32,124.00                          |
| <b>Total Rebate Amount:</b>   | <b>\$39,453.00</b>                   |

The information contained herein is correct as at 19 Jul 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                    |
|----------------------------|------------------------------------|
| Date Of Report             | 15/07/2019 12:30                   |
| Date Of Accident           | 13/07/2019 16:00                   |
| Exact Location Of Accident | PIE (TUAS) BEFORE CLEMENTI RD EXIT |
| Country/State of Loss      | SINGAPORE                          |

### DETAILS OF OWN VEHICLE

|                             |                        |
|-----------------------------|------------------------|
| Vehicle Registration Number | SLE2601J               |
| <b>Insured/Policyholder</b> |                        |
| Name Of Registered Owner    | MD SYAHMEER BIN ROSMAN |
| NRIC No                     | S9242050G              |
| Email Address               | NOEMAIL                |
| Mobile Phone No             | (LOCAL) +65-94897579   |
| Alternative Phone No        | OFFICE-94897579        |

### Vehicle Particulars

|  |                |
|--|----------------|
| Manufacturer   | HONDA          |
| Model  | VEZEL 1.5X CVT |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE    |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO             |
| If No, Please state action to be taken                                       | THIRD PARTY    |
| Vehicle Category   | PRIVATE CAR    |

### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | COMPREHENSIVE                          |
| Fleet Policy              | NO                                     |
| Policy Number             | 5103565069                             |
| Cover Note Number         |  |

### Driver

|                      |                              |
|----------------------|------------------------------|
| Name of Driver       | MUHAMMAD SYAHMEER BIN ROSMAN |
| NRIC No              | S9242050G                    |
| Date Of Birth        | 12/11/1992                   |
| Occupation           | OUTDOOR                      |
| Date Of Driving Pass | 30/06/2011                   |
| Driving Experience   | 8 YEARS AND 0 MONTHS         |
| Gender               | MALE                         |
| Mobile Number        | (LOCAL) +65-94897579         |
| Fax Number           |                              |
| Contact Number       | OFFICE-94897579              |
| Email Address        | NOEMAIL                      |

|   |                                   |
|---|-----------------------------------|
| Address   | BLK 19 BEDOK SOUTH ROAD<br>#08-21 |
| Postcode  | 460019                            |
| Was driver an employee of the Insured's Company     | NO                                |
| If No, Relationship of the Driver with the Insured  | OWNER                             |
| Vehicle Registration Number of Driver's Own Vehicle | -                                 |
|   | -                                 |
| Insurance Company of Driver's Own Vehicle           | -                                 |
|   | -                                 |
|   | -                                 |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|   |                               |
|---|-------------------------------|
| Was any foreign vehicle involved in this accident?  | NO                            |
| Number of vehicles (including own vehicle) involved in the accident                         | 2                             |
| Was any body injured in the Accident?   | NO                            |
| Was any injured conveyed to hospital by ambulance?  |                               |
| Was any other material or property damaged?   | YES                           |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO                            |
| Number of Passengers (Including Driver)   | 2                             |
| Passenger 1   | NAME: : -<br>GENDER: : FEMALE |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY STOPPED ALONG THE STATED VENUE AS IT WAS CONGESTED. SUDDENLY I FELT AN IMPACT OF MY VEHICLE AND REALIZE THAT VEHICLE B HIT ONTO MY VEHICLE REAR PORTION.

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |                           |
|-----------------------------|---------------------------|
| Vehicle Registration Number | SLB9084X                  |
| Vehicle Make/Model/Colour   |                           |
| Details Of Properties       |                           |
| Vehicle Category            | PRIVATE CAR               |
| Name of Driver              | ANG HAN WEE (HONG HANWEI) |
| NRIC/Passport Number        | S8415697C                 |
| Contact Number              |                           |
| Address                     |                           |
| Postcode                    |                           |
| Insurance Company Name      |                           |

Nature Of Damage

No. Of Passenger (Including Driver)

3

Passenger 1

NAME: ;

GENDER: ;

Passenger 2

NAME: ;

GENDER: ;

## Accident Sketch Plan

### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


#### **8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### Accident Sketch Plan

### SKETCH PLAN


PIE (Trans)

|   |
|---|
| A |
| B |

A. SLE26UJ  
B. SLE26UJ

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement.



## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel Signature  
Name:  
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                              | Ins Auth'ed | Status  |
|------|-------------|---------------|--|--|--|-------------|---|
| Main | 17 Jul 2019 |               | 18 Jul 2019<br>16:43<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |   |                        |  |
|-----------------------------|---|------------------------|--|
| Insured:                    | -, Co. Reg. No.: -  |                        |  |
| Main Claimant:              | MD SYAHMEER BIN ROSMAN, ID: S9242050G   |                        |  |
| Vehicle Reg. No.:           | SLE2601J  | Date of Loss:          | 13/07/2019 16:00 - :59<br>[35 Months and 29 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | TP / SNM19D203297C02  | Policy/Cover Note No.: | DMPCSN3014101900   |
| Vehicle Reg. No. (Insured): | SLB9084X  | Policy No. (Claimant): | 5103565069   |
|                             |   | Excess:                | S\$1,500.00  |
| Repairer:                   | K & M Motor Pte Ltd (HQ) 53 Ubi Ave 1 #01-19 Paya Ubi Industrial Park, 408934 Ubi - Tel: 66945965                 |                        |  |
| Handling Insurer:           | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]                |                        |  |
| Claimant's Insurer:         | NTUC Income Insurance Co-operative Ltd (HQ) - Tel:  |                        |  |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 29/07/2019] |                        |  |

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)



















































| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |







































## Claim Documents



\*SLE2601J (SNM19D203297C02)  
[SLB9084X]  
TP  
MD SYAHMEER BIN ROSMAN  
Jul 13 2019 4:00PM  
[-]  
K & M Motor Pte Ltd











|                    |                 |  |               |  |  |                    |  |  |                                 |                                     |                                     |
|--------------------|-----------------|--|---------------|--|--|--------------------|--|--|---------------------------------|-------------------------------------|-------------------------------------|
| Upload Documents   |                 |  | Upload Photos |  |  | Compose New Letter |  |  | View <div>View In Browser</div> |                                     |                                     |
| Assessment Reports |                 |  |               |  |  |                    |  |  | 1 per page                      |                                     | <input checked="" type="checkbox"/> |
| No                 | Finalized On    | National Assessment Centre Services (Ubi)            |               |  |  |                    |  |  | Thumbnail                       | Print                               |                                     |
| 1                  | 15/07/19 12:36  | Accident Statement                                   |               |  |  |                    |  |  | Load HTM                        |                                     |                                     |
|                    |                 |  |               |  |  |                    |  |  | 3 per page                      |                                     | <input checked="" type="checkbox"/> |
| No                 | Finalized On    | National Assessment Centre Services (Ubi)            |               |  |  |                    |  |  | Thumbnail                       | Print                               |                                     |
| 1                  | 15/07/19 12:34  | Accident Photo<br>[Linked Accident Report Documents] |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 2                  | 15/07/19 12:34  | Accident Photo<br>[Linked Accident Report Documents] |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 3                  | 15/07/19 12:34  | Accident Photo<br>[Linked Accident Report Documents] |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 4                  | 15/07/19 12:34  | Accident Photo<br>[Linked Accident Report Documents] |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 5                  | 15/07/19 12:34  | Accident Photo<br>[Linked Accident Report Documents] |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 6                  | 15/07/19 12:34  | Accident Photo<br>[Linked Accident Report Documents] |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 7                  | 15/07/19 12:34  | Accident Photo<br>[Linked Accident Report Documents] |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 8                  | 15/07/19 12:34  | Accident Photo<br>[Linked Accident Report Documents] |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 9                  | 15/07/19 12:34  | Accident Photo<br>[Linked Accident Report Documents] |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 10                 | 15/07/19 12:34  | Accident Photo<br>[Linked Accident Report Documents] |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 11                 | 15/07/19 12:34  | Accident Photo<br>[Linked Accident Report Documents] |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                    |               |  |  |                    |  |  | Thumbnail                       | Print                               |                                     |
| 1                  | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 2                  | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 3                  | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 4                  | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 5                  | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 6                  | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 7                  | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 8                  | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 9                  | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 10                 | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 11                 | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 12                 | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 13                 | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 14                 | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 15                 | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 16                 | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 17                 | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |
| 18                 | 19/07/19 09:30  | General View   |               |  |  |                    |  |  | Load JPG                        | <input checked="" type="checkbox"/> |                                     |

| Assessment Reports |                |   | 1 per page   | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|--|-------------------------------------|
| No                 | Finalized On   | National Assessment Centre Services (Ubi) | Thumbnail  | Print                               |
| 19                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 20                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 21                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 22                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 23                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 24                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 25                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 26                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 27                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 28                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 29                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 30                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 31                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 32                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 33                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 34                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 35                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                 | 19/07/19 09:30 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                 | 19/07/19 09:30 | Chassis Number                            |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                 | 19/07/19 09:30 | Odometer Reading                          |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG  | <input checked="" type="checkbox"/> |
| 42                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 43                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 44                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 45                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 46                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 47                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 48                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 49                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 50                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 51                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 52                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 53                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 54                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 55                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 56                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 57                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 58                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 59                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 60                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 61                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 62                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 63                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 64                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 65                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 66                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 67                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |
| 68                 | 29/07/19 09:35 | Photographs of Damaged Parts              |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                |  | 1 per page   | <input checked="" type="checkbox"/> |
|--------------------|----------------|--|--|-------------------------------------|
| No                 | Finalized On   | National Assessment Centre Services (Ubi)                  | Thumbnail  | Print                               |
| 69                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 70                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 71                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 72                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 73                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 74                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 75                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 76                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 77                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 78                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 79                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 80                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 81                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 82                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 83                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 84                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 85                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 86                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 87                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 88                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 89                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG   | <input checked="" type="checkbox"/> |
| 90                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG | <input checked="" type="checkbox"/> |
| 91                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG | <input checked="" type="checkbox"/> |
| 92                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG | <input checked="" type="checkbox"/> |
| 93                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG | <input checked="" type="checkbox"/> |
| 94                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG | <input checked="" type="checkbox"/> |
| 95                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG | <input checked="" type="checkbox"/> |
| 96                 | 29/07/19 09:35 | Photographs of Damaged Parts                               |  Load JPG | <input checked="" type="checkbox"/> |
| 97                 | 29/07/19 09:36 | Photo After Spray  |  Load JPG | <input checked="" type="checkbox"/> |
| 98                 | 29/07/19 09:36 | Photo After Spray  |  Load JPG | <input checked="" type="checkbox"/> |
| 99                 | 29/07/19 09:36 | Photo After Spray  |  Load JPG | <input checked="" type="checkbox"/> |
| 100                | 29/07/19 09:36 | Photo After Spray  |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation      |                |  | 1 per page   | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | China Taiping Insurance (Singapore) Pte. Ltd. (HQ)         | Thumbnail  | Print                               |
| 1                  | 18/07/19 16:44 | PRS - SLE2601J   |  Load PDF |                                     |
| 2                  | 18/07/19 16:47 | PRS - NON SJE (SLE2601J                                    |  Load PDF |                                     |
| No                 | Finalized On   | National Assessment Centre Services (Ubi)                  | Thumbnail  | Print                               |
| 1                  | 15/07/19 12:35 | Accident Sketch Plan<br>[Linked Accident Report Documents] |  Load JPG | <input checked="" type="checkbox"/> |
| 2                  | 15/07/19 12:35 | Accident Sketch Plan<br>[Linked Accident Report Documents] |  Load JPG | <input checked="" type="checkbox"/> |

## Linked Accident Report Documents

| Assessment Reports |                |   | 1 per page   | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|--|-------------------------------------|
| No                 | Finalized On   | National Assessment Centre Services (Ubi) | Thumbnail  | Print                               |
| 1                  | 15/07/19 12:36 | Accident Statement                        |  Load HTM |                                     |
| Photos/Images      |                |   | 3 per page   | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | National Assessment Centre Services (Ubi) | Thumbnail  | Print                               |
| 1                  | 15/07/19 12:34 | Accident Photo                            |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                |   | 1 per page   | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|--|-------------------------------------|
| No                 | Finalized On   | National Assessment Centre Services (Ubi) | Thumbnail  | Print                               |
| 2                  | 15/07/19 12:34 | Accident Photo                            |  Load JPG | <input checked="" type="checkbox"/> |
| 3                  | 15/07/19 12:34 | Accident Photo                            |  Load JPG | <input checked="" type="checkbox"/> |
| 4                  | 15/07/19 12:34 | Accident Photo                            |  Load JPG | <input checked="" type="checkbox"/> |
| 5                  | 15/07/19 12:34 | Accident Photo                            |  Load JPG | <input checked="" type="checkbox"/> |
| 6                  | 15/07/19 12:34 | Accident Photo                            |  Load JPG | <input checked="" type="checkbox"/> |
| 7                  | 15/07/19 12:34 | Accident Photo                            |  Load JPG | <input checked="" type="checkbox"/> |
| 8                  | 15/07/19 12:34 | Accident Photo                            |  Load JPG | <input checked="" type="checkbox"/> |
| 9                  | 15/07/19 12:34 | Accident Photo                            |  Load JPG | <input checked="" type="checkbox"/> |
| 10                 | 15/07/19 12:34 | Accident Photo                            |  Load JPG | <input checked="" type="checkbox"/> |
| 11                 | 15/07/19 12:34 | Accident Photo                            |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation      |                |   | 1 per page   | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | National Assessment Centre Services (Ubi) | Thumbnail  | Print                               |
| 1                  | 15/07/19 12:35 | Accident Sketch Plan                      |  Load JPG | <input checked="" type="checkbox"/> |
| 2                  | 15/07/19 12:35 | Accident Sketch Plan                      |  Load JPG | <input checked="" type="checkbox"/> |

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT19012717/GCF3E2

Date: 29/07/2019

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3014101900

Claimant Vehicle  
No : SLE2601JInsured Vehicle  
No : SLB9084X

Date of Loss: 13/07/2019

Nature of Claim: TP

Claim  
No: SNM19D203297C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE2601J**

Make &amp; Model: HONDA VEZEL, 1.5 1.5X CVT (A)

Engine No: L15B4031080

Reg. Date: 14/07/2016 (Man. Year: 2015)

Chassis No: RU11111076

Colour: Black

Odometer: 59774 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

Front Tyre Size: 225/50 R18

Rear Tyre Size: 225/50 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

### INSPECTION

Date of Assignment: 18/07/2019

Date Inspected: 18/07/2019 Inspected At:

51 UBI AVE 1 #03-18

Repairer : K &amp; M Motor Pte Ltd (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

### Reference

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 29 Jul 2019)                  |
| <b>Parts:</b>        | M1-SUV   | HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                              |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLE2601J)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >