

2/2

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 8503Y(Supplementary)

DATE : 22.07.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Filter Assy -Oil Done Done			\$ 380.00
	Timing Chain Inlet Case Assy OK OK			\$ 987.60
	Timing Chain Outlet Case Assy OK OK			\$ 958.40
	Crankshaft Pulley Done Done			\$ 1,226.50
	Engine Oil- 6 Litre OK OK			\$ 300.00
	Rod Assy-Oil Level Gauge broken broken			\$ 295.50
	Actuator broken broken			\$ 814.60
	Pulley-Idler Done Done			\$ 189.50
	Tension Assy Done Done			\$ 260.80
	Pulley-Idler- Front destroyed destroyed			\$ 189.50
	SUB TOTAL		5302.40	\$ 5,602.40
	LESS 20%		4241.92	\$ 1,120.48
	DISCOUNTED TOTAL			\$ 4,481.92
	<p>22/07/2019</p> <p></p> <p>2 KK Auto</p> <p></p>			
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

✓
✓
✓
✓
X
✓
✓
✓
✓
✓
✓

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 8503Y(Supplementary)

DATE : 23.07.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Gasket -Timing Chain Case Upper <i>Nec</i>			\$ 128.50
	Gasket -Timing Chain Case Lower <i>Nec</i>			\$ 128.50
	Lever- Timing Chain <i>broken</i>			\$ 238.00
	Pump Assy Coolant <i>Dome</i>			\$ 380.00
	Bonnet Hinge (LH/RH) <i>1st</i>	\$	41.00	\$ 82.00
	Bonnet Absorber (LH/RH) <i>NW</i>	\$	58.10	\$ 116.20
	SUB TOTAL		957.00	\$ 1,073.20
	LESS 20%			\$ 214.64
	DISCOUNTED TOTAL		765.60	\$ 858.56
<p><i>23/07/2019</i></p> <p><i>[Signature]</i></p> <p><i>2 Kk Auto</i></p> <p><i>[Signature]</i></p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

✓
✓
✓
✓
✓
X

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 8503Y(Supplementary)

DATE : 25.07.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Frt Tyre Rim <i>Paint</i>			\$ 325.30 ✓
	SUB TOTAL			\$ 325.30
	LESS 20%			\$ 65.06
	DISCOUNTED TOTAL			\$ 260.24
	<p><i>25/07/2019.</i></p> <p><i>[Signature]</i></p> <p><i>244 And</i></p> <p><i>[Signature]</i></p>			
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 8503Y(Supplementary)

DATE : 2.08.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	High Pressure Pump <i>Dem</i>			\$ 4,397.60
	SUB TOTAL			\$ 4,397.60
	LESS 20%			\$ 879.52
	DISCOUNTED TOTAL			\$ 3,518.08
	 dkk And 02/08/2019 			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.