

REF: C/TPD190127H8/R
ASS. REC. BY: _____
SUBJECT: ASSIGNMENT (Office)
From (Person): Kamaliah Kamie or SPF Date/Time: 8/7/2019
Estimated Cost: _____ Bill to: _____
OD+TP+WS+TP RES / OD RES / EVA / INV / MV / CS
To Inspect Vehicle No: 80H 28228 Insured: _____
at Workshop m/s _____ Tel: _____
of _____
Policy No: MHA8PF0600000102011 Claim No: TP/19/40595/2019
Sum Insured: _____ Excess: _____
Make of Veh: _____ D.O.A. 21/6/2019
(Client's Record)
CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____
Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	80H 28228 - NBA/MCG19011668/Y DON: 21/6/2019.

E99
Kos.

IO In-Charge: SIO Mohd Yazid

(FAIT)

- e) Case IAFP-IB-20190708 - Mechanical Inspection of Motor Car, SDH2822S (TP/IP/40595/2019)
- f) Case IAFP-IB-20190708 - Mechanical Inspection of Tipper, XD6857A (TP/IP/40595/2019)
- g) Case IAFP-IB-20190708 - Mechanical Inspection of Motorcycle, FBP1505X (TP/IP/40595/2019)

On 29 June 2019 at about 12.33 pm, the deceased riding motorcycle FBP 1505 X was travelling on lane 1 of 4 lanes road along AYE towards CTE when the rider collided onto the rear of motor car SDH 2822 S on lane 1 before falling onto lane 2 and colliding onto the right side of the tipper XD 6857 A. The rider died on the spot.

Vehicles to be inspected: SDH2822S - Involved Party
Vehicles to be inspected: XD6857A - Involved Party
Vehicles to be inspected: FBP1505X - Rider (Deceased)

IO In-Charge: SIO Mohd Yazid

- h) Case IAFP-IB-20190708 - Mechanical Inspection of Motor Car, SGD5561K (TP/IP/34807/2019)

On 2 June 2019 (Sunday) at or about 1.03am, the motor car driver was travelling along the single lane carpark of Stadium Boulevard when the front right portion of his m/car collided onto the Deceased who was walking on the right side of the carpark. After the impact, the Deceased fell and was run over by the left tyre of the m/car. As a result of the accident, A1 sustained head injuries and was conveyed to Tan Tock Seng Hospital in an unconscious state. At the hospital, the Deceased succumbed to his injuries and was pronounced dead at 1.45 am.

Vehicles to be inspected: SGD5561K - Potential Defendant

IO In-Charge: SIO Saleha

- i) Case IAFP-IB-20190708 - Mechanical Inspection of Garbage Truck, XD6910D (TP/IP/36651/2019)

On 10 June 2019 (Monday) at about 12.58pm, driver of garbage truck had just finished loading garbage at Blk 179 Yun Sheng Rd loading/unloading bay. As he started to move off and made a left turn towards the carpark exit, he suddenly felt a bump. He immediately stopped to check and saw pedestrian (deceased) underneath his truck, just behind the right front tyre. As a result of the accident, pedestrian sustained head injuries and was pronounced dead at scene at 1.11pm by Paramedic Sgt Siti.

Vehicles to be inspected: XD6910D - Potential Defendant

IO In-Charge: SIO Saleha

- j) Case IAFP-IB-20190708 - Mechanical Inspection of Motorcycle, FBK2748G (TP/IP/39529/2019)

On 24 June 2019 (Monday) at about 7.37 am, the deceased was travelling on the right lane of 2 lanes along Choa Chu Kang Ave 1 towards Teck Whye Crescent, when he suddenly lost control, mounted the centre divider before colliding onto a tree. Due to the impact, the deceased landed beside the tree while his helmet was flung to the opposite road. As a result of the accident, the Deceased sustained head injuries and was conveyed to National University Hospital in an unconscious state. At the hospital, the Deceased succumbed to his injuries and was pronounced dead at 8.55am.

Vehicles to be inspected: FBK2748G - Rider (Deceased)