

DATE/2019

ASS. REC. BY:

REF: C/TPD19012750/P

Special Instructions:

Survivor:

ASSIGNMENT (Office)

From (Person): Kamaliah Kamie

of SPF

Date/Time: 8/7/2019

Estimated Cost:

Bill to:

OD+TP+WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBT 253K

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPF060000210201

Claim No: TP/IP/40685/2019

Sum Insured:

Excess:

D.O.A 30/6/2019

Make of Veh:

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction ( ) Estimate
	GBT 253 K-X

*[Handwritten Signature]*

E103 A  
K15 in

IO In-Charge: SIO Saleha

- k) Case IAFP-IB-20190708 - Mechanical Inspection of Tipper Truck, XD2090X (TP/IP/40513/2019)  
l) Case IAFP-IB-20190708 - Mechanical Inspection of Garbage Truck, XD4956K (TP/IP/40513/2019)

On 24 June 2019 (Monday) at about 7.37 am, the deceased was travelling on the right lane of 2 lanes along Choa Chu Kang Ave 1 towards Teck Whye Crescent, when he suddenly lost control, mounted the centre divider before colliding onto a tree. Due to the impact, the deceased landed beside the tree while his helmet was flung to the opposite road. As a result of the accident, the Deceased sustained head injuries and was conveyed to National University Hospital in an unconscious state. At the hospital, the Deceased succumbed to his injuries and was pronounced dead at 8.55am.

Vehicles to be inspected: XD2090X - Driver (Deceased)

Vehicles to be inspected: XD4956K - Involved Party

IO In-Charge: SIO Saleha

(FAIT)

- m) Case IAFP-IB-20190708 - Mechanical Inspection of Motor Lorry, GBJ253K (TP/IP/40685/2019)

On 30 June 2019 (Sunday) at or about 7.07 a.m., The Witness claimed that he was travelling along New Upper Changi Road towards the direction of Upper Changi Road East on lane 1 of the 4-lanes road, directly behind of the Accused's motor lorry. He then noticed that the Accused's motor lorry was making a right turn into Bedok South Road on green light only and in the midst of doing so, the frontal right portion of the Accused's motor lorry collided into the Deceased who was still walking along the signalised pedestrian crossing while on flickering green man, ahead of the Accused's motor lorry from the Accused's right side to left side. Due to the collision, the Deceased was reported to be unconscious and case was classified as standby due to trauma thus he was conveyed by an ambulance to Changi General Hospital. However, on the same day at 8.50 a.m., the Deceased had succumbed to his injuries and he was pronounced dead by Dr Jonathan in Changi General Hospital.

Vehicles to be inspected: GBJ253K - Potential Defendant

IO In-Charge: SIO Kamaliah

2. These request has been approved by my management.

3. Thank you Sirs.

cc: FAIT Team & IO Afiq, fyip

Best regards,

Kamaliah Kamis (Miss)

Senior Investigation Officer | Fatal Accident Investigation Team

Traffic Police Department | Singapore Police Force

DID: (65) 6547 6435 | FAX: (65) 6547 6352