

ASS. REC. BY:

REF: CS3/INC1908527/B1031

Special Instructions:

Surveyor: Mr. Lim

## ASSIGNMENT (Office)

From (Person): Motor Insurance

of INC

Date/Time: 19/07/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 9127E

Insured:

SMS 245D

at Workshop in/s

Teamwork

Tel:

68442975

of

53 ubi Ave 1 #01-24

Policy No:

Claim No:

MT/1043407-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 6/5/2019

CA / REV / REP. / REV 24 HRS 'up'

Date/Time: 10:30am 14/5/19

Person Contacted:

Jumien

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction

Example 1

SLG 9127E - NA/INC1908527/21


SMS 245D - NA/INC1908527/21

D.O.A. 06/5/2019

D.O.A. 6/5/2019

lump sum \$2050 (cred: 2950; 59%), 5 days.

618- File pass to typist.

  
 11/8/2019

RECEIVED 06 AUG 2019



**Nivitha (LKK Auto)**

---

**From:** do\_not\_reply@income.com.sg  
**Sent:** Friday, 19 July 2019 2:01 PM  
**To:** assignments@lkkauto.com  
**Subject:** MT/1043407-002 - Claim Involving SMJ245D / SLG9127E on 06 May 2019  
**Attachments:** LOD2 2019-7-15.pdf.PDF; TP SR.PDF; EBGI-300002963-0000004525-1563502589682\_EBAOGICLM\_DLET\_MT.pdf

Dear Sir / Madam,

We refer to the above claim.

Enclosed is the letter / document for your necessary attention.

Yours sincerely

Motor Insurance  
Income

Note: This is a system generated email. Please do not reply to this email.

Your Ref: SLG9127E

Our Ref: MT/CA/TP/036/1043407-002/JL

19 Jul 2019

LKK AUTO CONSULTANTS PTE LTD  
51 UBI AVENUE 1  
#01-25 PAYA UBI INDUSTRIAL PARK  
SINGAPORE 408933

**WITHOUT PREJUDICE  
SAVE AS TO COSTS  
BY FAX & POST**

Dear Sir/Madam

**CLAIM NUMBER: MT/1043407-002  
ACCIDENT INVOLVING SMJ245D / SLG9127E on 6 May 2019**

We refer to the claim.

Please let us have your complete PRS report/recommendation.

If you have any queries, please contact Juliana Lee at 6430 7936 or email us at [juliana.lee@income.com.sg](mailto:juliana.lee@income.com.sg).

Yours sincerely



Jenny Pe  
Deputy Vice President  
Motor Insurance

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 07/05/2019 20:54  
Date Of Accident 06/05/2019 18:10  
Exact Location Of Accident MANDAI RD  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SLG9127E  
**Insured/Policyholder**  
Name Of Registered Owner CHUA YEOW LENG ERIC  
NRIC No S6840929B  
Email Address NOEMAIL  
Mobile Phone No (LOCAL) +65-91454748  
Alternative Phone No OFFICE-91454748

### Vehicle Particulars

Manufacturer CHEVROLET  
Model ORLANDO 1.4AT TURBO  
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number 5094832975-01  
Cover Note Number

### Driver

Name of Driver CHUA YEOW LENG  
NRIC No S6840929B  
Date Of Birth 26/10/1968  
Occupation INDOOR  
Date Of Driving Pass 03/03/1989  
Driving Experience 30 YEARS AND 2 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-91454748  
Fax Number  
Contact Number OFFICE-91454748  
Email Address NOEMAIL

|   |                               |
|---|-------------------------------|
| Address   | BLK 789 CHOA CHU KANG NORTH 6 |
| Postcode  | #06-230                       |
| Was driver an employee of the Insured's Company     | NO                            |
| If No, Relationship of the Driver with the Insured  | OWNER                         |
| Vehicle Registration Number of Driver's Own Vehicle | -                             |
| Insurance Company of Driver's Own Vehicle           | -                             |

#### General Information of the Accident

|                    |                               |
|--------------------|-------------------------------|
| Type Of Accident   | COLLISION - CHANGE/CROSS LANE |
| Weather Conditions | CLEAR                         |
| Road Surface       | DRY                           |

#### Other Information

|   |     |
|---|-----|
| Was any foreign vehicle involved in this accident?  | NO  |
| Number of vehicles (including own vehicle) involved in the accident                         | 2   |
| Was any body injured in the Accident?   | YES |
| Was any injured conveyed to hospital by ambulance?  | NO  |
| Was any other material or property damaged?   | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (including Driver)   | 1   |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

|   |                           |
|---|---------------------------|
| Are accident photos available for attachment? | YES                       |
| Was there any video captured by Car Camera?   | YES                       |
| Remarks/ Reasons                              | VIDEO FOOTAGE WITH DRIVER |
| Was there any audio recorded?                 | NO                        |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |             |
|-------------------------------------|-------------|
| Vehicle Registration Number         | SMJ245D     |
| Vehicle Make/Model/Colour           | HONDA VEZEL |
| Details Of Properties               |             |
| Vehicle Category                    | PRIVATE CAR |
| Name of Driver                      | ONG SHI HAN |
| NRIC/Passport Number                | S9446420Z   |
| Contact Number                      | 96301793    |
| Address                             |             |
| Postcode                            |             |
| Insurance Company Name              |             |
| Nature Of Damage                    |             |
| No. Of Passenger (including Driver) |             |

#### DETAILS OF INJURED PERSON 1

Name

CHUA YEOW LENG

Approximate Age

Injuries Sustain

NECK & BACK

Injured person in which vehicle?

SLG9127E

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

## Accident Sketch Plan


### SKETCH PLAN


#### IMPORTANT NOTICE


- 1) Please report correctly on the details of the accident to speed up the claims process.
- 2) This form must be completed by the policy holder and/or the authorised driver.
- 3) Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4) The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5) Any false reporting may be referred to the police for investigation.
- 6) The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7) By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8) **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of:
  - (i) Processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigations the accident and/or my claims;
  - (iii) Carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) Administering my claims (including the making of correspondence, statement, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages); and/or
  - (v) Complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "purposes").
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
- (c) My personal information may/can be disclosed by any of the insurer and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) My personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
  - (i) To all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) For complying with requirements under my regulations, laws or court orders.

  
Policy holder's signature  
Date / time:


  
Driver's signature  
(if driver is not policy holder)  
Date / time:

  
reporting centre personnel's Signature  
Date / time:



# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG WINDY ROAD, AS THE TRAFFIC WAS BAD, WE WERE  
 ALL MOVING VERY SLOWLY. VEHICLE B WHICH WAS TURNING INTO MY LANE DID NOT  
 CHECK THAT THE ROAD IS CLEAR BEFORE DOING SO AND COLLIDED INTO MY REAR RIGHT  
 PART OF MY VEHICLE. I HAVE VIDEO FOOTAGE TO PROVE MY STATEMENT

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policy holder's signature  
 Date & time:

Driver's signature  
 (if driver is not policy holder)  
 Date & time:

reporting centre personnel's signature  
 Name:  
 NRIC/FIN No.:

# C L APPRAISER PTE LTD

Vehicle Registration No: SLG 9127 E

Our Ref No: TWG/05/1907/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 5,000.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

## Disclaimer

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

C L APPRAISER PTE LTD



Cheong K. H  
Automotive Appraiser

# CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440  
Email: [clappraiser@yahoo.com](mailto:clappraiser@yahoo.com) Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## INVOICE

Chua Yeow Leng Eric  
C/o: Teamwork Garage Pte Ltd  
53 Ubi Avenue 1 #01-24  
Paya Ubi Industrial Park, Singapore 408934

Invoice No: CL/190734  
Ref No: TWG/05/1907/TP  
Date: 20 June 2019

### DESCRIPTION

### AMOUNT

#### OUR SERVICE FEE CHARGES:

- SURVEY INSPECTION FOR VEHICLE NO. SLG 9127 E
- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES  
(INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)
- TRANSPORTATION

GRAND TOTAL SS 535.00

E & O. E

All cheque payment should be "Crossed" and made payable to "CL APPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

# L APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440  
Email: [clappraiser@yahoo.com](mailto:clappraiser@yahoo.com) Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Chua Yeow Leng Eric  
C/o: Teamwork Garage Pte Ltd  
53 Ubi Avenue 1 #01-24  
Paya Ubi Industrial Park, Singapore 408934

Date : 20 June 2019  
Our ref : TWG/05/1907/TP

Accident Date : 06 May 2019  
Inspection Date : 14 May 2019  
Repairer Name : Teamwork Garage Pte Ltd  
53 Ubi Avenue 1 #01-24  
Paya Ubi Industrial Park, Singapore 408934

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

|                 |                     |                 |                  |
|-----------------|---------------------|-----------------|------------------|
| Registration No | : SLG 9127 E        | Year / Capacity | : 2016 / 1362 cc |
| Make / Model    | : Chevrolet Orlando | Colour          | : White          |
| Chassis No      | : KL1YA7589HK606800 | Mileage         | : 106830         |
| Engine No       | : A14NET162320208   |                 |                  |

### CONDITION OF TYRES

|                | Make     | Size       | Thread Balance | Rim   |
|----------------|----------|------------|----------------|-------|
| Front Nearside | : Revelo | 215/60 R16 | 5 mm           | Sport |
| Front Offside  | : Revelo | 215/60 R16 | 5 mm           | Sport |
| Rear Nearside  | : Revelo | 215/60 R16 | 5 mm           | Sport |
| Rear Offside   | : Revelo | 215/60 R16 | 5 mm           | Sport |

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the o/s portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: 35 copies

### REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis  
and we have not given authorization and instruction to the repairer to proceed with the repair

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 5,000.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

# SCL APPRAISER PTE LTD

Vehicle Registration No: SLG 9127 E

Our Ref No: TWG/05/1907/TP

| Qty | Description | Conditions | Repairer's Estimate | Revised Amount |
|-----|-------------|------------|---------------------|----------------|
|-----|-------------|------------|---------------------|----------------|

## SPARE PARTS - LIST ITEMS

|   |                                    |           |                    |                            |
|---|------------------------------------|-----------|--------------------|----------------------------|
| 1 | Rear o/s door                      | Damage    | \$ 913.00          | \$ 913.00 DDV              |
| 1 | Rear o/s door lock                 | Intact    | \$ 245.00          |                            |
| 1 | Rear o/s door rubber               | Necessary | \$ 186.00          | \$ 186.00 NNX              |
| 1 | O/s rocker panel side garnish      | Damage    | \$ 485.00          | \$ 342.00 485.00 BTV       |
| 1 | Rear bumper                        | Repair    | \$ 1,151.00        |                            |
| 1 | Rear bumper side retainer          | Intact    | \$ 45.00           |                            |
| 1 | Rear o/s fender                    | Damage    | \$ 1,194.00        | \$ 1,194.00 R X            |
| 1 | Rear o/s fender wheel arch garnish | Damage    | \$ 355.00          | \$ 256.00 355.00 CUTV      |
|   |                                    |           | <b>\$ 4,574.00</b> | <b>\$ 3,133.00</b> 1505.00 |
|   |                                    | Less 10%  | \$ 457.40          | \$ 313.30 150.50           |
|   | <b>Total Cost - List Items</b>     |           | <b>\$ 4,116.60</b> | <b>\$ 2,819.70</b> 1354.50 |

## SPECIAL NETT ITEMS

|   |  |           |                    |                    |
|---|--|-----------|--------------------|--------------------|
| 1 | Rear o/s fender quarter glass sealant  | Necessary | \$ 120.00          | \$ 80.00 NNX       |
| 1 | Rear o/s tyre (Depreciation)           | Damage    | \$ 400.00          | \$ 200.00 NNX      |
| 1 | Rear o/s wheel rim                     | Damage    | \$ 750.00          | \$ 750.00 WSK R    |
|   | <b>Total Cost - Special Nett items</b> |           | <b>\$ 1,270.00</b> | <b>\$ 1,030.00</b> |

**Total cost of parts**

**\$ 5,386.60 \$ 3,849.70**

# SCL APPRAISER PTE LTD

Vehicle Registration No: SLG 9127 E

Our Ref No: TWG/05/1907/TP

| S/No | Description             | Repairer's Estimate | Revised Amount |
|------|-------------------------|---------------------|----------------|
|      | Total cost of parts c/f | \$ 5,386.60         | \$ 3,849.70    |

1354.50

## LABOUR

|   |  |             |                               |
|---|--|-------------|-------------------------------|
| 1 | To remove, refit, replaced damaged lamps and check up rear electrical wiring   | \$ 80.00    | \$ 50.00 N N X                |
| 2 | To remove and refit inner garnishes, inner trim to assist repair.  | \$ 150.00   | \$ 120.00 <sup>60.00</sup> ✓  |
| 3 | To conduct wheel alignment.  | \$ 150.00   | \$ 120.00 <sup>60.00</sup> ✓  |
| 4 | To remove and refit quarter glass to assist repair.  | \$ 120.00   | \$ 80.00 N N X                |
| 5 | To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door.  | \$ 150.00   | \$ 120.00 <sup>60.00</sup>    |
| 6 | To apply undercoating on repaired and replaced panel.  | \$ 150.00   | \$ 90.00 <sup>50.00</sup>     |
| 7 | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident. | \$ 1,400.00 | \$ 1,000.00 <sup>600.00</sup> |
| 8 | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.  | \$ 1,200.00 | \$ 880.00 <sup>400.00</sup>   |

## GRAND TOTAL

|             |             |
|-------------|-------------|
| \$ 8,786.60 | \$ 6,309.70 |
|-------------|-------------|

Parts 1354.50

S/N 00.00

Labour 1230.00

2584.50

@ 20% 515.10

2060.60

L/S 2050/2 Tatum Wm  
1/8/19

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS3/INC19008527/Btd3s2-1

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date : 07-08-2019

189556



ATTN: JARED LIU

Code : INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

|              |                        |                |            |
|--------------|------------------------|----------------|------------|
| Insured Veh. | SMJ 245D               | Veh. Inspected | SLG 9127E  |
| Policy No.   |                        | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1043407-002         | Excess (\$)    | 0.00       |
| Assign From  | MOTOR INSURANCE INCOME | Assign Date    | 19/07/2019 |

**2. Vehicle Particulars & Condition**

|              |                       |              |            |
|--------------|-----------------------|--------------|------------|
| Make & Model | CHEVROLET ORLANDO 1.4 | c.c          | 1362       |
| Engine No.   | HIDDEN                | Year of Reg. | 2016       |
| Chassis No.  | KL1YA7589HK606800     | Colour       | WHITE      |
| Odometer     | 106830                | Steering     | IN ORDER   |
| Brakes       | IN ORDER              | Modification | SPORTS RIM |
| General      | GOOD                  |              |            |

**3. Conditions of Tyres**

|                | Size      | Make   | Balance |
|----------------|-----------|--------|---------|
| R/H Front Tyre | 215/60R16 | ROVELO | 6 mm    |
| L/H Front Tyre | 215/60R16 | ROVELO | 6 mm    |
| R/H Rear Tyre  | 215/60R16 | ROVELO | 6 mm    |
| L/H Rear Tyre  | 215/60R16 | ROVELO | 6 mm    |

**4. Description of Damages**

|  |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.<br>DAMAGES SEE DETAILS. |
|--|

**5. General Information**

|                |   |                 |            |
|----------------|---|-----------------|------------|
| Accident Date  | 06/05/2019  | Inspection Date | 14/05/2019 |
| Survey held at | TEAMWORK GARAGE PTE LTD<br>53 UBI AVENUE 1<br>#01-24<br>SINGAPORE 408934. |                 |            |

**5a. Remarks**

|  |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

**5b. Estimate Days of Repair**

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>5 Working Days</b> |
|-------------------------------------|-----------------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 9127E

| Qty                                | Description of Parts   | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |  |                      |                           |                   |
| 1                                  | REAR O/S DOOR  | DENTED               | 913.00                    | 913.00            |
| 1                                  | REAR O/S DOOR LOCK   | INTACT               | 245.00                    | -                 |
| 1                                  | REAR O/S DOOR RUBBER   | NOT NECESSARY        | 186.00                    | -                 |
| 1                                  | O/S ROCKER PANEL SIDE GARNISH  | BENT                 | 485.00                    | 342.00            |
| 1                                  | REAR BUMPER  | TO REPAIR SEE LABOUR | 1,151.00                  | -                 |
| 1                                  | REAR BUMPER SIDE RETAINER  | INTACT               | 45.00                     | -                 |
| 1                                  | REAR O/S FENDER  | TO REPAIR SEE LABOUR | 1,194.00                  | -                 |
| 1                                  | REAR O/S FENDER WHEEL ARCH GARNISH   | CUT                  | 355.00                    | 250.00            |
|                                    | LESS 10% DISCOUNT  |                      | -457.40                   | -150.50           |
|                                    |  |                      | 4,116.60                  | 1,354.50          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |  |                      |                           |                   |
| 1                                  | REAR O/S FENDER QUARTER GLASS SEALANT (SN)   | NOT NECESSARY        | 120.00                    | -                 |
| 1                                  | REAR O/S TYRE (SN)   | NOT NECESSARY        | 400.00                    | -                 |
| 1                                  | REAR O/S WHEEL RIM (SN)  | TO REPAIR SEE LABOUR | 750.00                    | -                 |
|                                    |  |                      | 1,270.00                  | -                 |
| <b><u>LABOUR</u></b>               |  |                      |                           |                   |
|                                    | TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.  | NOT NECESSARY        | 80.00                     | -                 |
|                                    | TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR.  |                      | 150.00                    | 60.00             |
|                                    | TO CONDUCT WHEEL ALIGNMENT.  |                      | 150.00                    | 60.00             |
|                                    | TO REMOVE AND REFIT QUARTER GLASS TO ASSIST REPAIR.  | NOT NECESSARY        | 120.00                    | -                 |
|                                    | TO REMOVE AND REFIT DOORS COMPLETE FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR.  |                      | 150.00                    | 60.00             |
|                                    | TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.  |                      | 150.00                    | 50.00             |
|                                    | TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR O/S FENDER AND REAR O/S WHEEL RIM. |                      | 1,400.00                  | 600.00            |

Report Ref No. CS3/INC19008527/Btd3s2-1





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty  | Description of Parts  | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--|---|-----------|---------------------------|-------------------|
|  | TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT. |           | 1,200.00                  | 400.00            |
|  |   |           | 3,400.00                  | 1,230.00          |
| GRAND TOTAL  |   |           | 8,786.60                  | 2,584.50          |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) |   |           |                           | 2,050.00          |

Report Ref No. CS3/INC19008527/Btd3s2-1

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.