

22/03/2002

ASS. REC. BY:

REF:

CS/MSG19012777/R1+A3<sup>SV</sup>

Special Instruction:

Surveyor: Rasu/

ASSIGNMENT (Office)

From (Person): Chia Myk Rui

of MSG

Date/Time: 19.7.19 13.21 p.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMB 3061P

Insured: SLK 1364T

at Workshop m/s Towar Transit

Tel: 9199 0025

of 21 Bullim Drive, Bullim Bus Depot

Policy No: A29114756 MKF

Claim No: 600069

Sum Insured:

Excess:

Make of Veh:

D.O.A. 16.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

"rwp"

H.O.D. Endorsement:

Date/Time: 19.7.19 1.28 p.m.

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SMB 3061P CC4/ICS17006678/Tleg 3g 2 DOA = 31/3/17

SLK 1364T CC4/LCR17020244/Swb 3g 2 DOA = 18/10/17

23/7@16:41 - Reused via menmen preli advise.

Part by Part \$1650/- (Red: 741, 53%)

Rasul

# ASSIGNMENT

From

Date

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMB 3061 P

at Workshop n/s Tower Transit

of Buem or

Insured: MS16

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Gen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SMB 3061 P

Yr Regn: 2013 July

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAN NL320 FCA227 c.c. 10518

Colour: GREEN A/C: Insured / Std / NI / NA

Sp Reading: 446067 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WMAA22ZZXD7001829

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Locked / Jammed / Leaked / Burnt or

Brake: Locked / Jammed / Leaked / Burnt or

Modi: Oil / S/Rim / STD A/Rim or

Tyre Size: F: 275/70R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8/8 mm

L/Bal. 8 mm L/Bal. 8/8 mm

D.O.A. 16/07/19 D.O.I. 19/07/19

Survey held at Tower Transit

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

s/s Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 04 SEP 2019

3/9/2019

Date/Time, File Pass to?

☐ : Prel. Report

☒ : Final Report

3/9 Typist

Date/Time, File Return to?

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

Report Format: TP

Lump Sum / L. (\$ 6501-

Survey Fee:

Transportation:

3 + 455 38

Photos

Others

TOTAL

|     |
|-----|
| 150 |
| 21  |
|     |

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified             | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status   |
|------|----------------------|---------------|--|---------|---------------|------------|--|
| Main | 17 Jul 2019<br>17:04 |               | 19 Jul 2019<br>13:21<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

## CLAIM SUBFOLDER DETAILS

|                             |   |                        |   |
|-----------------------------|---|------------------------|---|
| Insured:                    | GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G  |                        | [Created by insurer]  |
| Main Claimant:              | TOWER TRANSIT SINGAPORE PTE LTD, Co. Reg. No.: 201419417K   |                        |   |
| Vehicle Reg. No.:           | SMB3061P  | Date of Loss:          | 16/07/2019 18:00 - :59<br>[72 Months and 15 Days From LTA<br>Reg Date (Man Yr)] |
| Claim Type:                 | TP / 600069   | Policy/Cover Note No.: | A29114756MKF (Comprehensive)<br>Coverage: 01/02/2019 -<br>31/01/2020            |
| Vehicle Reg. No. (Insured): | SLK1364T  | Policy No. (Claimant): |   |
|                             |   | Excess:                |   |
| Repairer:                   | Tower Transit Singapore Pte Ltd (HQ) 21 Bulim Drive, Bulim Bus Depot, 648170 Jurong West - Tel: 81688950  |                        |   |
| Handling Insurer:           | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]  |                        |   |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/07/2019]  |                        |   |
| Adj Asg. Remarks:           | on WP. Please advise if the survey appointment could be arranged morning 19/07/2019. OI: Grab. Liab: Dispute(NR). TP Req for LKK. Contact: Lynn @ +65 9199 0025 |                        |   |

## ASSOCIATED MAIL RECEIVED

- MSIG\_SG (18/07/2019): Cancellation of Assignment: SMB3061P

[View All](#)[Compose Case Mail](#)

## ALL ASSOCIATED TASKS

| Due Date    | Priority | Type | Task Group | Subject | Handler | <a href="#">View All</a> | <a href="#">Search Tasks</a> | <a href="#">Create New Task</a> | <a href="#">Complete</a> |
|-------------|----------|------|------------|---------|---------|--------------------------|------------------------------|---------------------------------|--------------------------|
| No results. |          |      |            |         |         | Assigned By              | Completed On                 | Created On                      | Done?                    |

## Denise Tay (LKKAUTO)

---

**From:** Bazlin Ahmad <Bazlin.Ahmad@towertransit.sg>  
**Sent:** Monday, 2 September 2019 1:57 PM  
**To:** Rasul (LKKAUTO)  
**Cc:** Wu Tzu Ying; Subramanian Kasi  
**Subject:** RE: SMB3061P DOA : 16/07/19

Dear Rasul

We accept cor \$650 before GST with 2 days of repair.  
We submit LOD to u or MSIG direct ?

Thank You

Best Regards

**Lynn Ahmad (Ms)**

Senior Executive, Claims

Office +65 6248 0987

Mobile +65 9199 0025

Email [bazlin.ahmad@towertransit.sg](mailto:bazlin.ahmad@towertransit.sg)



**Tower Transit Singapore Pte Ltd**

21 Bulim Drive, Bulim Bus Depot, Singapore 648170

Registration number 201419417K

[www.towertransit.sg](http://www.towertransit.sg)

---

**From:** Rasul (LKKAUTO) <Rasul@lkkauto.com>  
**Sent:** Monday, 2 September, 2019 12:30 PM  
**To:** Bazlin Ahmad <Bazlin.Ahmad@towertransit.sg>  
**Subject:** SMB 3061P DOA : 16/07/10

---

**THIS EMAIL IS FROM AN EXTERNAL SOURCE** – Do not click links or open attachments unless you recognise the sender/email.

If in doubt, please check with IT Support!

---

Hi Lynn,

Finalised amount for this case is \$650 / 2 days of repair  
Kindly for the resurvey after repair photos  
Kindly confirm

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 23 Jul 2019

**Preliminary Advice**

|                    |   |                         |              |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : SLK1364T  | Accident Date           | : 16/07/2019 |
| TP Vehicle No      | : SMB3061P  | Assignment Date         | : 19/07/2019 |
| Make               | : MAN NL320F (A22)  | Est. Duration of Repair | : 2.00       |
| Date of Inspection | : 19/07/2019  |                         |              |
| Inspection At      | : TOWER TRANSIT SINGAPORE PTE LTD (HQ)<br>21 BULIM DRIVE, BULIM BUS DEPOT<br>SINGAPORE 648170 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 1,391.00 |
| Revised Amount              | :S\$ | 650.00   |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 650.00   |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( x ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                               |
|----------------------------|-------------------------------|
| Date Of Report             | 17/07/2019 16:33              |
| Date Of Accident           | 16/07/2019 18:25              |
| Exact Location Of Accident | ORCHARD ROAD TWDS SHENTON WAY |
| Country/State of Loss      | SINGAPORE                     |

### DETAILS OF OWN VEHICLE

|                             |                                 |
|-----------------------------|---------------------------------|
| Vehicle Registration Number | SMB3061P                        |
| <b>Insured/Policyholder</b> |                                 |
| Name Of Registered Owner    | TOWER TRANSIT SINGAPORE PTE LTD |
| Co Reg No                   | 201419417K                      |
| Email Address               | NOEMAIL                         |
| Mobile Phone No             |                                 |
| Alternative Phone No        | OFFICE-62480987                 |

### Vehicle Particulars

|              |                                   |
|--------------|-----------------------------------|
| Manufacturer | MAN                               |
| Model        | NL320F (A22)-10.5 D ABS TURBO (A) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

### Insurance Company

|                           |                                |
|---------------------------|--------------------------------|
| Name of Insurance Company | MS FIRST CAPITAL INSURANCE LTD |
| Type Of Coverage          | COMPREHENSIVE                  |
| Fleet Policy              | YES                            |
| Policy Number             | D-18092210MFBP                 |
| Cover Note Number         |                                |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | HU BEI                |
| Passport No/FIN      | G6911622T             |
| Date Of Birth        | 13/10/1970            |
| Occupation           | OUTDOOR               |
| Date Of Driving Pass | 12/09/2011            |
| Driving Experience   | 7 YEARS AND 10 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-98888888  |
| Fax Number           |                       |
| Contact Number       |                       |
| Email Address        | NOEMAIL               |

## Sketch Plan

### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 16/7/2019


Reporting Centre Personnel's Signature  
Name:  
NRIC/PIN No.:

20151

Accident Photo



Accident Photo





**TOWER TRANSIT  
ENGINEERING**

|                         |          |
|-------------------------|----------|
| BUS REGISTRATION NUMBER | SMB3061P |
| BUS TYPE (SD/DD)        | SD       |
| BUS ROUTE NUMBER        |          |
| BUS ADVERTS (Y/N)       | N        |

| Part No. | Part or Item Description | Quantity         | Total Cost |
|----------|--------------------------|------------------|------------|
|          |                          |                  |            |
|          |                          |                  |            |
|          |                          |                  |            |
|          |                          |                  |            |
|          |                          |                  |            |
|          |                          |                  |            |
|          |                          |                  |            |
|          |                          |                  |            |
|          |                          |                  |            |
|          |                          | 7% GST           | \$0.00     |
|          |                          | FINAL TOTAL COST | \$0.00     |

| LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT) | TOTAL COST              |
|---|-------------------------|
| TO REMOVE & REINSTALL FRONT RIGHT CORNER BUMPER                       | 325 <del>\$650.00</del> |
| SPRAY PAINTING  | 325 <del>\$650.00</del> |
|   | 650                     |
|   | 2 days                  |
|   | 1300x                   |
|   | 7% GST                  |
|   | \$91.00                 |
|   | FINAL TOTAL COST        |
|   | \$1,391.00              |

# ESTIMATED ACCIDENT REPAIR COST



## SECTION 3: REPAIRS TO BUS ADVERTISEMENT VINYL/PANELS (ADVERTISEMENT COST)

|                                 |   |
|---------------------------------|---|
| TOTAL ADVERTISEMENT REPAIR COST | - |
|---------------------------------|---|

## SECTION 4: RECOVERY OF ACCIDENT BUS (TOWING COST)

|                   |   |
|-------------------|---|
| TOTAL TOWING COST | - |
|-------------------|---|

## SECTION 5: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

|                    |  |                             |   |
|--------------------|--|-----------------------------|---|
|                    |  | Date In For Repairs         |   |
|                    |  | Date Out From Repairs       |   |
|                    |  | Number of Days Under Repair | 0 |
| BUS TYPE (SD / DD) |  | LOSS OF USE COST            |   |
|                    |  | \$300.00                    |   |

| SUMMARY                                    |            |
|--|------------|
| SECTION NO.                                | COST       |
| 1  | \$0.00     |
| 2  | \$1,391.00 |
| 3  | -          |
| 4  | -          |
| 5  | \$300.00   |
| ESTIMATED ACCIDENT REPAIR COST (1+2+3+4+5) | \$1,691.00 |

*Jimmy*  
23/7/19

*Rasul*  
Hp 90010068  
2 days  
19/07/19 @ 1610  
Ready after repair

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

| Case | Notified             | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                                | Ins Auth'd | Status  |
|------|----------------------|---------------|--|--|--|------------|---|
| Main | 17 Jul 2019<br>17:04 |               | 19 Jul 2019<br>13:21<br><a href="#">Edit Adj Rpt</a> | <b>S\$650.00</b><br><a href="#">Edit Estimates</a> | <b>S\$650.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |   |                        |  |
|-----------------------------|---|------------------------|--|
| Insured:                    | GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G  |                        |  |
| Main Claimant:              | TOWER TRANSIT SINGAPORE PTE LTD, Co. Reg. No.: 201419417K   |                        |  |
| Vehicle Reg. No.:           | SMB3061P  | Date of Loss:          | 16/07/2019 18:00 - :59<br>[72 Months and 15 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | TP / 600069   | Policy/Cover Note No.: | A29114756MKF (Comprehensive)<br>Coverage: 01/02/2019 - 31/01/2020            |
| Vehicle Reg. No. (Insured): | SLK1364T  | Policy No. (Claimant): |  |
|                             |   | Excess:                |  |
| Repairer:                   | Tower Transit Singapore Pte Ltd (HQ) 21 Bulim Drive, Bulim Bus Depot, 648170 Jurong West - Tel: 81688950  |                        |  |
| Handling Insurer:           | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]  |                        |  |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/08/2019]   |                        |  |
| Adj Asg. Remarks:           | on WP. Please advise if the survey appointment could be arranged morning 19/07/2019. OI: Grab. Liab: Dispute(NR). TP Req for LKK. Contact: Lynn @ +65 9199 0025 |                        |  |

[View All](#)[Compose Case Mail](#)

### ASSOCIATED MAIL RECEIVED

- MSIG\_SG (18/07/2019): Cancellation of Assignment: SMB3061P

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |



## Claim Documents

**\*SMB3061P (600069)**  
**[SLK1364T]**

**TP**

**TOWER TRANSIT SINGAPORE PTE LTD**

**Jul 16 2019 6:00PM**

**[GRAB RENTALS PTE LTD]**

**Tower Transit Singapore Pte Ltd**

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

| Assessment Reports |                 |   |  | 1 per page ▼ | <input checked="" type="checkbox"/> |
|--------------------|-----------------|---|--|--------------|-------------------------------------|
| No                 | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)         |  | Thumbnail    | Print                               |
| 1                  | 23/07/19 16:41  | Adjuster Immediate Advice                 |  | Load HTM     |                                     |
| Photos/Images      |                 |   |  | 3 per page ▼ | <input checked="" type="checkbox"/> |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         |  | Thumbnail    | Print                               |
| 1                  | 03/09/19 11:28  | General View                              |  | Load JPG     | <input checked="" type="checkbox"/> |
| 2                  | 03/09/19 11:28  | General View                              |  | Load JPG     | <input checked="" type="checkbox"/> |
| 3                  | 03/09/19 11:28  | General View                              |  | Load JPG     | <input checked="" type="checkbox"/> |
| 4                  | 03/09/19 11:28  | General View                              |  | Load JPG     | <input checked="" type="checkbox"/> |
| 5                  | 03/09/19 11:28  | General View                              |  | Load JPG     | <input checked="" type="checkbox"/> |
| 6                  | 03/09/19 11:28  | General View                              |  | Load JPG     | <input checked="" type="checkbox"/> |
| 7                  | 03/09/19 11:28  | General View                              |  | Load JPG     | <input checked="" type="checkbox"/> |
| 8                  | 03/09/19 11:28  | General View                              |  | Load JPG     | <input checked="" type="checkbox"/> |
| 9                  | 03/09/19 11:28  | General View                              |  | Load JPG     | <input checked="" type="checkbox"/> |
| 10                 | 03/09/19 11:28  | General View                              |  | Load JPG     | <input checked="" type="checkbox"/> |
| 11                 | 03/09/19 11:28  | General View                              |  | Load JPG     | <input checked="" type="checkbox"/> |
| 12                 | 03/09/19 11:28  | General View                              |  | Load JPG     | <input checked="" type="checkbox"/> |
| 13                 | 03/09/19 11:28  | General View                              |  | Load JPG     | <input checked="" type="checkbox"/> |
| 14                 | 03/09/19 11:29  | General View                              |  | Load JPG     | <input checked="" type="checkbox"/> |
| Documentation      |                 |   |  | 1 per page ▼ | <input checked="" type="checkbox"/> |
| No                 | Finalized On    | MSIG Insurance (Singapore) Pte. Ltd. (HQ) |  | Thumbnail    | Print                               |
| 1                  | 17/07/19 17:08  | TP SMB3061P E-FILE REPORT                 |  | Load PDF     |                                     |
| 2                  | 17/07/19 17:08  | PRI from Tower Transit Singapore          |  | Load PDF     |                                     |
| 3                  | 17/07/19 17:08  | Photo                                     |  | Load JPG     | <input checked="" type="checkbox"/> |
| 4                  | 17/07/19 17:08  | Photo                                     |  | Load JPG     | <input checked="" type="checkbox"/> |
| 5                  | 17/07/19 17:08  | Photo                                     |  | Load JPG     | <input checked="" type="checkbox"/> |
| 6                  | 18/07/19 08:53  | OI SLK1364T E-FILE REPORT                 |  | Load PDF     |                                     |
| 7                  | 18/07/19 09:09  | Acknowledge PRI                           |  | Load PDF     |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                          | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. |       |      |       |

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19012777/R1TF3S2  
Date: 05/09/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29114756MKF  
Claimant Vehicle No: SMB3061P Insured Vehicle No: SLK1364T  
Date of Loss: 16/07/2019 Nature of Claim: TP Claim No: 600069

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMB3061P**  
Make & Model: MAN NL320F (A22), 10.5 D ABS TURBO (A) Engine No: 50333912153383  
Reg. Date: 01/07/2013 (Man. Year: 2012) Chassis No: WMAA22ZZXD7001829  
Colour: Green Odometer: 446067 km  
Engine Capacity: 10518 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)  
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8/8 mm  
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8/8 mm  
*The above values represent the remaining tyre treads depth*

### COST OF CLAIMS

|                               | Repairer's      | Adjuster's    | Difference    | Diff %       |
|-------------------------------|-----------------|---------------|---------------|--------------|
| Parts                         | 0.00            | 0.00          | 0.00          |              |
| Miscellaneous Items           | 0.00            | 0.00          | 0.00          |              |
| Labour                        | 1,300.00        | 650.00        | 650.00        | 50.00        |
| Paintwork Labour              | 0.00            | 0.00          | 0.00          |              |
| Towing                        | 0.00            | 0.00          | 0.00          |              |
| <b>Gross Total (S\$)</b>      | <b>1,300.00</b> | <b>650.00</b> | <b>650.00</b> | <b>50.00</b> |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>91.00</b>    | <b>45.50</b>  | <b>45.50</b>  | <b>50.00</b> |
| <b>Nett Amount (S\$)</b>      | <b>1,391.00</b> | <b>695.50</b> | <b>695.50</b> | <b>50.00</b> |

### INSPECTION

Date of Assignment: 19/07/2019  
Date Inspected: 19/07/2019 Inspected At: Tower Transit Singapore Pte Ltd (HQ)  
21 Bulim Drive, Bulim Bus Depot  
Singapore 648170  
Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

|                      |   |   |
|----------------------|---|---|
| <b>Part Source:</b>  | (Last Synchronised: 05 Sep 2019)  |   |
| <b>Parts:</b>        | N/A   | MAN NL320F (A22) 10.5 D ABS TURBO (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's  | (Price-denominated Standard List)                                       |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SMB3061P)   |   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the<br>END OF ESTIMATES marker on the last estimate page |   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.  |   |

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                      | Lab.Type | Repairer's      | Amount        |
|---------------------------------|--|----------|-----------------|---------------|
| <b>Labour Items</b>             |  |          |                 |               |
| 1                               | TO REMOVE & REINSTALL FRONT RIGHT CORNER BUMPER. | New      | 650.00          | 325.00        |
| 2                               | SPRAY PAINTING.                                  | New      | 650.00          | 325.00        |
| <b>Gross Labour Cost (\$\$)</b> |  |          | <b>1,300.00</b> | <b>650.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >