

ASS. REC. BY:

REF:

CS3/CT119012793/R1 ct3

Special Instruction:

Survey: Rasul

## ASSIGNMENT (Office)

From (Person): Tan Kah Leong

of

CTI

Date/Time: 19/7/19 @ 2.55pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBN 5906G

Insured:

SJR 3006B

at Workshop m/s

Speedway Motor

Tel:

0316 1611

of

No. 36 Johansen Road East #01-32

Policy No:

DMHCEN19181900

Claim No:

SNM119D003371C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17/07/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3.27pm @ 19/7/19

Person Contacted:

Sally

Vehicle IN/OUT

Date/Time

Action/Instruction

Ishtimol (X)

FBN 5906G X

SSR 3006B NPA/CT119010212/Y POA = 7/6/19

(08/11/19)

ASS. REC. BY:

REF

## ASSIGNMENT

From

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBN 5906 G

at Workshop n/s SPEEDWAY MOTOR

of 26, TOTT GUNN RD EAST #01-32

Insured: CTI

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBN 5906 G

Yr Regn:

2018 / NOV

Type: M.Car / ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda CBR 150 R M

c.c

149

Colour

MULTI

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MH1KC9116JK 209075

Gen. Cond: Good ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

100/80-17

R:

130/80-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

IRC

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

17/07/19

D.O.I.

19/07/19

Survey held at

SPEEDWAY

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range ~~→ \$2,500 → \$3,000~~

Days - 3

*Signature*  
9/9/2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Report Format:

PRE

Lump Sum / L.B.I. (\$)

Survey Fee:

150

Transportation:

3 x 100 = 300

Photos

Others

TOTAL

150

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jul 2019		19 Jul 2019 17:54 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by insurer]</b>						
Insured:									
Main Claimant:	SOO WEI ZHONG MIGUEL, ID: S9011245G								
Vehicle Reg. No.:	FBN5906G	Date of Loss:	17/07/2019 08:00 - :59						
Claim Type:	TP / SNM19D203371C02	Policy/Cover Note No.:	DMHCSN19181819000						
Vehicle Reg. No. (Insured):	SJR3006B	Policy No. (Claimant):	5105190926						
		Excess:	S\$0.00						
Repairer:	Speedway Motor Pte Ltd (Toh Guan) No. 36 Toh Guan Road East #01-32 Enterprise Hub, 608580 Jurong East - Tel: 63161611								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... <b>[Final Rpt due 30/07/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>			<a href="#">View All</a>	<a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Sent:** Friday, 19 July 2019 2:55 PM  
**To:** admin; assignments  
**Cc:** 'Sally Gan'; 'Ashley'; William Lee  
**Subject:** RE: OUR REF : SNM19D203371/TANKL - FW: Our Ref: MKR/201/9100/2019/as.wl;  
Your Ref: Your insured vehicle no. SJR 3006B;

WITHOUT PREJUDICE  
SAVE AS TO COSTS

Dear William,

We refer to our email below.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis instead.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Aside LBS,

Please cancel assignment.

Regards

**Tan Kah Leong**  
Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Tan Kah Leong  
**Sent:** Friday, 19 July, 2019 2:42 PM  
**To:** 'William Lee' <william@roypartners.com.sg>; 'admin' <admin@lbs-auto.com>  
**Cc:** 'Sally Gan' <sallygan\_0123@yahoo.com.sg>; 'Ashley' <ashley@roypartners.com.sg>  
**Subject:** RE: OUR REF : SNM19D203371/TANKL - FW: Our Ref: MKR/201/9100/2019/as.wl; Your Ref:  
Your insured vehicle no. SJR 3006B;

WITHOUT PREJUDICE  
SAVE AS TO COSTS

Dear William,

We refer to your email of 19.07.2019.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s L.B.S. Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LBS,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards

**Tan Kah Leong**

Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** William Lee [<mailto:william@roypartners.com.sg>]

**Sent:** Friday, 19 July, 2019 2:19 PM

**To:** Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)>

**Cc:** 'Sally Gan' <[sallygan\\_0123@yahoo.com.sg](mailto:sallygan_0123@yahoo.com.sg)>; 'Ashley' <[ashley@roypartners.com.sg](mailto:ashley@roypartners.com.sg)>

**Subject:** RE: OUR REF : SNM19D203371/TANKL - FW: Our Ref: MKR/201/9100/2019/as.wl; Your Ref: Your insured vehicle no. SJR 3006B;

**Importance:** High

Dear Sirs,

We refer to your email on even date.

Our client reject your list of proposed motor surveyors.

Our client does not have a list of 10 motor surveyors. Our client propose Mr. J T Bok from Prudent Adjustors Services and Mr. Dylan Lee from Lee Appraisal Services.

Pursuant to the new NIMA protocol, kindly let us know within 2 working days of receipt of our letter whether you agree or has any objections to the motor surveyor proposed by our client, failing which you are deemed to have agreed to the appointment of the motor surveyor proposed by our client.

Thanks & regards,

**William Lee**

M/s Roy & Partners  
101 Cecil Street  
#11-09 Tong Eng Building  
Singapore 069533

Tel : 6536 8466 Fax : 6536 1963  
Email : [william@roypartners.com.sg](mailto:william@roypartners.com.sg)

*IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.*

**From:** Tan Kah Leong [<mailto:KahLeong.Tan@sg.cntaiping.com>]

**Sent:** Friday, 19 July, 2019 12:13 PM

**To:** [william@roypartners.com.sg](mailto:william@roypartners.com.sg)

**Subject:** RE: OUR REF : SNM19D203371/TANKL - FW: Our Ref: MKR/201/9100/2019/as.wl; Your Ref: Your insured vehicle no. SJR 3006B;

### Without Prejudice

Dear William,

We refer to your email dated 18 July 2019.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
LOW SAR HUEI
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
HONG FOOK CHOY
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards

**Tan Kah Leong**  
Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Claims Dept of CTI

**Sent:** Friday, 19 July, 2019 11:46 AM

**To:** Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>;  
Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; [william@roypartners.com.sg](mailto:william@roypartners.com.sg)

**Subject:** OUR REF : SNM19D203371/TANKL - FW: Our Ref: MKR/201/9100/2019/as.wl; Your Ref:  
Your insured vehicle no. SJR 3006B;

**Importance:** High

Dear Kah Leong,

Please conduct PRS for FBN5906G.

Note : Officer in charge – Kah Leong 63896193.

Thanks,  
shumin

---

**From:** William Lee [<mailto:william@roypartners.com.sg>]

**Sent:** Thursday, July 18, 2019 4:14 PM

**To:** Claims Dept of CTI

**Cc:** 'Ashley'; 'Sally Gan'

**Subject:** Our Ref: MKR/201/9100/2019/as.wl; Your Ref: Your insured vehicle no. SJR 3006B;

**Importance:** High

Our Ref: MKR/201/9100/2019/as.wl;

Your Ref: Your insured vehicle no. SJR 3006B;

Dear Sirs,

**Attn: Motor claims department**

**CLAIMANT: SOO WEI ZHONG MIGUEL (OWNER OF FBN 5906G)**  
**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NO. FBN 5906G AND SJR 3006B ALONG**  
**SELETAR EXPRESSWAY ON 17.07.2019 AT ABOUT 0815 HOURS.**

We refer to the above matter.

We act for Soo Wei Zhong Miguel, the owner of motorcycle No. **FBN 5906G**.

We are instructed by our client to notify you of a road traffic accident on 17.07.2019 at about 8.15 am along Seletar Expressway involving our client's motorcycle registration number **FBN 5906G** and motor car registration number **SJR 3006B** driven by your insured at the material time. A copy of the Singapore Accident Statement and traffic police report is attached.

As a result of the accident, our client's motorcycle **FBN 5906G** has been damaged. Before our client proceed to repair the damaged motorcycle, please let us know within **two (2) working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motorcycle **FBN 5906G** at our client's repairer workshop, M/s Speedway Motor Pte Ltd at No. 36 Toh Guan Road East #01-32 Enterprise Hub, Singapore 608580, Your said surveyor may contact Sally at 6316 1611. If we do not receive

any reply from you within the stipulated timeline, our client shall proceed to repair the motorcycle without further reference to you.

Thanks & regards,

**William Lee**

M/s Roy & Partners

101 Cecil Street

#11-09 Tong Eng Building

Singapore 069533

Tel : 6536 8466 Fax : 6536 1963

Email : [william@roypartners.com.sg](mailto:william@roypartners.com.sg)

*IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.*

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	245G
Vehicle Details	
Vehicle No.:	FBN5906G
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	CBR150R MANUAL
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	KC91E1201188
Chassis No.:	MH1KC9116JK209075
Maximum Power Output:	-
Open Market Value:	\$3,326.00
Original Registration Date:	01 Nov 2018
First Registration Date:	01 Nov 2018
Transfer Count:	1
Actual ARF Paid:	\$499.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,951.00
COE Rebate Amount:	\$3,656.00
Total Rebate Amount:	\$3,656.00

The information contained herein is correct as at 29 Jul 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/07/2019 10:35
Date Of Accident	17/07/2019 08:15
Exact Location Of Accident	SELETAR EXPRESSWAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBN5906G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SOO WEI ZHONG MIGUEL
NRIC No	S9011245G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96338510
Alternative Phone No	OFFICE-96338510

### Vehicle Particulars

Manufacturer	HONDA
Model	MOTOR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5105190926
Cover Note Number	

### Driver

Name of Driver	SOO WEI ZHONG MIGUEL
NRIC No	S9011245G
Date Of Birth	27/03/1990
Occupation	INDOOR
Date Of Driving Pass	20/08/2018
Driving Experience	0 YEAR AND 10 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96338510
Fax Number	
Contact Number	OFFICE-96338510
EMail Address	NOEMAIL

Address	BLK 469 CHOA CHU KANG AVE 3 #08-97
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	BT BATOK NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER. POLICE REPORT NO. T/20190717/2126

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR3006B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	RIDER
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBN5906G
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

## Sketch Plan


### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

18/9/2017

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IDAC, BUKIT BATOK (VAC)  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

As per police report.

I/We declare the foregoing particulars are true in every respect.

dupl

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

1. DAC BUKIT BATOK (VAC)  
2  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190717/2126

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

1 of 3

Report No. T/20190717/2126

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 17/07/2019 16:39		Vide Report No.:		Station Diary No.: 112
<b>Informant's Particulars</b>				
Name of Informant: SOO WEI ZHONG, MIGUEL		Address: APT BLK 469 CHOA CHU KANG AVENUE 3 #08-97 SINGAPORE 680469		
ID Type / ID No.: NRIC NO / S9011245G		Contact No.: Home/Office: Mobile: 96338510		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 29	Date of Birth: 27/03/1990	Type of Informant: Rider	
Race: Chinese		Language: English	Institution / School Name:	
Occupation: Wealth Planning Manager		Driving Licence Information: Class: 2B,3 Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/07/2019 08:15	Type of Location: Straight Road
Location: Along Road 1 SELETAR EXPRESSWAY  along SLE towards Woodlands, after Lentor Ave exit				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBN5906G	Motorcycle	HONDA	CBR150R MANUAL	Black	Slightly Damaged	0
SJR3006B	Car				Slightly Damaged	0

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBN5906G	NTUC Income Insurance Co-Operative Limited	5105190926	01/11/2018	31/10/2019

Sketch Plan #4



**SINGAPORE  
POLICE FORCE**



T/20190717/2126

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

2 of 3

Report No. T/20190717/2126

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	SOO WEI ZHONG, MIGUEL	ID No.	S9011245G
Related Vehicle	FBN5906G (Motorcycle)	Contact No.	96338510
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	17/07/2019	Date Discharge	17/07/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight
<b>Driver</b>			
Name	HILMAN BIN HASHIM	ID No.	S9738511D
Related Vehicle	SJR3006B (Car)	Contact No.	87421070
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 17/07/2019 at about 0815hrs, I was riding my motorcycle, FBN5906G, alone along SLE towards Woodlands, after Lentor Ave exit on the second lane. The traffic was slow moving and suddenly a car, SJR3006B, swerved from the right lane and into my lane, hitting on my right. I managed to gain my balance and did not fall off the motorcycle. We then moved to lane one and stopped our vehicles. I obtained some abrasions on my right arm and my right calf, and some lacerations on my heels and toes. We made a check on our vehicles and my motorcycle obtained some dents on the brake paddle, damaged right side signal and scratches on the exhaust. His car obtained some dents and scratches to the front left side of the passenger door and a damaged left side mirror. We exchanged particulars and the driver wanted to settle the matter privately. No police nor ambulance was called. We called for EMAS where my motorcycle was towed away. There is an in-car camera installed in the car. There is not passenger in the car.

The driver later sent me to Ng Teng Fong Hospital where I was given stitches on the heels and was informed that there are fractures on the toe. I was also given hospitalization leave till 21/07/2019.





**SINGAPORE  
POLICE FORCE**



T/20190717/2126

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

3 of 3



Report No. T/20190717/2126

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Sgt 3 NUR' FAIZZAHASHIKIN BINTE SUBTU	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 17/07/2019 16:39
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LUI Contact No: 65476151 SN 114	Classification Of Case:
Authentication Stamp NP168  Singapore Police Force	

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jul 2019		19 Jul 2019 17:54 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	SOO WEI ZHONG MIGUEL, ID: S9011245G								
Vehicle Reg. No.:	FBN5906G	Date of Loss: 17/07/2019 08:00 - :59 [8 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / SNM19D203371C02	Policy/Cover Note No.: DMHCSN19181819000							
Vehicle Reg. No. (Insured):	SJR3006B	Policy No. (Claimant): 5105190926							
		Excess: S\$0.00							
Repairer:	Speedway Motor Pte Ltd (Toh Guan) No. 36 Toh Guan Road East #01-32 Enterprise Hub, 608580 Jurong East - Tel: 63161611								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/07/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBN5906G (SNM19D203371C02)  
[SJR3006B]

TP

SOO WEI ZHONG MIGUEL


































Jul 17 2019 8:00AM

[-]













Speedway Motor Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser v

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/07/19 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
2	29/07/19 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
3	29/07/19 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
4	29/07/19 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
5	29/07/19 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
6	29/07/19 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
7	29/07/19 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
8	29/07/19 10:45	General View	 Load JPG	<input checked="" type="checkbox"/>
9	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
10	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
11	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
12	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
13	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
14	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
15	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
16	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
17	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
18	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
19	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
20	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
21	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
22	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
23	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
24	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
25	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
26	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
27	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
28	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
29	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
30	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
31	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
32	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
33	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
34	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
35	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
36	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
37	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
38	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
39	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
40	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
41	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
42	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
43	29/07/19 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

			View	View in Browser
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	18/07/19 10:48	Accident Statement	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	18/07/19 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	18/07/19 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	18/07/19 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	18/07/19 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	18/07/19 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	18/07/19 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	18/07/19 10:48	Sketch Plan	 Load TIF	
2	18/07/19 10:48	Sketch Plan #2	 Load TIF	
3	18/07/19 10:48	Sketch Plan #3	 Load TIF	
4	18/07/19 10:48	Sketch Plan #4	 Load TIF	
5	18/07/19 10:48	Sketch Plan #5	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT19012793/R1CF3E2

Date: 17/09/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMHCSN19181819000

Claimant  
Vehicle No : FBN5906GInsured  
Vehicle No : SJR3006B

Date of Loss: 17/07/2019

Nature of Claim: TP

Claim  
No: SNM19D203371C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBN5906G

Make &amp; Model: HONDA CBR, 150cc 150M (M)

Engine No: KC91E1201188

Reg. Date: 01/11/2018 (Man. Year: 2018)

Chassis No: MH1KC9116JK209075

Colour: Multi-colour

Odometer: 0 km

Engine Capacity: 149 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 100/80-17

Rear Tyre Size: 130/80-17

Front Left Side: IRC 4 mm

Rear Left Side: IRC 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 19/07/2019

Date Inspected: 19/07/2019 Inspected At:

Speedway Motor Pte Ltd (Toh Guan)  
No. 36 Toh Guan Road East #01-32  
Enterprise Hub  
Singapore 608580

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 -\$3,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 17 Sep 2019)	
<b>Parts:</b>	N/A	HONDA CBR 150cc 150M (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBN5906G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >