

22/03/2002

ASS. REC. BY:

REF: CS/C12 19012795/ USF3124

Special Instruction:

Surveyor: MarcusASSIGNMENT (Office)From (Person): Chong Boon Senof C12Date/Time: 19.7.19 5.36pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

G1B7 26637

Insured:

4P 4741M

at Workshop m/s

Liu's Brother

Tel:

67411730of 1 Kaki Bukit Ave 6 #01-01

Policy No:

Claim No:

SNM 190703364

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17.5.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

rep.

H.O.D. Endorsement:

Date/Time:

19.7.19 9.45am

Person Contacted:

SusanVehicle IN/OUT

Date/Time

Action/Instruction (☒) Estimate

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 19393

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

G3Y 2663Y

Yr Regn:

3 / 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M)

Make:

mit canter

C.C.

2998

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

6824

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

FEA01BA30065

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/75R15

R:

PS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

17/5/19

D.O.I.

19/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

R/L N/S mirror

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/7/19 Confirmed final ty & 599 w. l. Suban

(£ 313.00 Red 34%)

RECEIVED 25 JUL 2019

Date/Time, File Pass to?



Preli. Report

1)

25/07/19
Typist

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

1

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

\$ + RS \$



Interview (\$

Photos



Tech. Invs (\$

Others



Weekend (\$

Report Format:

Lump Sum (L.B.) (\$ 599.00 P/R)

TOTAL

210

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 19 July 2019 5:36 PM
To: liusbro@ymail.com
Cc: 'assignments'
Subject: RE: SNM19D203364/CHONGBS - FW: Request for 3rd party claims survey GBJ2663Y Claims against YP4741M

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Friday, 19 July, 2019 11:12 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; liusbro@ymail.com

Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: SNM19D203364/CHONGBS - FW: Request for 3rd party claims survey GBJ2663Y Claims against YP4741M

Dear Boon Sen,

Fya.

Thanks,
shumin

From: Susan Low [mailto:liusbro@ymail.com]

Sent: Friday, July 19, 2019 10:37 AM

To: Jowyn Tay; Sharon Han; Claims Dept of CTI; Irene Tay

Subject: Fw: Request for 3rd party claims survey GBJ2663Y Claims against YP4741M

We refer to our email and requested dated 18/07/2019.

Kindly arrange.

Thank.

Best Regards,

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67411730 Fax: 67445746

----- Forwarded message -----

From: Susan Low <liusbro@ymail.com>
To: China Taiping - Motor Claims Department <claimsdept@sg.cntaiping.com>
Sent: Thursday, 18 July 2019, 2:56:23 pm SGT
Subject: Request for 3rd party claims survey GBJ2663Y Claims against YP4741M

Accident on 17/05/2019 Along 24 Penjuru Road Level 5

Involving GBJ2663Y and YP4741M

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regard!

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 6741 1730
Fax: 6744 5746

Date of Survey:- _____

Name of Authorise Surveyor:- _____

Surveyor Email: _____

Remark :-

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 196N

Vehicle Details

Vehicle No.: GBJ2663Y
Vehicle to be Exported: No
Intended Deregistration Date: 18 Jul 2019
Vehicle Make: MITSUBISHI
Vehicle Model: CANTER FEA01BR2SDEK (CBU)

Primary Colour: White
Manufacturing Year: 2018
Engine No.: 4P10D42206
Chassis No.: FEA01BA30065
Maximum Power Output: -
Open Market Value: \$29,002.00
Original Registration Date: 04 Mar 2019
First Registration Date: 04 Mar 2019
Transfer Count: 0
Actual ARF Paid: \$1,451.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 03 Mar 2029
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
PQP Paid: \$20,157.00
COE Rebate Amount: \$19,393.00
Total Rebate Amount: \$19,393.00

The information contained herein is correct as at 18 Jul 2019

OK

LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931, Tel: 6741-1730 / 731, Fax: 6744-5746, Email: liusbro@ymail.com

Invoice/Ref No: GBJ2663Y190517

Estimate

Customer

Name: China Taiping Insurance (Singapore) Pte Ltd

Date: 18-07-19

Address Motor Claims Department

Vehicle No: GBJ2663Y

3 Anson Road #16-00

Model/Make: Mitsubishi

Springleaf Tower Singapore 079909

Canter FEA01BR2SDEK

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Lh Mirror Arm	\$ 513.80	
2	Side Mirror "Square"	\$ 107.70	
3	Side Mirror "Round"	\$ 110.50	
	To remove, replace and transfer Mirror Arm, fitting and mechanisms	\$ 180.00	

Total Parts & Labour of estimate for damaged vehicle	
--	--

\$ 912.00

Total amount in Lump Sum Basis for repaired vehicle	
---	--



SDLS:

M/s Liu's Brother Auto Engrg Wks

Not Authorized
Holt
Take photo After repair
1 day.
19/7/19
912 @ 599/

$$\begin{array}{r} 1-732 \\ 252 \\ \hline 549 \\ 50 \\ \hline 599 \end{array}$$

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119012795/USF3N2

Date: 26/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN16869018022	
Claimant Vehicle No :	GBJ2663Y	Insured Vehicle No :	YP4741M	
Date of Loss:	17/05/2019	Nature of Claim:	TP	Claim No: SNM19D203364C021

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ2663Y	Engine No:	4P10D42206
Make & Model:	MITSUBISHI CANTER, 3.0 D (A)	Chassis No:	FEA01BA30065
Reg. Date:	04/03/2019 (Man. Year: 2018)	Odometer:	6824 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/75R15	Rear Tyre Size:	185/75R15 (D)
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9/9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	732.00	549.00	183.00	25.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	180.00	50.00	130.00	72.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	912.00	599.00	313.00	34.32

INSPECTION

Date of Assignment: 24/07/2019

Date Inspected: 19/07/2019 Inspected At:

Liu's Brother Auto Engineering
Workshop (HQ)
BLK 1 KAKI BUKIT AVE 6, #01-01
AUTO BAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 1.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Jul 2019)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ2663Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH MIRROR ARM	Bent/Cracked	513.80 F	*513.80 FL
2	1		*FRONT LH SIDE MIRROR SQUARE	Cut	107.70 F	*107.70 FL
3	1		*FRONT LH SIDE MIRROR ROUND	Cracked	110.50 F	*110.50 FL
					Sub Total (S\$)	732.00
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00
					Total Parts (S\$)	732.00
						549.00

F=Franchise part. L=List/ItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACE AND TRANSFER MIRROR ARM,FITTING AND MECHANISMS	New	180.00	50.00
Gross Labour Cost (\$\$)			180.00	50.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >