

ASS. REC. BY:

REF: CS3/81019012831/FC43<sup>sr</sup>

Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

From (Person): Agnes Chan Shu Hui of SMO Date/Time: 19.7.19 17:11 p.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 1205M Insured: SLM 4232K

at Workshop m/s Sin Hwa Spray Tel: 94817286

of BIK 160, #07-10 Sin Ming Autoady

Policy No: D19M1RENT000151 Claim No: CMTD1903483

Sum Insured: Excess:

Make of Veh: D.O.A. 18.7.19  
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 22.7.19 9.15 a.m. Person Contacted: Mr Chia H.O.D. Endorsement:

Vehicle IN OUT

| Date/Time | Action/Instruction ( X ) Estimate |
|-----------|-----------------------------------|
|           | SLQ 1205M X                       |
|           | SLM 4232K X                       |
|           | Dismantle: 28/7/2019              |
|           |                                   |
|           |                                   |
|           |                                   |

REF: Somp

PRS

## ASSIGNMENT

From: Date: 22.7.2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 1205 M

at Workshop m/s Sin Hwat Spray

of Blk 160, #07-10 Sin Ming Autocity

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SE SLQ 1205 M Yr Regn: JON / 2017

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda VEZEL

cc 1496

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 54180

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: DBA - RU1

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: 215/60 R16

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A: 18/07/19

D.O.I: 22/07/19

Survey held at Sin Hwat Spray

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range: \$4000 - \$5000

Repair days: 5 days

MV: \$74000

PV: \$43877

NV: \$30123

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status   |
|------|-------------|---------------|--|---------|---------------|------------|--|
| Main | 19 Jul 2019 |               | 19 Jul 2019<br>17:11<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |   |                        |                                    |
|-----------------------------|---|------------------------|------------------------------------|
| Insured:                    | SAN'S TOURS & CAR RENTALS, Co. Reg. No.: -  |                        |                                    |
| Main Claimant:              | CHIA CHEE KIONG, ID: S6942885A  |                        |                                    |
| Vehicle Reg. No.:           | SLQ1205M  | Date of Loss:          | 18/07/2019 08:00 - :59             |
| Claim Type:                 | TP / CMTD1903483  | Policy/Cover Note No.: | D19MTRENT000151 (Third Party Only) |
| Vehicle Reg. No. (Insured): | SLM4232K  | Policy No. (Claimant): |                                    |
|                             |   | Excess:                |                                    |
| Repairer:                   | Sin Huat Spray Painting (HQ) Blk160, #07-10, Sin Ming AutoCity, 575722 Sin Ming - Tel:                    |                        |                                    |
| Handling Insurer:           | Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327] |                        |                                    |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/07/2019]                         |                        |                                    |
| Driver/Custodian (Insured): | MENON RAJEEV (), NRIC: G3069903W, Tel: +6581683579 Email:   |                        |                                    |
| Adj Asg. Remarks:           | WS: MR. CHIA 94817286   |                        |                                    |

## ASSOCIATED MAIL RECEIVED

[View All](#) | [Compose Case Mail](#)

There are no mail for this case.



## ALL ASSOCIATED TASKS

[View All](#) | [Search Tasks](#) | [Create New Task](#) | [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

**Nivitha (LKK Auto)**

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Friday, 19 July 2019 5:10 PM  
**To:** tonygn tonygn; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'  
**Cc:** Chan, Shu Hui Agnes; Ye, Yong Kang Melvin  
**Subject:** CMTD1903483/AGC - PRI/LKK / SLM4232K & SLQ1205M ACC ON 18.07.19 Please contact the workshop

Our Reference : CMTD1903483/AGC  
Your Reference: 19 – G 469 SHS

**Without Prejudice**

Date: 19/07/2019

OUR Email: [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)

**Attention:**  
**M/S WU LLC**

Dear Tony

**ACCIDENT INVOLVING SLM4232K & SLQ1205M ON 18.07.2019**

We refer to your email of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards  
**Grace Teo**  
Claims Division  
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)



**SOMPO**  
INSURANCE

**A Century of Trust**

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG



<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** tonygn tonygn [mailto:tonygn18@hotmail.com]

**Sent:** Friday, July 19, 2019 5:06 PM

**To:** Teo, Grace

**Subject:** Re: CMTD1903483/AGC - PRI/ SLM4232K & SLQ1205M ACC ON 18.07.19 Please contact the workshop

We'd like to reject your list of surveyors and we propose **Absolute Appraisal Services Pte. Ltd.** to be our surveyor.

Please update us your decision as soon as possible

Thank You

Yours

Sincerely,

**Sin Huat Spray Painting**

**1. Person / HandPhone No. : Mr. Chia / 9481 – 7286**

**2. Fax : 6459 – 4940**

Sent from [Outlook](#)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>

**Sent:** Friday, July 19, 2019 4:53 PM

**To:** tonygn tonygn <tonygn18@hotmail.com>

Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>  
Subject: CMTD1903483/AGC - PRI/ SLM4232K & SLQ1205M ACC ON 18.07.19

Our Reference : CMTD1903483/AGC  
Your Reference: 19 – G 469 SHS

Date: 19/07/2019

**Without Prejudice**

OUR Email: [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)

Attention:  
M/S WU LLC

Dear Tony

**ACCIDENT INVOLVING SLM4232K & SLQ1205M ON 18.07.2019**

We refer to your Notice of Accident dated 19/07/2019.

Please be informed that **Ms. Agnes Chan** is the handler of this case who can be contacted at 63295 327.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

|   | Motor Surveyor                   | Surveyor                  | Selection (Indicate as tick) |
|---|----------------------------------|---------------------------|------------------------------|
| 1 | Raleigh Services                 | Andrew Ow Yong            |                              |
|   |                                  | Vincent Ng                |                              |
| 2 | LKK Auto Consultants             | Kenneth Kong (North area) |                              |
|   |                                  | Marcus Chua (East area)   |                              |
|   |                                  | Mohd Rasul (West area)    |                              |
|   |                                  | Mohd Taufikh (West area)  |                              |
| 3 | Priority Services                | Jimmy Lee                 |                              |
|   |                                  | Lawrence Ng               |                              |
|   |                                  | Jeffrey Ong               |                              |
| 4 | JP Knights Adjusters & Surveyors | Jason Lek                 |                              |
|   |                                  |                           |                              |

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: [www.sompo.com.sg](http://www.sompo.com.sg) | Facebook: [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG

Download now @  or 

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** tonygn tonygn [mailto:[tonygn18@hotmail.com](mailto:tonygn18@hotmail.com)]

**Sent:** Friday, July 19, 2019 3:34 PM

**To:** Claims - Motor Survey

**Subject:** pri G 469 SHS SLQ 1205 m

1. **Person / HandPhone No. : Mr. Chia / 9481 – 7286**
2. **Fax : 6459 – 4940**

Sent from [Outlook](#)



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                       |
|----------------------------|---------------------------------------|
| Date Of Report             | 18/07/2019 17:57                      |
| Date Of Accident           | 18/07/2019 08:25                      |
| Exact Location Of Accident | ALONG HOLLAND RD (OPP ALLSWORTH PARK) |
| Country/State of Loss      | SINGAPORE                             |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SLQ1205M             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | CHIA CHEE KIONG      |
| NRIC No                     | S6942885A            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-93686419 |
| Alternative Phone No        | OFFICE-93686419      |

### Vehicle Particulars

|              |       |
|--------------|-------|
| Manufacturer | HONDA |
| Model        | VEZEL |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY  
Vehicle Category PRIVATE CAR

### Insurance Company

|                           |   |
|---------------------------|---|
| Name of Insurance Company | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage          | COMPREHENSIVE                                 |
| Fleet Policy              | NO  |
| Policy Number             | DMPCSN1744831902                              |
| Cover Note Number         |   |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | CHIA CHEE KIONG       |
| NRIC No              | S6942885A             |
| Date Of Birth        | 05/12/1969            |
| Occupation           | INDOOR                |
| Date Of Driving Pass | 15/04/1995            |
| Driving Experience   | 24 YEARS AND 3 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-93686419  |
| Fax Number           |                       |
| Contact Number       | OFFICE-93686419       |
| Email Address        | NOEMAIL               |



Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle  
 Insurance Company of Driver's Own Vehicle

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

### Circumstances of Accident

refer attached report.

### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number SLM4232K  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver RAJEEV MENON  
 NRIC/Passport Number  
 Contact Number 81683579  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)


**SKETCH PLAN****IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/07/2019 at 0825 HRS, I was driving my vehicle (SLD 1205M) going to the main Holland Road. I stopped my vehicle to check if there are any oncoming cars when suddenly vehicle B (SLM 4232K) hit my vehicle from the back.

No one was injured.

I was in full control of my car.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*Col.*  
Policyholder's Signature  
Date & Time:

*Col.*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                      |
|-------------------------------------|--------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                      |
| Owner ID Type:                      | Singapore NRIC                       |
| Owner ID:                           | 885A                                 |
| <b>Vehicle Details</b>              |                                      |
| Vehicle No.:                        | SLQ1205M                             |
| Vehicle to be Exported:             | No                                   |
| Intended Deregistration Date:       | 22 Jul 2019                          |
| Vehicle Make:                       | HONDA                                |
| Vehicle Model:                      | VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR  |
| Primary Colour:                     | Blue                                 |
| Manufacturing Year:                 | 2016                                 |
| Engine No.:                         | L15B4035714                          |
| Chassis No.:                        | RU11115709                           |
| Maximum Power Output:               | 96.0 kW (128 bhp)                    |
| Open Market Value:                  | \$22,318.00                          |
| Original Registration Date:         | 28 Jun 2017                          |
| First Registration Date:            | 28 Jun 2017                          |
| Transfer Count:                     | 0                                    |
| Actual ARF Paid:                    | \$13,246.00                          |
| <b>Intended PARF Rebate Details</b> |                                      |
| PARF Eligibility:                   | Yes                                  |
| PARF Eligibility Expiry Date:       | 27 Jun 2027                          |
| PARF Rebate Amount:                 | \$9,934.00                           |
| <b>Intended COE Rebate Details</b>  |                                      |
| COE Expiry Date:                    | 27 Jun 2027                          |
| COE Category:                       | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):                  | 10                                   |
| QP Paid:                            | \$42,801.00                          |
| COE Rebate Amount:                  | \$33,943.00                          |
| <b>Total Rebate Amount:</b>         | <b>\$43,877.00</b>                   |

The information contained herein is correct as at 22 Jul 2019

DOA : 18/07/19

OK

COE : 27/06/27

Remaining months of 7 years 11 months 9 days (95.2) months  
COE from DOA

Depri : \$8500 (yearly) \$708 (monthly)

PARF :  $13246 \times 50\% = 6623$

$95.2 \times \$708 = \$67401.60$

$\$67401.60 + \$6623 = \$74024.60$



## Need Items for Your Car?

We have thousands of car parts &amp; accessories to explore.

The best online platform to sell and buy car parts &amp; accessories - Marketplace

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Citroen C4 Cactus 1.2A PureTech 13,800Km Best Deal.



Only 13800Km. I Am A Car  
Enthusiast So The Car Is In  
Absolute Best Condition!  
Direct Owner - StarAd

**PRIME MOTOR & LEASING**  
(CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)  
With over 200 units of vehicles  
to choose from, ranging from  
all European to Japanese Makes.

Browse by Category

« Back ( 1 2 3 ) Next »

Sort by Date Posted

20 results/page

45 vehicles

honda vezel

Advanced Search

Search Selection

| Make        | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status    |
|-------------|-------|-------|--------------|----------|---------|---------|----------|-----------|
| honda vezel |       | Any   | Any          | 2017     | Any     | Any     | Any      | Available |



**Honda Vezel Hybrid 1.5A X**  
**Honda Sensing**

\$85,800

\$9,870 /yr

28-Dec-2017

1,496 cc

28,000 km

SUV

Available

Fuel Type: Petrol-Electric

(Full Loan Available) Offer Bank Interest Rate From 1.98%. Free 2 Years Hybrid Battery Warranty With Certified 120 Points Test Report  
With Detailed Chassis Inspection. Extra Passengers Safety With Honda Sensing Technology. Blue Body With Black Interior. 1 x Free Serv...

Dynamic Motoring

Posted: 22-Jul-2019

Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

PREMIUM AD

**Honda Vezel 1.5A X (OPC)**

\$62,000

\$7,270 /yr

18-May-2017

1,496 cc

30,000 km

SUV

Available

30k Mileage OPC Only Used On Weekend Driving In Town Accident Free, Mint Condition With Scheduled Servicing

Posted: 22-Jul-2019

Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

DIRECT OWNER



**Honda Vezel 1.5A X Honda**  
**Sensing**

\$74,800

\$8,770 /yr

21-Apr-2017

1,496 cc

32,000 km

SUV

Available

100% Loan Available! Just Arrived. 1 Owner, Accident Free, Owner's Weekend Car, Super Low Mileage, As Good As New. Grab It Before  
It's Gone. Call For Viewing Appointment.

Autotrust Traders Pte Ltd

Posted: 21-Jul-2019

Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

PREMIUM AD

**Honda Vezel 1.5A X**

\$76,800

\$8,610 /yr

29-Sep-2017

1,496 cc

38,189 km

SUV

Available

100% Not A PHV Unit. Previous Owner Trade In To Us To Buy A New MPV. The Best Well Dressed Unit In The Market! Sporty Red With  
Matching Sports Rims And Side Steps. Fabulous Condition Which You Must View First If You Are Looking To Own A Vezel. High Loan Ava...

Posted: 20-Jul-2019

Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

PREMIUM AD

**Nexen N'Fera SU1 16" Tyre**

Nexen N'Fera SU1 16" Tyre 195/55/R16/91V selling at \$118.40. Made in Korea.

Find out more!

**Honda Vezel 1.5A X**

\$74,999

\$8,830 /yr

20-Jun-2017

1,496 cc

39,000 km

SUV

Available

Newest Arrival! Hot Deal! Beautiful Unit, Low Depreciation, Low Mileage, Certified Premium Preowned Multipoint Check. Flexible Financing  
And Special 2.28% Bank Rates! High Trade In Value! Please Call/SMS/Whatsapps. For Details And Viewing, Thanks.

Premium Automobiles

Posted: 20-Jul-2019

Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

PREMIUM AD

**Honda Vezel 1.5A X**

\$73,800

\$8,720 /yr

04-Apr-2017

1,496 cc

32,000 km

SUV

Available

Well Maintained By 1 Lady Owner. Do Not Miss This Beautiful Unit, Flawless And Excellent Condition, Nice Number! STA Inspection  
Welcome. Loan / Trade-in Available. Call Now Before It Is Gone.

Viking Motor Pte Ltd

Posted: 20-Jul-2019

Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel 1.5A X Honda**  
**sensing (OPC)**

\$61,800

\$7,400 /yr

19-Jan-2017


1,496 cc

SUV

Available

With Revised OPC. Minimum PARF \$6276. 1 Owner Unit. 6 Months Warranty. Original Paint And Condition. Well Maintained By

Compare



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                              | Ins Auth'd | Status  |
|------|-------------|---------------|--|--|--|------------|---|
| Main | 19 Jul 2019 |               | 19 Jul 2019<br>17:11<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |   |                        |  |
|-----------------------------|---|------------------------|--|
| Insured:                    | <b>SAN'S TOURS &amp; CAR RENTALS</b> , Co. Reg. No.: -  |                        |  |
| Main Claimant:              | <b>CHIA CHEE KIONG</b> , ID: S6942885A  |                        |  |
| Vehicle Reg. No.:           | <b>SLQ1205M</b>   | Date of Loss:          | 18/07/2019 08:00 - :59<br>[24 Months and 20 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | <b>TP / CMTD1903483</b>   | Policy/Cover Note No.: | D19MTRENT000151 (Third Party Only)   |
| Vehicle Reg. No. (Insured): | <b>SLM4232K</b>   | Policy No. (Claimant): |  |
|                             |   | Excess:                |  |
| Repairer:                   | <b>Sin Huat Spray Painting (HQ)</b> Blk160, #07-10, Sin Ming AutoCity, 575722 Sin Ming - Tel:   |                        |  |
| Handling Insurer:           | <b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>CHAN SHU HUI AGNES</b> - 6329 5327]               |                        |  |
| Adjuster:                   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>PARASURAM SHANMUGAM</b> ] ... [Final Rpt due 30/07/2019] |                        |  |
| Driver/Custodian (Insured): | <b>MENON RAJEEV ()</b> , NRIC: G3069903W, Tel: +6581683579 Email:   |                        |  |
| Adj Asg. Remarks:           | WS: MR. CHIA 94817286   |                        |  |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |





## Claim Documents

\*SLQ1205M (CMTD1903483)  
[SLM4232K]  
TP  
CHIA CHEE KIONG  
Jul 18 2019 8:00AM  
[SAN'S TOURS & CAR RENTALS]  
Sin Huat Spray Painting

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

### Assessment Reports

| No | Finalized On   | Sompo Insurance Singapore Pte. Ltd. (HQ)   | 1 per page ▼ | <input checked="" type="checkbox"/> |
|----|----------------|--|--------------|-------------------------------------|
|    |                |  | Thumbnail    | Print                               |
| 1  | 19/07/19 17:08 | <b>Accident Statement</b><br>From: SC - Reg. No: SLM4232K, Claimant: SAN'S TOURS & CAR RENTALS | Load HTM     |                                     |

### Photos/Images

| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | 3 per page ▼ | <input checked="" type="checkbox"/> |
|----|-----------------|-----------------------------------|--------------|-------------------------------------|
|    |                 |                                   | Thumbnail    | Print                               |
| 1  | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 2  | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 3  | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 4  | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 5  | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 6  | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 7  | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 8  | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 9  | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 10 | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 11 | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 12 | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 13 | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 14 | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 15 | 23/07/19 17:18  | Odometer Reading                  | Load JPG     | <input checked="" type="checkbox"/> |
| 16 | 23/07/19 17:18  | Chassis Number                    | Load JPG     | <input checked="" type="checkbox"/> |
| 17 | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 18 | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 19 | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 20 | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 21 | 23/07/19 17:18  | General View                      | Load JPG     | <input checked="" type="checkbox"/> |
| 22 | 29/07/19 11:30  | Photographs of Damaged Parts      | Load JPG     | <input checked="" type="checkbox"/> |
| 23 | 29/07/19 11:30  | Photographs of Damaged Parts      | Load JPG     | <input checked="" type="checkbox"/> |
| 24 | 29/07/19 11:30  | Photographs of Damaged Parts      | Load JPG     | <input checked="" type="checkbox"/> |
| 25 | 29/07/19 11:30  | Photographs of Damaged Parts      | Load JPG     | <input checked="" type="checkbox"/> |
| 26 | 29/07/19 11:30  | Photographs of Damaged Parts      | Load JPG     | <input checked="" type="checkbox"/> |
| 27 | 29/07/19 11:30  | Photographs of Damaged Parts      | Load JPG     | <input checked="" type="checkbox"/> |
| 28 | 29/07/19 11:30  | Photographs of Damaged Parts      | Load JPG     | <input checked="" type="checkbox"/> |
| 29 | 29/07/19 11:30  | Photographs of Damaged Parts      | Load JPG     | <input checked="" type="checkbox"/> |
| 30 | 29/07/19 11:30  | Photographs of Damaged Parts      | Load JPG     | <input checked="" type="checkbox"/> |
| 31 | 29/07/19 11:30  | Photographs of Damaged Parts      | Load JPG     | <input checked="" type="checkbox"/> |

| Assessment Reports |                |  | 1 per page ▼ | ✓     |
|--------------------|----------------|--|--------------|-------|
| No                 | Finalized On   | Sompo Insurance Singapore Pte. Ltd. (HQ) | Thumbnail    | Print |
| 32                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 33                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 34                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 35                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 36                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 37                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 38                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 39                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 40                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 41                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 42                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 43                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 44                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 45                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 46                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 47                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 48                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 49                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 50                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| 51                 | 29/07/19 11:30 | Photographs of Damaged Parts             | Load JPG     | ✓     |
| Documentation      |                |  | 1 per page ▼ | ✓     |
| No                 | Finalized On   | Sompo Insurance Singapore Pte. Ltd. (HQ) | Thumbnail    | Print |
| 1                  | 19/07/19 17:02 | Third Party E-filed GIA report(M)        | Load PDF     |       |
| 2                  | 19/07/19 17:11 | Pre-Repair Survey - ASSIGN LKK           | Load PDF     |       |

## Documents Checklist

| DOCUMENTS CHECKLIST  | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured.   |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>   |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19012831/FCF3S2  
Date: 29/07/2019

### REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D19MTRENT000151  
Claimant Vehicle No: SLQ1205M Insured Vehicle No: SLM4232K  
Date of Loss: 18/07/2019 Nature of Claim: TP Claim No: CMTD1903483

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ1205M**  
Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4035714  
Reg. Date: 28/06/2017 (Man. Year: 2016) Chassis No: RU11115709  
Colour: Blue Odometer: 54180 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16  
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm  
Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

### INSPECTION

Date of Assignment: 19/07/2019  
Date Inspected: 22/07/2019 Inspected At: Sin Huat Spray Painting (HQ)  
Estimated Period of Repair: 5.0 days Blk160, #07-10, Sin Ming AutoCity  
Singapore 575722

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

## REPAIR DETAILS

### Reference

|                      |  |   |
|----------------------|--|---|
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 29 Jul 2019)         |
| <b>Parts:</b>        | M1-SUV   | HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                     |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLQ1205M)  |   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >