

ASS. REC. BY:

REF:

CS3/FDD14012855/9c/LS

Special Instruction:

Surveyor:

Cao Qiang

ASSIGNMENT (Office)

From (Person):

Eileen Bay

of

FDD

Date/Time:

22/7/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJA 1651 R

Insured:

SMM 1551 Y

at Workshop m/s

Seen Lee Choon

Tel:

9686 8855

of BIK: 5033 AMK #01-283.

Policy No:

PNPV2018-00009706

Claim No:

1201900020875

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/7/2019

(Client's Record)

23.7.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

22/7

Person Contacted:

Phyllis

Vehicle IN/OUT

Date/Time

Action/Instruction Estimate (X)

SJA 1651 R - X

SMM 1551 Y - X

After repair: 26/7/2019

PRS

Gul.

ASSIGNMENT

(-2027)

From: Date: 23.7.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJA 1651R

at Workshop m/s Soon Le choon

of Blk 50 32 AMK Ind Park 2 #01-283

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: After 1.00 p.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJA 1651R Yr Regn: 28 Nov 2007

Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis

C.C. 1598

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 222624

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRO538EC 107155417

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD / STD A/Rim or

Tyre Size: F: 185/70 R14

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 23-07-19

Survey held at w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$500 - \$1000

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: PR

Lump Sum / I.B.I.: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Jul 2019 Edit Reg		22 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:			
Main Claimant:	NG BOON HEON, ID: S1660971D		
Vehicle Reg. No.:	SJA1651R	Date of Loss:	18/07/2019 19:00 - :59
Claim Type:	TP / 1201900020875	Policy/Cover Note No.:	PNPV2018-00009706 (Comprehensive)
Vehicle Reg. No. (Insured):	SMM1551Y	Policy No. (Claimant):	
		Excess:	S\$2,500.00
Repairer:	Soon Lee Choon Auto Sevices (HQ) BLK 5032 ANG MO KIO INDUSTRIAL PARFK 2 #01-283, 569535 Ang Mo Kio - Tel: 64840217		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 31/07/2019]		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: eileen.bay@fwd.com
Sent: Monday, 22 July 2019 12:06 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: 2nd PRS - Your ref:1201900020875 and our ref: SJA 1561R/SLC/jp/cl
Attachments: 2nd PRS (reject) - 22.07.19.pdf; 1ST PRS - SJA 1651R_20190719182821.pdf

Dear LKK,

Please refer to the email below and liaise with TP repairer for PRS.
Please create the case in Merimen.

Kind regards,

Eileen Bay

Executive, Claims


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 69217411

E eileen.bay@fwd.com

W www.fwd.com.sg



From: Eileen Bay - SGUser
Sent: Monday, 22 July 2019 12:02 PM
To: 'Accident@kscgp.com'
Cc: jiapei@kscgp.com; Motor Claims SG - SG Common
Subject: RE: 2nd PRS - Your ref:1201900020875 and our ref: SJA 1561R/SLC/jp/cl

WITHOUT PREJUDICE

Dear Sir / Madam,

Veh Out

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK Auto Consultants Pte Ltd, to conduct the pre-repair survey (PRS) on your client's vehicle. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

**Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.*

***Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.**

Kind regards,

Eileen Bay

Executive, Claims


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 69217411

E eileen.bay@fwd.com

W www.fwd.com.sg



From: Accident@kscgp.com [mailto:Accident@kscgp.com]

Sent: Monday, 22 July 2019 11:59 AM

To: Eileen Bay - SGUser

Cc: jiapei@kscgp.com

Subject: 2nd PRS - Your ref:1201900020875 and our ref: SJA 1561R/SLC/jp/cl

Dear Eileen,

We refer to the matter above and your email dated 22 July 2019.

Please see enclosed our 2nd Notice to Conduct Pre-Repair Survey.

The workshop details are as follows:

Soon Lee Choon Auto Services Pte Ltd

Block 5032 Ang Mo Kio Industrial Park 2

#01-283

Singapore 569535

Contact person: Ms Phyllis / Tel: 9686 8855

Thank you.

Regards,

CL

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: eileen.bay@fwd.com [<mailto:eileen.bay@fwd.com>]

To: Accident@kscgp.com

Cc: motorclaims.sg@fwd.com

Sent: Mon, 22 Jul 2019 03:06:19 +0000

Subject:

WITHOUT PREJUDICE

Dear Sir / Madam,

Please find our panel surveyors as follows: -

1. LKK Auto Consultants Pte Ltd
2. Infiniti Appraisal Service
3. AJAX Inspection Services Pte Ltd
4. RT Appraisal Pte Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receive your reply.

**Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.*

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind regards,

Eileen Bay

Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 69217411

E eileen.bay@fwd.com

W www.fwd.com.sg





From: Accident@kscgp.com [mailto:Accident@kscgp.com]

Sent: Friday, 19 July, 2019 6:33 PM

To: Motor Claims SG - SG Common

Subject: URGENT - 1st Notice to conduct Pre-Prepair Survey - Your insured's vehicle: SMM1551Y and our ref: SJA1651R/SLC/jp/cl

Dear Sirs,

Please find enclosed herewith our 1st Notice to Conduct Pre-Prepari Survey for your kind attention and necessary action.

Thank you.

Regards,

CL

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0982 / Fax: 6538 3708

Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

This email has been scanned by the MxScan Email Security System.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Your Ref : 1201900020875
Our Ref : SJA 1651R/SLC/jp/cl
Date : 22 July 2019

Fax : 6538 3708
Tel : 3152 0985
Email : jiapei@kscgp.com

FWD Singapore Pte. Ltd.

BY EMAIL ONLY

DATE OF ACCIDENT: 18 July 2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email dated 22 July 2019.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/no.	Name of Surveyor	Company Name
1.	Richard Wong	RW Automotive Appraisers Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Soon Lee Choon Auto Services Pte Ltd
Block 5032 Ang Mo Kio Industrial Park 2
#01-283
Singapore 569535

Contact Person/Tel : Ms Phyllis / Tel: 9686 8855

Yours faithfully,

f CL

Your Ref : 1201900020875

Our Ref : SJA 1651R/SLC/jp/cl

Date :

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of
_____ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

Your Ref : SMM 1551Y
Our Ref : SJA 1651R/SLC/jp/cl
Date : 19 July 2019

Fax : 6538 3708
Tel : 3152 0985
Email : jiapei@kscgp.com

FWD SINGAPORE PTE. LTD.

BY EMAIL ONLY

DATE OF ACCIDENT: 18 JULY 2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We are instructed by the owner of SJA 1651R to notify you of a road traffic accident on 18 July 2019 at about 7.20pm along Ang Mo Kio Avenue 8, involving our client's vehicle registration number SJA 1651R and vehicle registration number **SMM 1551Y** which was insured by you at the material time. A copy of the Singapore accident statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

NB. Any settlement or offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude client's driver/passenger from claiming injury-related damages arising from this accident.

Yours faithfully,

f CL

Enc.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/07/2019 16:50
Date Of Accident	18/07/2019 19:20
Exact Location Of Accident	ANG MO KIO AVENUE 8
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJA1651R
Insured/Policyholder	
Name Of Registered Owner	NG BOON HEON
NRIC No	S1660971D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96607631
Alternative Phone No	OFFICE-96607631

Vehicle Particulars

Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No. Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80314263QMX
Cover Note Number	

Driver

Name of Driver	HOI GUM LING, CHRISTINE
NRIC No	S1787147A
Date Of Birth	03/01/1967
Occupation	INDOOR
Date Of Driving Pass	09/10/1992
Driving Experience	26 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96607631
Fax Number	
Contact Number	
EMail Address	NGHOIC@YAHOO.COM.SG

Address	BLK 443 ANG MO KIO AVENUE 10 #08-1227
Postcode	560443
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED ; REMARKS: TYPE OF ACCIDENT PLEASE REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMM1551Y
Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED
Vehicle Category	PRIVATE CAR
Name of Driver	LAN CHIWAI, OLIVER
NRIC/Passport Number	
Contact Number	97488835
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REFER ATTACHED
No. Of Passenger (Including Driver)	


DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMD8978B
-----------------------------	----------

Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED
Vehicle Category	PRIVATE CAR
Name of Driver	TAN SIEN WEI
NRIC/Passport Number	
Contact Number	96499006
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REFER ATTACHED
No. Of Passenger (Including Driver)	

SKETCH PLAN

A-SJA1651R.
B-Smm1551Y.
C-SMD 89788.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was stationary at the traffic light as it was RED light. Not long after felt a small impact. When I looked at my rear mirror, I noticed that an accident has taken place. Vehicle B has hit on the rear portion of my vehicle.

No injuries incurred

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature:
Date & Time:

Driver's Signature:
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature:
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	971D
Vehicle Details	
Vehicle No.:	SJA1651R
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	3ZZ4698158
Chassis No.:	MR053ZEC107155417
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,757.00
Original Registration Date:	28 Nov 2007
First Registration Date:	28 Nov 2007
Transfer Count:	1
Actual ARF Paid:	\$16,233.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2027
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$44,081.00
COE Rebate Amount:	\$36,085.00
Total Rebate Amount:	\$36,085.00

The information contained herein is correct as at 23 Jul 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jul 2019 Edit Reg		22 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	NG BOON HEON, ID: S1660971D		
Vehicle Reg. No.:	SJA1651R	Date of Loss:	18/07/2019 19:00 - :59 [139 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201900020875	Policy/Cover Note No.:	PNPV2018-00009706 (Comprehensive)
Vehicle Reg. No. (Insured):	SMM1551Y	Policy No. (Claimant):	
		Excess:	S\$2,500.00
Repairer:	Soon Lee Choon Auto Seivices (HQ) BLK 5032 ANG MO KIO INDUSTRIAL PARFK 2 #01-283, 569535 Ang Mo Kio - Tel: 64840217		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/07/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents























***SJA1651R (1201900020875)**
[SMM1551Y]
TP
NG BOON HEON
Jul 18 2019 7:00PM
[-]
Soon Lee Choon Auto Sevices

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images

3 per page ▼

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/07/19 12:42	General View	 Load JPG	<input checked="" type="checkbox"/>
2	29/07/19 12:42	General View	 Load JPG	<input checked="" type="checkbox"/>
3	29/07/19 12:42	General View	 Load JPG	<input checked="" type="checkbox"/>
4	29/07/19 12:42	General View	 Load JPG	<input checked="" type="checkbox"/>
5	29/07/19 12:42	General View	 Load JPG	<input checked="" type="checkbox"/>
6	29/07/19 12:42	General View	 Load JPG	<input checked="" type="checkbox"/>
7	29/07/19 12:42	General View	 Load JPG	<input checked="" type="checkbox"/>
8	29/07/19 12:42	General View	 Load JPG	<input checked="" type="checkbox"/>
9	29/07/19 12:42	General View	 Load JPG	<input checked="" type="checkbox"/>
10	29/07/19 12:42	General View	 Load JPG	<input checked="" type="checkbox"/>
11	29/07/19 12:42	General View	 Load JPG	<input checked="" type="checkbox"/>
12	29/07/19 12:42	General View	 Load JPG	<input checked="" type="checkbox"/>
13	29/07/19 12:42	General View	 Load JPG	<input checked="" type="checkbox"/>
14	29/07/19 12:42	General View	 Load JPG	<input checked="" type="checkbox"/>
15	29/07/19 12:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
16	29/07/19 12:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
17	29/07/19 12:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
18	29/07/19 12:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
19	29/07/19 12:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
20	29/07/19 12:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
21	29/07/19 12:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
22	29/07/19 12:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19012855/GCF3S2
Date: 01/08/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00009706
Claimant Vehicle No : SJA1651R **Insured Vehicle No :** SMM1551Y
 Date of Loss: 18/07/2019 Nature of Claim: TP Claim No: 1201900020875

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJA1651R**
 Make & Model: TOYOTA COROLLA, 1.5 (M) Engine No: 3ZZ4698158
 Reg. Date: 28/11/2007 (Man. Year: 2007) Chassis No: MR053ZEC107155417
 Colour: Silver Odometer: 222624 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/07/2019
 Date Inspected: 23/07/2019 Inspected At: Soon Lee Choon Auto Seives (HQ)
 BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-283
 Singapore 569535
 Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$500.00 - \$1,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2019)
Parts:	143	TOYOTA COROLLA 1.5 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJA1651R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >