

12/20/2018

ASS. REC. BY:

REF:

CS/AIG/19012868

f3

Special Instructions:

Surveyor: Ch

ASSIGNMENT (Office)

From (Person): Hor Yinnul

of

AIGDate/Time: 22/7/2019Estimated Cost: 11,683.17

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBG 4794 E

Insured:

at Workshop m/s STK AutoTel: 6386 0669of B Kaki Bukit Ave 4 #03-21Policy No: 1700042883Claim No: 825971167136

Sum Insured:

Excess:

800

Make of Veh:

D.O.A.

18/7/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction
	Example ()
	GBG 4794 E - X
23/7/19	Revert via merimen
24/7/19	Recd approved \$4191.63 from Victor by merimen
24/7/19	Informed Guo Hui c/A on LS repair ex TBA by email

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: STK Auto
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Est. or Market Value: \$54K
 IDAC Accident Rpt.: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No
 CA / ☒ REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBG4794E Yr Regn: 21 Aug 2017
 Type: M.Car / M.Cycle / Bus / ☒ Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Nissan NV350 cc 2488
 Colour: white A/C Insured / Std / NI / NA
 Sp. Reading: 55676 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JN1MC2E268 0009/22
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Mod: ☒ M / S/Rim / STD A/Rim or
 Tyre Size: F: 195 R15 R: 11
 BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal: 6 mm Rear R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. 22-07-19
 Survey held at W/S 4pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S TA
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
26/7/19	Informed Guo Hua vehicle ex \$800
29/7/19	Recd email from Guo Hua insured change to TP claim
29/7/19	@2320pm check with Linda TP claiming AXA
29/7/19	Submit preli report
30/7/19	Linda said AXA already assign surveyor
31/7/19	Cancel assignment - Assign wrongly

RECEIVED 30 JUL 2019

[Signature] 7/8

Date/Time, File Pass to? ☒ Preli. Report ☐ Final Report
 1) _____
 Date/Time, File Return to? _____
 2) 29/7 - typist
 Report Format: _____
 Lump Sum / I.B.I: (\$ _____)
 Days Of Repair: 4
 Resurvey No. of Trip: _____
 Add Fee: ☐ Site Insp (\$ _____)
☐ Interview (\$ _____)
☐ Tech. Invs (\$ _____)
☐ Weekend (\$ _____)
 Survey Fee: _____
 Transportation: _____
) \$ + RS \$ _____
) Phone _____
) Others _____
 TOTAL: _____

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 26 July 2019 4:18 PM
To: stkautosg@gmail.com; SUR
Subject: RE: GBG 4794E-DOA: 18/7/2019 (AIG OD)

Dear Guo Hua,

Vehicle excess \$800/-.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 24 July 2019 12:01 PM
To: stkautosg@gmail.com; SUR <sur@lkkauto.com>
Subject: GBG 4794E-DOA: 18/7/2019 (AIG OD)

Dear Guo Hua,

As instructed by our client , please proceed to repair the **insured vehicle GBG 4794E on Lump Sum Repair (Excess TBA).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 24 July 2019 12:01 PM
To: stkautosg@gmail.com; SUR
Subject: GBG 4794E-DOA: 18/7/2019 (AIG OD)

Dear Guo Hua,

As instructed by our client, please proceed to repair the **insured vehicle GBG 4794E on Lump Sum Repair (Excess TBA)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***GBG4794E (8259711677SG)**

OD

Jul 18 2019 12:00PM

[SINCHONG MEHECO LTD]

Stk Auto (s) Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 24/07/2019 11:39 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4191.63) - GBG4794E

Approved:4191.63:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	AIG Asia Pacific Insurance Pte. Ltd, AIG Building 78 Shenton Way #07-16 Singapore 079120	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:		Date:	23 Jul 2019

Preliminary Advice

Vehicle No	: GBG4794E	Accident Date	: 18/07/2019
Make	: NISSAN NV350	Policy No.	: 1700042883
Assignment Date	: 23/07/2019	Excess	: S\$0.00
Date of Inspection	: 22/07/2019	Est. Duration of Repair	: 4.00
Inspection At	: STK AUTO (S) PTE LTD (HQ) 8 KAKI BUKIT AVE4, #03-21 SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,653.62
Revised Amount	:S\$	4,191.63
Check Items (Estimated)	:S\$	545.63
Total	:S\$	4,737.26

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	54,000.00
COE / PARF Rebate	:S\$	32,472.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,528.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

PRE-REPAIR INSPECTION REQUEST – YP1119E vs GBG4794E (OI) on D.O.A.: 18/07/2019 (OD Claim)

From: Hor, Yinnul
To: 'assignments@stkauto.com'; Admin A (admin-a@stkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tong, Watsun
Sent: 7/22/2019 2:01:21 PM
Attachments:  Accident Repair Estimate GBG4794E.XLS

Hi,

Please refer to the enclosed request from **STK AUTO (S) PTE LTD**.

Claim no : 8259711677SG001
Case Owner : Decban A/L Nadaraja

If you have any queries/concerns, please let us know.
Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks & Regards,

Hor Yui Rut (Viviane)
AIG
PNOL Adjuster I
Singapore PNOL | Claims Operations – Auto

Yinnul.Hor@aig.com | www.aig.sg

From: stkautosg@gmail.com [mailto:stkautosg@gmail.com]
Sent: Monday, July 22, 2019 12:15 PM
To: Abu Kassim, Noor Mariesa
Cc: Fong, Andy-SY; Chin, Lee-Ying; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Watsun; Hor, Yinnul
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBG4794E AND YP1119E ON 18/07/2019

Dear Motor Claim Dept

We conduct a pre-repair of the damage vehicle no.: GBG4794E, LKK Marcus chua.

Thank you

From: Abu Kassim, Noor Mariesa
Sent: Mon, 22 Jul 2019 02:58:44 +0000
To: stkautosg@gmail.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tong, Watsun, Hor, Yinnul
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBG4794E AND YP1119E ON 18/07/2019

Without Prejudice

Your Reference : GBG4794E
Our Reference : 8259711677SG001

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Loh	Automobile Inspection Services Pte Ltd
Fang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd

Veh In - XGR

Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Marissa Abu Kassim (Marissa)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Marissa.AbuKassim@aig.com | www.aig.com

From: STK STK (<mailto:stkautosg@gmail.com>)

Sent: Saturday, July 20, 2019 2:26 PM

To: AIG SGP, Claims-Survey

Subject: [EXTERNAL] RE: GBG4794E OD CLAIM DQA : 18/07/2019

This message is from an external sender; be cautious with links and attachments.

Hi Madam/Sir

We refer to the above accident.

We have been appointed by the owner SINCHONG MEHECO LTD the registered owner of vehicle No.: GBG4794E.

Kindly arrange your surveyor to handle the pre-repair inspection within 2 working days.

The said vehicle can be inspection at No.8 KAKI BUKIT AVE 3 #03-21 SINGAPORE 415875.

Yours sincerely,

Tan Guohua

Chief Executive Officer

STK AUTO (S) PTE LTD | www.stkauto.com.sg

Mobile: (65) 9123 7949 | Tel: (65) 63860669

8 Kaki Bukit Ave 4 #03-21 Singapore 415875 @PREMIER

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details	
Owner ID Type:	Company
Owner ID:	430H
Vehicle Details	
Vehicle No.:	GBG4794E
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jul 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 SAT 5DR EURO V
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	YD25426662A
Chassis No.:	JN1MC2E26Z0009122
Maximum Power Output:	-
Open Market Value:	\$26,142.00
Original Registration Date:	21 Aug 2017
First Registration Date:	21 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$1,308.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Details	
COE Expiry Date:	20 Aug 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$40,212.00
COE Rebate Amount:	\$32,472.00
Total Rebate Amount:	\$32,472.00

The information contained herein is correct as at 23 Jul 2019

OK



CERTIFICATE OF INSURANCE

COMMERCIAL AUTOPLUS COMMERCIAL VEHICLE

Name of Policyholder : Sinchong Meheco Ltd
 Period of Insurance : 21 Aug 2018 To 20 Aug 2019
 Engine No. : YD25426662A
 Chassis No. : JN1MC2E2E7000H122

Vehicle No. : GBG4794E
 Policy No. : 1700042883-01
 Endorsement No. :
 Issued Date : 11 Jul 2018

ABOUT THE COVER

Make/Model : NISSAN NV350 PANEL VAN
 Engine Capacity/Tonnage : 1.5 Tonnage
 Driver Restriction : NA
 Person or Class of Persons Entitled to Drive* :
 Any person who is driving in the Insured's interest with their consent.
 The Policy will indemnify the Policyholder in any accident where only a single vehicle is involved.

Some Insured : No
 Market Value : No
 First Year of Registration : 2017
 Insuring with COE/PARE : Yes

The Insured is covered by a sum insured of \$1,000,000 (One Million Dollars) for the period of the Policy. The Insured is required to maintain the vehicle in good condition and to comply with all traffic laws.

Age Condition : All Age Condition

Limitation as to use*

1. Use in connection with the Insured's business.
 2. Use for the carriage of passengers other than for hire or reward in connection with the Insured's business.
 3. Use for social, domestic or pleasure purposes. This Policy does not cover the Insured for any liability arising from the use of the vehicle for any purpose other than those stated above.

* Uninsured motorist coverage for Section 2 of the Motor Vehicle Third Party Rules and Compensation Act (Cap. 189) and Section 95 of the Road Transport Act 1987 (Malaysia) are not included under this insurance.

EXCESS

Section 1
 Fire - \$5,000 (Five Thousand) / \$100,000 (One Hundred Thousand)

Section 2
 Property Damage - \$0

Windscreen - \$100

Named Driver and Excess (where applicable)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

All accident repairs to the vehicle must be carried out by one of our Authorized Repairers. Within the first 1 year of the first registration of the vehicle in Singapore, You have the option of having the accident repairs carried out at the Insured's workshop.
 For other Approved Reporting Centres/Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6284 0000. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App, App Store and download "AIG SG" from Google Play.

IMPORTANT NOTES

How Purchase Company/Employee's Loan : TAM CHONG CREDIT PTE LTD

5500132090

LIU HENG KAT
 AIG BUILDING 78 SHENTON WAY #05-18
 SINGAPORE 341120 AND AFFILIATES
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORIZED REPRESENTATIVE

78 Shenton Way #05-18 AIG Building Singapore 341120 T +65 6415 3333 F +65 6415 3323 www.aig.com.sg

AIG Asia Pacific Insurance Pte. Ltd.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/07/2019 15:45
Date Of Accident	18/07/2019 12:00
Exact Location Of Accident	193 GUILLEMARD ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG4794E
Insured/Policyholder	
Name Of Registered Owner	SINCHONG MEHECO LTD
Co Reg No	A199205430H
Email Address	LIMNEN2325@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98815780
Alternative Phone No	Office-98815780

Vehicle Particulars

Manufacturer	NISSAN
Model	NV350-2.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700042883-01
Cover Note Number	

Driver

Name of Driver	VINCENT LIM TZE NEN
NRIC No	G2241964T
Date Of Birth	23/11/1991
Occupation	OUTDOOR
Date Of Driving Pass	12/04/2016
Driving Experience	3 YEARS AND 3 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-98815780
Fax Number	
Contact Number	
EMail Address	LIMNEN2325@GMAIL.COM
Address	10 JALAN KILANG TIMOR #02-01 LTH BLDG
Postcode	159306
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACHED SKETCH PLAN AND PHOTO

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP1119E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SEE AH PENG
NRIC/Passport Number	S0654342A

Contact Number 93586996
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKN8860C
Vehicle Make/Model/Colour BMW/BLACK
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver TAN HOCK KENG
NRIC/Passport Number S0193865G
Contact Number 67412422/98522907
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SHC3959D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver KOH TENG HOCK
NRIC/Passport Number S1443803C
Contact Number 97880234
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SKS2001D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver TANSY TAN HWEE LING
NRIC/Passport Number S7418272J
Contact Number 96741989
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

SINCHONG MEHECO LTD
ONE KM BRANCH
11 TANJONG KATONG ROAD
#B1-31, SINGAPORE 437157
TEL: 6702-8482 FAX: 6702-2481

Date & Time:

18/7/19 3:30pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:


18/7/19 3:30pm

Reporting Centre Personnel's Signature

Name: EMMER AUFONSO

NRIC/FIN No:

EP462824L



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

18/07/2019 - I was driving my vehicle A at 193 Guillemard Road my vehicle was stationary because of the 'give lane' and waiting for green light to go. Vehicle B was at the first lane going to Paya Lebar. Suddenly vehicle C came out from Guillemard Road going to Lor 20 Geylang and hit the vehicle B then vehicle B hit the vehicle A & D. Vehicle D hit vehicle E.

DECLARATION

SINCHONG MEHCO LTD
 ONE KM BRANCH
 11 TANJONG KATONG ROAD
 #B1-31, SINGAPORE 437157
 TEL: 6702-2482 FAX: 6702-2481

Driver's Signature

Date & Time:

18/7/19 / 3.30pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

18/7/19 / 3.30pm

Reporting Centre Personnel's Signature

Name:

NRIC/ID No:

63462824L



LETTER OF AUTHORITY AND INDEMNITY

- Tan Chong Motor Sales Pte Ltd, 813, Bukit Timah Road, Singapore 589625
 Tan Chong Motor Sales Pte Ltd, 11, Lorong 8, Tia Payer, Singapore 318254
 AutoLition Industrial Pte Ltd, 15, Ubi Road 4, Singapore 408627
 TC AutoLition Pte Ltd, 25, Ling Kee Road, Singapore 158007
 TC AutoLition Pte Ltd, 1, Sixth Lok Yang Road, Singapore 628009

Type of Claim

- ☐ Third Party (Direct Settlement)
☒ Own Damage (Recovery Claim)

ACCIDENT INVOLVING VEHICLE REGISTRATION No. 63647946 AND YP11196
 ON 18/7/19 AT Guillemard Road

- I, the owner of vehicle no. 63647946 hereby instruct you and authorise you to act for me with respect to the following -
 - To submit my claims for all losses including uninsured loss, rental car charges, medical fees, excess payment and cost of repairs.
 - To settling my claim as they deem fit, including settling the matter on basis of my contributory negligence if any.
 - To receive payment for settlement of my claim where all payment is to be made payable to the repair workshop for cost of repairs and other uninsured losses.
 - To sign discharge voucher on my behalf.
- I further acknowledge that any settlement that workshop may reach on my behalf is on a without prejudice basis and without admission of liability fully insofar as the driver/owner/insurers of the other vehicle is concerned.
- In the event that I am required to attend meetings, interviews, court and/or provide statements or any information in connection with my claim, I shall render full cooperation.
- In the event that my claim against the third party or his insurers is not successful or cannot be proceeded with or if any settlement is not honoured or satisfied by the third party or his insurers, I authorise you to revert to my own insurers for the cost of repairs and any losses recoverable under my policy of insurance. In this respect, I understand and accept that the excess amount applicable under the policy of insurance shall be borne by me.
- If for whatever reason, my insurers rejects my claim for indemnity for the cost of repairs and/or any other losses recoverable under the policy of insurance or make an offer to pay less than the amount claimed by you, I agree and undertake to pay the difference between what was claimed and paid out by the insurers or the full amount of my repair bill and survey fees and any other expenses reasonably incurred on my behalf or to pay you the difference in amount, as the case may be.
- I undertake to state truthfully and to make full and frank disclosure of all facts leading up to and of the accident and of my action and/or omissions in connection with my part in the accident. If any facts stated are inaccurate and my claim cannot be paid out or fails, I agree that I shall be liable to you for the repair and other costs incurred by you.
- I further undertake to sign any document or discharge voucher that is required for the purposes of my claim and if as a result of my failure to do so, my claim cannot be paid out or is delayed, I agree that I shall be liable to you for the repair and other costs incurred by you.
- I understand that the claim for loss of use of my vehicle will be based on the number on the days estimated by the surveyor in his report for the required repair. The actual number of days may be more due to unavailability of parts, weekend, holidays and other operational exigencies and I accept that it may not be possible to claim for these extra days. In addition, any contributory negligence part of my claim can also affect portion of my claim for loss of usage.
- I shall keep you informed of any correspondence and/or summons that I may receive in connection with the accident before agreeing to pay or receive any monies due under this claim.
- In the event, the insurers pay the claimed amount to me instead of you, I will inform you as soon as possible and reimburse you for the repair and other costs incurred by you.
- For successful recovery of upfront Excess payment by claimant, the workshop shall effect refund accordingly to the mode of upfront payment.
 - For upfront Excess payment by credit card, the refund shall be credited to the respective Credit Card Account via Credit Card Company handling the transaction.
 - For Excess payment by cash, the workshop shall refund the amount to the claimant via cheque payment.

Claimant's Particulars		Authorized Workshop	
Name <u>SINCHONG MATECO LTD</u>		Company Name <u>AUTOLITION INDUSTRIAL PTE LTD</u>	
Address		Claims Officer's Name <u>ELMER ALONSO</u>	
Telephone No.		Telephone No. <u>9245 2054</u>	
Date	Email	Date	Claim Officer Signature
<u>18/7/19</u>		<u>18/7/2019</u>	<u>[Signature]</u>
Authorized Signature		Claim Officer Signature	
<u>[Signature]</u>		<u>[Signature]</u>	

SINCHONG MATECO LTD
 ONE KIA BRANCH
 11 TANJONG KATONG ROAD
 #B1-31, SINGAPORE 437157
 TEL: 6702-2482 FAX: 6702-2481

18/7/19 / 4 35P



OD REC
AIG

DATE OF REGN:
ENGINE NO:

JOB CARD

DATE: 15/07/2017
TIME: 5:18
MILEAGE: 55475
FUEL TANK LEVEL:
①
E 1/4 1/2 3/4 F
JNo.

CUSTOMER REQUEST / SERVICE QUOTATION

DATELINE	ETD	SERVICE ADVISOR	BLOCK NO	VEHICLE NO
Visit Time	Time			685 47941
WICK SERVICE:	☐ MINERAL OIL	☐ SYNTHETIC OIL	FRONT RETURN	SPRINKLES RETURN
N SERVICE	☐ 1K ☐ 5K ☐ 10K	☐ 5W20 ☐ 5W40	☐ Yes ☐ No	☐ Cash ☐ Card
oil Ser	☐ 5K/10K(A) ☐ 20K(R) ☐ 40K(C)	☐ 0W-30 ☐ 5W-50	☐ ROTATE & BALANCE TYRE	
MP	☐ NPMP1(A) ☐ NPMP2(B) ☐ NPMP3(A) ☐ NPMP4(C) ☐ ATP ☐ CVT			
CIL USA DOOR BUSTER	☐ CBYME OB & MICRO FILTER	☐ NC 250 NC LUBRICANT	☐ FRP ENGINE REFRESH	
BYON	☐ BYOM2 WAX & POLISH WHOLE VEHICLE	☐ LC LEATHER CLEAN & TREATMENT	☐ WOTMA	☐ WOTRO MAGIC WINDSCREEN COATING
IN No	Code	Job Description		

DRIVER DECIDED TO LEAVE THE VEHICLE
CARD CASH CARD
FRONT CAMERA
THROTTLE
Sunglasses
Cable

Quotation
Amount

TERM: CASH

NOTE:

Quotation may vary and will only be finalised upon completion of repairs.

Name

Signature of Customer Representative

Tel

IN NO

COLLECTION SLIP

TEL: 6498 8866 / 87028000
COLLECTION FRS
8:00am - 5:30pm
9:00am - 5:30pm

STOMER NAME

TEIN

TIME IN

NTACT PERSON


TEL

WE DO NOT OVERSEE ANY STOMER STOMER CASH VALUABLES OR IMPORTANT ITEMS IN THE VEHICLE
AGREEMENT WILL BE Liable FOR LOSS OF CASH VALUABLES OR ANY IMPORTANT ITEMS FROM THE VEHICLE

O - Dent

X - Scratch

☐ See attachment for detail illustration



PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875



STK AUTO (S) PTE LTD

DID : 63860669

Fax : 63860669

HP : 97519596

Date : 19/07/2019

TP Vehicle Number : YP1119E

To : AXA INSURANCE PTE LTD

Attn : Motor Claim Department

Owner : SINCHONG MEHECO LTD
AIG ASIA PACIFIC INSURANCE PTE LTD

Certificate Number : 1700042883-01

Accident Date : 18/07/2019

Vehicle Number : GBG4794E

Make & Model : NISSAN NV350

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
List Item			
1	FRONT BUMPER / Cut	\$ 534.70	
10	FRONT BUMPER RETAINER RH X NN	\$ 147.00	
2	FRONT BUMPER RETAINER LH / mis	\$ 147.00	
2	FRONT BUMPER BRACKET RH X	\$ 104.70	
1	FRONT BUMPER BRACKET LH X	\$ 104.70	
1	FRONT BUMPER FOG LAMP X	\$ 311.80	
1	FRONT BUMPER FOG LAMP COVER X	\$ 107.00	
1	FRONT BUMPER TOWING X	\$ 55.00	
1	FRONT BUMPER REINFORCEMENT X	\$ 630.00	
1	FRONT BUMPER LOWER GRILLE X	\$ 165.80	
2	FRONT GRILLE X	\$ 495.00	
1	FRONT GRILLE LOGO X	\$ 59.70	
2	LH HEADLAMP / Cut	\$ 403.00	
3	LH HEADLAMP BRACKET X	\$ 98.50	
4	LH FRONT DOOR / BT	\$ 1,350.00	
1	LH FRONT DOOR STEP PANEL X Repair	\$ 123.00	
1	LH FRONT DOOR STEP PANEL GARNISH / mis	\$ 94.30	
1	LH FRONT DOOR PILLAR X Repair	\$ 143.50	
1	LH FRONT DOOR INNER TRIM BOARD ?	\$ 550.70	
1	LH FRONT DOOR LOCK X	\$ 216.70	
1	FRONT SUPPORT PANEL X NN	\$ 1,450.60	
1	LH WING MIRROR WITH MOTOR / dis	\$ 520.50	
1	LH WING MIRROR MOTOR COVER / mis	\$ 150.80	
1	LH WING MIRROR BASE COVER / cut	\$ 190.40	
1	WASH TANK X NN	\$ 222.10	
1	RH CORNER PANEL X Repair	\$ 240.00	
	Sub Total	\$ 8,081.80	
	Discount 10% on Parts	\$ (808.18)	
		\$ 7,273.62	

PAGE : 1

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875



Date: 19/07/2019

STK AUTO (S) PTE LTD

DID: 63860669

Fax: 63860669

HP: 97519596

TP Vehicle Number: YP1119E

To: AXA INSURANCE PTE LTD

Attn: Motor Claim Department

Owner: SINCHONG MEHECO LTD

AIG ASIA PACIFIC INSURANCE PTE LTD

Certificate Number: 1700042883-01

Accident Date: 18/07/2019

Vehicle Number: GBG4794E

Make & Model: NISSAN NV350

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
Special Nett Item			
	LH FRONT DOOR COMPANY TELPHONE STICKER	\$ 220.00	X NN
	LH FRONT DOOR COMPANY STICKER	\$ 50.00	
	FRONT BUMPER CLIPS	\$ 50.00	
	LH FRONT DOOR GLASS SEALANT	\$ 50.00	X
	SUB TOTAL:	\$ 370.00	
Labour & Misc			
	TO CHECK ALL NECESSARY WIRINGS	\$ 50.00	30
	TO RUST PROOF ON AFFECTED AREAS	\$ 100.00	X NN
	TO REMOVE & REFIX LH FRONT DOOR	\$ 60.00	
	TO REMOVE & REFIX LH FRONT DOOR GLASS	\$ 150.00	60
	TO REMOVE & REFIX LH FRONT DOOR TERIOR	\$ 150.00	
	COMPONENTS TO FACILITATE REPAIRS	\$ 100.00	X NN
	LABOUR TO FACILITATE REPAIR	\$ 1,200.00	400
	LABOUR & SPRAY PAINTING	\$ 1,200.00	600
	Sub Total	\$ 3,010.00	
	Sub Total	\$ 10,653.62	
	7% GST	\$ 745.75	
	Total	\$ 11,399.37	

PAGE: 2

STK AUTO (S) PTE LTD 8 KAKI BUKIT AVENUE 4 #03-21 SINGAPORE 415875 | Tel: 63860669 |

Company Registration No.: 201539883N

4 Days.
Lumpsum repair.
After repair photos.
Eno Qiang - 82880282
Not Authorised.
22/7/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Veron Chen (LKKAUTO)

From: STK STK <stkautosg@gmail.com>
Sent: Monday, 29 July 2019 1:03 PM
To: Veron Chen (LKKAUTO)
Subject: Re: GBG 4794E-DOA: 18/7/2019 (AIG OD)
Attachments: GBG4794E AMENDED GIA REPORT 1 TP 18.07.2019 (1).PDF

Dear Veron

Please refer to attached GIA Report.

Thank you

Yours sincerely

Tan Guohua

Chief Executive Officer

STK AUTO (S) PTE LTD | www.stkauto.com.sg

Mobile: (65) 9123 7949 | Tel: (65) 63860669

8 Kaki Bukit Ave 4 #03-21 Singapore 415875 @PREMIER



Veron Chen (LKKAUTO) <veronchen@lkkauto.com> 于2019年7月29日周一 下午12:45写道 :

Dear Guo Hua,

Noted with thanks.

Kindly forward addendum GIA for our record purpose.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: STK STK <stkautosg@gmail.com>

Sent: Monday, 29 July 2019 9:31 AM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: Re: GBG 4794E-DOA: 18/7/2019 (AIG OD)

Dear Ms Chen

The owner change to third party claim.

Thank you

Yours sincerely


Tan Guohua

Chief Executive Officer

STK AUTO (S) PTE LTD | www.stkauto.com.sg

Mobile: (65) 9123 7949 | Tel: (65) 63860669

3 Kaki Bukit Ave 4 #03-21 Singapore 415875 @PREMIER



Veron Chen (LKKAuto) <veronchen@lkkauto.com> 于2019年7月26日周五 下午4:17写道 :

Dear Guo Hua,

Vehicle excess \$800/-.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 24 July 2019 12:01 PM

To: stkautosg@gmail.com; SUR <sur@lkkauto.com>

Subject: GBG 4794E-DOA: 18/7/2019 (AIG OD)

Dear Guo Hua,

As instructed by our client , please proceed to repair the **insured vehicle GBG 4794E on Lump Sum Repair (Excess TBA).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/07/2019 15:45
Date Of Accident	18/07/2019 12:00
Exact Location Of Accident	193 GUILLEMARD ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	G8G4794E
Insured/Policyholder	
Name Of Registered Owner	SINCHONG MEHECO LTD
Co Reg No	A199205430H
Email Address	LIMNEN235@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98815780
Alternative Phone No	OFFICE-98815780

Vehicle Particulars

Manufacturer	NISSAN
Model	NV350-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700042883-01
Cover Note Number	

Driver

Name of Driver	VINCENT LIM TZE NEN
NRIC No	G2241964T
Date Of Birth	23/11/1991
Occupation	OUTDOOR
Date Of Driving Pass	12/04/2016
Driving Experience	3 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98815780
Fax Number	
Contact Number	
Email Address	LIMNEN235@GMAIL.COM

Address	10 JALAN KILANG TIMOR #02-01 LTH BLDG
Postcode	159306
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACHED SKETCH PLAN AND PHOTO

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP1119E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SEE AH PENG
NRIC/Passport Number	S0654342A
Contact Number	93586996
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKN8860C
-----------------------------	----------

Vehicle Make/Model/Colour	BMW/BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN HOCK KENG
NRIC/Passport Number	S0193865G
Contact Number	67412422/98522907
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SHC3959D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	KOH TENG HOCK
NRIC/Passport Number	S1443803C
Contact Number	97880234
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	SKS2001D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TANSY TAN HWEE LING
NRIC/Passport Number	S7418272J
Contact Number	96741989
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

SINCHONG MEHECO LTD
 ONE KM BRANCH
 11 TANJONG KATONG ROAD
 #B1-31, SINGAPORE 437157
 TEL: 6702-2482 FAX: 6702-2481

Date & Time:

18/7/19 / 3:30pm

Driver's Signature:

(If driver is not the policyholder)

Date & Time:

18/7/19 / 3:30pm


Reporting Centre Personnel's Signature

Name: **THOMAS ALFONSO**

NRIC/FIN NO: **G5462824L**

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

18/07/2019 - I was driving my vehicle A at 193 Guillemard Road my vehicle was stationary because of the 'que lane' and waiting for green light to go. Vehicle B was at the first lane going to Paya Lebar. Suddenly vehicle C came out from Guillemard Road going to Lor 20 Geylang and hit the vehicle B then vehicle B hit the vehicle A and D. Vehicle D hit vehicle E.

DECLARATION

SINCHONG MEHCO LTD
ONE KM BRANCH
11 TANJONG KATONG ROAD
#B1-31, SINGAPORE 437157
TEL: 6702-2482 FAX: 6702-2481

Date & Time:

18/7/19 / 3.30pm

Driver's Signature
(If driver is not the policyholder)

Date & Time: 18/7/19 / 3.30pm

Reporting Centre Personnel's Signature
Name: EIMER ALFONSO
NRC/PA No: 63462824L

