

22/03/2019

ASS. REC. BY:

REF: C53/111 19012878/T1cf30b

Special Instruction:

Surveyor: Tankich

ASSIGNMENT (Office)

From (Person): Gabriel Wee

of UL

Date/Time: 22/7/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: RKC 500IT

Insured: SHB 4215R

at Workshop in/s Garage B.

Tel: 62623295

of No. 1 Kater Street Crescent #05-55 WCFGA

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 22/7/2019

Person Contacted: Xiao Qi

Vehicle IN/OUT

Date/Time	Action/Instruction	Initials (X)
	RKC 500IT X	
	SHB 4215R X	
	Dismantle: 22/7/2019. 1240pm	



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	(Not Notified) <a href="#">Edit Reg</a>		22 Jul 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		[Created by adjuster]							
Insured:									
Main Claimant:	-								
Vehicle Reg. No.:	<b>SKC5001T</b>	Date of Loss:	19/07/2019 00:00 - :59						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	<b>SHB4215R</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Garage B Pte Ltd (HQ)</b> No. 1 Bukit Batok Cresnet, #05-55 WCEGA Plaza, 658064 Bukit Batok - Tel:								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Priya</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>PARASURAM SHANMUGAM</b> ] ... [Final Rpt due 31/07/2019]								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Monday, 22 July 2019 3:01 PM  
**To:** Jenny; 'sur@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Manivel Priyadarshini  
**Subject:** RE: PRE-REPAIR INSPECTION NOTICE FOR VEH SLJ 1413 R [ Your ref: SHB 4215 R ]  
**Attachments:** PRI - SKC 5001 T (III) dtd 22.07.2019.pdf; LIST OF INDEPENDENT SURVEYORS.DOCX

Dear Sir / Mdm

### **This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO. : SLJ1413R  
III INSURED VEHICLE NO. : SHB4215R  
DATE OF LOSS : 19.07.19

**Kindly note that DOA is 19.07.19 not 26.06.19.**

We acknowledge receipt of your email.

### **In compliance to Pre-Action Protocol for NIMA cases, we note that**

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by Priya.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

**\*\*We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

**\*\*Surveyor kindly upload this assignment to Merimen.**

**Thank You.**

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

---

**From:** Jenny [mailto:jenny@tcmg.com.sg]  
**Sent:** 22 July, 2019 2:20 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** 'Garage B' <emailgarageb@gmail.com>; 'HUI VON CHANG' <huivon.chang@gmail.com>; 'Ling

Leong Hui' <lhling@tcmg.com.sg>; Rachel Ling <jin@tcmg.com.sg>; 'Mdm Ling'  
<mdmling@tcmg.com.sg>; 'tcmg backup' <tcmg.backup@gmail.com>

**Subject:** RE: PRE-REPAIR INSPECTION NOTICE FOR VEH SLJ 1413 R [ Your ref: SHB 4215 R ]

**Importance:** High

**IMMEDIATE ATTENTION**

**WITHOUT PREJUDICE**

**Your ref: (III)(SHB 4215 R)**

**Our ref: TCMG/SKC5001T/0719/GBP**

Dear Gabriel

We refer to the above matter and to your email of even date.

Our client is not agreeable to any of your appointed panel of surveyors as the Single Joint Expert.

Our client's panel of surveyors nominated as the Single Joint Expert is as attached.

(P/S : Please acknowledge receipt of this e-mail. Thank you.)

Regards

Jenny Tham  
TOMMY CHOO, MARK GO LLC  
151 Chin Swee Road  
#14-15/16 Manhattan House  
Singapore 169876  
Tel: 6532 2455 - Fax: 6538 9850  
Email Address: [jenny@tcmg.com.sg](mailto:jenny@tcmg.com.sg)

---

**From:** Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

**Sent:** 22 July 2019 13:39

**To:** Jenny <[jenny@tcmg.com.sg](mailto:jenny@tcmg.com.sg)>

**Subject:** RE: PRE-REPAIR INSPECTION NOTICE FOR VEH SLJ 1413 R [ Your ref: SHB 4215 R ]

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,  
Gabriel Wee



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

---

**From:** Jenny [mailto:jenny@tcmg.com.sg]  
**Sent:** 22 July, 2019 11:53 AM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** 'Garage B' <emailgarageb@gmail.com>; 'HUI VON CHANG' <huivon.chang@gmail.com>; 'Ling Leong Hui' <lhling@tcmg.com.sg>; Rachel Ling <jin@tcmg.com.sg>; 'Mdm Ling' <mdmling@tcmg.com.sg>; 'tcmg backup' <tcmg.backup@gmail.com>  
**Subject:** PRE-REPAIR INSPECTION NOTICE FOR VEH SLJ 1413 R [ Your ref: SHB 4215 R ]  
**Importance:** High

**IMMEDIATE ATTENTION**

Dear Sirs

We refer to the above matter.

We attached herein a copy of our Notice of Pre-Repair Inspection for your attention.

Thank you.

*(P/S : Please acknowledge receipt of this e-mail. Thank you.)*

Regards

Jenny Tham  
TOMMY CHOO, MARK GO LLC  
151 Chin Swee Road  
#14-15/16 Manhattan House  
Singapore 169876  
Tel: 6532 2455 - Fax: 6538 9850  
Email Address: [jenny@tcmg.com.sg](mailto:jenny@tcmg.com.sg)

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling

and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

# TOMMY CHOO, MARK GO LLC

Advocates & Solicitors UEN NO : 201523418E  
(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16  
MANHATTAN HOUSE  
SINGAPORE 169876  
TEL : (65) 6532 2455  
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg

Our Ref: TCMG/SKC5001T/0719/GBP

Your Ref: SHB 4215 R

22 July 2019

*BY FAX NO. 6224-4174 &  
Email: [motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)*

**M/s India International Insurance Pte Ltd**  
64 Cecil Street#04-00  
IOB Building  
Singapore 049711

Attn: Motor Claims Department

Dear Sirs,

## PRE-REPAIR INSPECTION NOTICE

We act for **Chu XueBing**, the owner and/or driver of motor vehicle no. **SKC 5001 T**, which was involved in an accident along PIE towards Tuas before Stevens Road Exit on 26 June 2019 at 13:45 hrs.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **SHB 4215 R** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Garage B Pte Ltd, (No. 1 Bukit Batok Crescent #05-55, WCEGA Plaza, Singapore 658064 – Ms Xiao Qi - 62623295).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully



**MR LING-LEONG HUI**

cc. M/s Aden Garage Pte Ltd  
(Your ref: SKC 5001 T)

*BY E-MAIL ONLY*

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	782X
Vehicle Details	
Vehicle No.:	SKC5001T
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jul 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 KOMPRESSOR
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	27191031346068
Chassis No.:	WDD2040452A584204
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$31,019.00
Original Registration Date:	01 Sep 2011
First Registration Date:	01 Sep 2011
Transfer Count:	2
Actual ARF Paid:	\$31,019.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Aug 2021
PARF Rebate Amount:	\$18,611.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$49,301.00
COE Rebate Amount:	\$10,297.00
<b>Total Rebate Amount:</b>	<b>\$28,908.00</b>

The information contained herein is correct as at 29 Jul 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	19/07/2019 16:12
Date Of Accident	19/07/2019 13:45
Exact Location Of Accident	627 ALJUNIED ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKC5001T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHU XUEBING
NRIC No	G6240782X
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91856783
Alternative Phone No	OFFICE-91856783
<b>Vehicle Particulars</b>	
Manufacturer	MERCEDES-BENZ
Model	C180-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107691515 (CLASSIC)
Cover Note Number	
<b>Driver</b>	
Name of Driver	CHU XUEBING
NRIC No	G6240782X
Date Of Birth	20/01/1979
Occupation	OUTDOOR
Date Of Driving Pass	06/11/2009
Driving Experience	9 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91856783
Fax Number	
Contact Number	OFFICE-91856783
Email Address	NOEMAIL

Address

Postcode

423 SERANGOON CENTRAL  
#08-344

S550423

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

### General Information of the Accident

Type Of Accident SIDE SWIPE  
Weather Conditions CLEAR  
Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance?  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

### Circumstances of Accident

I WAS DRIVING ALONG ALJUNIRD ROAD ON THE LEFT SIDE GOING STRAIGHT, THERE WAS A TAXI THAT WAS MAKING U-TURN FROM THE RIGHT SIDE AFTER ALIGHTING A PASSENGER. THE SAID TAXI FRONT PORTION HIT ONTO THE RIGHT SIDE PORTION OF MY VEHICLE.

### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB4215R  
Vehicle Make/Model/Colour COMFORT TAXI  
Details Of Properties  
Vehicle Category TAXI  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**IDAC BUKIT BATON (VAC)**  
 511 Bukit Batok Street 23  
 Singapore 650543  
 Tel: 6560 3312 Fax: 6569 0772  
 Email: vacub@singnet.sg

19 JUL 2019

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jul 2019 10:10 <a href="#">Edit Reg</a>		22 Jul 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	<b>SKC5001T</b>	Date of Loss:	19/07/2019 00:00 - :59 [94 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	<b>SHB4215R</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Garage B Pte Ltd (HQ)</b> No. 1 Bukit Batok Cresent, #05-55 WCEGA Plaza, 658064 Bukit Batok - Tel:								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Priya</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 31/07/2019]								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>	<a href="#">Compose Case Mail</a>				
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SKC5001T  
[SHB4215R]  
TP

-  
Jul 19 2019 12:00AM  
[-]  
Garage B Pte Ltd

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View	View in Browser <input type="button" value="v"/>	
<b>Photos/Images</b>			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
2	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
3	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
4	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
5	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
6	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
7	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
8	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
9	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
10	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
11	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
12	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
13	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
14	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
15	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
16	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
17	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
18	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
19	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
20	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
21	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
22	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
23	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
24	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
25	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
26	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
27	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
28	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
29	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
30	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
31	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
32	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
33	29/07/19 12:30	General View		Load JPG	<input checked="" type="checkbox"/>
34	29/07/19 12:30	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
35	29/07/19 12:30	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
36	29/07/19 12:30	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
37	29/07/19 12:30	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	29/07/19 12:30	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	23/07/19 08:49	Singapore Accident Statement	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer  
Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19012878/T1CF3E2

Date: 30/07/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SKC5001T

Insured Vehicle No : SHB4215R

Date of Loss: 19/07/2019

Nature of Claim: TP Claim No: N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKC5001T

Make &amp; Model: MERCEDES-BENZ C180, 1.6 Kompressor (A)

Engine No: 27191031346068

Reg. Date: 01/09/2011 (Man. Year: 2011)

Chassis No: WDD2040452A584204

Colour: Black

Odometer: 120308 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 22/07/2019

Date Inspected: 23/07/2019 Inspected At:

Garage B Pte Ltd (HQ)  
No. 1 Bukit Batok Crescent, #05-55  
WCEGA Plaza  
Singapore 658064

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 30 Jul 2019)
<b>Parts:</b> 143	MERCEDES-BENZ C180 1.6 Kompressor (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKC5001T)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >