

22/03/2012

ASS. REC. BY:

REF:

CS3/SMD19012888/FCB

Special Instruction:

Surveyor: Kam

ASSIGNMENT (Office)

From (Person):

Thelma choo

of

SMD

Date/Time:

22/7/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJL 5455G

Insured:

SKA 879X

at Workshop m/s

Lian Heng Painter Co

Tel:

9863 2371 Henry.

of

160 Sin Ming Dr #06-10 Sin Ming Autocity

Policy No:

D19MTPV01010267

Claim No:

CMTD1903354

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/7/19

CA / REV / REP. / REV 24 HRS

"rup"

H.O.D. Endorsement:

Date/Time:

22.7.19 4.10p.m

Person Contacted:

Henry

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SKA 879X NS/INC15007127/H1gy/352 DOA=24/4/15

SJL 5455G X

19/8/19 @ 4.27pm Henry will check & call CES.

Dismantle: 4/9/2019

After repair: 6/9/2019

REF: Ram

REF:

SNO

ASSIGNMENT

From

Date: 02/9/19

Veh No. SJL 5455G

Yr Fagn. Dec 2008

Estimated Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SJL 5455G

Make: Honda Stream

CC 1799

at Workshop m/s

LIAN HENG PAINTER CO.

Colour: Black

A/C: Insured / Std / NI / NA

of 01K 160 s/m price #06-10 s/m Auto City.

Sp. Reading 135985

T/Ratio: Insured / Std / NI / NA

Insured

Eng/No:

Policy No.

C/No: RN6-1084847

Claims No.

Gen. Cond: Good (Fair) / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil (S/Rim) / STD A/Rim or

(Policy Condition)

Tyre Size: F: 225/45 R17

R: 225/45 R17

Remark: The veh had commenced its repair at the time of inspection.



BSY / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal. 4 mm

R/Bal. 4 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal. 4 mm

L/Bal. 4 mm

Est. Repairs:

days

Res.: Yes or No

D.O.A. 11/07/2019

D.O.I. 3/9/2019

Lum Sum:

%

3 Val.: Yes or No

Survey held at Lian Heng Painters

CA / REV / REP. / 24 HRS

PRS

Des. of Damages: (Frt) / Rear / O/S / (N/S) / UIC / Rooftop or

Front / N/S & N/S front

Date:

Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range: \$2000-\$3000

Repair days: 4 days

13/9/2019

MV: \$30000

PV: \$13625

NV: \$16000

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 4

1)

☐

: Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format

PRS

Lump Sum / I.B.I: (\$

Survey Fee:

Transportation:

___ S + RS ___ \$

Photos

Others

TOTAL

100

60

60

11

231

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jul 2019		22 Jul 2019 16:06 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	TAN CHIA LONG RAYMOND, Co. Reg. No.: S8201039D		
Main Claimant:	ONG JIE TING GLADYS, ID: S9519288B		
Vehicle Reg. No.:	SJL5455G	Date of Loss:	11/07/2019 13:00 - :59
Claim Type:	TP / CMTD1903354	Policy/Cover Note No.:	D19MTPV01010267 (Comprehensive)
Vehicle Reg. No. (Insured):	SKA879X	Policy No. (Claimant):	
		Excess:	
Repairer:	Lian Heng Painter Company () 160 SIN MING DRIVE, #06-10 SIN MING AUTOCITY, 575722 Sin Ming - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/07/2019]		
Driver/Custodian (Insured):	NG SOK CHEW (), NRIC: S1336922D, Tel: +6598934876 Email:		
Adj Asg. Remarks:	WS: NOMY/HENRY 64535779/ 98632371		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 22 July 2019 4:05 PM
To: Serene Tan; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Choo, Thelma; Ye, Yong Kang Melvin
Subject: CMTD1903354/THE - PRI(LKK)/ SKA879X & SJL5455G ACC ON 11.07.19

Our Reference : CMTD1903354/THE
Your Reference: MN/IG/L1/1913181/st

Without Prejudice
EMAIL ONLY

Date: 22/07/2019

OUR Email: motorsurvey@sompo.com.sg

Attention:
M/S M NEDUMARAN & CO

Dear Serene,

ACCIDENT INVOLVING SKA879X & SJL5455G ON 11.07.2019

We refer to your email of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Serene Tan [mailto:serene.tan@mneduco.com.sg]

Sent: Monday, July 22, 2019 3:51 PM

To: Teo, Grace

Cc: Choo, Thelma; Ye, Yong Kang Melvin

Subject: RE: CMTD1903354/THE - PRI/ SKA879X & SJL5455G ACC ON 11.07.19

Our Ref : MN.IG.L1.1913181.st

WITHOUT PREJUDICE
SAVE AS TO COSTS

NOTICE TO INSURERS OBJECTING TO THE LIST OF MOTOR SURVEYORS PROVIDED WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2.6 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)

Dear Grace,

1. We refer to your email below.
2. We are instructed by our client, ONG JIE TING GLADYS, the claimant and/or Lian Heng Painter Company, the motor workshop for **SJL 5455G** that they are **not** agreeable to the appointment of the motor surveyors as stated in your said email.
3. **In compliance with The State Courts Practice Directions (Amendment No. 1 of 2016)**, we propose to use one of the below mentioned motor surveyor to conduct the joint pre-repair survey ("hereinafter referred to as PRS") as a Single Joint Expert ("hereinafter referred to as a SJE").

1.	NICKY SEAH (Absolute Appraisal Services)	6.	ANDREW HOW (Prominent Appraiser Services)
2.	MICHAEL YAP TECK CHYE (MC-COY Appraiser Pte Ltd)	7.	NG KONG BENG PATRICK (Carlink Consultancy)
3.	DIXON YEO (Treasure Appraisal Services)	8.	ANANDA KUMAR BISWAS S/O B N BISWAS (United Appraisal & Management Pte Ltd)
4.	LOI BOON JUAN (PAR Automotive Consultancy)	9.	DENNIS YAP TECK WEE (PAL's Appraiser Pte Ltd)
5.	AMAS ONG (AEON Auto Consultants LLP)	10.	ANDY YAP TECK LEE (LCW Appraiser Pte Ltd)

4. Please let us know **within two (2) working days** whether you agree to the appointment of any of the above motor surveyors as proposed by the claimant and/or the motor workshop as a Single Joint Expert ("hereinafter referred to as "SJE").

Thanks & Best Regards,
(For and on behalf of Mr Nedumaran Muthukrishnan)
Serene Tan (Ms)
M NEDUMARAN & CO
Advocates & Solicitors
Commissioner for Oaths

Branch Office:
11 Sin Ming Road
#B2-09 (Unit 2), Thomson V Two
Singapore 575629
Tel: 6509-8480 / 6509-8481
Fax: 6509-8482
Email : serene.tan@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Monday, 22 July 2019 3:42 PM
To: Serene Tan <serene.tan@mneduco.com.sg>
Cc: Choo, Thelma <thelma.choo@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD1903354/THE - PRI/ SKA879X & SJL5455G ACC ON 11.07.19

Our Reference : CMTD1903354/THE
Your Reference: MN/IG/L1/1913181/st

Date: 22/07/2019

Without Prejudice
EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Attention:
M/S M NEDUMARAN & CO

Dear Serene,

ACCIDENT INVOLVING SKA879X & SJL5455G ON 11.07.2019

We refer to your Notice of Accident dated 22/07/2019.

Please be informed that **Ms. Thelma Choo** is the handler of this case who can be contacted at 63224 681.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom

From: Serene Tan [<mailto:serene.tan@mneduco.com.sg>]
Sent: Monday, July 22, 2019 2:35 PM
To: Claims - Motor Survey
Cc: Claims - Motor Survey
Subject: PRE-REPAIR SURVEY

URGENT

WITHOUT PREJUDICE

Our Ref: MN.IG.L1.1913181.st

Dear Sirs,

Notice of Accident dated 22/7/2019 attached herein.

Thanks & Best Regards,
(For and on behalf of Mr Nedumaran Muthukrishnan)
Serene Tan (Ms)
M NEDUMARAN & CO
Advocates & Solicitors
Commissioner for Oaths

Branch Office:
11 Sin Ming Road
#B2-09 (Unit 2), Thomson V Two
Singapore 575629
Tel: 6509-8480 / 6509-8481
Fax: 6509-8482
Email : serene.tan@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
*Owner ID Type:		Singapore NRIC
Owner ID:	288B	
Vehicle Details		
Vehicle No.:	SJL5455G	
Vehicle to be Exported:	No	
Intended Deregistration Date:	03 Sep 2019	
Vehicle Make:	HONDA	
Vehicle Model:	STREAM 1.8X A	
Primary Colour:	Black	
Manufacturing Year:	2008	
Engine No.:	R18A1794140	
Chassis No.:	RN61084847	
Maximum Power Output:	103.0 kW (138 bhp)	
Open Market Value:	\$18,520.00	
Original Registration Date:	01 Dec 2008	
First Registration Date:	01 Dec 2008	
Transfer Count:	1	
Actual ARF Paid:	\$18,520.00	
Intended PARF Rebate Details		
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:	-	
PARF Rebate Amount:	\$0.00	
Intended COE Rebate Details		
COE Expiry Date:	30 Nov 2023	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	5	
PQP Paid:	\$16,061.00	
COE Rebate Amount:	\$13,625.00	
Total Rebate Amount:	\$13,625.00	
Message		
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.		

The information contained herein is correct as at 03 Sep 2019

Remaining : 4 years 4 months 19 days (52.6 months) OK

Depn: \$7000 / - (yearly) \$583.33 (monthly)

$$52.6 \times \$583.33 = \$30683.15$$

Exclusive Roadshow Deal - up to **\$10,000** off all Toyota Models.

Bedok Mall, Level 1 Atrium, 28 Aug – 3 Sep 2019



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2009 Honda Stream at \$39,800. \$0 drive away



Very good condition ! Low monthly installment ! \$0 drive away !
StarAd



rowse by Category ▾

« Back (1 2 3 4 5 6) Next »

Sort by Date Posted ▾

20 results/page ▾

106 vehicles

Honda Stream

Advanced Search



Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Stream	Any	Any	Any	Any	Any	Any	Available



Honda Stream 1.8A X (COE till 07/2024)

\$38,800

\$8,030 /yr

03-Jul-2009

1,799 cc

98,000 km

MPV

Available

1 Owner! New Paintwork / Leather. Fully Done Up. 6 Months Warranty. 100% Loan Available.

Very good condition ! Low monthly installment ! \$0 drive away !

Viking Motor Pte Ltd

Posted: 03-Sep-2019

Tags: 2009 Honda Stream, 2009 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A X (New 5-yr COE)

\$36,800

\$7,350 /yr

17-Jul-2009

1,799 cc

-

MPV

Available

Graded **B** by **STA**

2.88% Per Annum. \$688 Monthly. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. In House Finance, In House Workshop And Paintshop All Under One Roof. Buy With Assurance. Warranty Booklet And STA Report Will Be Given.

2.88% P.A. \$2800 Down, Monthly From \$688, Sta "B", 2 Yrs Warranty Engine, Gearbox

GV Credit Pte Ltd

Posted: 03-Sep-2019

Tags: 2009 Honda Stream, 2009 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A (COE till 08/2023)

\$28,000

\$7,090 /yr

16-Aug-2008

1,799 cc

148,250 km

MPV

Available

Consignment Code: A330 Flexible And Attractive Loan Available. Trade-In Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

Posted: 02-Sep-2019

Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A RSZ (COE till 05/2028)

\$48,800

\$5,630 /yr

02-May-2008

1,799 cc

-

MPV

Available

6 Months Warranty, Brand New Engine Mounting And Brake Pad, Loan Available, Trade In Welcome.

Posted: 02-Sep-2019

Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



Honda Stream 1.8A (COE till 01/2023)

\$23,800

\$7,030 /yr

22-Jan-2008

1,799 cc

-

MPV

Available

Very Clean Interior And Own By Non Smoker. Fuel Saving Yet Powerful Drive. Accident Free Still In Original Condition Since Day. Feel Free To Visit And Test Drive.

Posted: 02-Sep-2019

Tags: 2008 Honda Stream, 2008 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda



Honda Stream 1.8A (COE till 07/2024)

\$36,800

\$7,620 /yr

02-Jul-2009

1,799 cc

-

MPV

Available

Graded **B** by **STA**

Per Annum. \$688 Monthly. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. In House Finance, In Workshop And Paintshop All Under One Roof. Buy With Assurance. Warranty Booklet And STA Report Will Be Given.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/07/2019 14:46
Date Of Accident	11/07/2019 13:30
Exact Location Of Accident	ANG MO KIO AVE 6 TOWARDS YISHUN (SLE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL5455G
Insured/Policyholder	
Name Of Registered Owner	ONG JIE TING GLADYS
NRIC No	S9519288B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92339287
Alternative Phone No	OTHERS-92339287
Vehicle Particulars	
Manufacturer	HONDA
Model	STREAM
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800140699
Cover Note Number	
Driver	
Name of Driver	FONG SOON LOONG GERALD
NRIC No	S8843967H
Date Of Birth	20/10/1988
Occupation	OUTDOOR
Date Of Driving Pass	26/07/2018
Driving Experience	0 YEAR AND 11 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-87504099
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 279C SENGKANG EAST AVENUE #05-533
Postcode	543279
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - BOYFRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ONG GLADYS GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKA879X
Vehicle Make/Model/Colour	TOYOTA ESTIMA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG SOK CHEW
NRIC/Passport Number	S1336922D
Contact Number	98934876
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 12 JUL 2019

(P=46hrs)

Driver's Signature

(If driver is not the policyholder)

Date & Time: 12 JUL 2019

(P=46hrs)

Reporting Centre Personnel's Signature

Name: Poh Kwee Choo

NRIC/FIN No.: S6840583A

SKETCH PLAN

green traffic light

Ang Mo Kio Ave 6 Towards (Yishion SLE)

A SJL 5K55G

B SKA 879X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date: 11/07/2019

Time: 1:30 pm

I was travelling along Ang Mo Kio Ave 6 Towards SLE when suddenly vehicle "B" SKA 879X cut into my lane ~~with~~ ^{recklessly} and collided onto my vehicle SJL 5K55G.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

12 JUL 2019

Driver's Signature

(If driver is not the policyholder)

Date & Time: 12 JUL 2019

Reporting Centre Personnel's Signature

Name: Pdt. Kwee Choe

NRIC/FIN No.: S6840583A

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jul 2019		22 Jul 2019 16:06 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN CHIA LONG RAYMOND, Co. Reg. No.: S8201039D								
Main Claimant:	ONG JIE TING GLADYS, ID: S9519288B								
Vehicle Reg. No.:	SJL5455G	Date of Loss:	11/07/2019 13:00 - :59 [127 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1903354	Policy/Cover Note No.:	D19MTPV01010267 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKA879X	Policy No. (Claimant):							
		Excess:							
Repairer:	Lian Heng Painter Company () 160 SIN MING DRIVE, #06-10 SIN MING AUTOCITY, 575722 Sin Ming - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 31/07/2019]								
Driver/Custodian (Insured):	NG SOK CHEW (), NRIC: S1336922D, Tel: +6598934876 Email:								
Adj Asg. Remarks:	WS: NOMY/HENRY 64535779/ 98632371								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJL5455G (CMTD1903354)

[SKA879X]

TP































ONG JIE TING GLADYS

Jul 11 2019 1:00PM

[TAN CHIA LONG RAYMOND]

Lian Heng Painter Company

Upload Documents Upload Photos Compose New Letter		View View in Browser
Assessment Reports		1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)
1	22/07/19 16:05	Accident Statement From: SC - Reg. No: SKA879X, Claimant: TAN CHIA LONG RAYMOND
		Thumbnail <input type="checkbox"/> <input checked="" type="checkbox"/>
		Load HTM
Photos/Images		3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	03/09/19 10:10	General View
2	03/09/19 10:10	General View
3	03/09/19 10:10	General View
4	03/09/19 10:10	General View
5	03/09/19 10:10	General View
6	03/09/19 10:10	General View
7	03/09/19 10:10	General View
8	03/09/19 10:10	General View
9	03/09/19 10:10	General View
10	03/09/19 10:10	General View
11	03/09/19 10:10	General View
12	03/09/19 10:10	General View
13	03/09/19 10:10	General View
14	03/09/19 10:10	General View
15	03/09/19 10:10	General View
16	03/09/19 10:10	General View
17	03/09/19 10:10	General View
18	03/09/19 10:10	General View
19	03/09/19 10:10	General View
20	03/09/19 10:10	General View
21	03/09/19 10:10	General View
22	03/09/19 10:10	General View
23	03/09/19 10:10	General View
24	03/09/19 10:10	General View
25	03/09/19 10:10	General View
26	03/09/19 10:10	General View
27	03/09/19 10:10	General View
28	03/09/19 10:10	General View
29	03/09/19 10:10	General View
30	03/09/19 10:10	General View
31	03/09/19 10:10	General View
32	03/09/19 10:10	General View
33	03/09/19 10:10	General View
34	03/09/19 10:10	General View
35	03/09/19 10:10	General View
36	03/09/19 10:10	General View
37	03/09/19 10:10	General View
38	03/09/19 10:10	General View
39	16/09/19 12:18	Photographs of Damaged Parts

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
40	16/09/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	16/09/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	16/09/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	16/09/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	16/09/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	16/09/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	16/09/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	16/09/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	16/09/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	16/09/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	16/09/19 12:21	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	22/07/19 15:43	Pre-Repair Survey + GIA	 Load PDF	
2	22/07/19 16:19	Pre-Repair Survey - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19012888/FCF3E2

Date: 17/09/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01010267
Claimant Vehicle No :	SJL5455G	Insured Vehicle No :	SKA879X
Date of Loss:	11/07/2019	Nature of Claim:	TP
		Claim No:	CMTD1903354

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL5455G	Engine No:	R18A1794140
Make & Model:	HONDA STREAM, 1.7 (A)	Chassis No:	RN61084847
Reg. Date:	01/12/2008 (Man. Year: 2008)	Odometer:	135985 km
Colour:	Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	22/07/2019	
Date Inspected:	03/09/2019 Inspected At:	Lian Heng Painter Company 160 SIN MING DRIVE, #06-10 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Sep 2019)
Parts:	M1-MPV	HONDA STREAM 1.7 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL5455G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >