

ASS. REC. BY:

REF:

CS/FCI 19012895/UN f322

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person):

Henry Kao

of

FCI

Date/Time:

20/7/19

Estimated Cost:

Bill to:

OD/IT/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLD 2239C

Insured:

SHD 8628X

at Workshop m/s

KAM MOTOR

Tel:

6846 5672

of

15 UBI RD 4

Policy No:

Claim No:

D19004751MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/7/19

CA / REV / REP. / REV 24 HRS

w/p

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate ()

SLD 2239C X

SHD 8628X X

24/7/19

Email preli revised to FCI

REF: P01

ASSIGNMENT

From: _____ Date: 23.7.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SUN 2239C

at Workshop m/s Kah motor

of 15 ubi road 4

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 2 up m owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 100k.

IDAC Accident Rpt: 9 Consistent? : Yes or No

GLA / PR Seen: 9 Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"up" 21054628

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLD 2239C Yr Regn: 6/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Honda Odyssey C.C. 2356

Colour: Purple A/C: Insured / Std / NI / NA

Sp. Reading: 75995 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JH/MRC/1890 GC 203245

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 215/55 R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. 6 mm L/Bal. 6 mm


D.O.A. 18/7/19 D.O.I. 23/7/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.



13/8/19 confirmed final by \$8168.42 with MR You. (Red 1803-55, 1810)

RECEIVED 15 AUG 2019

14/8/2019

Date/Time. File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time. File Return to?

2) 14/8 - typist

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: CWS

Lump Sum / I.B.I: (\$ 8168.42)

170

50

50+50

75

395

MOTOR SURVEY ASSIGNMENT

| | | |
|---------------------------|---|--------------------------------------|
| Date | 22-07-2019 | Our Ref No. D19004751MFSH |
| Accident Date | 18-07-2019 | Claim Type. Third Party |
| Insured Vehicle | SHD8628X | Third Party Vehicle. SLD2239C |
| Survey Location | 15 UBI ROAD 4 | |
| Contact Person. | YOU PO SOON | |
| Contact No. | 68465672/ 0 | Fax No. 0 |
| Survey Type | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: | |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD | |
| Contact Person | NA | Fax No. 68416315 |
| Contact Number. | NA | |

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

| | | |
|--------------------------|-------------------------|--------------------------------|
| Cc : Workshop | KAH MOTOR CO SDN BHD | Attention. NIL |
| Cc : TP Solicitor | NA | TP Solicitor Fax No. NA |
| Officer Incharge | HENRY KAO | |

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 24 July 2019 12:27 PM
To: 'CWS Motor Claims'; SUR
Cc: 'Henry Kao'
Subject: RE: SURVEY ASSESSMENT - D19004751MFSH/1
Attachments: SLD 2239C PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLD 2239C
Date of survey: 23/7/2019
Number of days : 7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 22 July 2019 4:50 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004751MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004751MFSH

Our ref: CS/FCI19012895/Uvf3

DATE: 24/7/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO SLD 2239C


We thank for your instruction on 22/7/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 23/7/2019 at the premises of M/s KAH MOTOR CO SDN BHD

| | |
|--------------------------|---------------|
| Workshop Estimate Amount | : S\$9,921.12 |
| Revised Estimate Amount | : S\$3,611.02 |
| "Check" Items Amount | : S\$5,928.72 |
| Market Value | : S\$ |
| LTA Reimbursement Value | : S\$ |
| Nett Value | : S\$ |

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|---------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 103G |
| Vehicle Details | |
| Vehicle No.: | SLD2239C |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 02 Nov 2020 |
| Vehicle Make: | HONDA |
| Vehicle Model: | ODYSSEY 2.4 EXV-S CVT SR NAVI RES |
| Primary Colour: | Purple |
| Manufacturing Year: | 2016 |
| Engine No.: | K24W72011498 |
| Chassis No.: | JHMRC1890GC203245 |
| Maximum Power Output: | 129.0 kW (172 bhp) |
| Open Market Value: | \$31,538.00 |
| Original Registration Date: | 08 Jun 2016 |
| First Registration Date: | 08 Jun 2016 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$36,154.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 07 Jun 2026 |
| PARF Rebate Amount: | \$27,115.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 07 Jun 2026 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$49,156.00 |
| COE Rebate Amount: | \$27,513.00 |
| Total Rebate Amount: | \$54,628.00 |

The information contained herein is correct as at 24 Jul 2019

OK

New Cars

Used Cars

Sell My Car


Directory

Products

Insurance

Articles

F



CYCLE & CARRIAGE GARAGE SALE

Management and demo units from **\$50,000** with COE

RSVP NOW

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

08/2018 Nissan NV200A at \$47.8k



Agent unit with warranty! Like brand new! Immediate delivery! Full accessories! Net Link Partners StarAd



HIN LUNG A
HoBee Group
One Stop Car
Finance, Insurance
New and Used Car

Browse by Category ▼

« Back (1 2) Next »





Sort by Date Posted

21 vehicles

Odyssey

Advanced Search



| | Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | V |
|--|---------|----------------------------|---|--------------|-------------|----------|-----------|---|
| Search Selection | Odyssey | | Any | Any | 2016 | Any | Any | |
|  | Honda | Odyssey 2.4A EX-S 8-Seater | \$99,800 | \$13,030 /yr | 02-Mar-2016 | 2,356 cc | 32,000 km | |
| Hard To Come By 8-Seaters. Comes With Bidded Number X88Y Owner Reluctant Sale But Due To Overseas Work Commitment. Genuine Low Mileage. Single Owner, Pre-Loved Condition With Zero Repairs Required. Always Shelter Parked. Flexible And High Loan Packages,... | | | | | | | | |
| Posted: 23-Jul-2019 | | | Tags: 2016 Honda Odyssey, 2016 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda | | | | | |
|  | Honda | Odyssey 2.4A EXV-S Sunroof | \$112,800 | \$13,330 /yr | 07-Sep-2016 | 2,356 cc | 38,250 km | |
| Immaculate Condition, Kah Motor Agent Unit With Warranty, Most Popular Spacious 7 Seaters MPV, Trade In And Loan Available, Hurry Make An Appointment To View This Unit Now. | | | | | | | | |
| Henly Enterprises Co | | | Posted: 23-Jul-2019 | | | | | |
| | | | Tags: 2016 Honda Odyssey, 2016 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda | | | | | |
|  | Honda | Odyssey 2.4A EXV-S Sunroof | \$112,800 | \$13,730 /yr | 07-Jul-2016 | 2,356 cc | 29,000 km | |
| Enjoy Unrivalled Travelling Comfort In This Popular MPV, This Is A Top Choice If You Are Looking For A Family Car. Call Our Sales Consultants For A View Today! | | | | | | | | |
| Inchcape Pre-Owned | | | Posted: 20-Jul-2019 | | | | | |
| | | | Tags: 2016 Honda Odyssey, 2016 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda | | | | | |
|  | Honda | Odyssey 2.4A EXV-S Sunroof | \$94,800 | \$12,010 /yr | 22-Feb-2016 | 2,356 cc | - | |
| Full Loan Available At \$1k Plus, We Can Help To Conver To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Fast, Easy And Flexible Loan Approval! Buy With Confidence! Viewing And Test Drive Available Daily Including Weekend From 10.30 A.M. To 6.30 P.M.! | | | | | | | | |
| 88 Motor Trading | | | Posted: 20-Jul-2019 | | | | | |
| | | | Tags: 2016 Honda Odyssey, 2016 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda | | | | | |

**The Hyundai Avante is poised and composed**

The facelifted Hyundai Avante brings with it a host of style and equipment enhancements, adding to an already appealing family sedan Find out more!

Compare

1a Odyssey 2.4A EXV-S \$98,800 \$12,510 /yr 02-Feb-2016 2,356 cc 93,000 km

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GlA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-------------------|
| Date Of Report | 19/07/2019 13:04 |
| Date Of Accident | 18/07/2019 17:10 |
| Exact Location Of Accident | PIE TOWARD CHANGI |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|-----------------------|
| Vehicle Registration Number | SLD2239C |
| Insured/Policyholder | |
| Name Of Registered Owner | NG KAH SER |
| NRIC No | S1461103G |
| Email Address | NGKAHSER@YAHOO.COM.SG |
| Mobile Phone No | (LOCAL) +65-81211977 |
| Alternative Phone No | OTHERS-90482427 |

Vehicle Particulars

| | |
|--|-----------------------|
| Manufacturer | HONDA |
| Model | ODYSSEY-2.4 EXV-S (A) |
| Exact Purpose for which vehicle was being used at time of accident | PERSONAL USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|---------------------------|
| Name of Insurance Company | LIBERTY INSURANCE PTE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | SD18V05426/VPC2/R00 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | NG KAH SER |
| NRIC No | S1461103G |
| Date Of Birth | 28/11/1961 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 10/04/1986 |
| Driving Experience | 33 YEARS AND 3 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-81211977 |
| Fax Number | |
| Contact Number | OTHERS-90482427 |
| Email Address | NGKAHSER@YAHOO.COM.SG |

| | |
|---|---|
| Address | APT BLK 240 COMPASSVALE WALK #13-582 SINGAPORE |
| Postcode | 540240 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - - - |
| Insurance Company of Driver's Own Vehicle | - - - |

General Information of the Accident

| | |
|--------------------|-----------------|
| Type Of Accident | CHAIN COLLISION |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|------------------------------------|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 3 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 6 |
| Passenger 1 | NAME: : MR WONG GENDER: : MALE |
| Passenger 2 | NAME: : MR WONG GENDER: : MALE |
| Passenger 3 | NAME: : MR WONG GENDER: : MALE |
| Passenger 4 | NAME: : MS LAO GENDER: : FEMALE |
| Passenger 5 | NAME: : MR LAU GENDER: : MALE |

Details of Police Action

| | |
|---|--|
| Was the accident reported to the police? | YES |
| If Yes, Please state which Police Station | |
| Police Station Name | SENGKANG NPC |
| Police Station Address | ROAD: 2 SENGKANG SQUARE #01-02 , POSTCODE: 545025 , COUNTRY: SINGAPORE |
| Police Station Contact | TEL NO: - FAX NO: |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO ATTACHED STATEMENT - THIRD PARTY DIRECT SETTLEMENT

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
|---|-----|

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD8628X
Vehicle Make/Model/Colour HYUNDAI
Details Of Properties
Vehicle Category TAXI
Name of Driver TANG SWEE CHOON
NRIC/Passport Number S0217075B
Contact Number 90600069
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMJ3120
Vehicle Make/Model/Colour MAZDA
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver LEE YEN LIN
NRIC/Passport Number S8212169B
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 2
Passenger 1
NAME: : UNKNOW
GENDER: : FEMALE

Vehicle Number:

SD2239C

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

18-7-2018

9.23 am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: You Po Soon


NRIC/FIN No.:

Sketch Plan Pg. 2

Vehicle Number

SD2239C

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police Report = No. T/20190718/2212

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time:

19-07-2019

9.23 am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

[Signature]

Reporting Centre Personnel's Signature

Name: You Po Soon

NRIC/FIN No.:



Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

REPORT OF A TRAFFIC ACCIDENT

| | | |
|--|------------------|---------------------------|
| Date/Time Report Made: 18/07/2019 23:39 | Vide Report No.: | Station Diary No.: 177 |
|--|------------------|---------------------------|

Informant's Particulars

| | | | | | |
|--|------------|------------------------------|--|--|----------------------------|
| Name of Informant: NG KAH SER | | | Address: APT BLK 240 COMPASSVALE WALK #13-582 SINGAPORE 540240 | | |
| ID Type / ID No.: NRIC NO / S1461103G | | | Contact No.: Home/Office: Mobile: 81211977 | | |
| Nationality: SINGAPORE CITIZEN | | | Email: | | |
| Sex: Male | Age: 57 | Date of Birth: 28/11/1961 | Type of Informant: Driver | | |
| Race: Chinese | | | Language: Mandarin | | Institution / School Name: |
| Occupation: Site Manager | | | Driving Licence Information: Class: 3 Date of Expiry: | | |

General Information of the Accident

| | | | | |
|---|----------------------|------------------------------------|--|-------------------------------------|
| Type of Accident: | Non-Injury Others | Drink Drive: No | Date/Time of Accident: 18/07/2019 17:10 | Type of Location: Straight Road |
| Location: Along Road 1 PAN ISLAND EXPRESSWAY PIE towards Changi before Macpherson Exit | | | | |
| Weather: Clear | | Road Surface: Dry | | Road Speed Limit: |
| Traffic Flow: One Way | | Traffic Control: Not Controlled | | Traffic Volume: Heavy |
| Type of Collision: Between Moving Vehicles - Head To Rear | | | | Anyone conveyed by ambulance: No |

Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Condition | No of Passenger |
|-------------|------|---------|--|--------|---------------------|-----------------|
| SHD8628X | Car | HYUNDAI | AE IONIQ HEV 1.6 DCT | Yellow | Slightly Damaged | 0 |
| SLD2239C | Car | HONDA | ODYSSEY 2.4 EXV-S CVT SR NAVI RES | Purple | Slightly Damaged | 5 |



**SINGAPORE
POLICE FORCE**



T/20190718/2212

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

2 of 4

Report No. T/20190718/2212

CONTINUATION OF REPORT

Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Condition | No of Passenger |
|-------------|------|-------|----------------------------------|-------|------------------|-----------------|
| SMJ3120K | Car | MAZDA | MAZDA5 5-DOOR WAGON 2.0L SP.6EAT | Grey | Slightly Damaged | 1 |

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA

Driver

| | | | |
|-----------------------------------|-----------------|--|-----------------------------------|
| Name | TANG SWEE CHOON | ID No. | S0217075B |
| Related Vehicle | SHD8628X (Car) | Contact No. | 90600069 |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |

Driver

| | | | |
|-----------------------------------|----------------|--|---------------------------------|
| Name | NG KAH.SER | ID No. | S1461103G |
| Related Vehicle | SLD2239C (Car) | Contact No. | 81211977 |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: 3 Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |

Driver

| | | | |
|-----------------------------------|----------------|--|-----------------------------------|
| Name | LEE YAW LIN | ID No. | S8212169B |
| Related Vehicle | SMJ3120K (Car) | Contact No. | 98766471 |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |



SINGAPORE
POLICE FORCE



T/20190718/2212

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

3 of 4

Report No. T/20190718/2212

CONTINUATION OF REPORT

Brief Details.

On 18/07/2019 at about 1710hrs, I was driving my car(SLD2239C) along PIE towards Changi on Lane 1 (most right lane). I observed the vehicles in front of me started to slow down and I followed suit. Suddenly there was an impact coming from the rear, I stopped my car and came out and noticed a taxi (SHD8628X) had collided into my vehicle.

I observed another car (SMJ3120K) had collided into the taxi as well, all the drivers exchanged particulars and assessed the damages to our vehicles. My car has a dent in the rear and the sensors are damaged. The taxi's front vehicle registration plate has been slanted downwards due to the impact, I was unable to assess the damage of the third car.

My vehicle is installed with a front and rear in-car cameras, I made a check with my passengers and they informed me that they are well and no injuries reported. All drivers drove off afterwards.



**SINGAPORE
POLICE FORCE**



T/20190718/2212

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

4 of 4

Report No. T/20190718/2212

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 1 KANG YONG LER, JAMESON

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

18/07/2019 23:39

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:

Authentication Stamp

NP168

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SLD2239C

Chassis No : JHMRC1890GC203245

Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES

Owner's Name : NG KAH SER

Ins Policy No. :

Date of Accident : 18/7/2019

Document No. : SQT19003185

Date : 20. Jul 2019

Customer No. : WZF002

Svc Advisor : YOU PO SOON

Engine No : K24W72011498

Date | Time : 20. Jul 2019 9:30:43 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|--|-----|------------|--------|--------|---------------|------------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER: NG KAH SER OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 18/07/2019 SURVEYED BY: DATE: REF NO: TP INSURER: SHD8628X TP VEH: MS FIRST CAPITAL INSURANCE LIMITED | | | | | | |
| 73214-T6A-003 | MOLDINGRR.WINDSHIELD SIDE | 2 | 18.00 | 25 | 27.00 | 1.89 | 28.89 |
| 73215-T6A-003 | MOLDINGRR.WINDSHIELD CORNER | 1 | 16.90 | 25 | 12.67 | 0.89 | 13.56 |
| 73216-T6A-003 | MOLDINGL.RR.WINDSHIELD CORNER | 1 | 16.90 | 25 | 12.67 | 0.89 | 13.56 |
| 73221-SR4-000 | SPACERRR.W/SHIELD | 4 | 3.90 | 25 | 11.70 | 0.82 | 12.52 |
| 73225-TM8-000 | RUBBER AWINDSHIELD DAM | 1 | 3.70 | 25 | 2.77 | 0.19 | 2.96 |
| 73226-SZW-000 | DAMPERSTD 5X5 | 2 | 8.50 | 25 | 12.75 | 0.89 | 13.64 |
| 76711-T6A-003 | CAPPVOT | 1 | 4.80 | 25 | 3.60 | 0.25 | 3.85 |
| BO-WS-SEALANT | WINDSCREEN SEALANT (N) | 1 | 60.00 | | 60.00 | 4.20 | 64.20 |
| 68100-T6A-Q10ZZ | TAILGATE COMP | 1 | 1070.80 | 25 | 803.10 | 56.22 | 859.32 |
| 74440-T6A-003 | WEATHERSTRIPTAILGATE | 1 | 117.40 | 25 | 88.05 | 6.16 | 94.21 |
| 74891-T6A-003 | MOLDING ASSYRR.LICENSE GARN | 1 | 175.50 | 25 | 131.62 | 9.21 | 140.83 |
| 74800-TF0-J02 | LOCKTAILGATE | 1 | 185.40 | 25 | 139.05 | 9.73 | 148.78 |
| 75701-T6A-000 | EMBLEMH | 1 | 26.30 | 25 | 19.72 | 1.38 | 21.10 |
| 91512-SR3-004 | CLIP TUBULAR | 2 | 2.30 | 25 | 3.45 | 0.24 | 3.69 |
| 04715-T6A-900ZZ | FACERR.BUMPER | 1 | 568.30 | 25 | 426.22 | 29.84 | 456.06 |
| 71593-T6A-003 | SPACERR.RR.BUMPER SIDE | 1 | 19.10 | 25 | 14.32 | 1.00 | 15.32 |
| 71598-T6A-003 | SPACERL.RR.BUMPER SIDE | 1 | 19.10 | 25 | 14.32 | 1.00 | 15.32 |
| 91505-TM8-003 | CLIP,BUMPER | 7 | 2.30 | 25 | 12.07 | 0.84 | 12.91 |
| 84431-T6A-J01ZA | LINING ASSYTAILGATE LOWER | 1 | 206.30 | 25 | 154.72 | 10.83 | 165.55 |

Printed on 20/7/2019 10:07:51 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SLD2239C

Chassis No : JHMRC1890GC203245

Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES

Owner's Name : NG KAH SER

Ins Policy No. :

Date of Accident : 18/7/2019

Document No. : SQT19003185

Date : 20. Jul 2019

Customer No. : WZF002

Svc Advisor : YOU PO SOON

Engine No : K24W72011498

Date | Time : 20. Jul 2019 9:30:43 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|--|-------------|------------|--------|---------|---------------|------------------|
| 84441-T6A-J01ZA | POCKETTAILGATE LINING PULL | 17 1 | 10.70 | X 25 | 8.02 | X 0.56 | 8.58 |
| 66100-T6A-Q00ZZ | PANEL COMP, REAR | Body 20/Sec | 460.80 | ✓ 25 | 345.60 | ✓ 24.19 | 369.79 |
| 84640-T6A-003ZA | LINING ASSYRR.PANEL | Cnc 1 | 103.60 | ✓ 25 | 77.70 | ✓ 5.44 | 83.14 |
| NMRS-4P-TM3040L | 4PCS ACT RR.SENSOR | Cnc/Stub 1 | 320.00 | ✓ | 320.00 | ✓ 22.40 | 342.40 |
| Sum Item | | | | | 2701.12 | 189.06 | 2,890.18 |
| BOSUN | SUNDRIES | nu 1 | 50.00 | 20 | 50.00 | 3.50 | 53.50 |
| BOBC | BODY UNDERSIDE COATING (N) | 1 | 100.00 | 20 | 100.00 | 7.00 | 107.00 |
| BP00R | APPLY BODY UNDERSIDE COATING (N). | 1 | 250.00 | 20 | 250.00 | 17.50 | 267.50 |
| BOJSE | BODY JOINT SEALANT. | 1 | 100.00 | 80 | 100.00 | 7.00 | 107.00 |
| BG02D | REMOVE & INSTALL RR. WINDSCREEN.(N) | 1 | 300.00 | ✓ | 300.00 | 21.00 | 321.00 |
| BC011R | REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA | 1 | 320.00 | 300 | 320.00 | 22.40 | 342.40 |
| BC012R | RESET VEHICLE SMART ENTRY SYSTEM | 1 | 350.00 | 300 | 350.00 | 24.50 | 374.50 |
| BA02R | REMOVE & RENEW REVERSE SENSORS-4 PCS (N) | 1 | 150.00 | 130 | 150.00 | 10.50 | 160.50 |
| BMI03D | REMOVE & INSTALL REAR COMPARTMENT LININGS | 1 | 350.00 | 280 | 350.00 | 24.50 | 374.50 |
| BKTG02R | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & | 1 | 450.00 | ✓ | 450.00 | 31.50 | 481.50 |
| BKRP21M | CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN | 1 | 2400.00 | 1960 | 2400.00 | 168.00 | 2568.00 |
| BP05R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P) | 1 | 2400.00 | 1800 | 2400.00 | 168.00 | 2568.00 |
| Sum Labor | | | | | 7220.00 | 505.40 | 7,725.40 |

Survey By

Date & Time

Excess

Status

Signature

Total Amount 9,921.12 694.46 10,615.58

Total (Inclusive of GST) 9921.97 10,615.58

Printed on 20/7/2019 10:12:53 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00, judged by Repairer

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

LKH Auto Consultants hereby notify the repairer of the following:

- To be survey before other spray painting
- To be survey damaged part(s) during resurvey
- This survey is subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No metal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Signature:

Date:

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLD2239C
Chassis No : JHMRC1890GC203245
Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES
Owner's Name : NG KAH SER
Ins Policy No. :
Date of Accident : 18/7/2019

Document No. : SQT19003509
Date : 10. Aug 2019
Customer No. : WZF002
Svc Advisor : YOU PO SOON
Engine No : K24W72011498
Date | Time : 10. Aug 2019 4:41:50 PM
Surveyor Name : MARCUS
Survey Date : 23/7/2019
Authorisation Date : 29/7/2019

Page 1

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount Incl GST |
|--------------------------------|----------------------|-----|------------|--------|--------|---------------|-----------------|
| SUPPLEMENTARY PARTS AND LABOUR | | | | | | | |
| 74827-T0A-A00 | STOPPERTAILGATE 3A00 | 2 | 3.60 | 25 | 5.40 | 0.38 | 5.78 |
| 38387-SLE-003 | ANTENNA ASSY, LRR | 1 | 60.60 | 25 | 45.45 | 3.18 | 48.63 |
| Sum Item | | | | | 50.85 | 3.56 | 54.41 |

Survey By

Date & Time

Excess

Status

Signature

Total Amount 50.85 3.56 54.41

Total (Inclusive of GST) 54.41

Printed on 10/8/2019 4:45:06 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.60 (Incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**HONDA**

Attn: Marcus

©

Page 1/2

SERVICE PRE-INVOICE**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

W/D = 7 Days

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

| | | | |
|--------------------|------------------------------|-------------------------|---------------|
| Customer: | CU0038822 / MS FIRST CAPITAL | Document No: | SVO19048819 |
| Chassis No: | JHMRC1890GC203245 | Printed By: | PSYOU |
| License No: | SLD2239C | Order Date: | 30. July 2019 |
| Mileage: | 76485 | Order Time: | 10:14:46 AM |
| Engine No: | K24W72011498 | Service Advisor: | YOU PO SOON |

| ITEM | DESCRIPTION | QTY | UNIT | DISC % | AMOUNT | 7% GST Amount | Amount Incl GST |
|-----------------|--|-----|----------|--------|-----------------|---------------|-----------------|
| | TP DIRECT SETTLEMENT (J/NO: 73155) | | | | | | |
| | OWNER: NG KAH SER | | | | | | |
| | OWNER INSURER: LIBERTY INSURANCE PTE LTD | | | | | | |
| | ACC DATE: 18/07/2019 | | | | | | |
| | SURVEYED BY: MARCUS | | | | | | |
| | DATE: 23/07/2019 | | | | | | |
| | REF NO: D19004751MFSH | | | | | | |
| | TP INSURER: SHD8628X | | | | | | |
| | TP VEH: MS FIRST CAPITAL INSURANCE LIMITED | | | | | | |
| 73214-T6A-003 | MOLDINGRR.WINDSHIELD SIDE | 2 | 18.00 | 25 | 27.00 | 1.89 | 28.89 |
| 73215-T6A-003 | MOLDINGR.RR.WINDSHIELD CORNER | 1 | 16.90 | 25 | 12.67 | 0.89 | 13.56 |
| 73216-T6A-003 | MOLDINGL.RR.WINDSHIELD CORNER | 1 | 16.90 | 25 | 12.67 | 0.89 | 13.56 |
| 73221-SR4-000 | SPACERRR.W/SHIELD | 4 | 3.90 | 25 | 11.70 | 0.82 | 12.52 |
| 73225-TM8-000 | RUBBER AWINDSHIELD DAM | 1 | 3.70 | 25 | 2.77 | 0.19 | 2.96 |
| 73226-SZW-000 | DAMPERSTD 5X5 | 2 | 8.50 | 25 | 12.75 | 0.89 | 13.64 |
| 76711-T6A-003 | CAPPIVOT | 1 | 4.80 | 25 | 3.60 | 0.25 | 3.85 |
| BO-WS-SEALANT | WINDSCREEN SEALANT (N) | 1 | 60.00 | | 60.00 | 4.20 | 64.20 |
| 68100-T6A-Q10ZZ | TAILGATE COMP | 1 | 1,070.80 | 25 | 803.10 | 56.22 | 859.32 |
| 75701-T6A-000 | EMBLEMH | 1 | 26.30 | 25 | 19.72 | 1.38 | 21.10 |
| 04715-T6A-900ZZ | FACERR.BUMPER | 1 | 568.30 | 25 | 426.22 | 29.84 | 456.06 |
| 91505-TM8-003 | CLIP,BUMPER | 7 | 2.30 | 25 | 12.07 | 0.84 | 12.91 |
| 84640-T6A-003ZA | LINING ASSYRR.PANEL | 1 | 103.60 | 25 | 77.70 | 5.44 | 83.14 |
| 38387-SLE-003 | ANTENNA ASSY,L.RR. | 1 | 60.60 | 25 | 45.45 | 3.18 | 48.63 |
| 66100-T6A-Q00ZZ | PANEL COMP,REAR | 1 | 460.80 | 25 | 345.60 | 24.19 | 369.79 |
| NMRS-4P-TM3040L | 4PCS ACT RR.SENSOR | 1 | 320.00 | | 320.00 | 22.40 | 342.40 |
| 74827-T0A-A00 | STOPPERTAILGATE | 2 | 3.60 | 25 | 5.40 | 0.38 | 5.78 |
| | SUM PARTS: | | | | 2,198.42 | 153.89 | 2,352.31 |
| BOSUN | 0760 | 1 | 20.00 | | 20.00 | 1.40 | 21.40 |
| | SUNDRIES | | | | | | |
| BOBC | 0760 | 1 | 100.00 | | 100.00 | 7.00 | 107.00 |
| | BODY UNDERSIDE COATING (N) | | | | | | |
| BP00R | EXT-YBH | 1 | 250.00 | | 250.00 | 17.50 | 267.50 |
| | APPLY BODY UNDERSIDE COATING (N). | | | | | | |
| BOJSE | 0760 | 1 | 80.00 | | 80.00 | 5.60 | 85.60 |
| | BODY JOINT SEALANT. | | | | | | |
| BG02D | EXT-YJ | 1 | 300.00 | | 300.00 | 21.00 | 321.00 |
| | REMOVE & INSTALL RR. WINDSCREEN. | | | | | | |
| | (N) | | | | | | |
| BC011R | 0760 | 1 | 300.00 | | 300.00 | 21.00 | 321.00 |
| | REMOVE INSTALL & CALIBRATE REAR | | | | | | |
| | VIEW CAMERA | | | | | | |
| BC012R | 0760 | 1 | 300.00 | | 300.00 | 21.00 | 321.00 |
| | RESET VEHICLE SMART ENTRY SYSTEM | | | | | | |
| BA02R | EXT-YJ | 1 | 130.00 | | 130.00 | 9.10 | 139.10 |
| | REMOVE & RENEW REVERSE | | | | | | |
| | SENSORS-4 PCS (N) | | | | | | |
| BMI03D | EXT-YJ | 1 | 280.00 | | 280.00 | 19.60 | 299.60 |
| | REMOVE & INSTALL REAR | | | | | | |
| | COMPARTMENT LININGS | | | | | | |
| | GARNISHES.(N) | | | | | | |



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

| | | | |
|-------------|------------------------------|------------------|---------------|
| Customer: | CU0038822 / MS FIRST CAPITAL | Document No: | SVO19048819 |
| Chassis No: | JHMRC1890GC203245 | Printed By: | PSYOU |
| License No: | SLD2239C | Order Date: | 30. July 2019 |
| Mileage: | 76485 | Order Time: | 10:14:46 AM |
| Engine No: | K24W72011498 | Service Advisor: | YOU PO SOON |

| | | | | | | |
|----------------------------|--|---|--------------------|-----------------|---------------|-----------------|
| BKTG02R | EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N) | 1 | 450.00 | 450.00 | 31.50 | 481.50 |
| BKRP21M | EXT-YJ CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN ALIGN CHASSIS INCLUDING FITTING ON ATTACHMENT ITEM | 1 | 1,960.00 | 1,960.00 | 137.20 | 2,097.20 |
| BP05R | EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P) | 1 | 1,800.00 | 1,800.00 | 126.00 | 1,926.00 |
| | | | SUM LABOUR: | 5,970.00 | 417.90 | 6,387.90 |
| | | | TOTAL SGD | 8,168.42 | 571.79 | 8,740.21 |
| Total Payable (SGD) | | | | | | 8,740.21 |

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|-----------------------------|------------|---|
| MS FIRST CAPITAL INSURANCE LTD | | Ref : CS/FCI19012895/Uvf3e2 | | |
| 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 | | Date : 15-08-2019 | |  |
| | | Code : FCI2 | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SHD 8628X | Veh. Inspected | SLD 2239C | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | D19004751MFSH | Excess (\$) | 0.00 | |
| Assign From | HENRY KAO | Assign Date | 22/07/2019 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HONDA ODYSSEY (A) | c.c | 2356 | |
| Engine No. | HIDDEN | Year of Reg. | 2016 | |
| Chassis No. | JHMRC1890GC203245 | Colour | PURPLE | |
| Odometer | 75995 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 215/55 R17 | YOKOHAMA | 6 mm | |
| L/H Front Tyre | 215/55 R17 | YOKOHAMA | 6 mm | |
| R/H Rear Tyre | 215/55 R17 | YOKOHAMA | 6 mm | |
| L/H Rear Tyre | 215/55 R17 | YOKOHAMA | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 18/07/2019 | Inspection Date | 23/07/2019 | |
| Survey held at | KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610 | | | |
| 5a. Remarks | | | | |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 7 Working Days | | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 2239C

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|-------------------------------------|------------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 2 | MOLDINGRR.WINDSHIELD SIDE (SN) | NECESSARY | 27.00 | 27.00 |
| 1 | MOLDINGR.RR.WINDSHIELD CORNER (SN) | NECESSARY | 12.67 | 12.67 |
| 1 | MOLDINGL.RR.WINDSHIELD CORNER (SN) | NECESSARY | 12.67 | 12.67 |
| 4 | SPACERRR.W/SHIELD (SN) | NECESSARY | 11.70 | 11.70 |
| 1 | RUBBER AWINDSHIELD DAM (SN) | NECESSARY | 2.77 | 2.77 |
| 2 | DAMPERSTD 5X5 (SN) | NECESSARY | 12.75 | 12.75 |
| 1 | CAPPIVOT (SN) | NECESSARY | 3.60 | 3.60 |
| 1 | WINDSCREEN SEALANT (SN) | NECESSARY | 60.00 | 60.00 |
| 1 | TAILGATE COMP (SN) | BADLY DENTED | 803.10 | 803.10 |
| 1 | WEATHERSTRIPTAILGATE (SN) | NOT NECESSARY | 88.05 | - |
| 1 | MOLDING ASSYRR.LICENSE GARN (SN) | NOT NECESSARY | 131.62 | - |
| 1 | LOCKTAILGATE (SN) | NOT NECESSARY | 139.05 | - |
| 1 | EMBLEMH (SN) | NECESSARY | 19.72 | 19.72 |
| 2 | CLIP TUBULAR (SN) | NOT NECESSARY | 3.45 | - |
| 1 | FACERR.BUMPER (SN) | DENTED / DEFORMED | 426.22 | 426.22 |
| 1 | SPACERR.RR.BUMPER SIDE (SN) | NOT NECESSARY | 14.32 | - |
| 1 | SPACERL.RR.BUMPER SIDE (SN) | NOT NECESSARY | 14.32 | - |
| 7 | CLIP, BUMPER (SN) | NECESSARY | 12.07 | 12.07 |
| 1 | LINING ASSYTAILGATE LOWER (SN) | NOT NECESSARY | 154.72 | - |
| 1 | POCKETTAILGATE LINING PULL (SN) | NOT NECESSARY | 8.02 | - |
| 1 | PANEL COMP, REAR (SN) | BADLY DENTED / BUCKLED | 345.60 | 345.60 |
| 1 | LINING ASSYRR.PANEL (SN) | CRACKED | 77.70 | 77.70 |
| 4 | ACT RR.SENSOR (SN) | CRACKED / SHORTED | 320.00 | 320.00 |
| 1 | SUNDRIES (SN) | NECESSARY | 50.00 | 20.00 |
| 2 | STOPPERTAILGATE (SN) (ADDITIONAL) | NECESSARY | 5.40 | 5.40 |
| 1 | ANTENNA ASSY,L.RR (SN) (ADDITIONAL) | CRACKED | 45.45 | 45.45 |
| | | | 2,801.97 | 2,218.42 |

Report Ref No. CS/FCI19012895/Uvf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|-----------|---------------------------|-------------------|
| | LABOUR | | | |
| | BODY UNDERSIDE COATING. | | 100.00 | 100.00 |
| | APPLY BODY UNDERSIDE COATING. | | 250.00 | 250.00 |
| | BODY JOINT SEALANT. | | 100.00 | 80.00 |
| | REMOVE & INSTALL RR. WINDSCREEN. | | 300.00 | 300.00 |
| | REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA. | | 320.00 | 300.00 |
| | RESET VEHICLE SMART ENTRY SYSTEM. | | 350.00 | 300.00 |
| | REMOVE & RENEW REVERSE SENSORS - 4 PCS. | | 150.00 | 130.00 |
| | REMOVE & INSTALL REAR COMPARTMENT LININGS. | | 350.00 | 280.00 |
| | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & | | 450.00 | 450.00 |
| | CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN. | | 2,400.00 | 1,960.00 |
| | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P) | | 2,400.00 | 1,800.00 |
| | | | 7,170.00 | 5,950.00 |
| | GRAND TOTAL | | 9,971.97 | 8,168.42 |
| RECOMMENDED COST OF REPAIRS | | | | 8,168.42 |

Report Ref No. CS/FCI19012895/Uvf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.