

Surveyor

REF: CS3/ASM19006857/Ucd3²

Special Instruction:

L/S: \$7,700.00

ASSIGNMENT (Office)

From (Person): Xin Yi of Seahong Date/Time: 17/7/19

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: Constant Appraiser Services

Workshop: Fastech Auto

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SFD 2182C Insured: WC 5006M

at Workshop m/s: Fastech Tel: 6746 5405

of: 1 kaki Bukit Ave 6 # 01-46

Policy No: 19.27172 Claim No: 19-27172 S9M01KJ3

Sum Insured: Excess:

Make of Vch: D.O.A. 13/04/2019

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 6 days)

Date/Time: 23/7/19 Submit Final Fig 456300 \$ days (Red \$ 1400 / 18%; Original 6 days)

Date/Time Action/Instruction

SFD 2182C - CS3/ASM19006857/Ucd3s2

D.O.A. 13/4/19

WC 5006M - CS3/ASM19006857/Ucd3s2

D.O.A. 13/4/19

456300 \$

RECEIVED 24 JUL 2019

23/7/2019

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1) Date/Time 23/7/19 File Pass to H2M48

3) Date/Time File Pass to

5) Date/Time File Pass to

2) Date/Time File Return to

4) Date/Time File Return to

6) Date/Time File Return to

Form 100
Rev. 10/10

Surveyor

Person/Owner

Estimated Cost

OD / (TP) WST / TP RES / OD RES / KYA / INV / MY / CT

To Request Vehicle No.

At Workshop no.

of

Policy No.

Sum Insured

Make of Veh

or Brand's Remarks

CA / REV / REP / REV 24 HRS

Date/Time: 17/4/19 @ 12.33pm Person Contacted

Date/Time

Action/Instruction (X) Estimate

SFD 2182 C - (03) AXA / 1012532 / Pg 1 of 1

WC 5006 M - X

Dismantle: 17/4/2019

After repair: 22/4/2019

REF CS3/ASM1900657/Med 3rd

ASSIGNMENT (Office)

ASM (AXA)

Date/Time 17/4/19 @ 11.29am.

Insured

WC 5006 M

Tel

6746 5405

Claim No.

89MOIKJ3

Excess

D.O.A 13/4/19

Hold Endorsement

Vehicle (IN) (OUT)

Nancy

Virtual Car

DVA: 24/6/2011

(08/11/13) wef

ASS. REC. BY: *MARUS*

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SFD2142C*

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: *68*

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: *5* days Res: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: *SFD2142C* Yr Regn: *9, 18*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *(A)*Make: *Hyundai Elantra* c.c. *1591*Colour: *Black* A/C: Insured / Std / NI / NASp. Reading: *19850* T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: *LMHD841CMJ4744784*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *205/55-R16*

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *LMHD*

Front

R/Bal. *2* mmL/Bal. *2* mmD.O.A. *13/4/19*

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*PRS No settlement.**Range + Days**4500 - 5800/-*

RECEIVED 06 MAY 2019

22/4/2019.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: *5*Resurvey No. of Trip: *2*

Survey Fee:

Transportation:

Report Format: *PRS*

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

) \$ + RS, SI

) Photos

) Others

TOTAL

Nivitha (LKK Auto)

From: Xin Yi <xinyi@seahong.com.sg>
Sent: Wednesday, 17 July 2019 9:17 AM
To: 'Admin-D (LKKAuto)'; 'Admin A'
Cc: 'Chee Kiong'; 'Samson'; amanda@seahong.com.sg
Subject: SOP file ref: 19.27172 combined | SFD 2182C
Attachments: OI GIA.pdf; SFD2182C TP GIA.PDF; TPPD LITIGATION LOD - SYED AHMAD BIN HASSAN ALJUNIED.pdf

Dear Nivitha

CLAIMANT : SYED AHMAD BIN HASSAN ALJUNIED (OWNER & DRIVER)
VEHICLE NUMBER : SFD 2182C
ALLEGED ACCIDENT DATE : 13 APRIL 2019
AXA VEHICLE NUMBER : WC 5006M

1. We act for AXA Insurance Pte Ltd for the above matter.
2. We understand that you were engaged to survey the claimant's vehicle.
3. The claimant has issued their LOD and their surveyor's report is attached. A copy is enclosed.
4. Please let us hear from you on the following: -
 - a) If you have conducted post-repair inspection already, please let us have your survey report urgently.
 - b) If you have not conducted post-repair inspection, please let us arrange for inspection with the claimant's solicitor and let us have your survey report in due course.
5. May we hear from you on the above soonest. Thanks!

Thanks & Best Regards

Heng Xinyi

(Secretary to Mr Tan Chee Kiong)

Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

Tel: 6536 5369

Fax: 6536 5811

This message is intended for the recipient named above. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Thank you.

Disclaimer: Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has not been tampered with, Seah Ong & Partners LLP cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this message for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the company shall be understood as neither given nor endorsed by Seah Ong & Partners LLP.



Our Ref: CG/ns/CH/5015.19.Syed Ahmad (PD)

WITHOUT PREJUDICE
BY HAND

TSS Construction And Transport Pte Ltd – Owner of WC 5006M
75 Whampoa Drive
#15-364 Whampoa Court
Singapore 320075

BY POST

Dear Sir,

**CLAIMANT: SYED AHMAD BIN HASSAN ALJUNIED (NRIC NO. S7202090A)
ACCIDENT INVOLVING SFD 2182C & WC 5006M ALONG MOUNTBATTEN ROAD TOWARD KALLANG
(OLD AIPT) ON 13TH APRIL 2019 AT ABOUT 1530 HOURS (PROPERTY DAMAGE CLAIM)**

1. We are instructed by our client to claim damages against you in connection with a road traffic accident on 13th April 2019 at about 1530 hours along Mountbatten Road toward Kallang (Old Airport) involving our client's vehicle registration number SFD 2182C and vehicle registration number WC 5006M driven by you at the material time.
2. We are instructed that the accident was caused by your negligent driving and/or management of your vehicle WC 5006M. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

a) Costs of repair	\$ 8,239.00
b) Loss of rental	\$ 1,000.00
c) Survey fee	\$ 758.00
d) Legal costs	\$ 535.00
e) Disbursements	\$ 80.00
Total	<u>\$10,612.00</u>



COSMAS LLC
Sole Agent for the Republic of Singapore
Insurance Claims Management Services

COSMAS LLC

Page 2

3. A copy each of the following supporting documents is enclosed:
 - a) Our client's traffic police report
 - b) LTA search
 - c) Cost of repair Invoice No. 21033 from Fastech Auto Pte Ltd
 - d) Car rental Invoice No. DCR-2019-04-23 from Dynamic Car Rental
 - e) Survey fee (Invoice No. IV19-04048/CAS) from Constant Appraiser Services
 - f) Surveyor report from Constant Appraiser Services
4. Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.
5. Please note that you or your insurer should send us an acknowledgement of receipt of this letter to us within 14 days of your receipt of this letter. Please also inform us, within 14 days of your acknowledgement of receipt of this letter.
6. Should you fail to acknowledge receipt of this letter within 14 days, our client may commence Court proceedings against you without further notice to you or your insurer.
7. Please also note that if you have a counterclaim against our client arising out of the accident, you are required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully

COSMAS LLC

encs

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 15/04/2019 13:07
Date Of Accident 13/04/2019 15:10
Exact Location Of Accident ALONG MOUNTBATTEN ROAD TOWARDS KALLANG
Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFD2182C
Insured/Policyholder
Name Of Registered Owner SYED AHMAD BIN HASSAN ALJUNIED
NRIC No S7202090A
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-82688984
Alternative Phone No OTHERS-82688984
Vehicle Particulars
Manufacturer HYUNDAI
Model ELANTRA AD 1.6 GLS AT (AMS)
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number VPA/P2185032
Cover Note Number
Driver
Name of Driver SYED AHMAD BIN HASSAN ALJUNIED
NRIC No S7202090A
Date Of Birth 11/01/1972
Occupation INDOOR
Date Of Driving Pass 02/04/1993
Driving Experience 26 YEARS AND 0 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-82688984
Fax Number
Contact Number OTHERS-82688984
Email Address NOEMAIL

Address 256 TAMPINES STREET 21 #05-170 SPORE 522256

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

-

Insurance Company of Driver's Own Vehicle -

-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1

NAME: : NG THOMAS

GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name BUKIT TIMAH NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD, 1 DUKE ROAD, POSTCODE: 268914, COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-4629999 - FAX NO: 64628933

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN/POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number WC5006M

Vehicle Make/Model/Colour ISUZU CYH52S

Details Of Properties

Vehicle Category GOODS VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SYED AHMAD BIN HASSAN ALJUNIED
Approximate Age
Injuries Sustain
Injured person in which vehicle? SFD2182C
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name NG THOMAS
Approximate Age
Injuries Sustain
Injured person in which vehicle? SFD2182C
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, notices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party vehicle providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or Court orders;

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NR/Ref No. 11-001-2121

Sketch Plan #2

SKETCH PLAN



7. 21 J 216 25

7. 21 J 216 25

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the police report 7/20190417/26

DECLARATION

We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time

Driver's Signature
of driver if not the policyholder
Date & Time

Reporting Officer's Signature
Name
Unit/ID No



SINGAPORE POLICE FORCE



T/20190413/2136

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

1 of 4

Report No: T/20190413/2136

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/04/2019 18:30	Vide Report No.:	Station Diary No.: 86
--	------------------	--------------------------

Informant's Particulars

Name of Informant: SYED AHMAD BIN HASSAN ALJUNIED			Address: APT BLK 256 TAMPINES STREET 21 #05-170 SINGAPORE 522256		
ID Type / ID No.: NRIC NO / S7202090A			Contact No.: Home/Office: Mobile: 82688984		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 47	Date of Birth: 11/01/1972	Type of Informant: Driver		
Race: Arab			Language:		Institution / School Name:
Occupation: SUPPORT ENGINEER			Driving Licence Information: Class: 2B,2A,3 Date of Expiry:		

General information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 13/04/2019 15:30	Type of Location: Straight Road
Location: Along Road 1 MOUNTBATTEN ROAD				
Towards Kallang(Old Airport)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SFD2182C	Car	HYUNDAI	ELANTRA AD 1.6 GLS AT (AMS)	Black	Slightly Damaged	1
WC5006M	Lorry				Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



SINGAPORE POLICE FORCE



T/20190413/2136

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

2 of 4

Report No. T/20190413/2136

CONTINUATION OF REPORT

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SFD2182C	AXA INSURANCE SINGAPORE PTE LTD	P2185032	01/09/2018	31/08/2019

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA

Passenger

Name	NG THOMAS	ID No.	S1416662I
Related Vehicle	SFD2182C (Car)	Contact No.	97508172
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	13/04/2019	Date Discharge	13/04/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Driver

Name	SYED AHMAD BIN HASSAN ALJUNIED	ID No.	S7202090A
Related Vehicle	SFD2182C (Car)	Contact No.	82688984
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A.3 Date of Expiry: NIL
Date Treatment	13/04/2019	Date Discharge	13/04/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Driver

Name	PONNUSAMY KAVIAMANI	ID No.	F8279983N
Related Vehicle	WC5006M (Lorry)	Contact No.	90849770
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



SINGAPORE
POLICE FORCE



T/20190413/2136

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

3 of 4

Report No. T/20190413/2136

CONTINUATION OF REPORT

Brief Details.

On the above mentioned date and time, I was driving my vehicle along Mountbatten Road towards Kallang(Old Airport). As I was approaching a traffic light junction, I came to a stop and queued behind every other vehicle waiting for the traffic light to turn green. My car was stationary on the extreme left lane. While waiting, I felt a bump from the rear of my vehicle. I alighted from my car immediately to make a check and discovered that a cement truck had collided onto my vehicle. There were scratches and dents on the rear of my car. The driver and I exchanged details and took pictures of the accident before leaving the scene. I later felt discomfort therefore I went to Mount Alvernia Hospital to seek treatment. I was given 5 days of MC. I am lodging this report as required by Traffic Police.



**SINGAPORE
POLICE FORCE**



T/20190413/2136

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

4 of 4

Report No. T/20190413/2136

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 ABDUL HAQ BIN JEFRY

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED
MOHD SAID

Contact No.: 65476172

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:


13/04/2019 18:30

Classification Of Case:

Police Report



**SINGAPORE
POLICE FORCE**



120180415021,00

Police Station Of Origin
Luhk Timah N P C
1 Duke's Road SINGAPORE 266914
Tel No: 1800 4520000

Report No: 120180415

REPORT OF A TRAFFIC ACCIDENT

Date Time Report Made
13/04/2019 18:30

Video Report No

Station Diary No
50

Informant's Particulars

Name of Informant SYED AHMAD BIN HASSAN			Address APT BLK 256 LAMPHINES STREET 21 #06-120 SINGAPORE		
ALJUNIED			522256		
ID Type / ID No			Contact No		
NRIC NO: S1202090A			Home/Office		
Nationality			Mobile: 82688984		
SINGAPORE CITIZEN			Email		
Sex	Age	Date of Birth	Type of Informant		
Male	47	11/01/1972	Driver		
Race			Language		
Arab			Institution / School Name		
Occupation			Driving Licence Information		
SUPPORT ENGINEER			Class: 2B, 2A, 3		
			Date of Expiry		

General Information of the Accident

Type of Accident	Injury Others	Drink Drive	Date/Time of Accident	Type of Location
		No	13/04/2019 18:30	Straight Road
Location				
Along Road 1				
MOONIBAH N ROAD				
Towards Katong/Orkney Airport				
Weather	Road Surface	Road Speed Limit		
Clear	Dry			
Traffic Flow	Traffic Control	Traffic Volume		
One Way	Traffic Light Working	Moderate		
Type of Collision	Anyone conveyed by ambulance			
Between Moving Vehicles Head To Rear	No			

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SD01820	Car	HYUNDAI	ELANTRA	Black	Slightly Damaged	1
AD5006M	Lorry		AD 1.5 GLS		Slightly Damaged	0
			AT (AMS)			

Details of Vehicle Insurance

Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date

Police Report



SINGAPORE
POLICE FORCE



1201904132135

Police Station Of Origin
Pulok Timah N P C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4620889

Report No: 1201904132135

CONTINUATION OF REPORT

Details of Vehicle Insurance

Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SFD2182C	AXA INSURANCE SINGAPORE PTE LTD	P2185032	01/09/2018	31/08/2019

Details of Person Involved

Any Pedestrian Involved: No
No. of Pedestrians Injured: NIL

Passenger		Use of Pedestrian Crossing: NA	
Name	NG THOMAS	ID No	S14166621
Related Vehicle	SFD2182C (Car)	Contact No	97508172
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: Nil Date of Expiry: Nil
Date Treatment	13/04/2019	Date Discharge	13/04/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Driver		Use of Pedestrian Crossing: NA	
Name	SYED AHMAD BIN HASSAN AL JUNEID	ID No	97202090A
Related Vehicle	SFD2182C (Car)	Contact No	82688954
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B, 2A, 3 Date of Expiry: NIL
Date Treatment	13/04/2019	Date Discharge	13/04/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Driver		Use of Pedestrian Crossing: NA	
Name	PONNUSAMY KAVIAMANI	ID No	P50759823N
Related Vehicle	UC5005M (Car)	Contact No	908445729
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: Nil Date of Expiry: Nil
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Police Report



SINGAPORE
POLICE FORCE



1291904132136

Police Station Of Origin

Rukh Daran N 270

1 Duke's Road SINGAPORE 266944

Tel No 1800 4625999

Date

Report Made To/By/For/Station

CONTINUATION OF REPORT

Brief Details

On the above mentioned date and time, I was driving my vehicle along Mountbatten Road towards Kallang (Old Airport). As I was approaching a traffic light junction, I came to a stop and queued behind every other vehicle waiting for the traffic light to turn green. My car was stationary on the extreme left lane. While waiting, I felt a bump from the rear of my vehicle. I alighted from my car immediately to make a check and discovered that a cement truck had collided onto my vehicle. There were scratches and dents on the rear of my car. The driver and I exchanged details and took pictures of the accident before leaving the scene. I later felt discomfort therefore I went to Mount Alvernia Hospital to seek treatment. I was given 5 days of MC. I am lodging this report as required by Traffic Police.

Police Report



SINGAPORE
POLICE FORCE

Police Station Of Origin
Bukit Timah N.P.C.
100kes Road SINGAPORE 268914
Tel No. 1800 4629099



1291594132113

4 of 4

Report No. 1291594132113

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 604 74885 stating the report number as reference.

Signature Of Officer Recording this Report

Sgt 2 ABDUL RAHMAN BERRY

Signature Of Informant

Date/Time
12/04/2019 18:30

Signature Of Interpreter
Not Applicable

Officer In Charge Of Case

TRABIT

Sgt 2 SHARIFAH NOR FARIZAN BINTI SYED

MUHLI SAID

Contact No. 65476112

Authentication Stamp

NR158

Classification Of Case

Enquire Vehicle & Owner Information (Vehicle No. WC5006M As At 13 Apr 2019 / 15:30:00)**Landlord/Owner Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CG/5015.19

Registered Address Details

Owner ID Type: Company

Owner ID: 201409501H

Owner Name: TSS CONSTRUCTION AND TRANSPORT PTE. LTD.

Registered Address Type: HDB / HUDC

Registered Block/House No.:75

Registered Street Name: WHAMPOA DRIVE

Registered Unit No.: # 15 - 364

Registered Building Name: WHAMPOA COURT

Registered Postal Code: 320075

Registered Vehicle Details

Vehicle No.: WC5006M

Make Description/Model: ISUZU / CYH525

Insurance Company Name: AXA INSURANCE PTE LTD

FASTECH AUTO PTE LTD

1 Kaki Bukit Avenue 6, #01-46/48/50
AutoBay, Singapore 417883
Tel: 6746 5405 / 6745 2063 Fax: 6745 8520
Email: general@fastechauto.com.sg
GST Reg. No.: 200006262D

This is to confirm that Merous (Name of Surveyor)
of 24/4 (Surveyor Company) has completed the pre-
repair survey on our customer Vehicle No _____ involved in a road
accident on 17/4/19 (Date of Accident)
Dated This 17 Day of 04 2019.

[Signature]
Appointed Surveyor (PRI)

Date/Time: 17/4/19 @ 11:30

Independent Surveyor

Date/Time: _____

Damaged Parts Survey

[Signature]
Appointed Surveyor

Date/Time: 17/4/19 @ 2:30

Independent Surveyor

Date/Time: _____

After Paint Survey

[Signature]
Appointed Surveyor

Date/Time: 22/4/19 @ 10:30

Independent Surveyor

Date/Time: _____

TAX INVOICE

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

SYED AHMAD BIN HASSAN ALJUNIED

BLK 256 TAMPINES STREET 21

#05-170

SINGAPORE 522256

Tax Invoice : 21033

Date : 06.05.2019

Vehicle No : SFD 2182C

Make/Model : HYUNDAI ELANTRA

Chassis/Eng# :

Accident Date : 13.04.2019

Claim No

Reference : 0419 -21033

Policy No

Amount

To proceed on lump sum repair

S\$

7700.00

E. & O. E.

Total : S\$ 7700.00

GST @ 7% : S\$ 539.00

Amount Due : S\$ 8239.00


for FASTECH AUTO PTE LTD

All Invoices are subjected to GST

DYNAMIC CAR RENTAL

1 Kaki Bukit Ave 6 #01-46 Autobay

Singapore 417883

Tel No: 6741 7244 / 6746 5405 Fax No: 6745 8520 / 6746 5786

Co. Reg No: 52928467K

To: AYED AHMAD BIN HASSAN ALJUNIED

Invoice : DCR-2019-04-23

Date : 23.04.2019

Agreement No : 20667

Payment Term : LOD

DESCRIPTION

AMOUNT

Rental charges for vehicle : SLH 7586X (0419-21033) \$ 1,000.00

Rental Period from 13.04.2019 to 23.04.2019 .

E. & O. E.

Total \$ 1,000.00

LINA PANG

for Dynamic Car Rental

Dynamic Car Rental

A SINGAPOREAN COMPANY S 401454350 A TORA SINGA 365 47283
 TEL: (+65) 6741 7244, 6746 4405 FAX: (+65) 6745 8520, 6746 5786
 11, 528204

TERMS, CONDITIONS AND CONDITIONS

No. 20667

Name: <u>Mr. Michael Lim Jia Joon</u>			REG NO:	MAKE/MODEL		
ADDRESS:			<u>2H1586 X</u>	DIESEL	PETROL	E 1M 10 34 F
			IN	DATE & TIME IN		
			OUT	DATE & TIME OUT		
			DRIVEN	Time Joon		
NAMED DRIVER						
DRIVER'S PASSPORT NO.	DATE OF BIRTH	PLACE OF ISSUE	HOURS		DAYS	
<u>8720290A</u>			10		DAYS	
PASSPORT NO.	DATE OF ISSUE	PLACE OF ISSUE	WEEKS		MONTHS	
ADD NAMED DRIVER			BY INITIALLING, RENTER AGREES TO PAY ADD FEE FOR COLLISION/DAMAGES, WAIVER (CDW)		SUB-TOTAL	
DRIVING LICENCE NO.	DATE OF EXPIRY	PLACE OF ISSUE			# 150.00	
PASSPORT NO.	DATE OF ISSUE	PLACE OF ISSUE				
EXCESS:					TOTAL RENTAL	
This vehicle is licensed to carry 04 passengers only. No refund will be given for whole day hire. No refund will be given for period when vehicle is under repair. Hire is liable to pay first \$4000 under section 6, this is only section plus loss of earnings while damaged vehicle is under repair. Hire is liable to pay all parking fees and traffic fines/movements.					DELIVERY FEE	
Vehicle return during office hour only. No Service on Public Holiday and Sunday.					COLLECTION FEE	
EXCESS:			X			
Sec 1 - Urban 5 Spore Only: \$600/day Sec 2 - Urban 5 Spore Only: \$500/day Sec 3 - Urban 5 Spore Only: \$400/day Sec 4 - Urban 5 Spore Only: \$300/day Sec 5 - Urban 5 Spore Only: \$200/day Sec 6 - Urban 5 Spore Only: \$100/day Sec 7 - Urban 5 Spore Only: \$50/day Sec 8 - Urban 5 Spore Only: \$25/day			PER DAY \$		PER WEEK \$	
Sec 9 - Urban 5 Spore Only: \$100/day Sec 10 - Urban 5 Spore Only: \$50/day Sec 11 - Urban 5 Spore Only: \$25/day Sec 12 - Urban 5 Spore Only: \$10/day Sec 13 - Urban 5 Spore Only: \$5/day Sec 14 - Urban 5 Spore Only: \$2/day			PER MONTH \$			
Additional Charges:			BY INITIALLING, RENTER AGREES TO PAY ADD FEE FOR PERSONAL ACCIDENT INSURANCE (PAI)			
Additional Charges:			X			
Additional Charges:			PER DAY \$		PER WEEK \$	
Additional Charges:			PER MONTH \$			
Additional Charges:			REPAYMENT		TOTAL CHARGE	
Additional Charges:			CHECK		DEPOSIT	
Additional Charges:			CASH			
Additional Charges:			RECEIPT NO.		NETT CHARGE	
Additional Charges:			AMOUNT DUE / REFUND			
I HAVE READ THE TERMS & CONDITIONS ON BOTH SIDES OF THIS RENTAL AGREEMENT AND AGREE THEREOF						
SIGNED BY THE PARTIES HERETO ON THE _____ DAY OF _____						
X			X			
DYNAMIC CAR RENTAL			RENTER'S DRIVER'S SIGNATURE			

15/04/2019

Invoice



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-058385

Date of Request: 15/04/2019

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 15/04/2019
Enquiry By: Tang Kok Wee, Allan
Vehicle No: WC5006M
Accident Date: 13/04/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
WC5006M	AXA Insurance Pte Ltd	15/06/2018-14/06/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

15/04/2019

Invoice



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-058385
Date of Request: 15/04/2019

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Inquiry Date: 15/04/2019
Enquiry By: Tang Kok Wee, Allan
Vehicle No: WC5006M
Accident Date: 13/04/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	
GST Amount	1.87
Total Amount Due (GST Inclusive)	0.13
	2.00

Thank You,

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

AXA INSURANCE PTE LTD
8 Shenton Way, #24-01
AXA Tower, Singapore 068811
Customer Centre #01-21
Tel: 1800 8804888 Fax:-
Website: www.axa.com.sg
GST Registration Number: 199903512M
customer.care@axa.com.sg



CERTIFICATE OF INSURANCE

■ Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) ■ Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 ■ Road Transport Act, 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VPA/P2185032 Account No. : 08260
Coverage : Comprehensive
Sum Insured : Market Value At The Time Of Loss
Name of Policy Holder : SYED AHMAD BIN HASSAN ALJUNIED
Vehicle Registration No. : SFD2182C
Period of Insurance : From 01/09/2018 To 31/08/2019 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

- (a) The Policyholder
The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner
- (b) Any other person who is driving on the Policyholder's order or with his permission
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

Basic Own Damage Excess : (01)

An Additional Excess is applicable as follows:
S\$500.00 for Unnamed Authorized Driver
S\$2,500.00 for Undeclared Young and Inexperienced Driver.
(Please refer to your policy on the terms & conditions)

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

N.B :

Your authorised workshop is Komoco Motors Pte Ltd.

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGOVKRS on 03/10/2018

IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189)).
The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

2090A

Vehicle Details

Vehicle No.:

SFD2182C

Vehicle to be Exported:

Yes

Intended Deregistration Date:

15 Apr 2019

Vehicle Make:

HYUNDAI

Vehicle Model:

ELANTRA AD 1.6 GLS AT (AMS)

Primary Colour:

Black

Manufacturing Year:

2018

Engine No.:

G4FGJU254384

Chassis No.:

KMHD841CMJU744784

Maximum Power Output:

93.8 kW (125 bhp)

Open Market Value:

\$14,578.00

Original Registration Date:

01 Sep 2018

First Registration Date:

01 Sep 2018

Transfer Count:

0

Actual ARF Paid:

\$14,578.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

31 Aug 2028

PARF Rebate Amount:

\$10,933.00

Intended COE Rebate Details

COE Expiry Date:

31 Aug 2028

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$31,997.00

COE Rebate Amount:

\$25,597.00

Total Rebate Amount:

\$36,530.00

The information contained herein is correct as at 15 Apr 2019

OK

FASTTECH AUTO PTE LTD

Sole Distributor for 401-76/48/50
177330, Singapore 117883
Tel: 6745 2003 Fax: 6745 8520
Email: general@fasttechinfo.com.sg
GST ID: S10000626210

This is to confirm that Mercury (Name of Surveyor)
of LLB (Surveyor Company) has completed the pre-
repair survey on our customer Vehicle No _____ involved in a road
accident on 17/4/19 (Date of Accident)
Dated This 17 Day of 04 20 19.

Appointed Surveyor (PRI)

Date/Time: 17/4/19 @ 11:30

Independent Surveyor

Date/Time: _____

Damaged Parts Survey

Appointed Surveyor

Date/Time: 17/4/19 @ 02:30

Independent Surveyor

Date/Time: _____

After Paint Survey

Appointed Surveyor

Date/Time: 22/4/19 @ 10:30

Independent Surveyor

Date/Time: _____

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
104-2 Rivervale Link, #01-02 Singapore 545040
Tel/Fax: 6586 1196/Mobile: 9907 8233
Email: constantappraiser@rediffmail.com
GST No. S 1580176

INVOICE

To: Syed Ahmad Bin Hassan Ahmed
256 Tampines St 11
#05-170
Singapore 520156

Date: 30/04/2019
Invoice No: IV19-04048 CAS

Particulars	Amount
Fee For Services Rendered In Respect Of	
Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle STD 2183 Inclusive Of Photographs And Transport Charges	\$758.00
Our reference: CAS 19-04-048	
Total	\$758.00

T & C

Constant Appraiser Services

Cheque Should Be Crossed And Made Payment To Constant Appraiser Services

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

INVOICE

To: Syed Ahmad Bin Hassan Aljunied
256 Tampines St 21
#05-170
Singapore 522256

Date : 30/04/2019

Invoice No : IV19-04048/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle SFD 2182C (Inclusive Of Photographs And Transport Charges) Our reference : CAS/19-04/048	\$758.00
Total	\$758.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Syed Ahmad Bin Hassan Aljunied 256 Tampines St 21 #05-170 Singapore 522256		Date : 30/04/2019 Reference No : CAS/19-04/048	
<u>General Information</u>			
Registration No.	: SFD 2182C		
Accident Date	: 13/04/2019		
<u>Particulars of Damaged Vehicle</u>			
Colour	: Black	Make & Model : Hyundai Elantra	
Engine Capacity	: 1591 cc	Pre-Accident Condition : Good	
Mileage (KM)	: 19850	Engine No. : G4FGJU254384	
Chassis No.	: KMHD841CMJU744784	Steering : In Order	
Registration Date	: 01/09/2018	Brake : In Order	
<u>Tyre Condition</u>			
	Size	Make	Balance
R/H Front Tyre	205/55R16	KUMHO	90%
L/H Front Tyre	205/55R16	KUMHO	90%
R/H Rear Tyre	205/55R16	KUMHO	90%
L/H Rear Tyre	205/55R16	KUMHO	90%
<u>Inspection</u>			
Repairer	: Fastech Auto Pte Ltd 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, Singapore 417883		
<u>Adjustment And Recommendation Cost Of Repair</u>			
Repairer's Estimate	: \$11,196.48		
Revised Amount	: \$7,700.00		
Less Excess	: -		
Nett Total	: \$7,700.00		
<u>Remarks</u>			
(A) Survey was done on 15/04/2019 (B) Re-survey was done on 17/04/2019 (C) Re-survey after repair was done on 22/04/2019 (D) The survey was conducted entirely on WITHOUT PREJUDICE basis. (E) We have NOT given any instruction to authorize the repair of the vehicle.			

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS</u>					
1	1pc	Rear boot lid	Dented/Buckled <i>DB</i>	1,628.60	1,628.60 ✓
2	1pc	Rear boot logo	Necessary <i>NI</i>	38.60	38.60 ✓
3	1pc	Rear boot emblem 'Elantra'	Necessary <i>NI</i>	42.20	42.20 ✓
4	1pc	Rear boot emblem 'Elite'	Necessary <i>NI</i>	42.20	42.20 ✓
5	2pcs	Rear boot lamp @ \$362.60	Cracked/Broken <i>CR</i>	725.20	725.20 ✓
6	2pcs	Rear boot licence lamp @ \$48.80	Cracked <i>NI</i>	97.60	97.60 X
7	1pc	Rear boot inner lock	Bent/Jammed <i>NI</i>	231.60	231.60 ✓
8	1pc	Rear boot inner trim	Serviceable <i>NI</i>	241.80	- X
9	1pc	Rear boot reverse camera	Damaged <i>NI</i>	680.90	680.90 ✓
10	1pc	Rear boot weatherstrip	Distorted <i>NI</i>	110.20	110.20 ✓
11	2pcs	Rear boot hinge @ \$89.90	Bent <i>NI</i>	179.80	179.80 X
12	2pcs	Rear boot stopper @ \$12.60	Necessary <i>NI</i>	25.20	25.20 ✓
13	1pc	Rear bumper <i>495.40</i>	Dented/Deformed <i>NI</i>	559.80	559.80 ✓
14	1pc	Rear bumper diffuser	Grazed/Deformed <i>NI</i>	312.60	312.60 ✓
15	2pcs	Rear bumper reflector @ \$89.60	Broken <i>NI</i>	179.20	179.20 X
16	1pc	Rear bumper reinforcement	Dented/Bent <i>NI</i>	481.90	481.90 ✓
17	2pcs	Rear bumper side retainer @ \$58.50	Necessary <i>NI</i>	117.00	117.00 ✓
18	1pc	Rear end panel	Dented/Warped <i>NI</i>	479.60	479.60 ✓
19	1pc	Rear end panel garnish	Deformed <i>NI</i>	126.60	126.60 ✓
20	1pc	Rear exhaust silencer	Dented/Bent <i>NI</i>	591.80	591.80 X
21	2pcs	Rear exhaust mounting @ \$28.20	Distorted <i>NI</i>	56.40	56.40 X
22	1pc	Rear exhaust insulator	Warped <i>NI</i>	120.20	120.20 ✓
23	1pc	Rear floor board	Dented/Bent <i>NI</i>	431.20	431.20 X
24	2pcs	Rear fender inner trim @ \$381.60	N/S Deformed <i>NI</i>	763.20	381.60 <i>100</i>
25	1pc	Rear smart keyless antenna	Damaged <i>NI</i>	191.60	191.60 ✓
26	2pcs	Rear taillamp @ \$520.30	Cracked/Broken <i>NI</i>	1,040.60	1,040.60 ✓
27	2pcs	Rear taillamp panel @ \$165.00	Repair <i>NI</i>	330.00	- X
				9,825.60	8,872.20
Less 20%				(1,965.12)	(1,774.44)
Sub total				7,860.48	7,097.76

7271.8

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	10pcs	Rear boot inner trim clip @ \$4.50	Necessary <i>NA</i>	45.00	45.00 <i>X</i>
2	10pcs	Rear bumper clip @ \$4.50	Necessary <i>NA</i>	45.00	45.00 <i>/</i>
3	10pcs	Rear fender inner trim clip @ \$4.50	Necessary <i>NA</i>	45.00	45.00 <i>/</i>
4	6pcs	Rear taillamp clip @ \$8.50	Necessary <i>NA</i>	51.00	51.00 <i>X</i>
5	1set	Rear reverse sensor	Damaged <i>shut</i>	280.00	220.00 <i>200</i>
Sub total				8,326.48	7,503.76
<u>LABOUR & MISC. CHARGES</u>					
1		To checking rear electrical wiring		50.00	30.00 <i>/</i>
2		To remove, refix rear interior trim to assist repair		120.00	80.00 <i>/</i>
3		To remove, refix exhaust silencer		100.00	60.00 <i>/</i>
4		To remove, refix reverse sensor / camera		80.00	60.00 <i>50</i>
5		To respray undercoating		120.00	80.00 <i>60</i>
6		To respray painting & etc		1,200.00	1,000.00 <i>900</i>
7		Panel beating, cut, weld, remove & replacing above parts		1,200.00	800.00 <i>600</i>
Grand total				11,196.48	9,613.76
Recommended cost of lump sum repair (To its pre-accident condition)					7,700.00

*7887
6309*

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$7,700.00** on a contractual basis. Under normal circumstances, the repair period would be about **6 (Six)** working days.

Yours faithfully,

Constant Appraiser Services


Lim Yong Tian (Sebastian)
Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)
MSAAA



Your Ref: 19.27172

Date: 24th July 2019

Our Ref: CS3/ASM19006857/Uqd3s2-1

M/s AXA Insurance Pte Ltd
C/o: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SFD 2182C
INSURED VEHICLE: WC 5006M ACCIDENT DATE: 13/04/2019**

We thank you for your instruction on 17/07/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SFD 2182C from M/s Constant Appraiser Services.
- b) Final Repair Bill of SFD 2182C from M/s Fastech Auto Pte Ltd.
- c) Singapore Accident Statement of Vehicle SFD 2182C.
- d) Damaged vehicle photographs of SFD 2182C.

Pre-Repair Inspection Date: 17/04/2019 at M/s Fastech Auto Pte Ltd, 1 Kaki Bukit Avenue 6 #01-46/48/50 Autobay Singapore 417883.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SFD 2182C
Make & Model	: Hyundai Elantra
Year of Registration	: 2018
Chassis Number	: KMHD841CMJU744784
Engine Capacity	: 1591 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFD 2182C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	DENTED / BUCKLED	1,628.60	1,628.60
1	REAR BOOT LOGO	NECESSARY	38.60	38.60
1	REAR BOOT EMBLEM 'ELANTRA'	NECESSARY	42.20	42.20
1	REAR BOOT EMBLEM 'ELITE'	NECESSARY	42.20	42.20
2	REAR BOOT LAMP @ \$362.60	CRACKED	725.20	725.20
2	REAR BOOT LICENCE LAMP @ \$48.80	NOT NECESSARY	97.60	-
1	REAR BOOT INNER LOCK	BENT	231.60	231.60
1	REAR BOOT INNER TRIM	NOT NECESSARY	241.80	-
1	REAR BOOT REVERSE CAMERA	DAMAGED	680.90	680.90
1	REAR BOOT WEATHERSTRIP	TWISTED	110.20	110.20
2	REAR BOOT HINGE @ \$89.90	TO REPAIR SEE LABOUR	179.80	-
2	REAR BOOT STOPPER @ \$12.60	NECESSARY	25.20	25.20
1	REAR BUMPER	DEFORMED	559.80	495.40
1	REAR BUMPER DIFFUSER	DEFORMED	312.60	312.60
2	REAR BUMPER REFLECTOR @ \$89.60	NOT NECESSARY	179.20	-
1	REAR BUMPER REINFORCEMENT	BENT	481.90	481.90
2	REAR BUMPER SIDE RETAINER @ \$58.50	NECESSARY	117.00	117.00
1	REAR END PANEL	DENTED	479.60	479.60
1	REAR END PANEL GARNISH	TWISTED	126.60	126.60
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	591.80	-
2	REAR EXHAUST MOUNTING @ \$28.20	NOT NECESSARY	56.40	-
1	REAR EXHAUST SILENCER	WARPED	120.20	120.20
1	REAR FLOOR BOARD	SERVICEABLE	431.20	-
2	REAR FENDER INNER TRIM @ \$381.60	N/S DEFORMED	763.20	381.60
1	REAR SMART KEYLESS ANTENNA	SHORTED	191.60	191.60
2	REAR TAILLAMP @ \$520.30	CRACKED	1,040.60	1,040.60
2	REAR TAILLAMP PANEL @ \$165.00	TO REPAIR SEE LABOUR	330.00	-
	LESS 20% DISCOUNT		-1,965.12	-1,454.36
			7,860.48	5,817.44
SPECIAL NETT ITEMS				
10	REAR BOOT INNER TRIM CLIPS @ \$4.50 (SN)	NOT NECESSARY	45.00	-

Report Ref No. CS3/ASM19006857/Uqd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	REAR BUMPER CLIP @ \$4.50 (SN)	NECESSARY	45.00	45.00
10	REAR FENDER INNER TRIM CLIP @ \$4.50 (SN)	NECESSARY	45.00	45.00
6	REAR TAILLAMP CLIP @ \$8.50 (SN)	NOT NECESSARY	51.00	-
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			466.00	290.00
	LABOUR			
	TO CHECK REAR ELECTRICAL WIRING.		50.00	30.00
	TO REMOVE, REFIX REAR INTERIOR TRIM TO ASSIST REPAIR.		120.00	80.00
	TO REMOVE, REFIX EXHAUST SILENCER.		100.00	60.00
	TO REMOVE, REFIX REVERSE SENSOR / CAMERA.		80.00	50.00
	TO RESPRAY UNDERCOATING.		120.00	60.00
	TO RESPRAY PAINTING & ETC.		1,200.00	900.00
	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOT HINGE, REAR EXHAUST SILENCER AND REAR TAILLAMP PANEL.		1,200.00	600.00
			2,870.00	1,780.00
GRAND TOTAL			11,196.48	7,887.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,300.00

Report Ref No. CS3/ASM19006857/Uqd3s2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.