

ASS. REC. BY:

REF: CS/LPC19012931/P: sf342

**Social instructions:**

Awaiting Records  
Services & maintenance

Surveyor: Sherwin

### ASSIGNMENT (Office)

From (Person): Chew Beng Lee of LPC Date/Time: 22/7/19

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

(OD) / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YM8613P Insured: \_\_\_\_\_

at Workshop no/s Cheng Hoe Motor Pte Ltd Tel: 67556142

of 131K1019 Yigheun Ind Park A #01-374/382

Policy No: \_\_\_\_\_ Claim No: 19/19/19/VCO5/072113

Sum Insured: \_\_\_\_\_

Make of Veh: \_\_\_\_\_

(Client's Record) \_\_\_\_\_ D.O.A. 5/7/74

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 23/7/19 9:10pm Person Contacted: fida Vehicle: IN/OUT

\_\_\_\_\_

[illegible]

## Investigation

## ASSIGNMENT

COR May 2023

From

Date

24/7/19

Estimated Cost

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.

YM 8613P

at Workshop m/s

Cheng Hoe Motor

of 38 woodlands Industrial Park E1 #

Insured

105-04

Policy No.

Claims No.

Sum Insured

Excess

TBA

(Client's Record)

Make of Veli:

Fire Case

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted

Vehicle: IN / OUT

Veh No:

YM 8613P

Vt Regd

13 MAY 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Fu30 (Anter)

c.c 3900

Colour:

white

A/C:

Insured / ☒ / NI / NA

Sp. Reading

-

T/Radio:

Insured / ☒ / NI / NA

Eng No:

4M42A51346

C/No:

FE83BEA10526

Gen. Cond: Good / Fair / Poor / ☒ BurntSteering: In order / Jammed / Leaked / ☒ orBrake: In order / Jammed / Leaked / ☒ orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F: 7.00 R16 4 MEC

R: 7.00 R16 4 BS

☒ BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

5.96 mm

R/Bal:

3.4 mm

L/Bal:

6.46 mm

L/Bal:

7.6 mm

D.O.A:

19/7/2019

D.O.I:

24/7/2019

Survey held at

Cheng Hoe Motor Woodlands

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Undercarriage / Engine fire

The ☒ UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV: 22K

LTA: 13.6K

NL: 8.4K

RECEIVED 19 AUG 2019

for repara

19/8/19 Vehicle recommended total loss due to uneconomical

MV - \$ 22K

LTA - \$ 13.613

NL - \$ 8.3971-

19/8/2019

Date/Time, File Pass / 17

17/08/19

11

Typ: 4

Date/Time, File Return / 17

3



: Prel. Report



: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp \$



Interview \$



Tech. Insp \$



Material \$

Report Format:

Total Loss

Lump Sum / T.B.D.:

Survey Fee

Transportation

S + PS \$

Tolls

Item SCDF

290
\$170
11
431

Total

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jul 2019 Sendback Est	22 Jul 2019 17:54 S\$80.00	22 Jul 2019 18:13 Assign				New Assignment Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

Insured:

TRANS FLORAND PTE LTD, Co. Reg. No.: 199606196W

Vehicle Reg. No.:

YM8613P

Date of Loss:

19/07/2019 11:00 - :59  
[134 Months and 6 Days From LTA Reg Date (Man Yr)]

Claim Type:

OD /  
19/19/19/VC05/022113

Policy/Cover Note No.:

Z19VC05002333 (TP, Fire & Theft)  
Coverage: 13/05/2019 -  
12/05/2020

Excess:

S\$0.00

Repairer:

Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142

Handling Insurer:

Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Chew Beng Kee - 6250 7388 ext 233]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/07/2019]

Driver/Custodian:

ZAIMAN BIN SARIPIN (47 / Male) , NRIC: S7144103B Email:

ASSOCIATED MAIL RECEIVED

View AllCompose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View AllSearch TasksCreate New TaskComplete

Due DatePriorityTypeTask GroupSubjectHandlerAssigned ByCompleted OnCreated OnDone?

No results.

&gt; Back to OneMotoring

YM 8613P

OD/Longue  
(7.12)

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	196W

## Vehicle Details

Vehicle No.:	YM8613P
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Jul 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	FE83BE6SRDEA
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	4M42A51346
Chassis No.:	FE83BEA10526
Maximum Power Output:	-
Open Market Value:	\$25,943.00
Original Registration Date:	13 May 2008
First Registration Date:	13 May 2008
Transfer Count:	0
Actual ARF Paid:	\$1,298.00

## Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

## Intended COE Rebate Details

COE Expiry Date:	12 May 2023
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$17,865.00
COE Rebate Amount:	\$13,613.00
<b>Total Rebate Amount:</b>	<b>\$13,613.00</b>

## Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 20 Jul 2019

OK

Balance 3 yrs 10 mths. using average 6k dep/yr  
 MV = 23K  
~~LRA = 13.61K~~  
 KIL = 9.4K



Fuel Type: Diesel

Good Condition. Low Mileage. Insurance And Road Tax Till 28/05/2019. Price Negotiable. Contact For More Details.



Posted: 07-Jun-2019

Tags: 2007 Mitsubishi Fuso, 2007 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi



☐ Mitsubishi Fuso Canter FE83  
(COE till 04/2023)

Fuel Type: Diesel



Posted: 10-May-2019

Tags: 2008 Mitsubishi Fuso, 2008 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi



Name your price, sell your car

Many car sellers are now turning to consignment dealers to get their car sold. It's simple, convenient and effective with no obligations to sell!

Find out more!



☐ Mitsubishi Fuso Canter FE83  
(COE till 06/2023)

Fuel Type: Diesel

\$5k Above Paper Rebates. Full Canopy With Custom Built Rear Foot Step For Easy Loading. Condition Well Maintained. Damage Will Be Repair Like New. Call Now For A Viewing And Test Drive.



Posted: 14-Jun-2019

Tags: 2008 Mitsubishi Fuso, 2008 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi



☐ Mitsubishi Fuso Canter FE83  
(COE till 07/2023)

Fuel Type: Diesel

Excellent 14 Feet High Deck Lorry Attached With Wooden Decks. Class 3 Can Drive. New Paintwork And Wrapped Seats. Servicing All Done Up. Call Our Friendly Sales Consultant Today For Viewing And Test Drive.

Car (S) Pte Ltd



Posted: 20-Jun-2019

Tags: 2008 Mitsubishi Fuso, 2008 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi



☐ Mitsubishi Fuso Canter FE83  
(COE till 08/2028)

Fuel Type: Diesel

One Careful Owner. Choice Of Colour. Engine In Good Condition. Loan/Trade In Available. Call Now. Don't Miss.



Posted: 03-Jun-2019

Tags: 2008 Mitsubishi Fuso, 2008 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi



☐ Mitsubishi Fuso Canter FE83  
(COE till 09/2023)

Fuel Type: Diesel

Mitsubishi FE83 With Box, Well Taken Care Off. View To Believe. Call In Now For Test Drive And Viewing.



Posted: 04-Jul-2019

Tags: 2008 Mitsubishi Fuso, 2008 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chew Beng Kee

Date: 25 Jul 2019

## Preliminary Advice

Vehicle No	: YM8613P	Accident Date	: 19/07/2019
Make	: MITSUBISHI FE83PE6SRDEB	Policy No.	: Z19VC05002333
Assignment Date	: 22/07/2019	Excess	: S\$0.00
Date of Inspection	: 24/07/2019	Est. Duration of Repair	: -
Inspection At	: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages undercarriage and engine caught fire.

Repairer's Estimate (Gross)	:S\$	80.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	TOTAL LOSS
Lump Sum Repair	:S\$	

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	22,000.00
COE / PARF Rebate	:S\$	13,613.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,387.00

### Remarks

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. Vehicle recommended total loss.
- ( ) Other comments :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/07/2019 10:11
Date Of Accident	19/07/2019 11:30
Exact Location Of Accident	NO. 14 TRACTOR ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	YM8613P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS FLORAND PTE LTD
Co Reg No	199606196W
Email Address	HARSHPAL@TRANSFLORAND.COM
Mobile Phone No	
Alternative Phone No	OFFICE-90624308

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FE83PE6SRDEB-3.9 D (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

### Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	Z19VC05002333
Cover Note Number	EXP 12.5.2020

### Driver

Name of Driver	ZAIMAN BIN SARIPIN
NRIC No	S7144103B
Date Of Birth	08/12/1971
Occupation	OUTDOOR
Date Of Driving Pass	20/12/2014
Driving Experience	4 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91691585
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 878 WOODLANDS AVE 9, 12-286
Postcode	730878
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	SEMBAWANG NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER POLICE REPORT ATTACH

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO



## Sketch Plan

### SKETCH PLAN

VEHICLE NO.: YM 8613P  
INSURER: LONPAC  
DATE & TIME: 19/07/19 12:00 Noon

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 20/7/2019

Driver's Signature

(If driver is not the policyholder)

Date & Time: 20/7/19

Reporting Centre Personnel's Signature


Name: Eduardo

NRIC/FIN No. WC

# Sketch Plan #2

SKETCH PLAN

PARK OPPOSITE 14 TRACTOR ROAD



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

## DECLARATION

I/We declare foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 20/7/2019

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 20/7/2019

Reporting Centre Personnel's Signature  
Name: [Signature]  
NRIC/FIN No. [Signature]

☒ Claim Own Policy ( ) Claim Third Party ( ) Reporting Only  
( ) Claim OD/TP at other workshop ( )

## Sketch Plan #3



**SINGAPORE  
POLICE FORCE**



L/20190719/2071

1 of 2

**POLICE REPORT (NP299)**

Report No. L/20190719/2071

Police Station Of Origin  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE 757633  
Tel No: 1800-5549999

Date/Time Report Made 19/07/2019 18:13	Vide Report No J/20190719/0096	Station Diary No. 69
Name Of Informant ZAIMAN BIN SARIPIN	Address APT BLK 878 WOODLANDS AVENUE 9 #12-286 SINGAPORE 730878	
ID Type / ID No. NRIC NO / S7144103B	Contact No. Home/Office Mobile 91691585	
Nationality SINGAPORE CITIZEN	Email Address	
Occupation DELIVERY DRIVER	Sex Male	Age 47
Institution/School Name	Date of Birth 08/12/1971	Race Boyanesse
	Language English	
Date/Time Of Incident 19/07/2019 12:00 - 19/07/2019 12:00	Location Of Incident 14 TRACTOR ROAD UNNAMED SINGAPORE 627973	

**Brief details.**

On 19/07/2019 at about 1130hrs, I started driving my company's, Trans Florand Pte Ltd, refrigerated 'Mitsubishi' lorry bearing registration number YM8613P, and nothing was amiss. I proceeded to do my delivery to No. 14 Tractor Road and upon reaching the location, I parked my lorry outside the said company and alighted from my lorry to wait for the company's staff to meet up with me. I then heard a pop sound coming from the lorry and subsequently, saw smoke coming from the front of the lorry. I made a check and could see fire from the engine compartment. I immediately approach the security guard and requested for fire extinguisher I tried putting out the fire with two fire extinguisher however was unable to

Signature Of Officer Recording The Report:

L / Sr Staff Sgt FATIN AZRIN BINTE AHAD

Signature Of Interpreter:  
Not applicable

Officer In-Charge Of Case:  
SPF  
Wang Yixin  
Contact No.: 63167398

Signature Of Informant:

Date/Time:  
19/07/2019 18:13

Classification Of Case:

Authentication Stamp





**SINGAPORE  
POLICE FORCE**



L/20190719/2071

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. L/20190719/2071

do so.

Eventually, SCDF arrived at scene to put off the fire. The damage was just to the engine compartment of the lorry and I did not sustained any injury due to the incident. The lorry was sent for servicing regularly and there were no issues with the lorry. There were no tampering marks when I made a check of the lorry.

I am lodging this report for insurance claim purposes.

Signature Of Officer Recording The Report:

L / Sr Staff Sgt FATIN AZRIN BINTE AHAD

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

SPF

Wang Yixin

Contact No.: 63167398


Signature Of Informant:


Date/Time:

19/07/2019 18:13

Classification Of Case:

Authentication Stamp






## YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		EFFECTIVE DATE
Class 2B	Motorcycles =< 200 cc	13 Jan 1993
Class 3	Motor cars with unladen weight =< 3000kg with =< 7 passengers, exclusive of driver; and other motor vehicles with unladen weight =< 2500kg	20 Dec 2014
Class 4	Motor vehicles which are constructed to carry load or passengers and the unladen weight > 2500kg	24 Oct 2016
	Motor vehicles which are not constructed to carry load or passengers and the unladen weight =< 7250kg	

NP 428A



Licence No: S7144103B

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/07/2019 10:11
Date Of Accident	19/07/2019 11:30
Exact Location Of Accident	NO. 14 TRACTOR ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	YM8613P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS FLORAND PTE LTD
Co Reg No	199606196W
Email Address	HARSHPAL@TRANSFLORAND.COM
Mobile Phone No	
Alternative Phone No	OFFICE-90624308

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FE83PE6SRDEB-3.9 D (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

### Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	Z19VC05002333
Cover Note Number	EXP 12.5.2020

### Driver

Name of Driver	ZAIMAN BIN SARIPIN
NRIC No	S7144103B
Date Of Birth	08/12/1971
Occupation	OUTDOOR
Date Of Driving Pass	20/12/2014
Driving Experience	4 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91691585
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 878 WOODLANDS AVE 9, 12-286
Postcode	730878
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	SEMPAWANG NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER POLICE REPORT ATTACH

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO



**SKETCH PLAN**

VEHICLE NO.: YM 8613P  
 INSURER : LONPAC  
 DATE & TIME: 19/07/19 12:00 Noon

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 20/7/2019

Driver's Signature

(If driver is not the policyholder)

Date & Time: 20/7/19

Reporting Centre Personnel's Signature


Name: Shudin

NRIC/FIN No.:

20/7/19

# SKETCH PLAN

PARK OPPOSITE 14 TRACTOR ROAD



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time: 20/7/2019

Driver's Signature

(If driver is not the policyholder)

Date & Time: 20/7/2019

Reporting Centre Personnel's Signature

Name: Efeet

NRIC/FIN No.:

GIANNAC SketchPlan.com V3

☒ Claim Own Policy ( ) Claim Third Party ( ) Reporting Only  
( ) Claim OD/TP at other workshop ( )

20/7/19



# SINGAPORE POLICE FORCE



L/20190719/2071

1 of 2

## POLICE REPORT (NP299)

Report No. L/20190719/2071

Police Station Of Origin  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE 757633  
Tel No: 1800-5549999

Date/Time Report Made 19/07/2019 18:13	Vide Report No. J/20190719/0096	Station Diary No. 69		
Name Of Informant ZAIMAN BIN SARIPIN	Address APT BLK 878 WOODLANDS AVENUE 9 #12-286 SINGAPORE 730878			
ID Type / ID No. NRIC NO / S7144103B	Contact No. Home/Office	Mobile 91691585		
Nationality SINGAPORE CITIZEN	Email Address			
Occupation DELIVERY DRIVER	Sex Male	Age 47	Date of Birth 08/12/1971	Race Boyanese
Institution/School Name	Language English			
Date/Time Of Incident 19/07/2019 12:00 - 19/07/2019 12:00	Location Of Incident 14 TRACTOR ROAD UNNAMED SINGAPORE 627973			

### Brief details.

On 19/07/2019 at about 1130hrs, I started driving my company's, Trans Florand Pte Ltd, refrigerated 'Mitsubishi' lorry bearing registration number YM8613P, and nothing was amiss. I proceeded to do my delivery to No. 14 Tractor Road and upon reaching the location, I parked my lorry outside the said company and alighted from my lorry to wait for the company's staff to meet up with me. I then heard a pop sound coming from the lorry and subsequently, saw smoke coming from the front of the lorry. I made a check and could see fire from the engine compartment. I immediately approach the security guard and requested for fire extinguisher I tried putting out the fire with two fire extinguisher however was unable to

Signature Of Officer Recording The Report:


L / Sr Staff Sgt FATIN AZRIN BINTE AHAD

Signature Of Informant:

Signature Of Interpreter:  
Not applicableDate/Time:  
19/07/2019 18:13Officer In-Charge Of Case:  
SPF  
Wang Yixin  
Contact No.: 63167398

Classification Of Case:

Authentication Stamp





POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. L/20190719/2071

do so.

Eventually, SCDF arrived at scene to put off the fire. The damage was just to the engine compartment of the lorry and I did not sustained any injury due to the incident. The lorry was sent for servicing regularly and there were no issues with the lorry. There were no tampering marks when I made a check of the lorry.

I am lodging this report for insurance claim purposes.

Signature Of Officer Recording The Report:

L / Sr Staff Sgt FATIN AZRIN BINTE AHAD

Signature Of Interpreter:  
Not applicable


Officer In-Charge Of Case:  
SPF  
Wang Yixin  
Contact No.: 63167398

Signature Of Informant:

Date/Time:  
19/07/2019 18:13

Classification Of Case:

Authentication Stamp



**General Checklist for Vehicle Fire Inspection and Investigation**  
**Collision and Non-Collision Fires**

Fire Information:

Date, time of fire 19/10/2019 @ 1130 hrs.  
Location, orientation, position (on road or off) 14 T.200th road.  
Weather (wind direction, speed, rain, etc.)

Summary of circumstances (collision, non-collision, brief description of event):

Fire Vehicle:

Make, model, model year, mileage  
VIN  
Vehicle condition (note unusual operation or configuration, after-market equipment)  
Pre-fire damage (collision, other)

Other Vehicles:

Fire Damage (areas affected):

Collision Damage (areas affected):

System Review for Fire Involvement:

*For each system check all components for evidence of pre-fire damage leading to non-collision fire, or collision damage leading to fire. Check for contribution to ignite or fuel fire. Check engine compartment, undercarriage, passenger compartment, cargo.*

Coolant  
Engine oil  
Automatic transmission fluid  
Power steering fluid  
Gasoline/Diesel/other  
Brake fluid  
Windshield washer fluid  
Electrical (evidence of beading, loose connections)

Exhaust system, turbo (ignition source)

Summary:

Possible Fuels

Possible ignition sources

Possible origin and propagation

Witness interview checklist:

Date of interview

Name of interviewee

Interviewee role in event (driver, passenger, witness)

Narrative of events (minimum questions until after hearing the first narrative)

Conditions at first observation (time in the sequence) Clear weather

- Witness position relative to vehicle (distance, orientation) front vehicle position.

Witness description of his or her own activities (for consideration of timeline) smell

- Time and position of first smoke, first flames, odors, appearance light burning outside.

- Time within sequence of first responder arrival (to compare events to logged times) Scott took 20mins.

- Fluid leaks, sounds Smoke.

Injuries (from collision and fire)

- Owner: Recent service, general condition, operation, system performance, history of performance

- Operator: Operation and conditions prior to and at time of fire, history of performance, occupants in vehicle prior to and at time of fire

- Suppression activities and conditions at the time of suppression

List documents, sources of information:

Police report

Fire report

Service Records ?

Vehicle data (owner's manual, service manual, recall history, service records) / driver to one car ?

Route taken ?

Trips.

Delivery his 11 to 1 @ food.

waiting for customer.

15mins waiting.

noticed  
Smell → sight → flame.

4th.

2x

Smoke → mini explosion → flame → fire extinguisher →

\* 1st

woodlands.

Holland V

NUH.


① Pioneer Sector 1 to 14 tractor.  
Engine not smooth.

on route Delivery Yes.

\* 2nd

off engine @ time of fire?  
off Engine - off-ed.

\* 3rd

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: **Lonpac Insurance Bhd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD LONPAC
Policy No:	Z19VC05002333	Date of Loss:	19/07/2019
Vehicle Reg. No.:	YM8613P	Driveable?	
Driver Age/Info:	47 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TRANS FLORAND PTE LTD		
Driver:	ZAIMAN BIN SARIPIN		

Make/Model:	MITSUBISHI FE83PE6SRDEB, 3.9 D Vehicle Reg. Date: 13/05/2008 (M)		
Vehicle Colour:	WHITE		
Engine No:	4M42A51346	Chassis No:	FE83BEA10526
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	0

Description of Accident/Loss	REFER EFILE REPORT
------------------------------	--------------------

Remarks:	PLS ARRANGE FOR SURVEY AND DISCUSS FURTHER . * FIRE CASE
----------	--

Present Location:	CHENG HOE MOTOR PTE LTD (WOODLANDS)
-------------------	-------------------------------------

**COST OF CLAIMS**

	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	80.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>80.00</b>
<b>+ GST 7.00% (\$\$)</b>	<b>5.60</b>
<b>Nett Amount (\$\$)</b>	<b>85.60</b>

This claim is handled by: **JUNE PHUA LIAN HUA**

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

24/7/2019 @ 1230  
 Not Authorise EXCESS TBA  
 Total LOSS  
 SH LKK Sherwin

Pending Inspection  
 on case of Fire  
 SH

**REPAIR DETAILS****Reference****Part Source:** (Last Synchronised: 22 Jul 2019)**Parts:** N/A MITSUBISHI FE83PE6SRDEB 3.9 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Hoe Motor Pte Ltd/YM8613P/22/07/2019 17:54**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

There are no new parts selected.

Cheng Hoe Motor Pte Ltd/YM8613P/22/07/2019 17:54. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

**Estimates on Miscellaneous Items**

There are no new miscellaneous items selected.

**Estimates on Labour**

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO TOWING	New	80.00
Gross Labour Cost (S\$)			80.00

Cheng Hoe Motor Pte Ltd/YM8613P/22/07/2019 17:54. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;





# Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403

Ah Di Mobile: 8588 8877

Email: efficienttowing.sg@gmail.com

Business Reg. No. 53349344K

NO. 33942

Date: 19/7/19

## CASH SALE / JOB ORDER

Messrs: CHENG HOE MOTOR PTE LTD  
车牌 9M8614 P 车型 2014 J4 1.8L  
Vehicle No. 9M8614 P Model No. 2014 J4 1.8L  
时间 (日/夜) 4.05 PM 联络号码  
Time (day/night) 4.05 PM Contact No.  
由 38 W L Ind Park 05-04  
Location: 22 W L Link 01-29  
To: 80  
Cash \$ 80 其他  
经手人 Others:  
Authorised By: 9L29026  
Tow Truck Driver Name: 9L29026

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

意: 本公司对所拖之车辆, 在拖行中如有任何损失或破坏, 一概由车主自行负责。

Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

E. & O. E.



24 Hours Towing Services

# Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403

Ah Di Mobile: 8588 8877

Email: efficienttowing.sg@gmail.com

Business Reg. No.: 53349344K

NO. 33942

Date: 19/7/19

## CASH SALE / JOB ORDER

Messrs: CHENG HOE MOTOR PTE LTD  
 车牌 9M8614 P 车型 2014 1.8L  
 Vehicle No. 9M8614 P Model No. 2014 1.8L  
 时间 (日/夜) 4.05 PM 联络号码  
 Time (day/night): 4.05 PM Contact No:  
 由 38 W L 1nd Park 05-04  
 Location: 22 W L Link 01-29  
 到  
 To:  
 银额 80 其他  
 Cash S 80 Others:  
 经手人  
 Authorised By: Driver Name: 9L23026

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

意: 本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一概由车主自行负责。

Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

E. & O. E.



## Fire Report Application

Your request for the Fire Report has been confirmed and the amount of SGD170.00 will be deducted from your account. You will receive the report within 8 working days upon completion of investigations. Please quote the following transaction number when making enquiries.

Download Tax Invoice/Receipt

Transaction Number: FR2019072603519

Date/Time: 26/07/2019 14:01

### INCIDENT DETAILS

Date and Time	19/07/2019 11:30
Location of Fire	NO.14 TRACTOR ROAD
Fire Involved	YM8613P

### REQUESTOR DETAILS

Requestor Type	Insurance Companies		
Requestor ID Type	Foreign International	Requestor ID	G2706880X
Name of Applicant	SHIRLEY HIEW		
Company Name	LKK Auto Consultants Pte Ltd		
Company UEN			
Company Reference Number			

### CONTACT DETAILS

Mode of Collection	Email		
Main Contact No.	62563561	Office No.	
Handphone No.		Fax No.	
Email Address	sur@lkkauto.com		
Address	Block No.	Blk Floor No.	02 Unit No. 25
	Street Name	Ubi Avenue 1	
	Building Name	Paya Ubi Industrial Park	Postal Code 408933

### PAYMENT DETAILS

Payment Mode	Credit/Debit Card
EP Reference No.	5641210875576189403234
PSi Reference No.	3df947d2-c9d7-46c7-a6c8-d66ea421dbdf
Total Fees	SGD170.00



SINGAPORE CIVIL DEFENCE FORCE  
91 UBI AVENUE 4  
SINGAPORE 408827  
TELEPHONE: 6280 0000  
GST REG NO: MG-8400000-5

## TAX INVOICE/RECEIPT

Name : SHIRLEY HIEW  
Address : Blk 51 Ubi Avenue 1  
#02-25 Paya Ubi Industrial Park  
Singapore 408933

Receipt No : 5641210875576189403234  
Date/Time : 26/07/2019 14:01  
eService ID : FR2019072603519

S/No	Payment Mode	Description	Reference No	Net Amount	GST (7% GST)	Gross Amount
1	Credit Card	Fire Report	FR2019072603519	170.00	0.00	170.00
					<b>Total Amount (SGD)</b>	<b>170.00</b>

### REMARKS:

Date and Time [19/07/2019 11:30] - Location of Fire [NO.14 TRACTOR ROAD]

Note: This is a computer generated receipt. No signature is required. Receipt is void if payment is dishonoured.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jul 2019 Sendback Est	22 Jul 2019 17:54 <b>S\$80.00</b>	22 Jul 2019 18:13 Edit Adj Rpt	<b>S\$0.00</b> Edit Estimates	<b>S\$0.00</b> View Rpt		<b>Pending for Survey Report</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured: <b>TRANS FLORAND PTE LTD</b> , Co. Reg. No.: 199606196W									
Vehicle Reg. No.: <b>YM8613P</b>		Date of Loss: 19/07/2019 11:00 - :59 <b>[134 Months and 6 Days From LTA Reg Date (Man Yr)]</b>							
Claim Type: <b>OD / 19/19/19/VC05/022113</b>		Policy/Cover Note No.: Z19VC05002333 (TP, Fire & Theft) Coverage: 13/05/2019 - 12/05/2020							
		Excess: S\$0.00							
Repairer: <b>Cheng Hoe Motor Pte Ltd (Yishun)</b> Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142									
Handling Insurer: <b>Lompac Insurance Bhd (HQ)</b> - Tel: +65 62507388 ... [Handled by <b>Chew Beng Kee</b> - 6250 7388 ext 233]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Sherwin Beh Swee Yang</b> ] ... <b>[Final Rpt due 31/07/2019]</b>									
Driver/Custodian: <b>ZAIMAN BIN SARIPIN (47 / Male)</b> , NRIC: S7144103B Email:									
<b>ASSOCIATED MAIL RECEIVED</b> <div style="float: right;">View All   Compose Case Mail</div>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <div style="float: right;">View All   Search Tasks   Create New Task   Complete</div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents





































YM8613P (19/19/19/VC05/022113)

















































OD

Jul 19 2019 11:00AM

[TRANS FLORAND PTE LTD]

Cheng Hoe Motor Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	22/07/19 17:54	Cheng Hoe Motor Pte Ltd (Yishun) <b>Repairer Estimates</b>	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/07/19 10:09	<b>Adjuster Immediate Advice</b>	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
29	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
30	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
31	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
32	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
33	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
34	25/07/19 16:08	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
36	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
37	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
38	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
39	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
40	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
41	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
42	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
43	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
44	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
45	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
46	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
47	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
48	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
49	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
50	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
51	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
52	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
53	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
54	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
55	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
56	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
57	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
58	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
59	25/07/19 16:08	General View	 Load JPG	<input checked="" type="checkbox"/>
60	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
61	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
62	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
63	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
64	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
65	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
66	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
67	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
68	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
69	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
70	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
71	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
72	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
73	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
74	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
75	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
76	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
77	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
78	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
79	25/07/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	22/07/19 17:52	E-filed GIA report	 Load PDF	
2	22/07/19 17:53	Driver's NRIC	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
				<input checked="" type="checkbox"/>
3	22/07/19 17:53	Driver's NRIC	 Load JPG	<input checked="" type="checkbox"/>
4	22/07/19 17:53	Driving Licence	 Load JPG	<input checked="" type="checkbox"/>
5	22/07/19 17:53	Driver's Driving License	 Load JPG	<input checked="" type="checkbox"/>
6	22/07/19 17:56	tow fee	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/07/19 10:27	YM 8613P GIA.pdf	 Load PDF	
2	25/07/19 10:27	ESTIMATE.pdf	 Load PDF	
3	19/08/19 15:50	Fire Report	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse  
Singapore 199555

Our File No: CS/LPC19012931/PSF3E2

Date: 19/08/2019

### REFERENCE

Insured/Claimant: TRANS FLORAND PTE LTD Policy No: Z19VC05002333  
Date of Loss: 19/07/2019 Nature of Claim: OD Claim No: 19/19/19/VC05/022113

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YM8613P**  
Make & Model: MITSUBISHI FE83PE6SRDEB, 3.9 D (M) Engine No: 4M42A51346  
Reg. Date: 13/05/2008 (Man. Year: 2007) Chassis No: FE83BEA10526  
Colour: White Odometer: 0 km  
Engine Capacity: 2977 cc  
Market Value/New Car Price: S\$22,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 7.00 R16 Rear Tyre Size: 7.00 R16  
Front Left Side: Michelin 6 mm Rear Left Side: Bridgestone 7 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	80.00	0.00	80.00	100.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>80.00</b>	<b>0.00</b>	<b>80.00</b>	<b>100.00</b>
<b>+ GST 7.00/0.00% (S\$)</b>	<b>5.60</b>	<b>0.00</b>	<b>5.60</b>	<b>100.00</b>
<b>Nett Amount (S\$)</b>	<b>85.60</b>	<b>0.00</b>	<b>85.60</b>	<b>100.00</b>

### INSPECTION

Date of Assignment: 22/07/2019 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)  
Date Inspected: 24/07/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)  
Blk 1019 #01-374/382, Yishun Industrial Park A  
Singapore 768761

Estimated Period of Repair: 0.0 days

Adjuster: Sherwin Beh Swee Yang

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :       \$ 22,000.00  
OMV :               \$ 25,943.00  
PARF Rebate (1) :     \$ 0.00  
Quota Premium Paid :   \$ 17,865.00  
COE Rebate (2) :     \$ 13,613.00  
Total Rebate (1) + (2) = : \$ 13,613.00

The total amount incurred will be Market Value \$ 22,000.00 minus Total Rebate \$ 13,613.00 = \$ 8,387.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 19 Aug 2019)	
<b>Parts:</b>	N/A	MITSUBISHI FE83PE6SRDEB 3.9 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YM8613P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TOWING	New	80.00	0.00
Gross Labour Cost (S\$)			80.00	0.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >