

(000000)

INS. CASE OWNER

CC 3/EQ1901

LKK

IDAC

Surveyor

KALVIN

DOI

ASSIGNMENT

W 7/19

Date / Time

W 7/19

Registered in Merimen

Pre-assign / CCU / FTE



Insured Vehicle No.

GBH 3626J

Name of Insured

MAJESTIC TRADER PLC

Insured Tel No.

HP:

Excess Sec II :SS

D.O.A:

20/7/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age: JOE VEO

Driver Tel No.:

(V/L: YES / NO)

Claim No.

0000000000

Policy No.

0000000000000000

Make / Model:

TOYOTA

Place of Accident:

WOODLANDS ME 6

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SHL 3090

INSRS:
WSP:
Tel:
Liability:
RMKS:L266
MINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

20/10 - send LOR
 10/11 - offer after 10/11/19.
 12/11 - offer \$1656.25 (pending acceptance)
 SHL 3090 \$1656.25, NO OR required.
 file paid SHL per to close.

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P12

SS

1211.05

1 days

Reduction:

1000

%

8

FINAL SETTLEMENT

Date/Time:

Confirm with:

JIM

Email

Call

Final Liability:

100

SS

1211.05

(Agreed / Assessed)

BOLA S/N No.:

23

If NO or B 28, Ass. Lia:

Repair Cost:

(W/LOR)

SS

1211.05

Loss of Rental (LOR):

SS

262.94

1

days

x

\$126.43

Loss of Use (LOU):

SS

15

x

days

x

\$126.43

Loss of Income (LOI):

SS

100.00

(5

x

2 days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

2.49

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost

SS

Total:

SS

1656.25

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

1656.25

Name 1:

Comfirm Digno Engineering Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$40

OK
4/11
OK

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO	:	305318825
REGN NO	:	SHC3381U
MILEAGE	:	0000000000
MAKE	:	TOYOTA
MODEL	:	PRIUS HYBRID(G4)
DATE OF REGN	:	02.05.2019
DATE/TIME IN	:	21.07.2019 07:40
ACCIDENT DATE	:	20.07.2019

JOB / PARTS DESCRIPTION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
-----	-----	------------	-------	--------

PART REQUISITION

0001	04-01-0302-0897-G	PRIG4 COVER OUTER MIRROR	1	107.40	25.00	80.55	✓
0002	04-01-0302-0600-G	PRIG4 MIRROR ASSY OUTER R	1	1,374.00	25.00	1,030.50	✓

SUB-TOTAL : 1,111.05

JOB NATURE

0000 PB	PANEL BEATING
0001 SP	SPRAYPAINT CHARGE

SUB-TOTAL : 200,00

TOTAL : 1,311.05

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE _____

DATE: _____

DATE: _____

AUTHORISED: YES / NO

the following:
- weather spray paint
- damaged parts(s) com-
- parts are subject to con-
- survey is on a "10"
- modifications
- accessory items
- subject to final inspec-

Acknowledged by the
Signature: _____
Date: _____

Kali 1000
2/7/19 10
1000
P18
Before point pl

COMFORTDELGRO

Date/Time: 22.07.2019 08:34

Page: 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JO NO.: 305318825

MEMBER NO. 7010045
COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755


REGN NO.	SHC3381U	MILEAGE
MAKE	TOYOTA	FUEL E 1/2 F
MODEL	PRIUS HYBRID(G4)	DATE/TIME IN 21.07.2019 07:40
YR OF MANUF	02.05.2019	TARGET DATE
CHASSIS CODE	JTDKCB3FU203080494	COMPLETION DATE/TIME

UNIT CARD NO.

JOB DESCRIPTION

Accident Date: 20.07.2019
NATURE: 3P 20.07.19

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

ID: SHC3381U

JU EQ

Vehicle No.: SHC3381U

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/EQ119012947/K1gb3

Date: 23.07.2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC3381U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.07.2019 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	1,311.05
Revised Estimate Amount	: S\$	1,211.05
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 1 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

COMFORTDELGRO ENGINEERING

Our Job Ref No 35318825
Date : 24/07/2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax :
Attn : KALVIN
: SHC3381U Date of Accident : 20/07/2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: EQ --- GBH3626J
###
2. The finalized amount shall be:

(a) Spare Parts after List discount		\$1,111.05
(b) Labour Charges	###	\$100.00
Total for Part-By-Part Repair Cost		\$1,211.05
(c) Lumpsum Repair (if applicable)	N	
Total for Lumpsum repair cost after Less: <u>20%</u>		
Final Lumpsum Repair cost		
3. Estimated normal period for repairs: 1 working days
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : Kahl
Date : 25/7/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305318825
REGN NO : SHC3381U
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 02.05.2019
DATE/TIME IN : 21.07.2019 07:40
ACCIDENT DATE : 20.07.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-0897-G	PRIG4 COVER OUTER MIRROR	1	107.40	25.00	80.55
0002 04-01-0302-0600-G	PRIG4 MIRROR ASSY OUTER R	1	1,374.00	25.00	1,030.50

SUB-TOTAL : 1,111.05

JOB NATURE

0000 PB	PANEL BEATING	50.00
0001 SP	SPRAYPAINT CHARGE	50.00

SUB-TOTAL : 100.00

TOTAL : 1,211.05

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305318825
 REGN NO : SHC3381U
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 02.05.2019
 DATE/TIME IN : 21.07.2019 07:40
 ACCIDENT DATE : 20.07.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-0897-G	PRIG4 COVER OUTER MIRROR	1	107.40	25.00	80.55	✓	~30%
0002 04-01-0302-0600-G	PRIG4 MIRROR ASSY OUTER R	1	1,374.00	25.00	1,030.50	✓	~2%
					SUB-TOTAL : 1,111.05		

JOB NATURE

0000 PB	PANEL BEATING	100.00	50
0001 SP	SPRAYPAINT CHARGE	100.00	50
		SUB-TOTAL : 200.00	

TOTAL : 1,311.05

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

- Third party must be approved
- No illegal modifications is allowed
- Supplementary items must be resubmitted and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10.4.6.

Jumani

Kali 1000

/

22/7/19

1 Dg.

P/P

Before Paint p/lk

Shu Pei (LKKAUTO)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Tuesday, 3 September 2019 3:02 PM
To: Shu Pei (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GBH3626J (OI : EQI - DM19HO02086-JG) AND SHC3381U (TP : LKK REF - CC3/EQI19012947/K1gb3) on 20.07.2019
Attachments: GBH3626J.PDF

Dear Shu Pei

Attached our insured's accident report for your attention.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

2 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg

A Member of Citistate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Joel Goh
Sent: Thursday, August 29, 2019 9:22 AM
To: 'Shu Pei (LKKAUTO)'
Subject: RE: Direct Settlement - Accident Involving GBH3626J (OI : EQI - DM19HO02086-JG) AND SHC3381U (TP : LKK REF - CC3/EQI19012947/K1gb3) on 20.07.2019

Dear Shu Pei

Our insured has not reported this accident.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6273 4190 | tel 65 6273 9433 ext 772 | fax 65 6273 4190

EQ Insurance Company Limited

A Member of CityU Life

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]

Sent: Thursday, August 29, 2019 9:18 AM

To: Joel Goh

Subject: RE: Direct Settlement - Accident Involving GBH3626J (OI : EQI - DM19HO02086-JG) AND SHC3381U (TP : LKK REF - CC3/EQI19012947/K1gb3) on 20.07.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg>

Sent: Wednesday, 14 August 2019 2:47 PM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBH3626J (OI : EQI - DM19HO02086-JG) AND SHC3381U (TP : LKK REF - CC3/EQI19012947/K1gb3) on 20.07.2019

Dear Shu Pei

Our insured has not reported this accident.

Best Regards,

Joel Goh

EQ Insurance Company Limited

eqinsurance
Where's Got 2 Friends

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6223 4190 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citicorp



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]

Sent: Wednesday, August 14, 2019 9:11 AM

To: Joel Goh

Subject: RE: Direct Settlement - Accident Involving GBH3626J (OI : EQI - DM19HO02086-JG) AND SHC3381U (TP : LKK REF - CC3/EQI19012947/K1gb3) on 20.07.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg>

Sent: Monday, 5 August 2019 9:02 AM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBH3626J (OI : EQI - DM19HO02086-JG) AND SHC3381U (TP : LKK REF - CC3/EQI19012947/K1gb3) on 20.07.2019

Dear Shu Pei

Our insured has not reported this accident.

Best Regards,

Joel Goh

EQ Insurance Company Limited

4

Joel Goh

Insurance Claims



EQ Insurance Company Limited

Maxwell Road #17-00 Lower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Tuesday, July 23, 2019 6:44 PM

To: Joel Goh

Cc: Admin A; Cecilia Chong (LKK Auto)

Subject: Direct Settlement - Accident Involving GBH3626J (OI : EQI - TBA) AND SHC3381U (TP : LKK REF - CC3/EQI19012947/K1gb3) on 20.07.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 3381U at M/s ComfortDelGro Engineering Pte Ltd - Loyang on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Cecilia and she can be contacted at DID: 6749 4274.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Cecilia Chong (LKK Auto)

From: Jim Wong See Pah <jimwong@cdge.com.sg>
Sent: Wednesday, 13 November 2019 3:13 PM
To: Cecilia Chong (LKK Auto)
Subject: Re: YOUR REF: T0719/SHC3381U (OUR REF: CC3/EQI19012947/K1gb3) *** ACCIDENT INVOLVING GBH 3626J & SHC 3381U ON 20/07/2019 ***

Dear Ms Chong

Please process settlement in sum \$ 1656.25 to resolve our property damage claim amicably.

Additionally, it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Thank you

Best Regards
Jim Wong
Claims Dept / ComfortDelgro Engineering Pte Ltd



Think Before Printing

From: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Sent: Wednesday, 13 November 2019 9:22 AM
To: Jim Wong See Pah <jimwong@cdge.com.sg>
Subject: YOUR REF: T0719/SHC3381U (OUR REF: CC3/EQI19012947/K1gb3) *** ACCIDENT INVOLVING GBH 3626J & SHC 3381U ON 20/07/2019 ***

WITHOUT PREJUDICE

Dear Jim,

We are pleased to offer total amount of \$1,656.25 (all-in).

Kindly confirm acceptance.

Thanks

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 19/11/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBH 3626J	(Insd Veh)	Your Ref. No. : DM19HO02086-JG
	SHC 3381U	(TP Veh)	Our Ref. No. : CC3/EQI19012947/K1gb3q2
Date of Accident	20/7/2019		

Liability	100%	
Final Repair Cost	: \$ 1,295.82	
Loss of Income	: \$ 100.00	2 days
Rental (If any)	: \$ 252.94	2 days
Others:	: \$ 7.49	
	: \$	
	1,656.25	
Final Settlement Sum	: \$ 1,656.25	
Remarks	:	

Payment Instruction: Payee's Breakdown		
1)	COMFORTDELGRO ENGINEERING PTE LTD	: \$ 1,656.25
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQI19012947/K1gb3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 19-11-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 3626J	Veh. Inspected	SHC 3381U
Policy No.	DMCPHQ19-002093	Coverage (\$)	0.00
Claim No.	DM19HO02086-JG	Excess (\$)	0.00
Assign From		Assign Date	22/07/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTDKB3FU203080494	Colour	BLUE
Odometer	38912	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S WING MIRROR.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/07/2019	Inspection Date	22/07/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3381U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER OUTER MIRROR	CRACKED	107.40	107.40
1	MIRROR ASSY OUTER R	MISSING	1,374.00	1,374.00
	LESS 25% DISCOUNT		-370.35	-370.35
			1,111.05	1,111.05
	<u>LABOUR</u>			
	PANEL BEATING.		100.00	50.00
	SPRAYPAINT CHARGE.		100.00	50.00
			200.00	100.00
	GRAND TOTAL		1,311.05	1,211.05
RECOMMENDED COST OF REPAIRS				1,211.05

Report Ref No. CC3/EQ119012947/K1gb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.