

Our F	Ref
-------	-----

T 0719 / SH 7012C /WT(st)

Your Ref:

Date

06-Aug-19

CDGE Taxi Claims Dept

59 Loyang Drive 4th Flr

Singapore 508969

ComfortDelGro Engineering Pte Ltd

Mainline +65 6383 6280 Facsimilie +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

Workshops

Braddell

59 Loyang Drive Singapore 508969

Sin Ming 383 Sin Ming Drive Singapore 575717

Pandan 45 Pandan Road Singapore 609286

Senoko 24 Senoko Loop Singapore 758156

Sungei Kadut Sungei Kadut Wa Singapore 728791

nun Industrial Parl Singapore 768732

CHINA TAIPING INSURANCE CO LTD 3 ANSON ROAD

#16-00 SPRINGLEAF TOWER SINGAPORE 079909

Attn: Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING OUR TAXI SH 7012C YOUR INSURED YN 2529J 19.07.19 AND OTHER ON

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor SH 7012C which was involved in the captioned accident with your insured Vehicle No: vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving YN 2529J we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 5,649.10
6	4.5 days Loss of Rental @ \$ 125.40 per day	\$ 564.30ish
3	Survey Report Fees (Surveyed by M/s LKK)	\$
4	LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transporation Fees	\$ -
	Sub Total :	\$ 6,220.89

HIRER'S CLAIM

days Loss of Income @ \$ 80.00 per days 360.00 \$ **Total Claims:** 6,580.89

We enclose herewith the following documents to support the claims: -

a) Original repair bill and photocopies of photographs:

5 pcs. YN 2529J

b) LTA search slip/s of:

c) GIA / Police report/s of:

SH 7012C

d) Letter of authority from owner / hirer / operator

() Traffic Compound () Towing/Medical bill/receipts () Certificate of Insurance

(X) Photograph/s of Accident Scen(x) Downtime/Mileage record

(x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully William Tan

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email: williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of









LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

SONATA SH7012C , YN2529J

ALONG PANDAN LOOP

I / We

ALONG

KELVIN LIONG

(Hirer) NRIC No.:

SXXXX417C

ON 19-Jul-19 18:40

and/or

(Relief) NRIC No.: SXXXX417C

Taxi Number

SH7012C

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

20-Jul-2019

Name of Hirer

KELVIN LIONG

Hirer NRIC

SXXXX417C

Signature:

Address

329 CLEMENTI AVENUE 2 #10-242

120329

Contact No.

87745949



A member of **COMFORTDELGRO**

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 7687

COMPANY REG. NO.: 199506048W

3 ANSON ROAD #16-00 SINGAPORE SG 079909

CONTACT NO: 62222366

VEHCLE NO SH 7012C

INV. NO/DATE 91458139 30.07.2019

MAKE TOYOTA

MODEL

ODOMETER READING

DATE OF REG 25.05.2017

DATE/TIME IN 19.07.2019 18:40

CHASSIS CODE JTDKB3FU103556797

20001		. 2025	O I DI LOCI	0100000171		
S/No	Part No.		Qty	Unit Price	%Disc	Net
PART	REQUISITION					
0001	04-01-0302-4891	PRIG4 LAMP ASSY FOG LH	1	920.00	25.00	690.00
0002	04-01-0302-2292	PRIG4 COVER FRONT BUMPER	1	499.90	25.00	374.92
0003	04-01-0302-2267	PRIVC BUMPER PIECE	10	2.20	25.00	16.50
0004	04-01-0302-2871	PRIG4 SUPPORT FRONT BUMPER SIDE LH	1	77.00	25.00	57.75
0005	04-01-0302-2815	PRIG4 UNIT ASSY HEADLAMP	1	3,455.00	25.00	2,591.25
0006	04-01-0302-0574	PRIG4 FENDER SUB-ASSY FRONT LH	1	945.32	25.00	708.99
0007	04-01-0302-2297	PRIG4 EMBLEM SIDE PANEL (HYBRID)	1	53.50	25.00	40.12
		PAT A STATE OF THE	TT MARKET			1 100 00

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

A	CCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
	8010012	91458139	5,649.10	

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops Workshops 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 76873

COMPANY REG. NO.: 199506048W

		1			5.3
	- 1	- 3			1
 \sim	radar 1		\sim	and the	Low

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE SG 079909

VEHCLE NO

MAKE TOYOTA

PRIUS HYBRID (G4)

DATE OF REG 25.05.2017

DATE/TIME IN 19.07.2019 18:40

CHASSIS CODE JTDKB3FU103556797

S/No	Part No.		Qty	Unit Price %Disc	Net
JOB N	ATURE				
0001	PB	PANEL BEATING		300.00	300.00
0002	23-502	SPRAYPAINT ON AFFECTED AREA		400.00	400.00
0003	17-01	WIRING CHARGE		20.00	20.00
0004	20-00	TUFF COAT ON AFFECTED PARTS.		20.00	20.00
0005	23-01	TOWING FEE		60.00	60.00
			SUB-TOTAL	137	800.00

			0,2,5,00
Add GST	@	7.000 %	369.57
Invoice	amount		5,649.10

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No. INVOICE No. **AMOUNT** BANK/CHQ No. 5,649.10

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649

3 ANSON ROAD #16-00 SINGAPORE SG 079909

VEHCLE NO

INV. NO/DATE 91458139 30.07.2019

MAKE

MODEL PRIUS HYBRID (G4) ODOMETER READING

DATE OF REG 25.05.2017

DATE/TIME IN 19.07.2019 18:40

CHASSIS CODE JTDKB3FU103556797

Issued by : CHEWBEELENG 30.0 Repair type : CLSO/57/57 Payment Type/Term: /Credit 30 days CHEWBEELENG 30.07.2019 10:33:46

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

BANK/CHQ No ACCOUNT No. **INVOICE No. AMOUNT** 5,649.10

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT19070516

Date: 25 July 2019



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

19/07/2019 @ 18:40 hrs

ALONG

ALONG PANDAN LOOP

INVOLVING

YN2529J

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SH7012C** (the "Taxi"). The Taxi was hired to **KELVIN LIONG IC NO S7343417C** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate \$125.40 per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

Γ	<u> </u>			~				AREA COLORED		
	SATED (TIME	10	l	1700						-
	HOURS OPERATED (TIME)	FROM	(846			×				
	MILEAGE	(KM)	2)	0 2		,				
	(5								
		MILEAGE READING								
-		AGE								
0						7.				
2										
010110	NAME OF DRIVER	AAVIAU OF DAIVER	Accupent	fee Posive	/				•	
	DATE	7	19.07.19	22.07.19						
	PERATED (TIME)	07								

Insurance Particulars Enquiry By Agents Detail

https://vrl.lta.gov.sg/lta/vrl/action/insPartDetailByAA?FUNCTIO...

Enquire Vehicle Insurance Details

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

C01

YN2529J

19 Jul 2019 / 18:40:00 Successful

ssful

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Previous

OK