1	ASS. REC. BY		REF: CS/M	15G19012958/AC	AVF3()) Special Instru	ction:
*,	The state of the s	Adrian	-	GNMENT (Office)		*
Milma			n Gelclag	msig	Date/Tim	ne: 23/1/19
	Estimated Co			Bill to:		
	To Inspect V	chicle No: Sr	RESIEVAINV NC 3769B		Insured:	5GK 5242U
242				Recovery sovias	Tel: 674	
				Road 1 #01-60)	
	Policy No:	2900	2696QMX	Claim No:	6	00347
	Sum Insured:			Excess:		
	Make of Veh (Client's Recor				D.O.A.	20.7.2019
		REP. / REV. 2.	4 HRS Open 2 Person Con	ntacted: Apple	нор	Endorsement:
	Late/Time	Action/Instructi	on (V) E	stimate		
			169B X			
			42U X		9	
	25/7/19	Informe	- P	ending workshop		meri men
1	16/8/19	Send Dre	confirmed '	LS \$ 2200 '	(Red 552	[1.33, 54]

(Zananiua)

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status		
Main	22 Jul 2019						Cancel C	The state of the s	
	Main	Re	ference	Clai	m Details	Docum	nents	Show All	
	WEEN DED DE	TATIC				[[reated by in	surer]	
nsured:	UBFOLDER DE		HIANG CHIAW,	ID: S1129524	z, Tel: +65962717	36, Email: NO	EMAIL		
	mant:		and the second s	S1709897G					
Main Claimant: Vehicle Reg. No.:			769B	Da	Date of Loss:		20/07/2019 14:00 - :59 [12 Months and 21 Days From LT Reg Date (Man Yr)]		
Claim Type:		TP /	500347	Po	Policy/Cover Note No.:		29002696QMX (Comprehensive) Coverage: 16/08/2018 - 15/08/2019		
Vahiela D	eg. No. (Insured	· SGK5	SGK5242U		Policy No. (Claimant):				
venicle K	eg. No. (Insured				cess:				
Repairer:		People	People's Vehicle Recovery Service (HQ) Blk 3023A Ubi Rd 1, #01-60, 408717 Ubi - Tel: 67433246 MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 [Handled by Irene Tan Gek Ing -						
Handling Insurer: MSIG Insurance (Sin			Insurance (Sing	apore) Pte. Lt	d. (HQ) - Tel: +65	5827 7888 [H	andled by Ire	ne Tan Gek Ing -	
Adjuster:		LKK A	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Imm.Advice due 24/07/2019]						
Driver/Cu	ustodian (Insured	d): CHUA	CHUA HIANG CHIAW (64 / Male) , NRIC: S1129524Z, Tel: +6596271736 Email: NOEMAIL						
Adj Asg.	Remarks:	on WP	. Liab:100% Assig	n LKK Apple 67	43 3246				
ASSOCI	ATED MAIL RE	CEIVED				View	All Co	mpose Case Mail	
There are	e no mail for this	case.							
=							Create New Ta	sk Complete	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

MSIG Insurance (Singapore) Pte. Ltd. To:

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Irene Tan Gek Ing

Date:

16 Aug 2019

Preliminary Advice

Insured Vehicle No : SGK5242U

: SMC3769B

Accident Date

: 20/07/2019

Make

: TOYOTA PRIUS

Assignment Date Est. Duration of Repair : 23/07/2019

Date of Inspection

: 25/07/2019

: 4

Inspection At

TP Vehicle No

: PEOPLE'S VEHICLE RECOVERY SERVICE (HQ)

BLK 3023A UBI RD 1, #01-60

SINGAPORE 408717

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,771.33
Revised Amount	:S\$	2,200.00 (LUMP SUM
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,200.00

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

The vehicle is economical/not economical for repair.

(X)

The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with:

*SMC3769B (600347) [SGK5242U]

TP CHUA SIA YONG
Jul 20 2019 2:00PM
[CHUA HIANG CHIAW]
People's Vehicle Recovery Service

Resend	View Recipients	Print Message	Delete Message	Forward	
From	LKK Auto Cons	ultants Pte Ltd	(LKK_HQ), sent	on 25/07 /	2019 17:26 PM.
То	MSI_ITAN				
Subject	TO CLIDVEY DE	PORT SMC 3769	98		

Dear Irene,

Please be informed that we have inspected the vehicle SMC 3769B on 25/7/2019.

We are pending estimate from repairer.

Best Regards, Veron Chen

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, yo aforesaid.	u hereby consent to the archiving of this report at the centre and to	copies of the report being made available	
	ACCIDENT STATEMENT		
Date Of Report	22/07/2019 11:02		
Date Of Accident	20/07/2019 14:00		
Exact Location Of Accident	JUNCTION OF MARTIA ROAD & ST.P.	ATRICK ROAD	
Country/State of Loss	SINGAPORE		
THE RESERVE OF THE PARTY OF THE	DETAILS OF OWN VEHICLE		
Vehicle Registration Number	SMC3769B		
Insured/Policyholder			
Name Of Registered Owner	CHUA SIA YONG		
NRIC No	S1709897G		
Email Address	LEOCHUA.9897@GMAIL.COM		
Mobile Phone No	(LOCAL) +65-93686241		
Alternative Phone No	OTHERS-93686241		
Vehicle Particulars			
Manufacturer	TOYOTA		
Model	PRIUS-1.5 HYBRID CVT (A)	32:1	
Exact Purpose for which vehicle was bei	ing used at	140	

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY PRIVATE HIRE

Insurance Company

Vehicle Category

Name of Insurance Company

FWD SINGAPORE PTE, LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

PNCV2019-00000652

Cover Note Number

Driver

Name of Driver CHUA SIA YONG NRIC No S1709897G

Date Of Birth 29/08/1965 Occupation **INDOOR** Date Of Driving Pass 29/06/1983

Driving Experience 36 YEARS AND 0 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-93686241

Fax Number

Contact Number OTHERS-93686241

EMail Address LEOCHUA.9897@GMAIL.COM Address

BLK 56 PIPIT ROAD #10-22

SINGAPORE

Postcode

370056

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CROSS JUNCTION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: PAX 1

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SGK5242U

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 14

DETAILS OF INJURED PERSON 1

Name

CHUA SIA YONG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SMC3769B

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, adnowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (iii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my dalms (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes"]
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GUA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of froud detection, investigation and management in present and all future claims.
- the information to collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder¹ Date & Tame: 20/07/2019

Orlver's Signature (If driver is not the policyholder) Date & Time:

11: 15 am

Reporting Centre Perso nel's Signature

KRIC/FIN No.:

		Vehicle A - 5 M C 5 주리 8 B - 56 F 52 주구
St Patrick Rd.	Partick Rd	Legend &
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT		
On 20/07/2019, at about 14.00 nour		
-towards patrick Road - At the junction		
before the stop line , maiting for re	oade to clear before	turning into
Patrick Road . A vehicle 66K 52+21	I came from patrick d	noticed the driver
was very distracted and looking an		
with signal might light not turning o		
into Martia Road, but with big.		
towards my vehicle, still stopped		
the driver of vehicle sak 5242U		
nitting my vehicle, causing damag		
guard dented. There was a passe		the time of
secident what's all a hours to c	ay.	
accident. That's all I have to so		
accident . that I all J have to s		

DECLARATION

I/We declare the foregoing particulars are true in every respect.
Please be advand the year place may have a fourteen (14) days clause othereby the claim against own policy neast be made within the stipulated timely and from the day of occurrence which check your policy for more details.

Policyholder's Signature Date & Time: 22/07/2019


11.15 aM

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

DRIVER NRIC & LICENSE Pg. 1













T/20190724/2204

1 of 3

Report No. T/20190724/2204

Police Station Of Origin: MacPherson NPP 54 Pipit Road #01-82/84 SINGAPORE 370054

Tel No: 1800-7449999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/07/2019 21:37			Vide Report No.:	Station Diary No.: 47	
tretare.	in Famile	ulars			
	Informant:	-	Address: APT BLK 56 PIPIT ROAD #	10-22 SINGAPORE 370056	
ID Type / ID No.: NRIC NO / S1709897G			Contact No.: Home/Office: Mobile: 93686241		
National SINGAP	ity: ORE CITIZ	ΈN	Email:		
Sex: Age: Date of Birth: Male 53 29/08/1965			Type of Informant: Driver		
Race: Chinese			Language:	Institution / School Name:	
Occupat	tion: hop sales n	nanager	Driving Licence Information: Class: 3	Date of Expiry:	

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 20/07/2019 14:00	Type of Location: X-Junction
Location: Along Road 1 MARTIA ROA Junction of Ma	.D artia Road & St.Patrio			Dayl Canad Limits
Weather: Clear		Road Surface: Dry		Road Speed Limit:
1141116		Traffic Control: Not Controlled		Traffic Volume:
Type of Collis	ion: ing Vehicles - Head (On		Anyone conveyed by ambulance:

Ver	Type		Model	Color	Condition	No of Passeng
SGK5242U	Car	Constitution and Constitution of the Constitut		W A	Slightly Damaged	0
SMC3769B	Car	TOYOTA	PRIUS C HYBRID 1.5 CVT	Beige	Slightly Damaged	1

DESCRIPTION OF THE PARTY OF THE	sercie insuralice			
Vehicle No.	Insurance Company	Insurance No.	- Effective	Expiry Date
SMC3769B	FWD Singapore Pte. Ltd	PNCV2019- 00000652	29/06/2019	28/06/2020





3 of 3

Report No. T/20190724/2204

Police Station Of Origin: MacPherson NPP 54 Pipit Road #01-82/84 SINGAPORE 370054 Tel No: 1800-7449999

CONTINUATION OF REPORT

Sketch Plan

NP168

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Sgt 1 YIP YONG NAN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 24/07/2019 21:37
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp	





Police Station Of Origin: MacPherson NPP 54 Pipit Road #01-82/84 SINGAPORE 370054 Tel No: 1800-7449999 2 of 3 Report No. T/20190724/2204

CONTINUATION OF REPORT

Brief Details.

On 20 july 2019, at about 1400hrs, i was driving along Martia Road towards Patrick Road. At the Junction of these two roads. I stopped before the stop line, waiting for the road to clear before turning into st patrick road. A vehicle SGK5242U came from St.Patrick road, i noticed that the driver was distracted and looking around while is car was still in motion with signal light not turning on. The vehicle just turned into Martia road, but with a big angle and came straight towards my vehicle. I honk at the vehicle however the vehicle collided to my vehicle, causing damage to front right door and mud guard was dented. There was a passenger in my vehicle at the time of the accident.

PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717 Tel No.: 67433246/ 67438552 Fax No.: 67430013

E-Mail: peoplevehicle@gmail.com

Tax Reg. No.: M90001895E Buss. Reg. No.: 31800200X

MSIG INSURANCE (SINGAPORE) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 (S) 068807

TPMS19. Attention: Motor Claim Department

Contact: 68277888 Fax No.: 6827 7800

Voren.

Estimate: ES19023

Date : 23/07/2019 Vehicle Num. : SMC 3769 B Make/Model : TOYOTA PRIUS

Chassis/Eng#:

Accident Date: 20/07/2019 Claim No.: TT 353-19

Reference: SGK 5242 U

Policy No.: FWD PNCV2019-00000652

S/N	Quantity	Particular		Unit Price	Amount S\$
1. 2. 3. 4. 5. 6. 7. 8. 9.	1 1 1 2 1 1 1 1 1 8 1	LIST ITEMS: FENDER R/H FRT DEVICE HYBRID EMBLEM DOOR R/H FRT DEVICE DOOR HINGE R/H FRT NEW DOOR OUTER MOULDING R/H FRT NEW DOOR BLACK TAPE R/H FRT NEW FENDER INNER SHIELD R/H FRT WHEEL BEARING HUP R/H FRT	1859.45	90.18	424.70 / 98.50 / 1,025.81 / 180.36 / 280.60 / 98.10 / 354.20 × 165.94 / 46.40 / 420.50 /
		List TotalS\$: 25.00% Discount S\$:			3,095.11 773.78
					2,321.33
1.	1	SPECIAL NETT ITEMS : SPORT RIM R/H FRT (J)	480		480.00
		Special Nett Total S\$:			480.00
		LABOUR: REMOVE & REPLACE ACCIDENT DAMAGED PARTS			800.06

CONTINUE / ...

PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717 Tel No.: 67433246/ 67438552 Fax No.: 67430013

E-Mail: peoplevehicle@gmail.com

Tax Reg. No.: M90001895E Buss. Reg. No.: 31800200X

MSIG INSURANCE (SINGAPORE) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 (S) 068807

Attention: Motor Claim Department Contact: 68277888 Fax No.: 6827 7800 Estimate: ES19023

Date: 23/07/2019 Vehicle Num.: SMC 3769 B Make/Model: TOYOTA PRIUS

Chassis/Eng#:

Accident Date: 20/07/2019 Claim No.: TT 353-19 Reference: SGK 5242 U

Policy No.: FWD PNCV2019-00000652

S/N Quantity

Particular

Unit Price

Amount S\$

SPRAY PAINTING ACCIDENT EFFECT PARTS COMPUTERIZED WHEEL ALIGHTMENT CHECKING WIRING REMOVE AND REFIX UNDERCARRIAGE UNDERCOAT

Labour Total S\$:

810

750.00 400 80.00 60.00 - 30 . 180.00 × 100.00 K

1,970.00

told: 278558 Adrian Ly 4/s: 2.2K 4/s 25/07/15.

SingDollars: Four Thousand Seven Hundred Seventy-One & Cents Thirty-Three Only

E. & O.E.

Total S\$:

4,771.33

for PEOPLE'S VEHICLE RECOVERY SERVICE

Computer Generated Invoice. No Signature Required.

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Merimen e-Claims

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj S	Submitted	Ins Auth'ed	Status	
Main	22 Jul 2019		23 Jul 2019 13:30 Edit Adj Rpt	S\$2,200.00 Edit Estimate		,200.00 ew Rpt		Pending for Survey Report Cancel Case	
1	Main	R	eference	Claim	Details		Documents		Show All
	BFOLDER D					-	by insurer]		
Insured: Main	CAN BE DOCUM	ANG CHIAW, ID A YONG, ID: S1	FO-CHOCK UPDZ	+6596271736	, Email: I	NOEMAIL			
Claimant: Vehicle Reg No.:	SMC376	SMC3769B			e of Loss:		9 14:00 - :59 s and 21 Days Fror	n LTA Reg Date	(Man Yr)]
Claim Type	re: TP / 600347			11,122	cy/Cover e No.:	290026960	Months and 21 Days From LTA Reg Date (Man Yr)] 2696QMX (Comprehensive) rage: 16/08/2018 - 15/08/2019		
Vehicle Reg No. (Insured):	SGK5242	:U			cy No. aimant):				
Danalisas	Desplais	Vahiala Bassussa	Service (HQ) Blk	1,00000	ess:	400717 Uhi	Tal. 67422246		
Repairer: Handling Insurer:			ore) Pte. Ltd. (HQ)					ng - 6594 2541]	ľ
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Ha	ndled by >	ING GUO	[Final	Rpt due 22/0	08/2019]
Driver/Cust dian (Insured):		NG CHIAW (64 / N	Male), NRIC: S112	9524Z, Tel: -	+6596271	736 Email: N	OEMAIL		
Adj Asg. Remarks:	on WP. Lie	ab:100% Assign Li	(K Apple 6743 3246	Я					
ASSOCIAT	ED MAIL RE	ECEIVED					View	All Compo	se Case Mai
There are n	o mail for this	s case.							
ALL ASSO	CIATED TA	sks⊡				View All	Search Tasks Cr	eate New Task	Complet
Due Date	e Priority	Type Task	Group Subjec	t Handler	_	ned By	Completed On	Created O	

Merimen e-Claims Page 1 of 2

Claim Documents

*SMC3769B (600347)

[SGK5242U]

TP

CHUA SIA YONG
Jul 20 2019 2:00PM

[CHUA HIANG CHIAW]

People's Vehicle Recovery Service

A ==	essment Reports			page V	
		1	1 per i		~
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement		Thumbnail	Print
1	22/07/19 13:45	From:SC - Reg. No: SGK5242U, Claimant: CHUA HIANG CHIAW	0	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/08/19 16:12	Adjuster Immediate Advice	0	Load HTM	
Pho	otos/Images		3 per i	page 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/08/19 14:21	General View	0	Load JPG	✓
2	16/08/19 14:21	General View	0	Load JPG	✓
3	16/08/19 14:21	General View	0	Load JPG	✓
4	16/08/19 14:21	General View	0	Load JPG	✓
5	16/08/19 14:21	General View	0	Load JPG	V
6	16/08/19 14:21	General View	0	Load JPG	✓
7	16/08/19 14:21	General View	0	Load JPG	✓
8	16/08/19 14:21	General View	0	Load JPG	V
9	16/08/19 14:21	General View	0	Load JPG	\checkmark
10	16/08/19 14:21	General View	0	Load JPG	✓
11	16/08/19 14:21	General View	0	Load JPG	✓
12	16/08/19 14:21	General View	O	Load JPG	✓
13	16/08/19 14:21	General View	0	Load JPG	☑
Dod	cumentation		1 per	page 🔽	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/07/19 13:45	Policy From:SC - Reg. No: SGK5242U, Claimant: CHUA HIANG CHIAW	0	Load PDF	
2	22/07/19 13:49	TP SMC3769B E-FILE REPORT	0	Load PDF	
3	22/07/19 13:49	PRI from People's Vehicle Recovery Service	0	Load PDF	
4	22/07/19 13:49	LTA Search	0	Load PDF	
5	22/07/19 17:10	email sje list to tp	0	Load PDF	
6	22/07/19 18:43	email to workshop	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			_
			6.3

Page 2 of 2

Merimen e-Claims

Show Remarks To: Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19012958/AGVF3E2

Date:

19/08/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29002696QMX

Claimant Vehicle No :

SMC3769B

Insured Vehicle No:

SGK5242U

Date of Loss:

20/07/2019

Nature of Claim:

TP

Claim No: 600347

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SMC3769B

Make & Model:

TOYOTA PRIUS, 1.5 HYBRID CVT (A)

Engine No:

1NZ8532349

Reg. Date:

29/06/2018 (Man. Year: 2018)

Chassis No:

JTDKD3B3101613406

Colour:

White

Odometer:

56585 km

Engine Capacity:

1497 cc

Market Value/New Car Price: N/A

1497 CC

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

1:

CONDITION OF TYRES

Front Tyre Size:

185/60 R15

Rear Tyre Size:

185/60 R15

Front Left Side: Front Right Side: Bridgestone 6 mm Bridgestone 6 mm Rear Left Side: Rear Right Side: Bridgestone 6 mm Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,801.33	1,874.59	926.74	33.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,970.00	910.00	1,060.00	53.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,771.33	2,784.59	1,986.74	41.64
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	4,771.33	2,200.00	2,571.33	53.89
+ GST 7.00/7.00% (S\$)	333.99	154.00	179.99	53.89
Nett Amount (S\$)	5,105.32	2,354.00	2,751.32	53.89

INSPECTION

Date of Assignment:

23/07/2019

Date Inspected:

25/07/2019 Inspected At:

People's Vehicle Recovery Service (HQ)

Blk 3023A Ubi Rd 1, #01-60

Singapore 408717

Estimated Period of Repair:

4.0 days

Adjuster Report Page 2 of 4

Adjuster: XING GUO QIANG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Page 3 of 4

REPAIR DETAILS

Referen		Version: 1.0 (Last Synchronised: 19 Aug 2019)
Parts:	144	TOYOTA PRIUS 1.5 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted	no print-code for SMC3769B)
Validity:		tes are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info		the END OF ESTIMATES marker on the last estimate page not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER R/H FRT	Dented	424.70 FL	*424.70 FL
2	1		*HYBRID EMBLEM	Necessary	98.50 FL	*98.50 FL
3	1		*DOOR R/H FRT	Dented	1,025.81 FL	*1,025.81 FL
4	2		*DOOR HINGE R/H FRT	Not Necessary	180.36 FL	*- FL
5	1		*DOOR OUTER MOULDING R/H FRT	Not Necessary	280.60 FL	*-FL
6	1		*DOOR BLACK TAPE R/H FRT	Necessary	98.10 FL	*98.10 FL
7	1		*DOOR RUBBER R/H FRT	Not Necessary	354.20 FL	*- FL
8	1		*FENDER INNER SHIELD R/H FRT	Deformed	165.94 FL	*165.94 FL
9	8		*FENDER INNER SHIELD CLIP R/H FRT	Necessary	46.40 FL	*46.40 FL
10	1		*WHEEL BEARING HUP R/H FRT	Not Necessary	420.50 FL	*- FL
11	1		*SPORT RIM R/H FRT	Cut	480.00 FS	*480.00 FS
F=Fra	anchise	part. S=SpcN	Nett. L=ListItemDisc.			0.0000000000000000000000000000000000000
				Sub Total (S\$)	3,575.11	2,339.45
			- List Item Discount on L Ite	ems 25.00/25.00% (S\$)	773.78	464.86
				Total Parts (S\$)	2,801.33	1,874.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
REMOVE & REPLACE ACCIDENT DAMAGED PARTS	New	800.00	400.00
SPRAY PAINTING ACCIDENT EFFECT PARTS	New	750.00	400.00
COMPUTERIZED WHEEL ALIGNMENT	New	80.00	80.00
CHECKING WIRING	New	60.00	30.00
REMOVE AND REFIX UNDERCARRIAGE	New	180.00	0.00
UNDERCOAT	New	100.00	0.00
Gross La	abour Cost (S\$)	1,970.00	910.00
	PUT Items REMOVE & REPLACE ACCIDENT DAMAGED PARTS SPRAY PAINTING ACCIDENT EFFECT PARTS COMPUTERIZED WHEEL ALIGNMENT CHECKING WIRING REMOVE AND REFIX UNDERCARRIAGE UNDERCOAT	REMOVE & REPLACE ACCIDENT DAMAGED PARTS REMOVE & REPLACE ACCIDENT DAMAGED PARTS New COMPUTERIZED WHEEL ALIGNMENT CHECKING WIRING REMOVE AND REFIX UNDERCARRIAGE New	REMOVE & REPLACE ACCIDENT DAMAGED PARTS REMOVE & REPLACE ACCIDENT DAMAGED PARTS SPRAY PAINTING ACCIDENT EFFECT PARTS COMPUTERIZED WHEEL ALIGNMENT CHECKING WIRING REMOVE AND REFIX UNDERCARRIAGE UNDERCOAT New 100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >