

22/07/2019

ASS. REC. BY:

REF: CS/AIG19012964/Ksf3 n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Mr. Yinnul

of AIG

Date/Time: 23/7/19 @ 2:08pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJM 9713E

Insured: SMF 296C

at Workshop m/s RC Auto

Tel: 9761 9383

of 160 Sin Ming Drive # 06-20

Policy No: \_\_\_\_\_ Claim No: 2258433027 SG003

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 19/7/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 2:15pm @ 23/7/19 Person Contacted: Mr. Tan

Vehicle  IN / OUT

Date/Time	Action/Instruction	Estimate	✓
	SJM 9713E CC4/EQ18013298/Ksub392	19/7/18	
	SMF 296C	X	
25/07/19	@ 15:06 pm checked with Mr. Tan (Carpenter),		
	got estimate		

REF: A19

ASSIGNMENT

From:

Date:

24/7/19

Veh No:

SJM9713E

Yr Regn:

01 09

Estimated Cost:

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD:  TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

SJM 9713E

Make:

Toy <sup>As</sup> Axio

c.c:

1496

at Workshop m/s

RC Auto

Colour

M. Grey

A/C:

Insured / Std / NI / NA

of

160 Sin Ming Drive # 06-20

Sp. Reading

173762

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

Claims No.

Gen. Cond:  Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering:  In order / Jammed / Leaked / Burnt or


(Client's Record)

Brake:  In order / Jammed / Leaked / Burnt or

Make of Veh:

Modif: Nil / S/Rim / STD A/Rim or

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size:

F: Yokco 185/70R14

R: Neter

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

9 mm

R/Bal.

8 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

9 mm

L/Bal.

8 mm

Est. Repairs:

05 days

Res: Yes or No

D.O.A.

19/7/19

D.O.I.

24/7/19

Lum Sum:

20 %

3 Val: Yes or No

Survey held at

✓

CA / REV / REP.

01/24

24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Est not ready

11 Py @ 35000 Cashsum (\$ 2,626.00 Red - 43%)

Date/Time, File Pass to?

22/08/19

Preli. Report

1) Typist

Final Report

Date/Time, File Return to?

Days Of Repair: 5/6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

250

3 + PS. \$

11

Photos

Other

TOTAL

261

Report Format:

Temp 20 / L.B.R. 3,500/- HS

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Inv. (\$)

Weekend (\$)

**PRE-REPAIR INSPECTION REQUEST – SJM9713E vs SMF296C (OI) on D.O.A.: 19/07/2019**

From: Hor, Yinrul  
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tong, Wahxin  
Sent: 7/23/2019 2:08:21 PM  
Attachments:  42259 (AIG).pdf

Hi,

Please refer to the enclosed request from **Teo Keng Siang LLC**.

Claim no : 2258433027SG003  
Case Owner : Bernard Ler Ji Qian

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rul (Viviane)  
AIG  
FNOL Adjuster I  
Singapore FNOL | Claims Operations – Auto

[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Shirley Loh [mailto:shirley.loh@ksteoptr.com]  
**Sent:** Tuesday, July 23, 2019 10:56 AM  
**To:** Hor, Yinrul  
**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin  
**Subject:** [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMF296C AND SJM9713E ON 19/07/2019; Our Ref: TKS/R469-ACC-42259.19/sl ; Your Ref: 2258433027SG003

**This message is from an external sender; be cautious with links and attachments.**

Dear Hor Yin Rul (Viviane),

We refer to your email dated 23/7/19.

Our client has agree to the usage of LKK Auto Consultants Pte Ltd as the Single Joint Expert to conduct the Pre-Repair Survey.

Kindly proceed to engage LKK Auto Consultants Pte Ltd to perform the said Pre-Repair Survey in accordance to the NIMA Protocol.

Thank you.

Regards  
Shirley  
Teo Keng Siang LLC  
Tel: 6333 4222 ext 59

Without Prejudice

Your Reference : TKS/R469-ACC-42259.19/sl  
Our Reference : 2258433027SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)  
AIG  
FNOL Adjuster I  
Singapore FNOL | Claims Operations – Auto

[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** Shirley Loh [<mailto:shirley.loh@ksteoptr.com>]  
**Sent:** Monday, July 22, 2019 4:49 PM  
**To:** Hor, Yinrul  
**Subject:** [EXTERNAL] FW: Your Ref: SMF 296 C Our Ref: TKS/R469-ACC-42259.19/si (SJM 9713 E)

This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

We refer to your letter dated 22/7/19.

Our client has propose to the usage of FormTeam Consultancy Pte Ltd or LKK Auto Consultants Pte Ltd as the Single Joint Expert to conduct the Pre-Repair Survey.

Please let us have your surveyor list soon.

Thank you.  
Regards  
Shirley  
Teo Keng Siang LLC  
Tel: 6333 4222 ext 59

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**From:** Hor, Yinrul [<mailto:Yinrul.Hor@aig.com>]  
**Sent:** Tuesday, July 23, 2019 9:03 AM  
**To:** 'shirley.loh@ksteoptr.com' <[shirley.loh@ksteoptr.com](mailto:shirley.loh@ksteoptr.com)>  
**Cc:** Fong, Andy-SY <[Andy-SY.Fong@aig.com](mailto:Andy-SY.Fong@aig.com)>; Chin, Lee-Ying <[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com)>; Abu Kassim, Noor Mariesa <[NoorMariesa.AbuKassim@aig.com](mailto:NoorMariesa.AbuKassim@aig.com)>; Azlan, Syazairdina <[Syazairdina.Azlan@aig.com](mailto:Syazairdina.Azlan@aig.com)>; Chan, Yoke Shi <[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com)>; Lim, Sheng Yang <[ShengYang.Lim@aig.com](mailto:ShengYang.Lim@aig.com)>; Mithoosingh, Aashweenjeetkaur <[Aashweenjeetkaur.Mithoosingh@aig.com](mailto:Aashweenjeetkaur.Mithoosingh@aig.com)>; Subramaniam, Divyashni <[Divyashni.Subramaniam@aig.com](mailto:Divyashni.Subramaniam@aig.com)>; Tong, Wahxin <[Wahxin.Tong@aig.com](mailto:Wahxin.Tong@aig.com)>  
**Subject:** PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMF296C AND SJM9713E ON 19/07/2019



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมัน ให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-07-30 09:03 +08 to read your message. After that, open the attachment.

[More Info](#)

**Disclaimer:** This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

张景祥大律師樓  
(律師兼公証及宣誓官)

# Teo Keng Siang LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098  
ROC: 201510228C GST Reg No.: 201510228C

Tel: 6333 4222 Fax: 6333 5676 / 5688  
Email: KSTEOCO@singnet.com.sg  
(FAX - NOT FOR SERVICE OF COURT DOCUMENTS)

Our Ref : TKS/R469-ACC-42259.19/sl (mc)  
Your Ref : SMF 296 C  
Date : 22 July 2019

Secretary in charge: Shirley  
Tel : 6333 4222 (ext 59)  
Fax : 6333 5676 / 6333 5688  
Email : shirley.loh@ksteopr.com

To: **AIG Asia Pacific Insurance Pte. Ltd**  
AIG Building  
78 Shenton Way  
#07-16  
Singapore 079120  
Attn: Motor Claims Dept

**WITHOUT PREJUDICE**  
**BY PDX# 8181 & FAX 6835 7416 ONLY**

Cc: **Yeo Kheng Jack (Owner)**  
Blk 325C Sengkang East Way  
#09-639  
Singapore 543325

**BY POST**  
**PDX Intercompany Exchange Pte Ltd**



010808782475  
FROM **TEO KENG SIANG LLC**  
PDX Box No. **8902**

Dear Sirs

**RE: ACCIDENT INVOLVING SJM 9713 E / SMF 296 C ON 19/7/19 ALONG KPE FLYOVER (TAMPINES ROAD EXIT)**

We are instructed by **R C Auto** to notify you of a road traffic accident on 19/7/19 at about 07:30 hours at **ALONG KPE FLYOVER (TAMPINES ROAD EXIT)** involving our client's vehicle registration number **SJM 9713 E** and vehicle registration number **SMF 296 C** driven by you at the material time. A copy of our client's Singapore accident statement is enclosed. Kindly let us have a copy your Singapore accident statement report on an urgent basis.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please note that our client's motor vehicle **SJM 9713 E** is now at the following workshop:-

**RC AUTO**  
160 Sin Ming Drive  
#06-20, Sin Ming AutoCity  
Singapore 575722  
Person I/C : Mr Tan  
Contact : 9761 9383

\*\*Survey was conducted by:-

Name of Surveyor:

Date of Survey:

Time of Survey:

\_\_\_\_\_  
Signature

Yours faithfully,

**M/s Teo Keng Siang LLC**  
Encs

Teo Keng Siang  
LL.M(Singapore),  
LL.B (Hons) (Singapore)

Wong Yong Sheng, Kenneth  
LL.B (Hons) University of Bristol

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/07/2019 12:07
Date Of Accident	19/07/2019 07:30
Exact Location Of Accident	KPE FLYOVER (TAMPINES ROAD EXIT)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM9713E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	R C AUTO
Co Reg No	53199168K
Email Address	RCAUTO5555@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-93251397
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	AXIO
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5107009473
Cover Note Number	
<b>Driver</b>	
Name of Driver	MUHAMMAD RASYIDE BIN ABDUL RAHIM
NRIC No	S88404311
Date Of Birth	17/10/1988
Occupation	OUTDOOR
Date Of Driving Pass	12/10/2010
Driving Experience	8 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93251397
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 418 HOUGANG AVENUE 8 #08-960
Postcode	530418
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

PLEASE REFER ATTACHED.

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH DRIVER
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SMF296C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- re) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**RC AUTO**  
 160, Sin Ming Drive  
 #06-20 Sin Ming AutoCity  
 Singapore 575722  
 Tel: 9761-9883  
 Fax: 9761-9883  
 Email: roadto55@gmail.com  
 Date & Time:

\_\_\_\_\_  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

\_\_\_\_\_  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The front vehicle slow down  
 I slow down my speed and  
 immediately another car SMF 296C  
 came from the rear and hit onto  
 my car.  
 I felt a bit discomfort after the  
 incident and seek outpatient clinic

DECLARATION

I/We declare the foregoing particulars are true in every respect.

**RC AUTO**  
 160, Sin Ming Drive  
 #06-20 Sin Ming AutoCity  
 Singapore 575722  
 Policyholder's Signature: [Signature]  
 Email: rcgauto5555@gmail.com  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Ks

# ESTIMATE RC AUTO

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722  
Tel : 97619383 Email: rcauto5555@gmail.com  
Reg. No. 53199168K

SJM 9713 E

*Not Authorized*  
*11 Day @ 3500k*  
*Return After Paint*  
*5 days*

Date : 25.07.2019

Quantity	Description/Particular	Unit Price	Amount
	REAR BOOTLID		By 960 00
	REAR LOGO EMBLEM		Per 46 00
	REAR AXIO EMBLEM		Per 43 00
	BOOT X EMBLEM		Per 28 00
	BOOTLID INNER LOCK		Per 180 00
	REAR BOOTLID GANISH		Per 260 00
	REAR BOOTLID RUBBER	93SN	Per 186 00
	REAR BUMPER		By 850 00
2	REAR BUMPER BRACKETS@83		R 166 00
8 PCS	REAR BUMPER CLIPS@3.80		Per 30 40
2 PCS	REAR LAMP @390		CM 780 00
	REAR PANEL		By 527 00
	REAR SPARE TYRE BOARD		Per 190 00
	TOTALS		4246 00
	TOWING		Per 60 00
	REVERSE SENSORS	Shan	280 00
	SPRAY PAINTING		800 00
	LABOUR TO REMOVE ABOVE PARTS		700 00
	ANTI RUST		40 00
			6126 00

✓  
✓  
✓  
✓  
✓  
✓  
500k  
✓  
X  
✓  
✓  
✓  
X  
2000k  
720k  
600k  
✓

6126.40

Received the above goods in good order and condition

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_ E & O.E.

for RC AUTO

**RC AUTO**  
160, Sin Ming Drive  
#06-20 Sin Ming AutoCity  
Singapore 575722  
HP: 9761 9383  
Email: rcauto5555@gmail.com

Authorized Signature \_\_\_\_\_

Received by \_\_\_\_\_

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Our File No: CS/AIG19012964/KSF3N2

Date: 22/08/2019

**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800127082  
 Claimant Vehicle No: SJM9713E Insured Vehicle No: SMF296C  
 Date of Loss: 19/07/2019 Nature of Claim: TP Claim No: 2258433027SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: SJM9713E  
 Make & Model: TOYOTA AXIO, 1.5 (A) Engine No: 1NZD068592  
 Reg. Date: 22/01/2009 (Man. Year: 2008) Chassis No: NZE1416083991  
 Colour: Metallic Grey Odometer: 173762 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 185/70R14 Rear Tyre Size: 185/70R14  
 Front Left Side: Yokohama 9 mm Rear Left Side: Nexen 8 mm  
 Front Right Side: Yokohama 9 mm Rear Right Side: Nexen 8 mm

*The above values represent the remaining tyre treads depth*

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,526.40	3,071.30	1,455.10	32.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	1,360.00	240.00	15.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,126.40</b>	<b>4,431.30</b>	<b>1,695.10</b>	<b>27.67</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,126.40</b>	<b>3,500.00</b>	<b>2,626.40</b>	<b>42.87</b>

**INSPECTION**

Date of Assignment: 23/07/2019  
 Date Inspected: 24/07/2019 Inspected At: Rc Auto-160 Sin Ming (HQ)  
 160 SIN MING DRIVE, #06-20 SIN  
 MING AUTOCITY  
 Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	960.00 F	*960.00 FL
2	1		*REAR LOGO EMBLEM	Necessary	46.00 F	*46.00 FL
3	1		*REAR AXIO EMBLEM	Necessary	43.00 F	*43.00 FL
4	1		*BOOT X EMBLEM	Necessary	28.00 F	*28.00 FL
5	1		*BOOTLID INNER LOCK	Dented	180.00 F	*180.00 FL
6	1		*REAR BOOTLID GARNISH	Dented	260.00 F	*260.00 FL
7	1		*REAR BUMPER	Bent	850.00 F	*850.00 FL
8	2		*REAR BUMPER BRACKETS	Repair	166.00 F	*- FL
9	8		*REAR BUMPER CLIPS	Necessary	30.40 F	*30.40 FL
10	2		*REAR LAMP	Cracked	780.00 F	*780.00 FL
11	1		*REAR PANEL	Bent	527.00 F	*527.00 FL
12	1		*REAR SPARE TYRE BOARD	Serviceable	190.00 F	*- FL
13	1		*REAR BOOTLID RUBBER (50%)	Distorted/Dented	186.00 FS	*93.00 FS
14	1		*REVERSE SENSORS	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,526.40</b>	<b>3,997.40</b>
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	926.10
<b>Total Parts (S\$)</b>	<b>4,526.40</b>	<b>3,071.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING	New	60.00	0.00
2	SPRAY PAINTING	New	800.00	720.00
3	LABOUR TO REMOVE ABOVE PARTS	New	700.00	600.00
4	ANTI RUST	New	40.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,600.00</b>	<b>1,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >