

2/10/2019

ASS. REC. BY:

REF:

CS/INC19012990/Egd302

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Hazalysn

of

INC

Date/Time:

23/7/19 @ 9.52am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFS 3816 Y

Insured:

YM 8463E

at Workshop m/s

Kah Motor

Tel:

82886302

of

6A Mendai Estate

Policy No:

Claim No:

MT/1053676-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:46am @ 23/7/19

Person Contacted:

Anilken

Vehicle IN OUT

| Date/Time | Action/Instruction |
|-----------|--------------------|
|           | Johnnold ✓         |
|           | SFS 3816 Y - X     |
|           | YM 8463E - X       |
|           |                    |
|           |                    |
|           |                    |
|           |                    |
|           |                    |

ASS. REC. BY:

Steve

REF:

INC

## ASSIGNMENT

From:

Date:

23/7/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SFS 3816 Y

at Workshop m/s

Kah Motor

of

6A Mendai estate

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

look for Iven

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Imp

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SFS 3816 Y

Yr Regn:

20/11/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

C.C.

1597

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

13961

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRHFC5650 HIT000454

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S(Rim) / STD A/Rim or

Tyre Size:

F:

215/55R16

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

12/7/19

D.O.I.

23/7/19

1152am

Survey held at

Kah Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/7/19

MV - 88K

Finalize confirm \$1825.21, 3 days (Anikka) (Red \$4268.14, 77%)

Date/Time, File Pass to?



: Preli. Report

1) 1/2 turn



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Other:

TOTAL

Report Format:

9P

Lump Sum / L.R. / G

1825.21

250

250

## Nivitha (LKK Auto)

---

**From:** Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>  
**Sent:** Tuesday, 23 July 2019 3:47 PM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** Hazalysa Binte Ibrahim  
**Subject:** FW: TP CASES FARMED OUT TO LKK ON 23/7/2019

Dear Nivitha,

Re-sent.

Thank you.

Warmest Regards

**Hazalysa Bte Ibrahim**  
Admin Assistant  
Motor Department  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
Find out more at [income.com.sg/careers](http://income.com.sg/careers)



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Tuesday, 23 July 2019 12:10 PM  
**To:** Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 23/7/2019

Dear Hazalysa,

Thank you for the assignment.

Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hazalysa Binte Ibrahim [mailto:hazalysa.ibrahim@income.com.sg]  
**Sent:** Tuesday, 23 July 2019 9:52 AM  
**To:** assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>

Subject: TP CASES FARMED OUT TO LKK ON 23/7/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

| SN | OIC            | Claim No.      | Survey Date | Vehicle  | WorkShop Name                       | WorkShop Address  | WorkShop Contact       | Survey Time | OI VEH   | DOA      | Additional Remarks    |
|----|----------------|----------------|-------------|----------|-------------------------------------|---|------------------------|-------------|----------|----------|-----------------------|
| 1  | Serene Lim     | MT/1050055-001 | 23/7/2019   | SLD5291E | BORNEO MOTORS (S) PTE LTD           | 2 PANDAN CRESCENT SINGAPORE 128462                            | JOE TAN / 6631 1874    | 10:00-12:00 | PC2161A  | 20/06/19 | OWNER WAITING         |
| 2  | Charlotte Chew | MT/1054291-002 | 23/7/2019   | SLB6051K | BP AUTO                             | 48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586 | YVETTE ZHAO / 62660555 |             | SJT4209R | 18/07/19 |                       |
| 3  | Cyndie Yong    | MT/1052989-002 | 23/7/2019   | GX2882Z  | BP AUTO                             | 48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586 | YVETTE ZHAO / 62660555 |             | YM9229J  | 08/07/19 |                       |
| 4  | Jared Liu      | MT/1052420-002 | 23/7/2019   | SJC886B  | CYCLE & CARRIAGE INDUSTRIES PTE LTD | 188 PANDAN LOOP SINGAPORE 128378                              | GO CHEE HAN / 91817717 | 14:00-16:00 | SKW7006L | 05/07/19 |                       |
| 5  | Eng Huey Huey  | MT/1053676-002 | 23/7/2019   | SFS3816Y | KAH MOTOR COMPANY SDN. BERHAD.      | 6A MANDAI ESTATE SINGAPORE 729903                             | ANNIKA LAI / 65145248  | 10:00-12:00 | YM8463E  | 12/07/19 |                       |
| 6  |                | MT/1052856-001 | 23/7/2019   | JQR5773  | LONG SHENG MOTOR SERVICE            | BLK 6-399-G WOODLANDS ROAD YEW-TEE INDUSTRIAL ESTATE          | MISS WOON / 67639733   | -           | -        |          | PLS CANCEL THE SURVEY |

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

**Hazalysa Bte Ibrahim**

Admin Assistant

Motor Department

T +65 6430 7902

[www.income.com.sg](http://www.income.com.sg)

**income**  
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)

**in** wi  
yc

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer


This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

---

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

---



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

---

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

[> Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

|                               |                                      |
|-------------------------------|--------------------------------------|
| Vehicle Owner Particulars     |                                      |
| Owner ID Type:                | Singapore NRIC                       |
| Owner ID:                     | 556I                                 |
| Vehicle Details               |                                      |
| Vehicle No.:                  | SFS3816Y                             |
| Vehicle to be Exported:       | No                                   |
| Intended Deregistration Date: | 23 Jul 2019                          |
| Vehicle Make:                 | HONDA                                |
| Vehicle Model:                | CIVIC 1.6 VTI CVT                    |
| Primary Colour:               | Blue                                 |
| Manufacturing Year:           | 2017                                 |
| Engine No.:                   | R16B22000864                         |
| Chassis No.:                  | MRHFC5650HT000454                    |
| Maximum Power Output:         | 92.0 kW (123 bhp)                    |
| Open Market Value:            | \$19,726.00                          |
| Original Registration Date:   | 20 Nov 2017                          |
| First Registration Date:      | 20 Nov 2017                          |
| Transfer Count:               | 0                                    |
| Actual ARF Paid:              | \$19,726.00                          |
| Intended PARF Rebate Details  |                                      |
| PARF Eligibility:             | Yes                                  |
| PARF Eligibility Expiry Date: | 19 Nov 2027                          |
| PARF Rebate Amount:           | \$14,794.00                          |
| Intended COE Rebate Details   |                                      |
| COE Expiry Date:              | 19 Nov 2027                          |
| COE Category:                 | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):            | 10                                   |
| QP Paid:                      | \$46,778.00                          |
| COE Rebate Amount:            | \$38,939.00                          |
| Total Rebate Amount:          | \$53,733.00                          |

The information contained herein is correct as at 23 Jul 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                  |
|----------------------------|------------------|
| Date Of Report             | 15/07/2019 19:31 |
| Date Of Accident           | 12/07/2019 16:35 |
| Exact Location Of Accident | CORPORATION RD   |
| Country/State of Loss      | SINGAPORE        |

### DETAILS OF OWN VEHICLE

|                             |                         |
|-----------------------------|-------------------------|
| Vehicle Registration Number | SFS3816Y                |
| <b>Insured/Policyholder</b> |                         |
| Name Of Registered Owner    | LOH SOCK HOON           |
| NRIC No                     | S7409556I               |
| Email Address               | ANGELALOH1531@GMAIL.COM |
| Mobile Phone No             | (LOCAL) +65-96410512    |
| Alternative Phone No        | OFFICE-96410512         |

### Vehicle Particulars

|  |                     |
|--|---------------------|
| Manufacturer   | HONDA               |
| Model  | CIVIC-1.6 L VTI (A) |
| Exact Purpose for which vehicle was being used at time of accident           |                     |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                  |
| If No, Please state action to be taken                                       | THIRD PARTY         |
| Vehicle Category   | PRIVATE CAR         |

### Insurance Company

|                           |                                      |
|---------------------------|--------------------------------------|
| Name of Insurance Company | TOKIO MARINE INSURANCE SINGAPORE LTD |
| Type Of Coverage          | COMPREHENSIVE                        |
| Fleet Policy              | NO                                   |
| Policy Number             |                                      |
| Cover Note Number         |                                      |

### Driver

|                      |                         |
|----------------------|-------------------------|
| Name of Driver       | LOH SOCK HOON           |
| NRIC No              | S7409556I               |
| Date Of Birth        | 31/03/1974              |
| Occupation           | INDOOR                  |
| Date Of Driving Pass | 25/05/1993              |
| Driving Experience   | 26 YEARS AND 1 MONTH    |
| Gender               | FEMALE                  |
| Mobile Number        | (LOCAL) +65-96410512    |
| Fax Number           |                         |
| Contact Number       | OFFICE-96410512         |
| EMail Address        | ANGELALOH1531@GMAIL.COM |

|   |       |
|---|-------|
| Address   | -     |
| Postcode  |       |
| Was driver an employee of the Insured's Company     | NO    |
| If No, Relationship of the Driver with the Insured  | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | -     |
|   | -     |
|   | -     |
| Insurance Company of Driver's Own Vehicle           | -     |
|   | -     |
|   | -     |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|   |     |
|---|-----|
| Was any foreign vehicle involved in this accident?  | NO  |
| Number of vehicles (including own vehicle) involved in the accident                         | 2   |
| Was any body injured in the Accident?   | NO  |
| Was any injured conveyed to hospital by ambulance?  |     |
| Was any other material or property damaged?   | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)   | 1   |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

AS ANNEX D&E

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | YES |
| Was there any audio recorded?                 | NO  |


#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |                     |
|-------------------------------------|---------------------|
| Vehicle Registration Number         | YM8463E             |
| Vehicle Make/Model/Colour           | ISUZU / BLUE        |
| Details Of Properties               |                     |
| Vehicle Category                    | COMMERCIAL VEHICLE  |
| Name of Driver                      | MAICHAL INNASIMUTHU |
| NRIC/Passport Number                | G7693046K           |
| Contact Number                      | 93859575            |
| Address                             |                     |
| Postcode                            |                     |
| Insurance Company Name              |                     |
| Nature Of Damage                    |                     |
| No. Of Passenger (Including Driver) |                     |



Vehicle Number: SFS 3816Y

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

|  |           |        |          |
|--|-----------|--------|----------|
| Date -   | 12/7/2019 | Time - | 16:34 hr |
| I was stopping at the junction (Chin Bee Dr / Corporation Dr / Corporation Road)                       |           |        |          |
| as it was red light  |           |        |          |
| The vehicle (Ym P463E) driving behind me and banged / collided into the rear of my vehicle (SFS 3816Y) |           |        |          |
| (Kindly refer to the attached video)   |           |        |          |
| My car has scratches mark and dented bumper due to the collision from vehicle Ym P463E                 |           |        |          |
| No injuries to drivers / passengers from both vehicles   |           |        |          |
| Vehicles arrived at Kah Mui (Jalan Ahmad Ibrahim)  |           |        |          |
| after the incident, together with the driver of Ym P463E   |           |        |          |
| on 12/7/19 @ 1730 hr   |           |        |          |
|  |           |        |          |
|  |           |        |          |
|  |           |        |          |
|  |           |        |          |
|  |           |        |          |
|  |           |        |          |
|  |           |        |          |

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 14/7/19  
13:16

Driver's Signature

(If driver is not the policyholder)

Date &amp; Time:

Same as policyholder

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Vehicle Number: SF 3816 Y**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.

Wong Jia  
Policyholder's Signature

Date & Time: 14/7/19  
13:16

Same as policyholder  
Driver's Signature

(If driver is not the policyholder)  
Date & Time:

[Signature]  
Reporting Centre Personnel's Signature

Name:  
NRIC/FIN No.:

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : NTUC INCOME INS CO-OPERATIVE LTD  
1 MARITIME SQUARE  
HARBOURFRONT CENTRE  
SINGAPORE 099253

**Registration No** : SFS3816Y

**Chassis No** : MRHFC5650HT000454

**Model** : CIVIC 1.6 VTI YM2017

**Owner's Name** : LOH SOCK HOON

**Ins Policy No.** :

**Date of Accident** : 12/7/2019

**Document No.** : SQT19003131 **Page** 1

**Date** : 17. Jul 2019

**Customer No.** : WZN008

**Svc Advisor** : ANIKKA LAI SWEE KAM

**Engine No** : R16B22000864

**Date | Time** : 17. Jul 2019 8:20:43 AM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

| Item            | Description   | Qty | Unit Price | Disc % | Amount  | 0% GST Amount | Amount incld GST |
|-----------------|---|-----|------------|--------|---------|---------------|------------------|
|                 | TP DIRECT SETTLEMENT (J/NO:<br>OWNER: LOH SOCK HOON<br>OWNER INSURER: TOKIO MARINE<br>ACC DATE: 12/07/2019<br>SURVEYED BY:<br>DATE:<br>REF NO:<br>TP INSURER: NTUC<br>TP VEH: YM8463E |     |            |        |         |               |                  |
| 71500-TEC-Q00ZZ | FACE ASSY,RR.BUMPER / <i>DD</i>   | 1   | 617.20     | 25     | 462.90  | 32.40         | 495.30           |
| 71593-TEA-T01   | SPACERR.RR.BUMPER SIDE / <i>MA</i>  | 1   | 11.50      | 25     | 8.62    | 0.60          | 9.22             |
| 71598-TEA-T01   | SPACERL.RR.BUMPER SIDE / <i>MA</i>  | 1   | 11.50      | 25     | 8.62    | 0.60          | 9.22             |
| 91505-TM8-003   | CLIP,BUMPER / <i>MA</i>   | 22  | 2.30       | 25     | 37.95   | 2.66          | 40.61            |
| 71502-TEX-Y00   | GARNISH,RR.BUMPER LOWER / <i>CVT</i>  | 1   | 36.40      | 25     | 27.30   | 1.91          | 29.21            |
| 71503-TEA-T00   | GARNISH R.RR.BUMPER SIDE / <i>CVT</i>   | 1   | 8.40       | 25     | 6.30    | 0.44          | 6.74             |
| 71508-TEA-T00   | GARNISHL.RR.BUMPER SIDE / <i>MA</i>   | 1   | 7.80       | 25     | 5.85    | 0.41          | 6.26             |
| 71530-TEA-T00ZZ | BEAM COMPRR.BUMPER / <i>MA</i>  | 1   | 164.70     | 25     | 123.52  | 8.65          | 132.17           |
| 71555-TBA-A00   | BRACKETL.RR.BUMPER SIDE / <i>MA</i>   | 1   | 2.30       | 25     | 1.72    | 0.12          | 1.84             |
| 71505-TBA-A00   | BRACKETR.RR.BUMPER SIDE / <i>MA</i>   | 1   | 2.30       | 25     | 1.72    | 0.12          | 1.84             |
| 68500-TEA-N00ZZ | LID COMP TRUNK / <i>MA</i>  | 1   | 486.20     | 25     | 364.65  | 25.53         | 390.18           |
| 75722-TBA-A00   | EMBLEM SETRR. / <i>MA</i>   | 1   | 11.80      | 25     | 8.85    | 0.62          | 9.47             |
| 75725-TEA-T01   | EMBLEMRR. / <i>MA</i>   | 1   | 11.00      | 25     | 8.25    | 0.58          | 8.83             |
| 75701-TBA-A10   | EMBLEM,H-MARK / <i>MA</i>   | 1   | 12.20      | 25     | 9.15    | 0.64          | 9.79             |
| 90301-ST0-003   | NUTPUSH 3MM / <i>MA</i>   | 2   | 2.10       | 25     | 3.15    | 0.22          | 3.37             |
| 74865-TEA-T01   | WEATHERSTRIPTRUNK LID / <i>MA</i>   | 1   | 70.00      | 25     | 52.50   | 3.68          | 56.18            |
| 66100-TEC-307ZZ | PANEL SETRR. / <i>MA</i>  | 1   | 243.10     | 25     | 182.32  | 12.76         | 195.08           |
| Sum Item        |   |     |            |        | 1313.37 | 91.94         | 1,405.31         |

Printed on 17/7/2019 9:10:56 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : NTUC INCOME INS CO-OPERATIVE LTD  
1 MARITIME SQUARE  
HARBOURFRONT CENTRE  
SINGAPORE 099253

**Registration No** : SFS3816Y

**Chassis No** : MRHFC5650HT000454

**Model** : CIVIC 1.6 VTI YM2017

**Owner's Name** : LOH SOCK HOON

**Ins Policy No.** :

**Date of Accident** : 12/7/2019

**Document No.** : SQT19003131 **Page** 2

**Date** : 17. Jul 2019

**Customer No.** : WZN008

**Svc Advisor** : ANIKKA LAI SWEE KAM

**Engine No** : R16B22000864

**Date | Time** : 17. Jul 2019 8:20:43 AM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

| Item      | Description  | Qty | Unit Price | Disc %     | Amount  | 0% GST Amount | Amount incld GST |
|-----------|--|-----|------------|------------|---------|---------------|------------------|
| BOSUN     | SUNDRIES   | 1   | 100.00     | 90 / 100   | 100.00  | 7.00          | 107.00           |
| BA02R     | REMOVE & RENEW REVERSE SENSORS-4 PCS (N)           | 1   | 120.00     | 1 / 120    | 120.00  | 8.40          | 128.40           |
| BC011R    | REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA        | 1   | 480.00     | X          | 480.00  | 33.60         | 513.60           |
| BC012R    | RESET VEHICLE SMART ENTRY SYSTEM                   | 1   | 480.00     | X          | 480.00  | 33.60         | 513.60           |
| BKTRR     | REMOVE & TRANSFER ITEMS TO NEW TRUNK LID           | 1   | 600.00     | X          | 600.00  | 42.00         | 642.00           |
| BKBU02R   | REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON     | 1   | 2000.00    | 360 / 2000 | 2000.00 | 140.00        | 2140.00          |
| BP02R     | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P) | 1   | 1500.00    | 450 / 1500 | 1500.00 | 105.00        | 1605.00          |
| Sum Labor |  |     |            |            | 5280.00 | 369.60        | 5,649.60         |

Survey By \_\_\_\_\_

Date & Time \_\_\_\_\_

Excess \_\_\_\_\_

Status \_\_\_\_\_

Signature \_\_\_\_\_

**Total Amount** 6,593.37 461.54 7,054.91

**Total (Inclusive of GST)** 7,054.91

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Printed on 17/7/2019 9:10:56 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.





# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer:** WZN008 / NTUC INCOME INS  
**Chassis No:** MRHFC5650HT000454  
**License No:** SFS3816Y  
**Mileage:** 9369  
**Engine No:** R16B22000864

**Document No:** SVO19047163  
**Printed By:** ANIKKALAI  
**Order Date:** 23. July 2019  
**Order Time:** 11:59:43 AM  
**Service Advisor:** ANIKKA LAI SWEE KAM

| ITEM            | DESCRIPTION   | QTY | UNIT   | DISC % | AMOUNT          | 7% GST Amount | Amount incld GST |
|-----------------|---|-----|--------|--------|-----------------|---------------|------------------|
|                 | TP DIRECT SETTLEMENT (J/NO: )<br>OWNER: LOH SOCK HOON<br>OWNER INSURER: TOKIO MARINE<br>ACC DATE: 12/07/2019<br>SURVEYED BY: STEVE / LKK<br>DATE: 23/07/2019<br>REF NO: MT/1053676-002<br>TP INSURER: NTUC<br>TP VEH: YM8463E |     |        |        |                 |               |                  |
| 71500-TEC-Q00ZZ | FACE ASSY,RR.BUMPER   | 1   | 617.20 | 25     | 462.90 /        | 32.40         | 495.30           |
| 71593-TEA-T01   | SPACERR.RR.BUMPER SIDE  | 1   | 11.50  | 25     | 8.62 /          | 0.60          | 9.22             |
| 71598-TEA-T01   | SPACERL.RR.BUMPER SIDE  | 1   | 11.50  | 25     | 8.62 /          | 0.60          | 9.22             |
| 91505-TM8-003   | CLIP,BUMPER   | 22  | 2.30   | 25     | 37.95 /         | 2.66          | 40.61            |
| 71502-TEX-Y00   | GARNISH,RR.BUMPER LOWER   | 1   | 36.40  | 25     | 27.30 /         | 1.91          | 29.21            |
| 71503-TEA-T00   | GARNISH R.RR.BUMPER SIDE  | 1   | 8.40   | 25     | 6.30 /          | 0.44          | 6.74             |
| 71530-TEA-T00ZZ | BEAM COMPRR.BUMPER  | 1   | 164.70 | 25     | 123.52 /        | 8.65          | 132.17           |
|                 | <b>SUM PARTS:</b>   |     |        |        | <b>675.21</b>   | <b>47.26</b>  | <b>722.47</b>    |
| BOSUN           | SUNDRIES  | 1   | 20.00  |        | 20.00 /         | 1.40          | 21.40            |
| BA02R           | 0671<br>REMOVE & RENEW REVERSE<br>SENSORS-4 PCS (N)   | 1   | 120.00 |        | 120.00 /        | 8.40          | 128.40           |
| BKBU02R         | 0671<br>REMOVE & RENEW RR BUMPER<br>INCLUDING FITTINGS ON<br>ATTACHMENT ITEMS   | 1   | 560.00 |        | 560.00 /        | 39.20         | 599.20           |
| BP02R           | 1610<br>SPRAY PAINTING ON REPAIRED OR<br>REPLACED AREAS.(2P)  | 1   | 450.00 |        | 450.00 /        | 31.50         | 481.50           |
|                 | <b>SUM LABOUR:</b>  |     |        |        | <b>1,150.00</b> | <b>80.50</b>  | <b>1,230.50</b>  |
|                 | <b>TOTAL SGD</b>  |     |        |        | <b>1,825.21</b> | <b>127.76</b> | <b>1,952.97</b>  |
|                 | <b>Total Payable (SGD)</b>  |     |        |        |                 |               | <b>1,952.97</b>  |

GST Amount is calculated from individual line(s)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19012990/Eqd3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 30-07-2019



ATTN: ENG HUEY HUEY

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | YM 8463E       | Veh. Inspected | SFS 3816Y  |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1053676-002 | Excess (\$)    | 0.00       |
| Assign From  | HAZALYSA       | Assign Date    | 23/07/2019 |

#### 2. Vehicle Particulars & Condition

|              |                   |              |            |
|--------------|-------------------|--------------|------------|
| Make & Model | HONDA CIVIC       | c.c          | 1597       |
| Engine No.   | HIDDEN            | Year of Reg. | 2017       |
| Chassis No.  | MRHFC5650HT000454 | Colour       | BLUE       |
| Odometer     | 13961 KM          | Steering     | IN ORDER   |
| Brakes       | IN ORDER          | Modification | SPORTS RIM |
| General      | GOOD              |              |            |

#### 3. Conditions of Tyres

|                | Size       | Make    | Balance |
|----------------|------------|---------|---------|
| R/H Front Tyre | 215/55 R16 | HANKOOK | 6 mm    |
| L/H Front Tyre | 215/55 R16 | HANKOOK | 6 mm    |
| R/H Rear Tyre  | 215/55 R16 | HANKOOK | 6 mm    |
| L/H Rear Tyre  | 215/55 R16 | HANKOOK | 6 mm    |

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

|                |  |                     |                         |
|----------------|--|---------------------|-------------------------|
| Accident Date  | 12/07/2019   | Inspect Date / Time | 23/07/2019 ( 11:52 AM ) |
| Survey held at | KAH MOTOR.CO.SDN.BHD<br>6A MANDAI ESTATE<br>SINGAPORE 729903 |                     |                         |

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFS 3816Y

| Qty                         | Description of Parts                               | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|--|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |  |               |                           |                   |
| 1                           | FACE ASSY,RR.BUMPER (SN)                           | DENTED        | 462.90                    | 462.90            |
| 1                           | SPACERR.RR.BUMPER SIDE (SN)                        | NECESSARY     | 8.62                      | 8.62              |
| 1                           | SPACERL.RR.BUMPER SIDE (SN)                        | NECESSARY     | 8.62                      | 8.62              |
| 22                          | CLIP, BUMPER (SN)                                  | NECESSARY     | 37.95                     | 37.95             |
| 1                           | GARNISH,RR.BUMPER LOWER (SN)                       | CUT           | 27.30                     | 27.30             |
| 1                           | GARNISH R.RR.BUMPER SIDE (SN)                      | CUT           | 6.30                      | 6.30              |
| 1                           | GARNISH L.RR.BUMPER SIDE (SN)                      | NOT NECESSARY | 5.85                      | -                 |
| 1                           | BEAM COMPRR.BUMPER (SN)                            | DENTED        | 123.52                    | 123.52            |
| 1                           | BRACKETL.RR.BUMPER SIDE (SN)                       | NOT NECESSARY | 1.72                      | -                 |
| 1                           | BRACKETR.RR.BUMPER SIDE (SN)                       | NOT NECESSARY | 1.72                      | -                 |
| 1                           | LID COMP TRUNK (SN)                                | NOT NECESSARY | 364.65                    | -                 |
| 1                           | EMBLEM SETRR (SN)                                  | NOT NECESSARY | 8.85                      | -                 |
| 1                           | EMBLEMRR (SN)                                      | NOT NECESSARY | 8.25                      | -                 |
| 1                           | EMBLEM,H-MARK (SN)                                 | NOT NECESSARY | 9.15                      | -                 |
| 2                           | NUTPUSH 3MM (SN)                                   | NOT NECESSARY | 3.15                      | -                 |
| 1                           | WEATHERSTRIP TRUNK LID (SN)                        | NOT NECESSARY | 52.50                     | -                 |
| 1                           | PANEL SETRR (SN)                                   | NOT NECESSARY | 182.32                    | -                 |
| 1                           | SUNDRIES (SN)                                      | NECESSARY     | 100.00                    | 20.00             |
|                             |  |               | 1,413.37                  | 695.21            |
| <b>LABOUR</b>               |  |               |                           |                   |
|                             | REMOVE & RENEW REVERSE SENSORS-4 PCS.              |               | 120.00                    | 120.00            |
|                             | REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.       | NOT NECESSARY | 480.00                    | -                 |
|                             | RESET VEHICLE SMART ENTRY SYSTEM.                  | NOT NECESSARY | 480.00                    | -                 |
|                             | REMOVE & TRANSFER ITEMS TO NEW TRUNK LID.          | NOT NECESSARY | 600.00                    | -                 |
|                             | REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON.    |               | 2,000.00                  | 560.00            |
|                             | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P) |               | 1,500.00                  | 450.00            |
|                             |  |               | 5,180.00                  | 1,130.00          |
| <b>GRAND TOTAL</b>          |  |               | <b>6,593.37</b>           | <b>1,825.21</b>   |

Report Ref No. CS/INC19012990/Eqd3e2



|  |  |  |  |          |
|--|--|--|--|----------|
| RECOMMENDED COST OF REPAIRS<br>(CONFIRMED) |  |  |  | 1,825.21 |
|--|--|--|--|----------|

Report Ref No. CS/INC19012990/Eqd3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.