

22/02/2019

A/S. REC. BY:

REF:

CS/A1919013004/KSF3ⁿ²

Special Instruction:

Surveyor: Kenneth

Murimen

ASSIGNMENT (Office)

From (Person): Hor, Yinnul

of AIG

Date/Time: 23/7/19 @ 446pm

Estimated Cost:

Bill to:

OD / FP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 80932

Insured:

SFX 1919X

at Workshop m/s:

Quon Motor

Tel:

6453 6111

of

176 Sin Ming Drive # 02-03

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 5:22pm @ 23/7/19

Person Contacted:

Ah Heng

Vehicle IN /

(YIP)

Date/Time	Action/Instruction	Estimated	✓
	PC 80932-X		
	SFX 1919X - N/A / AVI 08033547 / A		
15/8	\$943.55 email & confirmed		
	(\$2,208.12 Red - 70%)		

DOA: 24/12/2008

PRE-REPAIR INSPECTION REQUEST – PC8093Z vs SFX1919X (OI) on D.O.A.: 22/07/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tong, Wahxin
Sent: 7/23/2019 4:46:12 PM
Attachments:  PRS PC8093Z.pdf  PRS PC8093Z.PDF

Hi,

Please refer to the enclosed request from **CK TEO & CO**.
Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
*Kindly assist to assign **KENNETH KONG** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Yinrul.Hor@aig.com | www.aig.com

From: Willow Tuang [mailto:wtuang@gmail.com]
Sent: Tuesday, July 23, 2019 4:45 PM
To: Hor, Yinrul
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFX1919X AND PC8093Z ON 22/07/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir

We refer to your email of even date.

We are agreeable of appointing KENNETH KONG (LKK AUTO) as a Single Joint Expert.

Our client's vehicle is available for pre-repair survey at:

Venue	:	Guan Motor Works 176 Sin Ming Drive #02-03 Sin Ming AutoCare Singapore 575721 Tel: 6453 6111 (AH HENG)
-------	---	--

Regards
Tuang Willow
CK TEO & CO
Tel: 65354788
Fax: 65354245

On Tue, Jul 23, 2019 at 4:04 PM Hor, Yinrul <Yinrul.Hor@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมัน ให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-07-30 16:04 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2006-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinru.Hor@aig.com
To: wtuang@gmail.com
Cc: Andy-SY.Fong@aig.com ,Lee-Ying.Chin@aig.com ,NoorMariesa.AbuKassim@aig.com ,Syazairdina.Azlan@aig.com ,yokashi.chan@aig.com ,ShengYang.Lim@aig.com ,Aashweenjeetkaur.Mithoosingh@aig.com ,Divyashni.Subramaniam@aig.com ,Wahxin.Tong@aig.com
Subject: aigencryt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFX1919X AND PC8093Z ON 22/07/2019
Date: Tue, 23 Jul 2019 08:04:21 +0000

Without Prejudice

Your Reference : PC8093Z
 Our Reference : SFX1919X

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
 AIG
 FNOL Adjuster I
 Singapore FNOL | Claims Operations – Auto

Yinru.Hor@aig.com | www.aig.sg

From: Willow Tuang [mailto:wtuang@gmail.com]
Sent: Tuesday, July 23, 2019 3:46 PM
To: Hor, Yinru
Cc: Azlan, Syazairdina; Lim, Sheng Yang
Subject: [EXTERNAL] PRE-REPAIR INSPECTION - ACCIDENT INVOLVING PC8093Z & SFX1919X ON 22.7.2019 ALONG BUKIT TIMAH ROAD

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

Enclosed is a copy each of the following:

- Notification of Accident & Pre-Repair Inspection;
- GIA Report of our Client; and
- LTA result

Regards

Tuang Willow
 CK TEO & CO
 Tel: 65354788
 Fax: 65354245

NOTIFICATION OF ACCIDENT & PRE-REPAIR INSPECTION

Date : 23/7/2019

Time :

By Fax :

TO :

AIG ASIA PACIFIC INSURANCE PTE LTD

Accident involving Your insured vehicle No. SFX1919X with
My vehicle No. PC8093Z on 22/7/19 along BUKIT TIMAH ROAD

1. I, the owner of Vehicle No. PC8093Z intend to make a 3rd party claim against your insured.
2. My Vehicle is now at the workshop **Guan Motor Works** Tel : 6453 6111 and is available for your inspection before repairs are carried out.
3. Please acknowledge receipt of this Notification by return fax to 6453 8292 and reply within 2 days whether you wish to inspect the vehicle or waive inspection.



Signature
Name :
NRIC :

CK TEO & CO
Advocates & Solicitors
101A Upper Cross Street #08-17
People's Park Centre Singapore 050011
Tel : 6535 4788 Fax : 6535 4245
wtuang@gmail.com

Enquire Vehicle & Owner Information (Vehicle No. SFX1919X As At 22 Jul 2019 / 10:00:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: TCK.WIT.LTA.2019 GM

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S7122039G

Owner Name: TAN AIK TI, RON

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 18

Registered Street Name: NASSIM HILL

Registered Unit No.: # 03 - 05

Registered Building Name:-

Registered Postal Code: 258485

Current Vehicle Details

Vehicle No.: SFX1919X

Make Description/Model: MERCEDES BENZ / S400L (R19 LED)

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	PC8093Z		
Vehicle Type :	P20 - Passenger Bus/Coach/Minibus		
Vehicle Attachment 1 :	Air-Conditioned		
Vehicle Scheme :	Public Service Vehicle (Others)		
Vehicle Make :	TOYOTA		
Vehicle Model :	REGIUS ACE DX 2.8 AUTO		
Chassis No. :	GDH2011017723		
Propellant :	Diesel		
Engine No. :	1GD8369115		
Engine Capacity :	2754 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	3175 kg		
Unladen Weight :	1800 kg		
Year Of Manufacture :	2018		
Original Registration Date :	21 Mar 2019		
Lifespan Expiry Date :	20 Mar 2039		
COE Category :	C - Goods Vehicle & Bus		
PQP Paid :	\$22,108.00		
COE Expiry Date :	20 Mar 2029		
Road Tax Expiry Date :	20 Mar 2020		
Inspection Due Date :	20 Mar 2020		
Intended Transfer Date :	26 Aug 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST	GST Amount	Amount After GST
	(S\$)	(S\$)	(S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
This vehicle has a road tax Over Payment of \$66.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			

You may print this page for reference.

OK

Print

MSH18098063 / STA INSPECTION PTE LTD - Sin Ming
 ENTRY DATE & TIME: 23/07/2019 10:04
 SUBMITTED BY: Wong Up Yong

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/07/2019 10:04
Date Of Accident	22/07/2019 10:00
Exact Location Of Accident	ALONG BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC8093Z
Insured/Policyholder	
Name Of Registered Owner	SG HR SERVICES PTE LTD
Co Reg No	200501861R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96253580
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107994762
Cover Note Number	
Driver	
Name of Driver	CHIA TZE PING
NRIC No	S7782379D
Date Of Birth	02/02/1977
Occupation	OUTDOOR
Date Of Driving Pass	07/12/1996
Driving Experience	22 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96253580
Fax Number	
Contact Number	OFFICE-96253580
EMail Address	HIDUPKUCING@YAHOO.COM.SG

Address APT BLK 520 JELAPANG ROAD
#03-265 SINGAPORE

Postcode 670520

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFX1919X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver FISHALL BIN MOHD SHAH

NRIC/Passport Number S1583256H

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports) or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 22/07/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Sketch Plan #2 Pg. 1

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I WAS TRAVELLING ALONG JULI TIMAH ROAD AT THE LANE 5 WHERE I HAVE TO CHANGE TO LANE 4 DUE TO THERES AN OBSTRUCTION IN FRONT. I GIVE SIGNAL TO THE RIGHT AND MAKE A CHECK THERES A VEHICLE SLOWED DOWN SEEMS LIKE TO GIVE WAY FOR MY VEHICLE AT I WAS MORE THAN A HALF CHANGING TO THE 4TH LANE THE SAID VEHICLE B START TO ACCELERATE AND HIT ON MY FRONT RIGHT PORTION. THE SAID VEHICLE B CUT INTO FRONT OF MY VEHICLE. NO ONE WAS INJURED. PLEASE REFER TO ATTACHED VIDEO.

DECLARATION

I/We declare that foregoing particulars are true in every respect.


 Date & Time: _____


 Driver's Signature
 (If driver is not the complainant)
 Date & Time: _____


 Reporting Centre Personnel's Signature
 Name: _____
 NAIC/PCP No.: _____

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR TOYOTA HIACE – PC 8093 Z

<u>List items</u>				
1 pc.	Front bumper	64	S 571.40	✓
1 pc.	RH Front bumper side retainer		191.30	X
1 pc.	RH Front door		1,600.20	X
			<hr/>	
			2,308.90	
		Less 25%	577.23	
			<hr/>	
			\$ 1,731.67	\$ 1,731.67

Labour

- | | | |
|--|-------------|-----|
| 1. Labour charges for remove/refit, panel beating, cutting/welding and replacement of damages. | 600.00 | 300 |
| 2. To putty and spray Spray Paintings charges. | 700.00 | 200 |
| 3. To check wirings & lightings. | 40.00 | 150 |
| 4. To remove and refix front RH door fittings. | 80.00 | X |
| | <hr/> | |
| | \$ 3,151.67 | |

Not Authorized

Return After Repair

2 days

943-55

3192.17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19013004/KSF3N2
Date: 26/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. **Policy No:** 2100503773
Claimant Vehicle No : PC8093Z **Insured Vehicle No :** SFX1919X
Date of Loss: 22/07/2019 **Nature of Claim:** TP **Claim No:** 9987635569SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC8093Z
Make & Model: TOYOTA REGIUSACE DX, 2.8 (A) **Engine No:** 1GD8369115
Reg. Date: 21/03/2019 (Man. Year: 2018) **Chassis No:** GDH2011017723
Colour: White **Odometer:** 11552 km
Engine Capacity: 2754 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 195/80R15 **Rear Tyre Size:** 195/80R15
Front Left Side: Bridgestone 9 mm **Rear Left Side:** Bridgestone 9 mm
Front Right Side: Bridgestone 9 mm **Rear Right Side:** Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,772.17	428.55	1,343.62	75.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	515.00	905.00	63.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,192.17	943.55	2,248.62	70.44

INSPECTION

Date of Assignment: 23/07/2019
Date Inspected: 25/07/2019 **Inspected At:** Guan Motor Works (HQ)
 176 Sin Ming Drive #02-03 Sin Ming
 Autocare
 Singapore 575721

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Cut	571.40 FL	*571.40 FL	
2	1		*RH FRONT BUMPER SIDE RETAINER	Serviceable	191.30 FL	*- FL	
3	1		*RH FRONT DOOR	Repair	1,600.20 FL	*- FL	
					Sub Total (S\$)	2,362.90	571.40
					- List Item Discount on L Items 25.00/25.00% (S\$)	590.73	142.85
					Total Parts (S\$)	1,772.17	428.55

F=Franchise part, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR REMOVE/REFIT.PANEL BEATING,CUTTING/WELDING AND REPLACEMENT OF DAMAGES	New	600.00	300.00
2	TO PUTTY AND SPRAY PAINTINGS CHARGES	New	700.00	200.00
3	TO CHECK WIRINGS & LIGHTINGS	New	40.00	15.00
4	TO REMOVE AND REFIX FRONT RH DOOR FITTINGS	New	80.00	0.00
Gross Labour Cost (S\$)			1,420.00	515.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >