

# SMRT Accident Vehicle Repair Estimates

Khna chng



60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63665592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 23/07/2019

User ID : TuckFoo

Section A - Accident Details		
Registration Number	SHB5506U	
Case Reference Number	TAX/07/19/2080	
Registration Date	11/1/2017	
Company Type	SMRT Taxis Pte Ltd	
Make	TOYOTA	
Model	PRIUS4	
Name of Driver	CHEW CHOON KEE ( JIANG JUNQI )	
Type of Accident	Side Swipe	
Accident Date and Time	7/20/2019 8:30 PM	
Accident Reported Date and Time	7/22/2019 11:30 AM	
Is Surveyor Required?	Yes	
Survey by		
Vehicle is Towed Back?	Yes	
Towed Back Date and Time	7/20/2019 9:45 PM	
Replacement Vehicle issued?	No	
Job Card Number	24102498	
Special Instruction to ARC, if any	TP/TOWED \$40	
Prepared Date and Time	7/23/2019 2:23 PM	
Chassis Number		
Mileage		
Work Shop		
Repair Completion Date and Time		

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$0.00	\$0.00
Total Spray Cost	\$180.00	\$80.00
Total Spare Part Cost	\$1,222.64	\$0.00
Total Other Cost	\$256.00	\$80.00
<b>TOTAL COST</b>	<b>\$1,658.64</b>	<b>\$160.00</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN
ARC / Surveyor Sign Off Date	23/07/2019 2:36 PM	23/07/2019 4:16 PM
Signature		
Remarks	P/P repair, finalize sent to stevechen@tkkauto.com	

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates	

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 23/07/2019

User ID : TuckFoo

## Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour		

## Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY VIEW MIRROR	\$180.00	\$80.00 ✓
Total Spray Painting & Panel Beating	\$180.00	\$80.00

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$60.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TOWING CHARGE	\$56.00	\$0.00 40 ✓
Total Other Costs	\$256.00	\$80.00 120

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		8794047440	MIRROR ASSY, OUTER REAR VIEW, LH	0.00	\$1,283.90	0.00	\$0.00	Replace	Not Given X MN
		8794547060A1	COVER, OUTER MIRROR, LH	0.00	\$89.50	0.00	\$0.00	Replace	Not Given X R
Total					\$1,373.40		\$0.00		

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

200

**LKK Auto Consultants** hence notify the Repairer of the following:



- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details	
Registration Number	SHB5506U
Case Reference Number	TAX/07/19/2080
Registration Date	1/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHEW CHOON KEE ( JIANG JUNQI )
Type of Accident	Side Swipe
Accident Date and Time	20/7/2019 8:30 PM
Accident Reported Date and Time	22/7/2019 11:30 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	20/7/2019 9:45 PM
Replacement Vehicle issued?	No
Job Card Number	24102498
Special Instruction to ARC, if any	TP/TOWED \$40
Prepared Date and Time	23/7/2019 2:23 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$0.00	\$0.00
Total Spray Cost	\$180.00	\$80.00
Total Spare Part Cost	\$1,222.64	\$0.00
Total Other Cost	\$256.00	\$120.00
TOTAL COST	\$1,658.64	\$200.00 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN (LKK) / AIG
ARC / Surveyor Sign Off Date	23/07/2019 2:36 PM	23/07/2019 4:16 PM
Signature		
Remarks	P/P repair, finalize sent to stevechen@lkkauto.com	



## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1907-0521	Invoice Number	
Quotation Date	30.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
Total Labour		

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY VIEW MIRROR	\$180.00	\$80.00
Total Spray Painting & Panel Beating	\$180.00	\$80.00

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$60.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TOWING CHARGE	\$56.00	\$40.00
Total Other Costs	\$256.00	\$120.00

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		87940474 40	MIRROR ASSY, OUTER REAR VIEW, LH	0.00	\$1,283.90	0.00	\$0.00	Replace	Not Given X
		87945470 60A1	COVER, OUTER MIRROR, LH	0.00	\$89.50	0.00	\$0.00	Replace	Not Given X
Total					\$1,373.40		\$0.00		

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

0.00  
+ 200.00  
-----  
200.00