

22/03/2002

ASS. REC. BY:

REF: CS3/CT119013024/R1C P307 Special Instruction:

Survivor: Rasu**ASSIGNMENT (Office)**From (Person): Tan Kah Leong of C12 Date/Time: 22.7.19 17.13 p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PBA 1410P Insured: SDZ 3810Aat Workshop m/s MS Car Auto Tel: 63851832of 8 Kaki Bukit Ave 4 #10107Policy No: DMPCSN30129819033 Claim No: SNM19D203385C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 17.7.19  
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 24.7.19 9.57 a.m Person Contacted: June H.O.D. Endorsement: \_\_\_\_\_Vehicle IN / OUT

Date/Time	Action/Instruction ( <u>X</u> ) Estimate
	<u>FBA 1410P NA/MSG19012926/24</u>
	<u>SDZ 3810A</u> <u>11</u>
	<u>No estimate,</u>
	<u>Disassemble: 30/7/2019</u>
	<u>After repair: 25/8/2019</u>

Surveyor P. Rame

REF: CT1


4601  
COE XPIRY: 2021/FEB

### ASSIGNMENT

From: \_\_\_\_\_ Date: 24.7.2019  
Estimated Cost: \_\_\_\_\_  
OD (TP) WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: PBA 1410P  
at Workshop m/s MS CAR AUTO  
of 8 Kaki Bukit Ave 4 #01-07  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: SK  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PF Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS mp'

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: PBA 1410P Yr Regn: 2006 / FEB  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: Honda Wave 125 SA c.c. 125  
Colour: Red A/C: Insured / Std / NI / NA  
Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: NF 125MT00/6025  
Gen. Cond: Good / Fail / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 80/90-17  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or MAXXIS  
Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. 3 mm R/Bal. 3 mm  
L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm  
D.O.A. 17/07/19 D.O.I. 24/07/19  
Survey held at MS CAR AUTO  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
N/S Prg  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Range + Days</u>
	<u>Range - 2,000 - 2,800</u>
	<u>Repair day - 3 days</u>
	<u>10/9/2019</u>

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\_\_\_\_\_ S + RS, \_\_\_\_\_ SI

Photos

Others

TOTAL

Report Format: PRQ

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

150

150

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jul 2019		23 Jul 2019 17:13 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:									
Main Claimant: <b>LOH CHIN CHOY</b> , ID: S7276460I									
Vehicle Reg. No.: <b>FBA1410P</b>									
Date of Loss: 17/07/2019 20:00 - :59									
Claim Type: <b>TP / SNM19D203385C02</b>									
Policy/Cover Note No.: DMPCSN30129819033									
Vehicle Reg. No. (Insured): <b>SDZ3810A</b>									
Policy No. (Claimant): MSD/VMT/19-997929-WTT									
Excess: S\$1,000.00									
Repairer: <b>Ms Car Auto Pte Ltd (HQ)</b> 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Tan Kah Leong</b> - 63896193]									
Claimant's Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 01/08/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"> <a href="#">View All</a> <a href="#">Compose Case Mail</a> </span>									
There are no mail for this case.									
<input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4601
Vehicle Details	
Vehicle No.:	FBA1410P
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	WAVE 125S A
Primary Colour:	Red
Manufacturing Year:	2005
Engine No.:	NF125MTE0016025
Chassis No.:	NF125MT0016025
Maximum Power Output:	-
Open Market Value:	\$1,767.00
Original Registration Date:	13 Feb 2006
First Registration Date:	13 Feb 2006
Transfer Count:	1
Actual ARF Paid:	\$266.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Feb 2021
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$3,243.00
COE Rebate Amount:	\$1,008.00
<b>Total Rebate Amount:</b>	<b>\$1,008.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 24 Jul 2019

OK

5000  
1008  
-----  
3992  
//

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/07/2019 21:16
Date Of Accident	17/07/2019 20:00
Exact Location Of Accident	JUNC YIO CHU KANG RD & SERANGOON GARDEN WAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBA1410P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LOH CHIN CHOY
NRIC No	S7276460I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97883905
Alternative Phone No	OFFICE-97883905

### Vehicle Particulars

Manufacturer	HONDA
Model	WAVE 125S A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MSD/VMT/19-997929-WTT
Cover Note Number	

### Driver

Name of Driver	LOH CHIN CHOY
NRIC No	S7276460I
Date Of Birth	05/04/1972
Occupation	OUTDOOR
Date Of Driving Pass	27/02/1997
Driving Experience	22 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97883905
Fax Number	
Contact Number	OFFICE-97883905
Email Address	NOEMAIL

Address	BLK 116 SERANGOON NORTH AVENUE 1 #05-493
Postcode	550116
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SERANGOON NORTH NEIGHBOURHOOD POLICE POST
Police Station Address	<b>ROAD:</b> BLK 108 SERANGOON NORTH AVENUE 1 #01-709 , <b>POSTCODE:</b> 550108 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-2849999 - <b>FAX NO:</b> 63431742
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20190718/2113.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDZ3810A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name LOH CHIN CHOY

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? FBA1410P

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

## Accident Sketch Plan

### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature Date  
& Time:

  
Driver's Signature  
(If driver is not the policyholder) Date  
& Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan

## SKETCH PLAN




## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


AS a police Report T/20190718/2113

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature Date  
& Time:

DIARYC SketchPlanForm\_V3

  
Driver's Signature  
(If driver is not the policyholder) Date  
& Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Police Report



**SINGAPORE  
POLICE FORCE**



T/20190718/2113

Police Station Of Origin:  
Serangoon North NPP  
108 Serangoon North Ave 1 #01-709  
SINGAPORE 550108  
Tel No: 1800-2849999

1 of 3  
Report No. T/20190718/2113

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15 JUL 2019 15:30		Video Report No.:		Station Diary No. 15
<b>Informant's Particulars</b>				
Name of Informant: LOH CHIN CHOY		Address: APT BLK 116 SERANGOON NORTH AVENUE 1 #05-49J SINGAPORE 550116		
ID Type / ID No. NRIC NO / S72764601		Contact No.: Home/Office: Mobile: 97883905		
Nationality MALAYSIAN		Email:		
Sex: Male	Age: 47	Date of Birth: 05/04/1972	Type of Informant: Rider	
Race: Chinese		Language:	Institution / School Name:	
Occupation: Senior System Analyst		Driving Licence Information: Class: Date of Expiry:		

## General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/07/2019 20:00	Type of Location: Straight Road
Location: Junction of Road 1 and Road 2 YIO CHU KANG ROAD SERANGOON GARDEN WAY Junction of Yio Chu Kang Road and Serangoon Garden Way				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBA1410P	Motorcycle	HONDA	WAVE 125S A	Red		0

5232810A CAN 116 Serangoon North Ave 1


## Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBA1410P	MSIG INSURANCE (SINGAPORE) PTE. LTD.	60838240	14/02/2019	13/02/2020

# Police Report



**SINGAPORE  
POLICE FORCE**



T/20190718/2113

Police Station Of Origin:  
Serangoon North NPP  
108 Serangoon North Ave 1 #01-709  
SINGAPORE 550108  
Tel No: 1800-2849999

2 of 3

Report No. T/20190718/2113

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	LOH CHIN CHOY	ID No.	S7276460I
Related Vehicle	FBA1410P (Motorcycle)	Contact No.	97883905
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	17/07/2019	Date Discharge	17/07/2019
No. of Days granted Medical Leave	14	Degree of Injury	Serious

### Brief Details.

On 17/7/2019 at about 1930hrs, I was riding my motorcycle (FBA1410P) along Yio Chu Kang road going towards Upp Thomson road. While at the junction of Serangoon Garden Way, one unknown vehicle suddenly filtered into my lane from Serangoon Garden Way and hit onto me.

After the accident, the driver did attend to me but I was in a shock therefore I did not take any photo of the accident. However, I only managed to take down the phone number of the driver which is 91728688. After awhile, traffic police and ambulance arrive and I was conveyed to Sengkang general hospital. The hospital then informed that I may have sustained a fracture in my right wrist and due to my spectacles that broke I sustained a cut on my left eye. I was then given 14 days MC due to my injuries and was asked to visit the hospital again to visit a bone specialist to verify the injury on my right wrist.

I am lodging this report for police assistance.

Police Report



**SINGAPORE  
POLICE FORCE**



T/20190718/2113

Police Station Of Origin:  
Serangoon North NPP  
108 Serangoon North Ave 1 #01-709  
SINGAPORE 550108  
Tel No: 1800-2849999

1 of 3

Report No. T/20190718/2113

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 CHO JUN XIONG

Signature Of Informant:



Signature Of Interpreter:

Not applicable

Date/Time:

18/07/2019 15:30

Officer In Charge Of Case:

TP / GIT /

Staff Sgt QHAIRIL BIN ZULKEFLÉE

Contact No.: 65476187

Classification Of Case:

SN 154

Authentication Stamp

NP158



Singapore Police Force

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jul 2019		23 Jul 2019 17:13 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<a href="#">[Created by insurer]</a>							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>LOH CHIN CHOY</b> , ID: S7276460I								
Vehicle Reg. No.:	<b>FBA1410P</b>	Date of Loss:	17/07/2019 20:00 - :59 [161 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D203385C02</b>	Policy/Cover Note No.:	DMPCSN30129819033						
Vehicle Reg. No. (Insured):	<b>SDZ3810A</b>	Policy No. (Claimant):	MSD/VMT/19-997929-WTT						
		Excess:	S\$1,000.00						
Repairer:	<b>Ms Car Auto Pte Ltd (HQ)</b> 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Tan Kah Leong</b> - 63896193]								
Claimant's Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 01/08/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> 		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									












































## Claim Documents


































**\*FBA1410P (SNM19D203385C02)**  
**[SDZ3810A]**

TP  
**LOH CHIN CHOY**  
**Jul 17 2019 8:00PM**  
 [-]  
**Ms Car Auto Pte Ltd**













Upload Documents | Upload Photos | Compose New Letter

View View in Browser v

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
2	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
3	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
4	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
5	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
6	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
7	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
8	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
9	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
10	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
11	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
12	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
13	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
14	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
15	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
16	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
17	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
18	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
19	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
20	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
21	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
22	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
23	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
24	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
25	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
26	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
27	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
28	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
29	26/07/19 15:48	General View	 Load JPG	<input checked="" type="checkbox"/>
30	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	05/08/19 16:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	10/09/19 11:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	22/07/19 21:26	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	22/07/19 21:25	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	22/07/19 21:25	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	22/07/19 21:25	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	22/07/19 21:25	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	22/07/19 21:25	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	22/07/19 21:25	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	22/07/19 21:21	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	22/07/19 21:21	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	22/07/19 21:21	Police Report	 Load JPG	<input checked="" type="checkbox"/>
4	22/07/19 21:21	Police Report	 Load JPG	<input checked="" type="checkbox"/>
5	22/07/19 21:21	Police Report	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19013024/R1CF3E2

Date: 17/09/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN30129819033

Claimant  
Vehicle No : FBA1410PInsured  
Vehicle No : SDZ3810A

Date of Loss: 17/07/2019

Nature of Claim: TP

Claim  
No: SNM19D203385C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBA1410P

Make &amp; Model: HONDA WAVE 125-S, 125cc

Engine No: NF125MTE0016025

Reg. Date: 13/02/2006 (Man. Year: 2005)

Chassis No: NF125MT0016025

Colour: Red

Odometer: 0 km

Engine Capacity: 125 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	80/90-17	Rear Tyre Size:	80/90-17
Front Left Side:	Maxxis 3 mm	Rear Left Side:	Maxxis 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 23/07/2019

Date Inspected: 24/07/2019 Inspected At:

Ms Car Auto Pte Ltd (HQ)  
8 KAKI BUKIT AVE 4 #01-07  
PREMIER @ KAKI BUKIT  
Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$2,800.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 17 Sep 2019)	
<b>Parts:</b>	N/A	HONDA WAVE 125-S 125cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBA1410P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >