

22/07/2019

ASS. REC. BY

REF:

CS3/CT/19013034/Fcl36

Instruction:

Assigner: Ram

## ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

28/7/19 5.45pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJY 5522

Insured:

SJU 6500E

at Workshop m/s

Paul Hui Batteries

Tel:

9623 5068

of

1 kaki Bukit Ave 6# 01-109

Policy No:

Claim No:

SNM19D203417

Sum Insured:

Excess:

Make of Veh:

D.O.A

19/07/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

10.38am @ 24/7/19

Person Contacted:

paul

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate (X)

SJY 5522

CS3/MSG16002963/MIVbid 1-1

DOA = 15/2/16

SJU 6500E

CC6/AIG14022149/Miha 392

DOA = 29/11/14

Dismantle: 30/7/2019

After repair: 1/8/2019



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Aug 2019		02 Aug 2019 16:06 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	ONG KIAN GUAN, JASON, ID: S7805969I
Vehicle Reg. No.:	SJY552Z
Claim Type:	TP / SNM19D203417C02
Vehicle Reg. No. (Insured):	SJU6500E
Date of Loss:	19/07/2019 19:00 - :59
Policy/Cover Note No.:	DMPCSN30125719000
Policy No. (Claimant):	5107211937
Excess:	S\$0.00
Repairer:	Paul Hoe Batteries & Motor Services (HQ) 1 KAKI BUKIT AVE 6 #01-109, 417883 Kaki Bukit - Tel:
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 15/08/2019]

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Tuesday, 23 July 2019 5:45 PM  
**To:** Rachel Ling  
**Cc:** 'Ling Leong Hui'; 'Mdm Ling'; 'assignments'  
**Subject:** RE: YOUR REF: SNM19D203417-CHONGBS & OUR REF: TCMG/SJY552Y/0719/PHB - PRE REPAIR INSPECTION NOTICE FOR SJY 552 Z -PRS

**WITHOUT PREJUDICE**  
**SAVE AS TO COSTS**

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

### **Chong Boon Sen**

Claims Executive  
Department

#### **China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平狮城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Rachel Ling [mailto:jin@tcmg.com.sg]  
**Sent:** Tuesday, 23 July, 2019 2:57 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Cc:** 'Ling Leong Hui' <lhling@tcmg.com.sg>; 'Mdm Ling' <mdmling@tcmg.com.sg>  
**Subject:** RE: YOUR REF: SNM19D203417-CHONGBS & OUR REF: TCMG/SJY552Y/0719/PHB - PRE REPAIR INSPECTION NOTICE FOR SJY 552 Z -PRS

**WITHOUT PREJUDICE**

Dear Boon Sen,

We refer to the above matter and to your mail of even date.

Our client is not agreeable to any of your appointed panel of surveyors as the Single Joint Expert.

Our client's panel of surveyors nominated as the Single Joint Expert is as attached.

Regards,  
Rachel Ling

---

**From:** Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

**Sent:** Tuesday, 23 July, 2019 2:52 PM

**To:** [lhling@tcmg.com.sg](mailto:lhling@tcmg.com.sg); [jln@tcmg.com.sg](mailto:jln@tcmg.com.sg); [mdmling@tcmg.com.sg](mailto:mdmling@tcmg.com.sg)

**Subject:** RE: OUR REF: SNM19D203417-CHONGBS & YOUR REF: SJY552Y - PRE REPAIR INSPECTION NOTICE FOR SJY 552 Z -PRS

**WITHOUT PREJUDICE**

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Claims Dept of CTI

**Sent:** Tuesday, 23 July, 2019 2:43 PM

**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; [lhling@tcmg.com.sg](mailto:lhling@tcmg.com.sg); [jln@tcmg.com.sg](mailto:jln@tcmg.com.sg); [mdmling@tcmg.com.sg](mailto:mdmling@tcmg.com.sg)

Cc: Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>

Subject: OUR REF: SNM19D203417-CHONGBS & YOUR REF: SJY552Y - PRE REPAIR INSPECTION NOTICE FOR SJY 552 Z -PRS

Dear Boon Sen

Please conduct PRS –SJY552Y soonest possible-

File to officer in charge –Chong Boon Sen-DID: 6389 6171

Regards

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

TEL: (65) 63896116 - F: (65) 6224 7478

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI

**Sent:** Tuesday, July 23, 2019 11:05 AM

**To:** Angie Foo

**Subject:** FW: PRE REPAIR INSPECTION NOTICE FOR SJY 552 Z | YOUR REF: SJU 6500 E

---

**From:** Rachel Ling [<mailto:jin@tcmg.com.sg>]

**Sent:** Tuesday, 23 July, 2019 10:53 AM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Cc:** 'Ling Leong Hui' <[lhling@tcmg.com.sg](mailto:lhling@tcmg.com.sg)>; 'Mdm Ling' <[mdmling@tcmg.com.sg](mailto:mdmling@tcmg.com.sg)>

**Subject:** PRE REPAIR INSPECTION NOTICE FOR SJY 552 Z | YOUR REF: SJU 6500 E

**Our Ref:** TCMG/SJY 552 Z/0719/PHB

**Your Ref:** SJU 6500 E

Dear Sirs,

**PRE-REPAIR INSPECTION NOTICE**

**ACCIDENT INVOLVING SJY 552 Z AND SJU 6500 E ON 19 JULY 2019 ALONG BRAS BASAH ROAD (NEAR BENCOOLEN MRT)**

We act for **Ong Kian Guan, Jason**, the owner and/or driver of motor vehicle no. **SJY 552 Z**, which was involved in an accident along Bras Basah Road (near Bencoolen MRT) on 19<sup>th</sup> July 2019 at 19:30 hrs.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **SJU 6500 E** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Paul Hoe Batteries & Motor Services, (1 Kaki Bukit Avenue 6 #01-109 - Paul Hoe @ 9623 5068).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Regards,  
Rachel Ling

TOMMY CHOO, MARK GO LLC  
151 Chin Swee Road  
#14-15/16 Manhattan House  
Singapore 169876

Tel: 6532 2455  
Fax: 6538 9850

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

969I

### Vehicle Details

Vehicle No.:

SJY552Z

Vehicle to be Exported:

No

Intended Deregistration Date:

29 Jul 2019

Vehicle Make:

FORD

Vehicle Model:

FOCUS TREND 1.6L AUTO

Primary Colour:

Silver

Manufacturing Year:

2010

Engine No.:

AJ73349

Chassis No.:

WF0SXXGCDSAJ73349

Maximum Power Output:

74.0 kW (99 bhp)

Open Market Value:

\$13,640.00

Original Registration Date:

30 Jul 2010

First Registration Date:

30 Jul 2010

Transfer Count:

1

Actual ARF Paid:

\$13,640.00 × 50% = \$6820

### Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

29 Jul 2020

PARF Rebate Amount:

\$7,502.00

### Intended COE Rebate Details

COE Expiry Date:

29 Jul 2020

COE Category:

A - Car (1600cc & below)

COE Period(Years):

10

QP Paid:

\$29,501.00

COE Rebate Amount:

\$2,950.00

Total Rebate Amount:

\$10,452.00

The information contained herein is correct as at 29 Jul 2019

DOA: 19/07/2019

OK

Remaining: 1 year 10 days (12.3 months)

Depri: \$7270 (yearly) \$605.83 (monthly)

$12.3 \times \$605.83 = \$7451.74$

$\$7451.74 + \$6820 = \$14271.74$



## Singapore Dollar Tumbles Big - After This Big Announcement

Many Singaporeans Don't Know But This Announcement Is Not Good For Singapore Citizens  
wealthyfortuner.com

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Honda Stream 1.8A



3.08% p.a. Std. Grade B No Major Damage, 2 Year Warranty \$2800 Down, Monthly Pmt \$688  
GV Credit Pte Ltd Starling

**HIN LUNG AUTO**  
Ho Bee Group

**One Stop Car Hub**  
Finance, Insurance, Workshop  
New and Used Cars

**30 years**  
of car sale


Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

1 vehicles

ford focus trend

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	ford focus trend	Any	Any	2010	Any	Any	Any	Available
	<b>Ford Focus 1.6A Trend</b>	<b>\$15,800</b>	<b>\$7,270 /yr</b>	<b>30-Sep-2010</b>	<b>1,596 cc</b>	<b>-</b>	<b>Sedan</b>	<b>Available</b>
Set To Sell! Extremely Well Maintained, 100% Accident Free, Original Condition With No Touch Up Done! No Repairs Required! Consignment Unit, Come View To Appreciate Anytime, Before It's Gone! Kindly Call To Arrange For Viewing!								
Posted: 25-Jun-2019 Tags: 2010 Ford Focus, 2010 ford focus, Ford Focus, ford focus, Ford, Focus, focus, Used Ford								

Save this search criteria, to get email alerts whenever a match is found.

Make: Model: Price: Depreciation: Reg Date: Eng Cap: Mileage: Veh Type: Status:

For old advertisements, view Expired ads

20 results/page

[Home](#) [New Cars](#) [Used Cars](#) [Sell My Car](#) [Directory](#) [Products](#) [Insurance](#) [Article](#) [Forum](#) [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used ford focus trend, ford focus trend Singapore, used ford focus trend Singapore, used vehicles Singapore or even buy used ford focus trend Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**

[About Us](#) [Careers](#) [Contact Us](#) [Sitemap](#) [Terms of Service](#) [Privacy Policy](#) [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[Compare](#)

MSME19085040 / SME Motor Pte Ltd - Kaki Bukit  
 ENTRY DATE & TIME: 20/07/2019 14:12  
 SUBMITTED BY: Wen Ying

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report	20/07/2019 14:12
Date Of Accident	19/07/2019 19:30
Exact Location Of Accident	ALONG BRAS BASAH ROAD (NEAR BENCOOLEN MRT).
Country/State of Loss	SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY552Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ONG KIAN GUAN, JASON
NRIC No	S7805969I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82987320
Alternative Phone No	OFFICE-82987320

## Vehicle Particulars

Manufacturer	FORD
Model	FOCUS WAGON

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

## Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107211937
Cover Note Number	

## Driver

Name of Driver	ONG KIAN GUAN, JASON
NRIC No	S7805969I
Date Of Birth	03/03/1978
Occupation	INDOOR
Date Of Driving Pass	09/06/2000
Driving Experience	19 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-82987320
Fax Number	
Contact Number	OFFICE-82987320
Email Address	NOEMAIL

Address BLK 281 TOH GUAN RD #12-223  
 Postcode 600281  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1  
 NAME: : MR TOMONORI TEZUKA  
 GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name EUNOS NEIGHBOURHOOD POLICE POST  
 Police Station Address ROAD: BLK 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-4439999 - FAX NO: 62444376  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

PLS REFER TO POLICE REPORT NO.T/20190720/2070.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJU6500E  
 Vehicle Make/Model/Colour  
 Details Of Properties VEH B  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

ONG KIAN GUAN, JASON

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJY552Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

## Accident Sketch Plan Pg. 1

## SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

19 SAT 14:56 FAX

## Accident Sketch Plan Pg. 1

TH PLAN



## DESCRIBE THE CIRCUMSTANCES OF THE ACCIDENT

The above mentioned accident happened on the 19 July around 19.30 hrs. while I was travelling along Bras Basah road heading to the Changi airport with a passenger onboard. My car came to a complete stop due to the red traffic light. Car B hit into the rear of my car which is Car A.

## DECLARATION

We declare the foregoing particulars are true in every respect.

X  
Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Aug 2019		02 Aug 2019 16:06 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>ONG KIAN GUAN, JASON,</b> ID: S7805969I								
Vehicle Reg. No.:	<b>SJY552Z</b>	Date of Loss:	19/07/2019 19:00 - :59 [107 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D203417C02</b>	Policy/Cover Note No.:	DMPCSN30125719000						
Vehicle Reg. No. (Insured):	<b>SJU6500E</b>	Policy No. (Claimant):	5107211937						
		Excess:	S\$0.00						
Repairer:	<b>Paul Hoe Batteries &amp; Motor Services (HQ)</b> 1 KAKI BUKIT AVE 6 #01-109, 417883 Kaki Bukit - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>PARASURAM SHANMUGAM</b> ] ... [Final Rpt due 15/08/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SJY552Z (SNM19D203417C02)**  
**[SJU6500E]**

**TP**

**ONG KIAN GUAN, JASON**



















































**Jul 19 2019 7:00PM**
























**[-]**

**Paul Hoe Batteries & Motor Services**



Upload Documents			Upload Photos			Compose New Letter			View			View in Browser			
Assessment Reports									1 per page			<input checked="" type="checkbox"/>			
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)								Thumbnail			Print		
1	20/07/19 14:51	Accident Statement								Load HTM					
Photos/Images									3 per page			<input checked="" type="checkbox"/>			
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)								Thumbnail			Print		
1	20/07/19 14:49	Accident Photo [Linked Accident Report Documents]								Load JPG			<input checked="" type="checkbox"/>		
2	20/07/19 14:49	Accident Photo [Linked Accident Report Documents]								Load JPG			<input checked="" type="checkbox"/>		
3	20/07/19 14:49	Accident Photo [Linked Accident Report Documents]								Load JPG			<input checked="" type="checkbox"/>		
4	20/07/19 14:49	Accident Photo [Linked Accident Report Documents]								Load JPG			<input checked="" type="checkbox"/>		
5	20/07/19 14:49	Accident Photo [Linked Accident Report Documents]								Load JPG			<input checked="" type="checkbox"/>		
6	20/07/19 14:49	Accident Photo [Linked Accident Report Documents]								Load JPG			<input checked="" type="checkbox"/>		
7	20/07/19 14:49	Accident Photo [Linked Accident Report Documents]								Load JPG			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail			Print		
1	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
2	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
3	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
4	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
5	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
6	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
7	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
8	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
9	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
10	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
11	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
12	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
13	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
14	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
15	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
16	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
17	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
18	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
19	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
20	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
21	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
22	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		
23	02/08/19 16:11	General View								Load JPG			<input checked="" type="checkbox"/>		



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
24	02/08/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
25	02/08/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
26	02/08/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
27	02/08/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
28	02/08/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
29	02/08/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
30	02/08/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
31	02/08/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
32	02/08/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
33	02/08/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
34	02/08/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
35	02/08/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
36	02/08/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
37	02/08/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
38	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
74	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	02/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	02/08/19 16:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	02/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	02/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	02/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	02/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	02/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	02/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	02/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	02/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
88	02/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	02/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	02/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	02/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	02/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	20/07/19 14:19	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	20/07/19 14:19	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
3	20/07/19 14:19	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
4	20/07/19 14:19	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
5	20/07/19 14:19	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
6	20/07/19 14:19	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
7	20/07/19 14:19	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
8	20/07/19 14:19	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	20/07/19 14:51	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	20/07/19 14:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	20/07/19 14:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	20/07/19 14:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	20/07/19 14:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	20/07/19 14:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	20/07/19 14:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	20/07/19 14:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	20/07/19 14:19	Accident Sketch Plan	 Load TIF	
2	20/07/19 14:19	Accident Sketch Plan	 Load TIF	
3	20/07/19 14:19	Accident Sketch Plan	 Load TIF	
4	20/07/19 14:19	Accident Sketch Plan	 Load TIF	
5	20/07/19 14:19	Accident Sketch Plan	 Load TIF	
6	20/07/19 14:19	Accident Sketch Plan	 Load TIF	
7	20/07/19 14:19	Accident Sketch Plan	 Load TIF	
8	20/07/19 14:19	Accident Sketch Plan	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19013034/FCF3E2

Date: 06/08/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN30125719000

Claimant Vehicle  
No : SJY552ZInsured Vehicle  
No : SJU6500E

Date of Loss: 19/07/2019

Nature of Claim: TP

Claim  
No: SNM19D203417C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJY552Z

Make &amp; Model: FORD FOCUS, 1.6 (A)

Engine No: AJ73349

Reg. Date: 30/07/2010 (Man. Year: 2010)

Chassis No: WF0SXXGCDSAJ73349

Colour: Silver

Odometer: 202900 km

Engine Capacity: 1596 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size: 225/50 R17

Front Left Side: Firenza 5 mm

Rear Left Side: Firenza 5 mm

Front Right Side: Firenza 5 mm

Rear Right Side: Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 02/08/2019

Date Inspected: 29/07/2019 Inspected At:

Paul Hoe Batteries & Motor Services (HQ)  
1 KAKI BUKIT AVE 6 #01-109  
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2019)
<b>Parts:</b>	143	FORD FOCUS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJY552Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >