

ASS. REC. BY:

REF:

CS3/11119013069/FcF302

Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

From (Person): Gabriel Wee

of

III

Date/Time: 24/7/19 @ 2.11pm

Estimated Cost:

Bill to:

OD / TP / FWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJP 1351C

Insured:

SHC 8455H

at Workshop m/s

T.W Lim Motor

Tel:

9740 9067

of

160 Sin Ming Drive # 08-12

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17/07/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4.09pm @ 24/7/19

Person Contacted:

Mr. Lim

Vehicle IN/OUT

Date/Time

Action/Instruction Estimate (X)

SJP 1351C X

SHC 8455H

CC3/AXA/2018824/H1edg2 DOA = 25/9/12

Dismantle : 26/7/2019. @ 11.00am

ASS. REC. BY: RAM

REF:

III

PRS

ASSIGNMENT

From:

Date:

25/7/19

Veh No:

SJP 1351C

Yr Regn: MAY 2009

Estimated Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SJP 1351C

Make: MITSUBISHI LANCER 1.6 CVT C.C 1584

at Workshop m/s

T.W. Lim Motor

Colour: BLUE

A/C: Insured / Std / NI / NA

of 160 & n Ming Drive # 08-12

Sp. Reading: 115717

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No: JMYSTCS3A9V005398

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

After 9am

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 195/60 R15

R: 195/60 R15

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Good year

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 5 mm

R/Bal. 5 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 5 mm

L/Bal. 5 mm

Est. Repairs: days Res.: Yes or No

D.O.A. 17/7/2019

D.O.I. 25/7/2019 0156pm

Lum Sum: % 3 Val.: Yes or No


Survey held at T.W LIM MOTOR

CA / REV / REP. / 24 HRS ^{1up}Des. of Damages rt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: \$2000 - \$3000
	Repair Days: 4 days
	
	26/7/2019
	MY: \$24000
	PV: \$11804
	NV: \$12000

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format: PRS.

Lump Sum / L.P.D. %

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

120

11

141

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	(Not Notified) Edit Reg		24 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	
Main Claimant:	GOH YUN KER LAWRENCE, ID: S6809788F
Vehicle Reg. No.:	SJP1351C
Claim Type:	TP
Vehicle Reg. No. (Insured):	SHC8455H
Date of Loss:	17/07/2019 01:00 - :59
Policy/Cover Note No.:	
Policy No. (Claimant):	
Excess:	
Repairer:	T.w. Lim Motor (HQ) 160 Sin Ming Drive, #08-12, Sin Ming Auto City, 575722 Sin Ming - Tel: 97409067
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/08/2019]

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 24 July 2019 2:11 PM
To: Oracle Law Corp; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Manivel Priyadarshini
Subject: RE: Our Ref: SB/PO/Acc/2019-9056 Your Ref: Insurer of SHC 8455H
Attachments: shc8455h_20190724115040.pdf; 9056 - List of MS_20190724122002.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SJP1351C
III INSURED VEHICLE NO. : SHC8455H
DATE OF LOSS : 17.07.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Priya**.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Oracle Law Corp [mailto:mail@oraclelaw.sg]
Sent: 24 July, 2019 12:28 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: Our Ref: SB/PO/Acc/2019-9056 Your Ref: Insurer of SHC 8455H

Dear Gabriel,

PRE-REPAIR INSPECTION

ACCIDENT INVOLVING SJP 1351C & SHC 8455H IN FRONT OF HOUSE NO. 16 THOMSON WALK ON 17-07-2019 @ 12.30 A.M.

Please refer to attachment the contents of which are self-explanatory for your kind attention and immediate action

Regards

Alvin Ong



• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Wednesday, 24 July 2019 11:59 AM

To: Oracle Law Corp <mail@oraclelaw.sg>

Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJP1351C (Accident involving SJP1351C and SHC8455H on 17.07.2019)

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Oracle Law Corporation

• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11
The Alexcler, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860
Email: mail@oraclelaw.sg

FACSIMILE TRANSMISSION

To	: India International Insurance Pte Ltd	Date	: 24 th July 2019
Attention	: Motor Claims	From	: Mr Stanley Bay / Miss Pauline Ong
Your Ref.	: Insurer of SHC 8455H	Our Ref.	: SB/PO/Acc/2019-9056
Facsimile	: 6225-7743 / 6224-4174	No. of Pages	: 5 (Including this page)

IMMEDIATE ATTENTION

Dear Sirs

PRE-REPAIR INSPECTION

ACCIDENT INVOLVING SJP 1351C & SHC 8455H IN FRONT OF HOUSE NO. 16 THOMSON WALK ON 17-07-2019 @ 12.30 A.M.

We act for the owner of vehicle registration no. **SJP 1351C**.

We are instructed by our client to notify you of the above accident involving our client's said vehicle and your insured's vehicle registration no. **SHC 8455H** driven at the material time. A copy of our client's motor accident report is enclosed herein.

As a result of the above accident, our client's said vehicle was damaged. Before our client proceeds to repair his damaged vehicle, please let us know within the next (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair his said vehicle without further reference to you.

Please note that this notification does not in any way prejudice our client's right nor shall it be deemed as a waiver of any of his rights, as such our client's rights are expressly reserved.

Yours faithfully



Mr Stanley Bay / Miss Pauline Ong
Enc

Details of Repairer

T.W. Lim Motors Works
160 Sin Ming Drive
#08-12 Sin Ming Autocity S(575722)
Tel No : 9740-9067 (hp) - Lim Tau Wing
Fax No. 6457-2371



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	788F
Vehicle Details	
Vehicle No.:	SJP1351C
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jul 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 CVT SPORTS GLX AIRBAG 2WD 4DR
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	4G18KB9989
Chassis No.:	JMYSTCS3A9U005398
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$14,734.00
Original Registration Date:	12 Mar 2009
First Registration Date:	12 Mar 2009
Transfer Count:	0
Actual ARF Paid:	\$14,734.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Mar 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$12,763.00
COE Rebate Amount:	\$11,804.00
Total Rebate Amount:	\$11,804.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Jul 2019

DOA: 17/07/2019

OK

Remaining : 4 years 7 months 25 days

(55.8 months)

Depri: \$5350 (Yearly) \$445.83 (monthly)

$55.8 \times \$445.83 = \$24,877.31$ *



CYCLE & CARRIAGE GARAGE SALE

Management and demo units from \$50,000 with COE

RSVP NOW



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Volkswagen Scirocco 1.4A TSI.



Good Fuel Consumption.
Serviced Every 5,000Kms. Well
Maintained & Taken Care By Me.
Direct Owner Star&A!



Browse by Category

« Back (1 2) Next »

Sort by Date Posted

20 results/page

23 vehicles

Mitsubishi Lancer glx 1.6

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mitsubishi Lancer glx 1.6		Any	Any	2009	Any	Any	Any	Available
	Mitsubishi Lancer 1.6M GLX (New 5-yr COE)		\$29,800	\$5,950 /yr	02-Jul-2009	1,584 cc	-	Sedan	Available
Full Body Kit With New Paintwork! Full Loan Available At \$663. Monthly, Interest From 3.18%. Bank Loan And In House Loan Available. Vehicle Checked By In House Workshop. Trade In Welcome.									
Posted: 24-Jul-2019 Tags: 2009 Mitsubishi Lancer, 2009 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi									
	Mitsubishi Lancer 1.6A GLX (COE till 03/2024)		\$24,800	\$5,330 /yr	18-Mar-2009	1,584 cc	110,000 km	Sedan	Available
Selling With Nice Auspicious Number Plate 388! Till 31.07.2017 Still Under Cycle And Carriage Maintain (Agent) Full Loan Available! Act Fast! Monthly At \$532. Car In Tip Top Condition, Well Maintained By Previous Owner! New Paintwork, New Road Tax, No Further Repair...									
SmartCars Boutique Pte Ltd									
Posted: 24-Jul-2019 Tags: 2009 Mitsubishi Lancer, 2009 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi									
	Mitsubishi Lancer 1.6A GLX (New 5-yr COE)		\$26,800	\$5,350 /yr	25-Aug-2009	1,584 cc	120,000 km	Sedan	Available
100% Cheapest In The Market, Sporty White On Black! High LTA Rebate. Low Depreciation. Smooth Engine, Low Mileage Done. Immaculate Condition. Please Call For Viewing.									
Posted: 24-Jul-2019 Tags: 2009 Mitsubishi Lancer, 2009 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi									
	Mitsubishi Lancer 1.6M GLX (New 5-yr COE)		\$29,800	\$5,950 /yr	06-Jul-2009	1,584 cc	70,000 km	Sedan	Available
Drift Racing Legal Full Pipe/Exhaust! Many More Mods! Full Loan Available At \$663. Monthly, Interest From 3.18%. Bank Loan And In House Loan Available. Vehicle Checked By In House Workshop. Trade In Welcome.									
Posted: 22-Jul-2019 Tags: 2009 Mitsubishi Lancer, 2009 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi									

\$5380
\$5330

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Mitsubishi Lancer 1.6A GLX Sports (COE till 07/2024)

\$26,800

\$5,390 /yr

15-Jul-2009

1,584 cc

125,000 km

Sedan

Available

100% Loan Available, After You Make Some Comparison Of The Prices And Depreciation Of Most Lancer, You'll Find That This Lancer Is Of Low Depreciation And Has The Best Value For Your Money. Owned By Executive Owner Selling Due To Upgrading, This Unit Had Served...

SmartCars Boutique Pte Ltd

Posted: 22-Jul-2019 Tags: 2009 Mitsubishi Lancer, 2009 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi



Mitsubishi Lancer 1.6A GLX (COE till 05/2029)

\$58,000

\$5,900 /yr

21-May-2009

1,584 cc

86,000 km

Sedan

Available

Posted: 21-Jul-2019 Tags: 2009 Mitsubishi Lancer, 2009 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi

DIRECT OWNER

Compare

Mitsubishi Lancer 1.6A GLX

-

N.A

13-Oct-2009

1,584 cc

-

Sedan

Available

DIRECT OWNER

MALE18088408 / Ah Lim Motor Company - Bin Ming
ENTRY DATE & TIME: 23/07/2019 16:08
SUBMITTED BY: Meli Tan

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 23/07/2019 16:27

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GI Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/07/2019 16:06
Date Of Accident 17/07/2019 00:30
Exact Location Of Accident IN FRONT OF HOUSE NO. 16 THOMSON WALK
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJP1351C
Insured/Policyholder
Name Of Registered Owner GOH YUN KER LAWRENCE
NRIC No S6809788F
Email Address LAWRENCEGOH@ME.COM
Mobile Phone No (LOCAL) +65-81888326
Alternative Phone No OFFICE-NOPHONE
Vehicle Particulars
Manufacturer MITSUBISHI
Model LANCER 1.6 CVT SPORTS GLX AIRBAG 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company
Name of Insurance Company FWD SINGAPORE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number PNPV2018-00002944-01
Cover Note Number 12/03/2019 TO 11/03/2020

Driver
Name of Driver GOH YUN KER LAWRENCE
NRIC No S6809788F
Date Of Birth 11/03/1968
Occupation INDOOR
Date Of Driving Pass 13/08/1990
Driving Experience 28 YEARS AND 11 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-81888326
Fax Number
Contact Number OFFICE-NOPHONE
Email Address LAWRENCEGOH@ME.COM

Address 16 THOMSON WALK
 Postcode 574463
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (Including own vehicle) Involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident**REFER TO SKETCH PLAN****Attachment(s)**

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC8455H
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category TAXI
 Name of Driver AMIR BIN ALI BANAMA
 NRIC/Passport Number S7822079A
 Contact Number 90518249
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

23/7/19
2:40pm

GIAMC Sketch Plan Form V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:


Mei Li

NRIC/FIN No.:

23/07/2019

Sketch Plan Pg. 2

Date of accident: 17/07/2019 Time: 1230am Location: 16 Thomson Walk S(57496)
 My Vehicle A: SJP1351C Vehicle B: SHC8455H Vehicle C: /
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the early morning on 17th July 2019, we heard a noise outside my house at 16 Thomson Walk. What we described is that Vehicle B SHC8455H driven by Amir Bin Ali Bangura (NRIC S7822079A) had hit my stationary vehicle on the left front corner. He reversed into us. We exchange contact details.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my file accident report to:
 My workshop: T.W. Lim Motor Works

Email address:

& myself:

Email address: lawrence6@ahlim.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Vehicle: SJP 1351C

Policyholder's Signature

Date & Time: 23/7/19 2:30 pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Neil

23/07/2019

AN LIM MOTOR COMPANY

CL-001 Sketch Plan Form 1/4






































...CLAIM SUBFOLDER...(Pending for Survey Report)


















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jul 2019 11:13 Edit Reg		24 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: S7822079A									
Main Claimant: GOH YUN KER LAWRENCE , ID: S6809788F									
Vehicle Reg. No.: SJP1351C		Date of Loss: 17/07/2019 01:00 - :59 [124 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SHC8455H		Policy No. (Claimant):							
		Excess:							
Repairer: T.w. Lim Motor (HQ) 160 Sin Ming Drive, #08-12, Sin Ming Auto City, 575722 Sin Ming - Tel: 97409067									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/08/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJP1351C
[SHC8455H]
TP
GOH YUN KER LAWRENCE
Jul 17 2019 1:00AM
[-]
T.w. Lim Motor

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
15	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
20	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
21	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/07/19 17:25	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
23	25/07/19 17:25	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
24	25/07/19 17:25	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
25	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
26	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
27	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
28	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
29	25/07/19 17:25	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
30	25/07/19 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>
31	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	29/07/19 12:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	25/07/19 08:34	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19013069/FCF3E2

Date: 30/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SJP1351C

Insured Vehicle No : SHC8455H

Date of Loss: 17/07/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJP1351C

Make & Model: MITSUBISHI LANCER, 1.6 CVT (A)

Engine No: 4G18KB9989

Reg. Date: 12/03/2009 (Man. Year: 2009)

Chassis No: JMYSTCS3A9U005398

Colour: Blue

Odometer: 115717 km

Engine Capacity: 1584 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Goodyear 5 mm

Rear Left Side: Goodyear 5 mm

Front Right Side: Goodyear 5 mm

Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/07/2019

Date Inspected: 25/07/2019 Inspected At:

T.w. Lim Motor (HQ)

160 Sin Ming Drive, #08-12, Sin Ming Auto City

Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jul 2019)
Parts:	143	MITSUBISHI LANCER 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP1351C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >