

22222222

ASS. REC. BY:

REF: CS/INC/19013072/Ksd302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Cynthia Ang

of INC

Date/Time: 24/7/19 @ 9.47am

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG 3325P

Insured: SMC 4602S

at Workshop n/s: Esteem Performance

Tel: 87990066

of 385 Sin Ming Drive

Policy No:

Claim No: MT/1053878-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13/07/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9.51am @ 24/7/19

Person Contacted: Carmen

Vehicle IN OUT

| Date/Time | Action/Instruction |
|-----------|---|
| | Lightning <input checked="" type="checkbox"/> |
| | SLG 3325P - X |
| | SMC 4602S - X |
| 6/8 | 81083.12 Carmen |
| | (@ 2,721.18 Rev - 72%) |

ASS. REC. BY:

REF: INCL

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no/s Epstein

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLG 3325P Yr Regn: 09, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Traller or

Make: Toy Prius c.c. 1798

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 293103 T/Radio: Insured / Std / NI / NA

Eng/No: 293213

C/No: JTDKB3U503595225

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 0 mm R/Bal. 0 mm

L/Bal. 0 mm L/Bal. 0 mm

D.O.A. 13/7/19 D.O.I. 24/7/19 02/21

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|----------------------|
| <u>1</u> | <u>File pass to</u> |

RECEIVED 19 AUG 2019

Date/Time, File Pass to? 19/08/19
1) Top
Date/Time, File Return to?

: Prell. Report
 : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

| | |
|-----------------|------------|
| Survey Fee: | <u>240</u> |
| Transportation: | |
| \$ - RS. \$ | |
| Fuel | |
| Others | |
| TOTAL | <u>240</u> |

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Report Format :
Lump Sum / I.B.k (\$ 1,083.12 P/P)

Nivjtha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Wednesday, 24 July 2019 11:38 AM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Cc: Cynthia Ang
Subject: RE: TP CASES FARMED OUT TO LKK ON 24/07/2019

Dear LKK,

Resend with following details.

Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Cynthia Ang
Sent: Wednesday, 24 July 2019 9:47 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; Cynthia Ang <Cynthia.Ang@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 24/07/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

| SN | DIC | Claim No. | Vehicle | WorkShop Name | WorkShop Address | WorkShop Contact | Survey Time | OI Veh | DOA | Additional Remarks |
|----|---------------|------------------|----------|-----------------------------------|---|-------------------|-------------|----------|------------|--------------------|
| 1 | Eric Tang | MT/1054041-002 | SKP40U | AUBURN AUTO PTE LTD | 176 SING MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721 | SAM NG / | | SJX5746D | 18/07/2019 | |
| 2 | | *Pending advise* | SLD8749H | COMFORTDELGRO ENGINEERING PTE LTD | 205 BRADDELL ROAD EAST WING 3RD FLR SINGAPORE 579701 | ANDREW / 63837656 | | | | |
| 3 | Fiona Shen | MT/1054783-001 | SLK1780A | ESTEEM PERFORMANCE PTE LTD | 385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718 | carmen / 87990066 | 10:00-12:00 | GBD9099L | 12/07/2019 | |
| 4 | Eng Huey Huey | MT/1053378-002 | SLG3325P | ESTEEM PERFORMANCE PTE LTD | 385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718 | CARM / 87990066 | 10:30-12:30 | SMC4602S | 13/07/2019 | |

| | | | | | | | | | |
|----|---------------|------------------|----------|---------------------------------|--|---------------------------------|-------------|----------|------------|
| 5 | Fiona Shen | MT/1054563-002 | SLQ2069H | ESTEEM PERFORMANCE PTE LTD | 385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718 | SERENE CHEE / 87990066 | | SLK9926U | 22/07/2019 |
| 6 | Jeff Lin | MT/1051997-002 | SKF8917R | LAI HUAT MENG KEE MOTOR PTE LTD | 160 SIN MING DRIVE #04-01 SIN MING AUTOCITY SINGAPORE 575722 | DEBORAH LAI / 64538110 | | SJS5571S | 05/07/2019 |
| 7 | | *Pending advise* | SME7036X | LEONG AUTO PTE LTD | 160 SIN MING DRIVE #02-13 SIN MING AUTOCITY | DANIEL TAN/CADY LEE / 9692 4113 | | | |
| 8 | Eng Huey Huey | MT/1052391-002 | SMC660A | MOTOR IMAGE ENTERPRISES PTE LTD | 19 LORONG 8 TOA PAYOH SINGAPORE 319255 | DANIEL A JUDE / 86113195 | 10:00-12:00 | SLT8341R | 07/07/2019 |
| 9 | Jared Liu | MT/1054437-002 | SMH6433Z | SKS AUTOMOBILE SOLUTION | 176 SIN MING DRIVE #01-17 SIN MING AUTOCARE SINGAPORE 575721 | MS YIWEN / 64550747 | | SME7134X | 20/07/2019 |
| 10 | | *Pending advise* | SMC7382G | THIAM HENG HUAT PTE LTD | 176 SIN MING DRIVE #05-14 SIN MING AUTOCARE | STEVEN / 82636295 | | | |
| 11 | Jeff Lin | MT/1054330-002 | SLG586Y | VIN'S AUTOMOTIVE GROUP | 160 SIN MING DRIVE #08-09 SIN MING DRIVE SINGAPORE 575722 | RAYMOND TEO / 64532121 | | SLQ6072X | 20/07/2019 |

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-------------------------------------|
| Date Of Report | 16/07/2019 01:32 |
| Date Of Accident | 13/07/2019 18:45 |
| Exact Location Of Accident | MARYMOUNT ROAD TOWARDS THOMSON ROAD |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SLG3325P |
| Insured/Policyholder | |
| Name Of Registered Owner | GRAB RENTALS PTE LTD |
| Co Reg No | 201617200G |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-66550005 |

Vehicle Particulars

| | |
|--|---------------------|
| Manufacturer | TOYOTA |
| Model | PRIUS HYBRID 1.8 CV |
| Exact Purpose for which vehicle was being used at time of accident | HIRE & REWARD |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE HIRE |

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | MSIG INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | YES |
| Policy Number | A29114756MKF |
| Cover Note Number | |

Driver

| | |
|----------------------|------------------------|
| Name of Driver | TAN ECK SOON |
| NRIC No | S1358198C |
| Date Of Birth | 01/06/1959 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 02/08/1980 |
| Driving Experience | 38 YEARS AND 11 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-98388012 |
| Fax Number | |
| Contact Number | |
| EMail Address | NOEMAIL |

| | |
|---|---------------|
| Address | NIL |
| Postcode | |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - HIRER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|---|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 3 |
| Passenger 1 | NAME: : PASSENGER 1 GENDER: : MALE |
| Passenger 2 | NAME: : PASSENGER 2 GENDER: : FEMALE |

Details of Police Action

| | |
|---|---------------|
| Was the accident reported to the police? | YES |
| If Yes, Please state which Police Station | |
| POLICE STATION NAME [OTHER] | PASIR RIS NPC |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

PLEASE REFER TO NOTICE OF REPORTING LODGE AT PASIR RIS NPC THIS IS TO CONFIRM THAT TAN ECK SOON, NRIC: S1358198C, HP: 98388012, HAS REPORTED TO THE POLICE A NON INJURY TRAFFIC ACCIDENT WHICH OCCURRED ALONG MARYMOUNT ROAD TOWARDS THOMSON ROAD, ON 13/07/2019 AT 18:41HRS INVOLVING THE FOLLOWING VEHICLES: 1) SLG3325P (COMPLAINANTS VEHICLE) 2) SMC4602S ON THE ABOVE MENTIONED DATE AND TIME, COMPLAINANTS WAS ON THE MIDDLE LANE ALONG MARYMOUNT ROAD TOWARDS THOMSON ROAD AT THE JUNCTION NEAR BUS STOP NUMBER 53129. AS THE TRAFFIC LIGHT WAS RED, COMPLAINANT HAD STOPPED ACCORDINGLY WITH OTHER TRAFFIC LIGHT. ALL OF A SUDDEN COMPLAINANT FELT AN IMPACT FROM THE REAR OF HIS VEHICLE. COMPLAINANT HAD 2 PASSENGERS WITH HIM AT CHAI POINT OF SIME AND THEY INFORMED THAT THEY WERE NOT INJURED AND DOES NOT REQUIRE ANY MEDICAL ATTENTION. DAMAGES ON V1 ARE AS FOLLOWS: MINIMAL TO NONE DAMAGE AT THE REAR BUMPER OF SCRATCHES DAMAGES ON V2 ARE FOLLOWS: SLIGHT DENT ON THE LICENCE PLATE HOWEVER MINOR DAMAGE PARTICULARS OF THE OTHER DRIVER: WONG CHEE HONG S1563259C 2. IF THIS ACCIDENT WAS REPORTED TO THE POLICE WITHIN 24 HOURS OF ITS OCCURRENCE THEN HE/SHE HAS COMPLIED WITH SEC 84 (2) OF THE ROAD TRAFFIC ACT. CAP 276 RANK / NAME OF ISSUING OFFICER: SGT180047 KHIRUL NAEM DATE: 13/07/2019 TIME: 2051HRS S/D REF NO:89 POLICE POST / UNIT: PASIR RIS NPC

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-------------------------------|
| Vehicle Registration Number | SMC4602S |
| Vehicle Make/Model/Colour | TOYOTA / VIOS G (AUTO) / BLUE |
| Details Of Properties | NA |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | WONG CHEE HONG |
| NRIC/Passport Number | S1563259C |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

3. Consent under the Personal Data Protection Act (PDPA)

- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) All insurer(s) who have insured vehicle(s) involved in the accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Handwritten signature]

VERIFIED BY AJAX MARS
REPORTING OFFICER
Hashim Kamaru


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

15/6/22

Sketch Plan



CONFIDENTIAL

NOTICE OF REPORTING

This is to confirm that Yan Jie Song (NIC: 92011990) of ST 156 3259C has reported to the Police a road traffic accident which occurred on Marine Drive Road towards Thomson Road, on 13/07/2019 at 10:00 AM involving the following vehicles:

- i. ST 156 3259C (complainant's vehicle)
- ii. ST 156 3259C

On the above-mentioned date and time, the complainant was driving in the left lane of Marine Drive Road towards Thomson Road at the junction with Marine Drive (53520). At the time of the accident, the complainant had stopped proceeding with other traffic. All of a sudden, complainant felt an impact from the side of his vehicle. Complainant and 2 passengers with him at that point of time and they informed that they were not injured and does not require any medical attention.

Damages on V1 are as follows:
Minimal to none damage at the rear bumper of scratches

Damages on V2 are as follows:
Slight dent on the license plate however minor damage

Particulars of the other driver:
Wong Choo Hong
ST 156 3259C

2. If this accident was reported to the Police within 24 hours of its occurrence then he/she has complied with Sec 84 (2) of the Road Traffic Act, Cap 276

Rank / Name of Issuing Officer: SGT T180047 Khiral Naem
Date: 13/07/2019 Time: 2051hrs
S/D Ref No: 89
Police Post / Unit: Pasir Ris NPC

Original to be issued to complainant
Duplicate to be submitted to Traffic Police


PASIR RIS NPC
101-01 Pasir Ris Drive 6
Singapore 519451
Tel: 6500-5251230

CONFIDENTIAL

N-til
24.07.2019



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLG 3325 P

*Not Authorized
Resurvey Required*

| | | | |
|-------------------------|-----------------------------|----|------------------------|
| Parts | (a) Cost / List Price Items | \$ | <u>2,912.40</u> |
| | Plus/Less 25% | \$ | <u>728.10</u> |
| | Total of Cost / List | \$ | <u><u>2,184.30</u></u> |
| | (b) Nett Price Items | | _____ |
| | Less | | _____ |
| | Total of Nett Item | | _____ |
| | (c) Special Nett Items | \$ | <u>200.00</u> |
| Total Parts Cost | | \$ | <u><u>2,384.30</u></u> |
| Labour | | \$ | <u><u>1,420.00</u></u> |
| Total | | | <u><u>2304.30</u></u> |

UOC Auto Consultants I hereby notify the Retailer of the following:

- To receive complete repair estimates
- To display the repair parts and labour charges
- Parts prices and subject to the same
- That any work done is subject to a 7% G.S.T. surcharge
- All legal notices of the manufacturer
- Secured by the manufacturer's warranty or subject to the applicable manufacturer's warranty

Acknowledged by Retailer:
Signature: _____
Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 24/7/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : lc Date: 24/7/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLG 3325 P
 Make & Model : TOYOT PRIUS
 Chassis No : JTDKB3FU503535225

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____

Cost / List

| S/No. | Part Description | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|----------------------------------|-----|------------|-------|-------------------------|
| 1 | Reverse sensor | 1 | \$200.00 | S.N | ✓ |
| 2 | Rear bumper | 1 | \$497.50 | | ✓ |
| 3 | Rear bumper clip | 10 | \$40.00 | | ✓ |
| 4 | Rear bumper side retainer LH | 1 | \$112.70 | | ✗ |
| 5 | Rear bumper side retainer RH | 1 | \$112.70 | | ✗ |
| 6 | Rear bumper reinforcement | 1 | \$398.90 | | ✗ |
| 7 | Rear bumper lower garnish centre | 1 | \$582.60 | | ✗ |
| 8 | Rear bumper tow cover | 1 | \$31.70 | | ✗ |
| 9 | Tail end panel | 1 | \$596.60 | | ✗ |
| 10 | Tail end panel garnish | 1 | \$151.60 | | ✗ |
| 11 | Tail end panel garnish clip | 10 | \$35.00 | | ✗ |
| 12 | Boot weatherstrip | 1 | \$353.10 | | ✗ |
| 13 | | | | | |
| 14 | | | | | |
| 15 | | | | | |
| 16 | | | | | |
| 17 | | | | | |
| 18 | | | | | |
| 19 | | | | | |
| 20 | | | | | |
| 21 | | | | | |
| 22 | | | | | |
| 23 | | | | | |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19013072/Ksd3e2
73 BRAS BASAH ROAD Date: 20-08-2019
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556
ATTN : ENG HUEY HUEY Code: INC



1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------|----------------|------------|
| Insured Veh. | SMC 4602S | Veh. Inspected | SLG 3325P |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | MT/1053378-002 | Excess (\$) | 0.00 |
| Assign From | CYNTHIA ANG | Assign Date | 24/07/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|----------------------|
| Make & Model | TOYOTA PRIUS (A) | c.c | 1798 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | JTDKB3FU503535225 | Colour | METALLIC PEARL WHITE |
| Odometer | 293213 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 195/65 R15 | YOKOHAMA | 8 mm |
| L/H Front Tyre | 195/65 R15 | YOKOHAMA | 8 mm |
| R/H Rear Tyre | 195/65 R15 | YOKOHAMA | 8 mm |
| L/H Rear Tyre | 195/65 R15 | YOKOHAMA | 8 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|----------------------------|---------------------|-------------------------|
| Accident Date | 13/07/2019 | Inspect Date / Time | 24/07/2019 (02:12 PM) |
| Survey held at | 385 SIN MING DRIVE | | |
| Repairer | ESTEEM PERFORMANCE PTE LTD | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 2 Working Days |
|-------------------------------------|----------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 3325P

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--|---|----------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | REAR BUMPER | BUCKLED | 497.50 | 497.50 |
| 10 | REAR BUMPER CLIP | NECESSARY | 40.00 | 40.00 |
| 1 | REAR BUMPER SIDE RETAINER LH | SERVICEABLE | 112.70 | - |
| 1 | REAR BUMPER SIDE RETAINER RH | SERVICEABLE | 112.70 | - |
| 1 | REAR BUMPER REINFORCEMENT | TO REPAIR SEE LABOUR | 398.90 | - |
| 1 | REAR BUMPER LOWER GARNISH CENTRE | SERVICEABLE | 582.60 | - |
| 1 | REAR BUMPER TOW COVER | SERVICEABLE | 31.70 | - |
| 1 | TAIL END PANEL | TO REPAIR SEE LABOUR | 596.60 | - |
| 1 | TAIL END PANEL GARNISH | SERVICEABLE | 151.60 | - |
| 10 | TAIL END PANEL GARNISH CLIP | NOT NECESSARY | 35.00 | - |
| 1 | BOOT WEATHERSTRIP | SERVICEABLE | 353.10 | - |
| | LESS 25% DISCOUNT | | -728.10 | -134.38 |
| | | | 2,184.30 | 403.12 |
| SPECIAL NETT ITEMS | | | | |
| 1 | REVERSE SENSOR (SN) | DENTED | 200.00 | 200.00 |
| | | | 200.00 | 200.00 |
| LABOUR | | | | |
| | TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL). INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND TAIL END PANEL. | | 600.00 | 200.00 |
| | TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL) | | 600.00 | 220.00 |
| | TO CHECK WIRING. | | 50.00 | 10.00 |
| | TO REMOVE & REFIT REVERSE SENSOR. | | 120.00 | 50.00 |
| | TO TUFF COAT. | NOT NECESSARY | 50.00 | - |
| | | | 1,420.00 | 480.00 |
| GRAND TOTAL | | | 3,804.30 | 1,083.12 |
| RECOMMENDED COST OF REPAIRS (CONFIRMED) | | | | 1,083.12 |

Report Ref No. CS/INC19013072/Ksd3e2



Report Ref No. CS/INC19013072/Ksd3e2

KONG SENG CHEONG

Licensed Appraiser

A handwritten signature in black ink, appearing to be 'K.K. LAU'.

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.