

12/20/2018

ASS. REC. BY:

REF: CS3 / FWD 19013077 / TIC / A3 Special Instruction:

Surveyor: Tau Aich

ASSIGNMENT (Office)

From (Person): Eileen Bay of PWD Date/Time: 24/7/19 @ 11:02am

Estimated Cost: _____ Bill to: _____

OD / IT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FEB1579H Insured: SKV 857Z

at Workshop m/s Excel Cycle Tel: 6842 2360

of 48 ton Auen Rd East #01-112

Policy No: PNPV2018-0009128 Claim No: 12019 000 20870

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 17/07/2019

(Client's Record) _____ 25/7/2019

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 11:33am @ 24/7/19 Person Contacted: Mr. David Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (X)
	FEB1579H	X
	SKV 857Z	X
	Dismantle: #/8/2019	
	After repair: 20/8/2019	

Merina

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jul 2019 Edit Reg		24 Jul 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	-		
Main Claimant:	-		
Vehicle Reg. No.:	FBH1579H	Date of Loss:	17/07/2019 16:00 - :59
Claim Type:	TP / 1201900020870	Policy/Cover Note No.:	PNPV2018-0009128 (Comprehensive)
Vehicle Reg. No. (Insured):	SKV857Z	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Excel Cycle (HQ) 48 TOH GUAN ROAD EAST #01-112, 608586 Jurong West - Tel:		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 02/08/2019]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
Subject	Handler	Assigned By	Completed On
Created On	Done?		
No results.			

Nivitha (LKK Auto)

From: eileen.bay@fwd.com
Sent: Wednesday, 24 July 2019 11:02 AM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: Pre Repair Inspection Notice - Our Ref: GTW.ACC.7082.19 | FWD ref: 1201900020870
Attachments: PRI Notice - 24.07.19.pdf

Dear LKK,

Please refer to the email below and liaise with TP repairer for PRS.
Please create the case in Merimen.

Kind regards,

Eileen Bay

Executive, Claims


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 69217411

E eileen.bay@fwd.com

W www.fwd.com.sg



From: Eileen Bay - SGUser
Sent: Wednesday, 24 July 2019 11:01 AM
To: 'Lee Wee Ka'
Cc: Motor Claims SG - SG Common
Subject: RE: Pre Repair Inspection Notice - Our Ref: GTW.ACC.7082.19 | FWD ref: 1201900020870

WITHOUT PREJUDICE

Dear Sir / Madam,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK AUTO CONSULTANTS PTE LTD, to conduct the pre-repair survey (PRS) on your client's vehicle. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

**Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/or insurers. We hereby maintain full reservation of rights and all defences available to us.*

***Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.**

Kind regards,

Eileen Bay

Executive, Claims

FWD Singapore Pte. Ltd.


6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 69217411

E eileen.bay@fwd.com

W www.fwd.com.sg

FWD
insurance



From: Lee Wee Ka [<mailto:weeka@gohipwong.com>]

Sent: Wednesday, 24 July 2019 10:52 AM

To: Eileen Bay - SGUser

Cc: Motor Claims SG - SG Common

Subject: Re: Pre Repair Inspection Notice - Our Ref: GTW.ACC.7082.19 | FWD ref: 1201900020870

Dear Mdm

We are not agreeable to your proposed motor surveyors.

Our list of proposed Single Joint Expert ("SJE") as follows:-

1. Dylan Lee of Lee Appraisal Services
2. Jayson Liaw Leong San of Pro-Option Services
3. Seah Kwang Boon of Absolute Appraisal Services
4. Oh Han Cheong of Oh Appraisal
5. Bok Jee Tan of Prudent Adjustors Services
6. Fong Kok Heng Stanley of Automax Survey
7. Sebastian Lim Yong Tian of Constant Appraiser Services
8. Lek Boon Hwee of Auto Performance Appraisal
9. Louis S C Ng Cae Amimi of Prestige Appraiser Services
10. Richard Wong Ah Kow of R W Automotive Appraiser Services

Lee Wee Ka

for and on behalf of Goh Teck Wee

Messrs Goh JP & Wong LLC

Advocates & Solicitors

Commissioner for Oath

133 New Bridge Road #16-09

Chinatown Point Singapore 059413

Tel: 6538 5868

Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business

hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No. : 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender.

You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Wed, Jul 24, 2019 at 10:47 AM <eileen.bay@fwd.com> wrote:

WITHOUT PREJUDICE

Dear Sir / Madam,

Please find our panel surveyors as follows: -

1. LKK Auto Consultants Pte Ltd
2. Infiniti Appraisal Service
3. AJAX Inspection Services Pte Ltd
4. RT Appraisal Pte Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receive your reply.

**Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.*

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

Kind regards,

Eileen Bay

Executive, Claims


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 69217411

E eileen.bay@fwd.com

W www.fwd.com.sg



From: Lee Wee Ka [<mailto:weeka@gohjpwong.com>]

Sent: Wednesday, 24 July, 2019 8:56 AM

To: Motor Claims SG - SG Common

Subject: Pre Repair Inspection Notice - Our Ref: GTW.ACC.7082.19

Dear Sir/Mdm

NOTIFICATION OF ACCIDENT

SUBJECT MATTER: TRAFFIC ACCIDENT INVOLVING FBP 1579H & SKV 857Z ON 17.7.2019 AT JUNCTION OF HO CHING ROAD AND YUNG SHENG ROAD

We enclosed herewith the pre repair inspection notice dated 24 July 2019 for your attention.

Lee Wee Ka

for and on behalf of Goh Teck Wee
Messrs Goh JP & Wong LLC
Advocates & Solicitors
Commissioner for Oath
133 New Bridge Road #16-09
Chinatown Point Singapore 059413
Tel: 6538 5868
Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No. : 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender.

You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.



GOH JP & WONG LLC

advocates & solicitors
commissioner for oaths & notary public

GOH TECK WEE

WONG TZE ROY

WONG FUNG KWAI

SOON WEI SONG

133 New Bridge Road #16-09 Chinatown Point Singapore 059413
Tel: 6538 5868 Fax: 6538 4898 (Not for service of Court documents) Email: mail@gohjpwong.com
Goh JP & Wong LLC is a law corporation with limited liability. GST/UEN: 201406078M

YOUR REF:

OUR REF: | GTW.ACC.7082.19.wk

WHEN REPLYING, PLEASE QUOTE OUR REFERENCE NO

DATE: | 24 July 2019

Zainal Bin Asmore
Block 230D Tampines Street 24
#10-55 Singapore 527230

Dear Sirs

NOTIFICATION OF ACCIDENT

SUBJECT MATTER: TRAFFIC ACCIDENT INVOLVING FBP 1579H & SKV 857Z ON 17.7.2019 AT JUNCTION OF HO CHING ROAD AND YUNG SHENG ROAD

We act for Muhammad Ridhwaan Bin Ramlee in the above matter.

We are instructed to notify you of the above accident on 17th July 2019 at 1645 hrs at junction of Yung Sheng Road and Ho Ching Road involving our client's motorcycle FBP 1579H and motorcar SKV 857Z driven by you at the material time. A copy of the Traffic Accident Report filed is enclosed.

As a result of the accident, our client's motorcycle FBP 1579H has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days (excluding Saturdays, Sundays and Public Holidays) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair inspection of the vehicle or whether you or your insurer waive the pre-repair inspection. If we do not receive any reply from you within the stipulated timeline our client shall proceed to repair the vehicle without further reference to you.

Kindly advise your surveyor to liaise with the workshop directly to conduct the post-repair inspection, if required.

Yours faithfully

Goh Teck Wee

Enc.

Cc **FWD Singapore Pte Ltd**
by email only: motorclaims.sg@fwd.com
Attention: Motor Claims Department

Cc **Excel Cycle Centre Pte Ltd**
Fax No. 6846 8644
Please do not proceed with repairs until further notice.

Nivitha (LKK Auto)

From: weeka@gohjpwong.com
Sent: Wednesday, 24 July 2019 11:13 AM
To: eileen.bay@fwd.com
Cc: motorclaims.sg@fwd.com
Subject: Re: Pre Repair Inspection Notice - Our Ref: GTW.ACC.7082.19 | FWD ref: 1201900020870

Dear Mdm

Our client's motorcycle FBP 1579H is now at:

Excel Cycle Centre Pte Ltd
48 Toh Guan Road East #01-112 Singapore 608586
Tel: 6842 2360 (Mr David)

Kindly proceed to conduct the pre-repair inspection forthwith and let us know once the pre-repair inspections has been conducted, failing which we shall assume that the pre-repair inspection is conducted within the next 2 working days. Kindly advise your surveyor to liaise with the workshop directly to conduct the post-repair inspection.

Kindly extend to us a copy of your surveyor's pre-repair inspection report once the report has been completed.

Lee Wee Ka
for and on behalf of Goh Teck Wee
Messrs Goh JP & Wong LLC
Advocates & Solicitors
Commissioner for Oath
133 New Bridge Road #16-09
Chinatown Point Singapore 059413
Tel: 6538 5868
Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No. : 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender.

You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	858I
Vehicle Details	
Vehicle No.:	FBP1579H
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jul 2019
Vehicle Make:	YAMAHA
Vehicle Model:	SNIPER T150
Primary Colour:	Green
Manufacturing Year:	2019
Engine No.:	G3E6E0478925
Chassis No.:	MH3UG0740K0149655
Maximum Power Output:	-
Open Market Value:	\$2,058.00
Original Registration Date:	16 Feb 2019
First Registration Date:	16 Feb 2019
Transfer Count:	1
Actual ARF Paid:	\$309.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Feb 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,709.00
COE Rebate Amount:	\$3,545.00
Total Rebate Amount:	\$3,545.00

The information contained herein is correct as at 26 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/07/2019 16:37
Date Of Accident	17/07/2019 16:45
Exact Location Of Accident	JUNCTION ON HO CHING RD TOWARDS YUNG SHENG RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBP1579H
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD RIDHWAAN BIN RAMLEE
NRIC No	S9622858I
Email Address	MUHD_RIDHWAAN@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-84281432
Alternative Phone No	OFFICE-84281432

Vehicle Particulars

Manufacturer	YAMAHA
Model	SNIPER T150-150CC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	AN3172426
Cover Note Number	

Driver

Name of Driver	MUHAMMAD RIDHWAAN BIN RAMLEE
NRIC No	S9622858I
Date Of Birth	06/07/1996
Occupation	OUTDOOR
Date Of Driving Pass	16/08/2016
Driving Experience	2 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	+65-84281432
Fax Number	
Contact Number	OFFICE-84281432
E Mail Address	MUHD_RIDHWAAN@HOTMAIL.COM

Address	APT BLK 424 JURONG WEST AVE 1 #01-354
Postcode	640424
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF INJURED PERSON 1

Name	MUHAMMED RIDHWAAN BIN RAMLEE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	APT BLK 424 JURONG WEST AVE 1 #01-354
Postcode	640424

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 17/07/2019 at about 1645hrs I was riding on my motorcycle (Exhibit B) along Corporation Drive. Subsequently, I came to the junction of Yung Sheng Road and Ho Ching Road. I saw a vehicle (Exhibit A) in a stationary position about to turn right therefore I continued as the green light was in my favour. Suddenly, he moved off and I collided onto his vehicle. There was a witness nearby, and he claimed he was on my left side.

DECLARATION

(We declare the foregoing particulars to be true in every respect.)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Officer's Signature
Name
NRG/19/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jul 2019 Edit Reg		24 Jul 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	FBP1579H	Date of Loss:	17/07/2019 16:00 - :59 [5 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900020870	Policy/Cover Note No.:	PNPV2018-0009128 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKV857Z	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Excel Cycle (HQ) 48 TOH GUAN ROAD EAST #01-112, 608586 Jurong West - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBP1579H (1201900020870)

[SKV857Z]

TP

-

Jul 17 2019 4:00PM

[-]

Excel Cycle

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View	View in Browser <input type="button" value="v"/>	
Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
2	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
3	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
4	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
5	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
6	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
7	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
8	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
9	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
10	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
11	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
12	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
13	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
14	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
15	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
16	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
17	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
18	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
19	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
20	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
21	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
22	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
23	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
24	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
25	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
26	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
27	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
28	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
29	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
30	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
31	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
32	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
33	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
34	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
35	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
36	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>
37	29/07/19 12:57	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
39	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
40	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
41	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
42	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
43	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
44	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
45	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
46	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
47	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
48	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
49	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
50	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
51	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
52	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
53	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
54	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
55	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
56	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
57	29/07/19 12:57	General View	 Load JPG	<input checked="" type="checkbox"/>
58	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	21/08/19 11:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	21/08/19 11:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19013077/T1CF3E2

Date: 22/08/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-0009128
Claimant Vehicle No : FBP1579H **Insured Vehicle No :** SKV857Z
 Date of Loss: 17/07/2019 Nature of Claim: TP Claim No: 1201900020870

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP1579H**
 Make & Model: YAMAHA SNIPER T150, 150cc Engine No: G3E6E0478925
 Reg. Date: 16/02/2019 (Man. Year: 2019) Chassis No: MH3UG0740K0149655
 Colour: Black Odometer: 0 km
 Engine Capacity: 150 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 70/90 R17 Rear Tyre Size: 120/70 R17
 Front Left Side: IRC 5 mm Rear Left Side: IRC 5 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/07/2019
 Date Inspected: 25/07/2019 Inspected At: Excel Cycle (HQ)
 48 TOH GUAN ROAD EAST #01-112
 Singapore 608586
 Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Aug 2019)

Parts: N/A YAMAHA SNIPER T150 150cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBP1579H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >