

ASS. REC. BY:

REF: CS3/MSG/19013095/Hcf301 Special Instruction:

Survivor: Rasu

ASSIGNMENT (Office)

From (Person): Pauline Tham

of

MSG

Date/Time: 24.7.19 1623 p.m

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SIB 4940H

Insured: SGH 3266E

at Workshop m/s Ghee Song Paint

Tel: 96605755

of 10 Buroh Street #08-22

Policy No: 27413149

Claim No: 600489

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18.7.19

CA / REV / REP. / REV 24 HRS

Date/Time: 25.7.19 9.07 a.m

mp' 30.7.2019

Person Contacted:

Gek Song

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SIB 4940H - X
	SGH 3266E - X
	After repair: 2/8/2019.

Surveyor

Fasou

REF: MS1G

ASSIGNMENT

From: _____ Date: 30.7.2019

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLB 4940H

at Workshop m/s Ghee Sing Paint

of 10 Buroh Street #08-22

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: After 10.30 a.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

myr

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLB 4940H Yr Regn: Jun / 11

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ c.c. 1796

Colour: GRAY A/C: Insured / Std / NI / NA

Sp. Reading: 74047 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W00 2120482A 318 580

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245 / 45 ZR17

R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 18/07/19 D.O.I. 30/07/19

Survey held at GHEE SING PAINT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	NO GIA
	Range only
	Range - 4,000 - 5,000
	Repair Day - 5 days.
	10/9/2019

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

120

11

131

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jul 2019		24 Jul 2019 16:23 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Dainan Tech (S) Pte Ltd, Co. Reg. No.: 198102767H		
Main Claimant:	NG BEE LIAN, ID: S1503908F		
Vehicle Reg. No.:	SLB4940H	Date of Loss:	18/07/2019 18:00 - :59 [96 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 600489	Policy/Cover Note No.:	27413149 (Comprehensive) Coverage: 07/12/2018 - 06/12/2019
Vehicle Reg. No. (Insured):	SGH3266E	Policy No. (Claimant):	
		Excess:	
Repairer:	Ghee Seng Paint Spraying Works - Buroh (HQ) 10 BUROH STREET, #08-22 WEST CONNECT BUILDING, 627564 Pioneer - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/07/2019]		
Driver/Custodian (Insured):	YU YO-JEN (54 / Male) , NRIC: S2191852J Email:		
Adj Asg. Remarks:	on WP Liab: Dispute. Lawyer disagree on SJE - assign LKK. Contact: Mr. Gan Gek Song (h/p: 9660 5755 tel: 6268 9640)		

ASSOCIATED MAIL RECEIVED

[View All](#)

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	908F
Vehicle Details	
Vehicle No.:	SLB4940H
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Aug 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 200CGI
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	27186030200056
Chassis No.:	WDD2120482A398580
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$51,151.00
Original Registration Date:	30 Jun 2011
First Registration Date:	30 Jun 2011
Transfer Count:	2
Actual ARF Paid:	\$51,151.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2021
PARF Rebate Amount:	\$28,133.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$67,700.00
COE Rebate Amount:	\$12,919.00
Total Rebate Amount:	\$41,052.00

The information contained herein is correct as at 02 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/07/2019 11:21
Date Of Accident	18/07/2019 18:10
Exact Location Of Accident	ALOG JALAN BUKIT HO SWEE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB4940H
Insured/Policyholder	
Name Of Registered Owner	NG BEE LIAN
NRIC No	S1503908F
Email Address	BEEBUZZZZ@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97481068
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00009955
Cover Note Number	

Driver

Name of Driver	KONG WEI REN
NRIC No	S9026979H
Date Of Birth	29/07/1990
Occupation	INDOOR
Date Of Driving Pass	27/03/2009
Driving Experience	10 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96681509
Fax Number	
Contact Number	OFFICE-NOPHONE
EEmail Address	BEEBUZZZZ@HOTMAIL.COM

Address	BLK 30 TANGLIN HALT ROAD #08-154
Postcode	140030
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SUBMIT TO FWD DIRECTLY
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGH3266E
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YU YO JEN
NRIC/Passport Number	
Contact Number	9762 7247 / 9368 1065
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

VEHICLE NO: 82B494021
ACCIDENT DATE: 18/07/2019 @ 18:10

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


NOTE: DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

CHARN'S CUSTOMCRAFT
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I (~~was~~ ^{KONG MEI REN}) was driving vehicle (SLB4940H) in my lane when ~~the~~ ~~car~~ ~~concerning~~ vehicle SGH 3266E was driving towards my lane and hit the right side of my vehicle.

~~Just~~ Just before the moment of impact, I saw the driver in ~~SGH~~ SGH 3266E was looking down and not straight at the road (see frame of video provided).

Also, in the video, it is very obvious the vehicle SGH 3266E was not driving straight (he had ample space on the left) but at an angle towards my vehicle.

The accident happened along Jalan Bukit Ho Swee, in front of block 34

OWN DAMAGE () 3RD PARTY CLAIM (X) REPORTING ONLY () OWN WORKSHOP (X)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:











































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Jul 2019		24 Jul 2019 16:23 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: Dainan Tech (S) Pte Ltd , Co. Reg. No.: 198102767H									
Main Claimant: NG BEE LIAN , ID: S1503908F									
Vehicle Reg. No.: SLB4940H		Date of Loss: 18/07/2019 18:00 - :59 [96 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 600489		Policy/Cover Note No.: 27413149 (Comprehensive) Coverage: 07/12/2018 - 06/12/2019							
Vehicle Reg. No. (Insured): SGH3266E		Policy No. (Claimant):							
		Excess:							
Repairer: Ghee Seng Paint Spraying Works - Buroh (HQ) 10 BUROH STREET, #08-22 WEST CONNECT BUILDING, 627564 Pioneer - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 25/07/2019]									
Driver/Customer (Insured): YU YO-JEN (54 / Male), NRIC: S2191852J Email:									
Adj Asg. Remarks: on WP Liab: Dispute. Lawyer disagree on SJE - assign LKK. Contact: Mr. Gan Gek Song (h/p: 9660 5755 tel: 6268 9640)									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB4940H (600489)
 [SGH3266E]
 TP
 NG BEE LIAN
 Jul 18 2019 6:00PM
 [Dainan Tech (S) Pte Ltd]
 Ghee Seng Paint Spraying Works - Buroh

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	02/08/19 17:01	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	02/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>	
24	02/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>	
25	02/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>	
26	02/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>	
27	02/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>	
28	02/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>	
29	02/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>	
30	02/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>	
31	02/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>	
32	02/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>	
33	02/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>	
34	02/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>	
35	02/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>	
36	02/08/19 17:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>	
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	22/07/19 09:53	OI Accident Report	 Load PDF		
2	22/07/19 09:53	TP SLB4940H E-REPORT	 Load PDF		
3	24/07/19 14:02	Disagree on SJE	 Load PDF		
4	24/07/19 14:02	Workshop details	 Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19013095/R1CF3E2

Date: 17/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27413149

Claimant
Vehicle No : SLB4940H

Insured Vehicle No : SGH3266E

Date of Loss: 18/07/2019

Nature of Claim: TP

Claim No: 600489

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB4940H**

Make & Model: MERCEDES-BENZ E200, 2.0 (A)

Engine No: 27186030200056

Reg. Date: 30/06/2011 (Man. Year: 2011)

Chassis No: WDD2120482A398580

Colour: Grey

Odometer: 74047 km

Engine Capacity: 1796 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45Z R17

Rear Tyre Size: 245/45Z R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/07/2019

Date Inspected: 30/07/2019 Inspected At:

Ghee Seng Paint Spraying Works -
Buroh (HQ)
10 BUROH STREET, #08-22 WEST
CONNECT BUILDING
Singapore 627564

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Sep 2019)
Parts:	143	MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB4940H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >