

T2400003

A.S. REC. BY:

Surveyor: Marcus

REF:

CS/CT/19013107/UT32

Special Instruction:

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

24/7/19 @ 3:51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMK 9960H

Insured:

GBE 6275J

at Workshop m/s

Autolution

Tel:

96450079

of

19 ubi Road 4

Policy No:

DMCVSN3005871901

Claim No:

SNM1910203418

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:55am 25/7/19

Person Contacted:

Humzah

Vehicle IN/OUT

Date/Time

Action/Instruction

1st time (✓)

SMK 9960H X

GBE 6275J X

ASSIGNMENT

From:

Date:

26/7/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMK9960H

at Workshop m/s

Autolution

of

19 ubi Road 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

1140.

(Client's Record)

Make of Veh:

Ham-11-30cm (waiting)

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

1.81

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMK9960H

Yr Regn:

4/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Nissan

S2phy

C.C

1598

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

2147

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MNTBBAB1720035241

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

20/7/19

D.O.I.

30/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Booked H7A44902

16/9/19

Confirmed fixed by #1767-36 with hamzah. (Red: 648.84, 262)

RECEIVED 16 SEP 2019

Date/Time, File Pass to?



Preli. Report

1) 16/9 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

220

Transportation:

3 + RS, SI

Fines:

Others:

TOTAL

220

Report Format:

Lump Sum /

0

1767.36

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Wednesday, 24 July 2019 3:51 PM
To: Hamzah; assignments
Cc: elmer@tanchong.com; mavis@tanchong.com
Subject: FW: OUR REF: SNM19D203418-CHEONGML - & YR REF: SMK9960H -Accident involving SMK9960H and GBE6275J on 20-7-2019. -PRS
Attachments: SMK9960H GIA REPORT 20.07.2019.pdf; smk9960h-estimate 200719.pdf

WITHOUT PREJUDICE

Your Ref: SMK9960H
Our Ref: SNM19D203418C02/5(EC)

Dear Hamzah,

We refer to your email pertaining to the above matter.

Liability is clear and we agree to go for Direct Settlement, subject to consistency of damages, based on findings from M/s LKK Auto Consultants Pte Ltd, with supporting documents.

Aside to M/s LKK Auto,

Please assist to arrange for the survey.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Claims Dept of CTI
Sent: Tuesday, 23 July, 2019 3:32 PM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; hamzah_saad@tanchong.com; elmer@tanchong.com; mavis@tanchong.com
Cc: Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>
Subject: OUR REF: SNM19D203418-CHEONGML - & YR REF: SMK9960H -Accident involving SMK9960H and GBE6275J on 20-7-2019. -PRS

Dear Elaine

Please conduct PRS –SMK9960H- soonest possible

File with officer in charge –Elaine Cheong-DID: 6389 6530

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

TEL: (65) 63896116 - F: (65) 6224 7478

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Hamzah [mailto:hamzah_saad@tanchong.com]

Sent: Tuesday, 23 July, 2019 12:48 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Mavis Chng <mavis@tanchong.com>; Elmer Alfonso <elmer@tanchong.com>

Subject: Accident involving SMK9960H and your insured GBE6275J on 20-7-2019.

Hi,

Prior to the above, my client wish to make TP claim against your insured, direct settlement with claiming for LOU/vehicle rental.

Kindly check your insured liability and revert.

Attachment are my client accident report and workshop estimate.

Regards

Hamzah Sa'ad

Service Supervisor

Autolution Industrial Pte Ltd

19 Ubi Road 4

S408623

TEL: +65 67038680 DID: +65 67038690 FAX: +65 68467483

Hp: +65 96450079 Email: hamzah_saad@tanchong.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	730G

Vehicle Details

Vehicle No.:	SMK9960H
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jul 2019
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.6 CVT
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	HR16941456C
Chassis No.:	MNTBBAB17Z0035241
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$16,713.00
Original Registration Date:	30 Apr 2019
First Registration Date:	30 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$16,713.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2029
PARF Rebate Amount:	\$12,534.00

Intended COE Rebate Details

COE Expiry Date:	29 Apr 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,199.00
COE Rebate Amount:	\$32,368.00
Total Rebate Amount:	\$44,902.00

The information contained herein is correct as at 30 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/07/2019 14:50
Date Of Accident	20/07/2019 12:10
Exact Location Of Accident	HAVELOCK ROAD TURNING INTO EU TONG SEN STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK9960H
Insured/Policyholder	
Name Of Registered Owner	SIIX SINGAPORE PTE LTD
Co Reg No	197400730G
Email Address	TAN.BOO.KHEE@SIIX.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-98562265

Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900093793
Cover Note Number	

Driver

Name of Driver	KOJIMA DAIKI
NRIC No	G3136632T
Date Of Birth	11/09/1988
Occupation	INDOOR
Date Of Driving Pass	09/06/2015
Driving Experience	4 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98170903
Fax Number	
Contact Number	
EMail Address	KOJIMA.DAIKI@SIIX.COM.SG

Address	8 KIM CHUAN DRIVE
Postcode	537083
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : KOJIMA HIROKO GENDER: : FEMALE
Passenger 2	NAME: : KOJIMA HONOKA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE6275J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN CHIN FUI
NRIC/Passport Number	5 23950320
Contact Number	97115017
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 22/7/19


2.40pm


Driver's Signature
(If driver is not the policyholder)
Date & Time: 22/7/19

2.40pm


Reporting Centre Personnel's Signature
Name: CHUA CHE YEN
NRIC/FIN No.: 68570709X

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20 July 2019 at about 12.10pm, as my vehicle was about to turn into Eu Tong Sen Street, a vehicle GBE6275J suddenly hit onto the back of my vehicle causing damage to the back of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 22/7/19
2.40pm



Driver's Signature
(If driver is not the policyholder)

Date & Time: 22/7/19
2.40pm

REPORTING CENTRE PERSONNEL PTE LTD
31 ROAD 1
SINGAPORE 408623
TEL: 6460 9063 FAX: 6460 7413

Reporting Centre Personnel's Signature

Name: CHUA CHE TEN
NRIC/FIN No.: 857079X

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0392/19

DATE : 22-JUL-2019

SINGAPORE 408625
TEL: 6490 9666 FAX: 6246 7483

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

S(079909)

TEL : 63896111

FAX : 62247175

OWNER'S NAME : SIIX SINGAPORE PTE.LTD.

ADDRESS : 8 KIM CHUAN DRIVE

SIIX BUILDING

S(537083)

TELEPHONE NO : 63818100

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : *

VEHICLE NO : SMK9960H

MODEL CODE : BDTARCZB17EWA----K19

MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2019

ENGINE NO : HR16941456C

CHASSIS NO : MNTBBAB17Z0035241

MILEAGE : 2032 KM

DATE IN : 22/07/2019

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : HAMZAH

ACCIDENT DATE : 20/07/2019

96450079

NOT Affect
Like morcus.

Take photo before painting
30/7/19

4 day.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMK9960H

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGES TO REPAIR REAR PANEL AND RENEW REAR BUMPER.	600.00	585
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	600.00	500
3 ZZ/003	REMOVE AND INSTALL REVERSE SENSOR AND RE-SETTING-RENEW IF NEC.	55.00	✓
TOTAL LABOUR CHARGES		1255.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMK9960H

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1 SUNDRIES	NPN		11	60.00	X
2 SENSOR-REVERSE	SENSOR		800	200.00	X
3 REAR BUMPER STAY LH	85213-EE530	11	42.70	X	
4 REAR BUMPER STAY RH	85212-EE530	11	45.20	X	
5 ENERGY ABSORBER REAR LH	85093-3ST0A	11	131.70	X	
6 ENERGY ABSORBER REAR RH	85092-3ST0A	11	87.70	X	
7 ENERGY ABSORBER REAR CENTRE	85090-3ST0A	11	35.00	X	
8 CLIP REAR BUMPER @ \$1.20 EACH	01553-10501	20	7.20		
9 REAR BUMPER FASCIA	85022-3ST4H	07/2	625.80		
SUB TOTAL		975.30	0.00	260.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		195.06	0.00	0.00	
GRAND TOTAL		780.24	0.00	260.00	
OVERALL TOTAL		1040.24			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

Rear Nissan emblem 98.90 net ✓
 Rear Styphy emblem 52.30 net ✓

120.96

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMK9960H

TOTAL LABOUR CHARGES	1255.00
TOTAL SPARE PARTS CHARGES	1040.24
GRAND TOTAL	2295.24 *

2416.20

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.



Autolution Industrial Pte Ltd

Tan Chong Motor Sales Pte Ltd's Authorised Dealer
19 Ubi Road 4
Singapore 408623
Tel (65) 64909666 / 67038680
Fax (65) 68467483
Business Reg. No.: 199500871W

14-September-2019

INS/SC/H/0470/19

China Taiping Insurance (S'pore) Pte Ltd
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : SMK9960H
CLAIM NO: SNM19D203418C02/5(EC)

Further to our claim INS/IC/H/0392/19 we are submitting a supplementary claim for the below mentioned part for the above mentioned case

Replacement of Damaged Items

1.	SYLPHY rear emblem	<i>me</i>	\$	98.90	Nett	/
2	NISSAN rear emblem	<i>me</i>	\$	52.30	Nett	/

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully
AUTOLUTION INDUSTRIAL PTE LTD

Hamzah Sa'ad
Insurance Claim Dept

Cc: Surveyor- Mr. Marcus (LKK Auto Consultant)



www.tanchong.com

Marcus

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0392/19

DATE : 22-JUL-2019

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

S(079909)

TEL : 63896111

FAX : 62247175

OWNER'S NAME : SIIX SINGAPORE PTE.LTD.

ADDRESS : 8 KIM CHUAN DRIVE

SIIX BUILDING

S(537083)

TELEPHONE NO : 63818100

4 days

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : *

VEHICLE NO : SMK9960H

MODEL CODE : BDTARCZB17EWA----K19

MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2019

ENGINE NO : HR16941456C

CHASSIS NO : MMTBBAB17Z0035241

MILEAGE : 2349 KM

DATE IN : 22/07/2019

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : HANIZAH

ACCIDENT DATE : 20/07/2019

- 96450079

AUTOLUTION INDUSTRIAL PTE. LTD.

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMK996DH

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGES TO REPAIR REAR PANEL, TRUNK LID, AND RENEW REAR BUMPER.	600.00	585.00
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	600.00	500.00
3 ZZ/003	REMOVE AND INSTALL REVERSE SENSOR AND RE-SETTING.	55.00	55.00
TOTAL LABOUR CHARGES		1255.00	1140.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMK9960H

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	EMBLEM REAR SLYPHY	84890-3RA1B	98.90		OK
2	EMBLEM REAR NISSAN	84890-3RA0B	52.30		OK
3	REAR BUMPER STAY LH	85213-EE530	42.70		X
4	REAR BUMPER STAY RH	85212-EE530	45.20		X
5	ENERGY ABSORBER REAR LH	85093-3ST0A	131.70		X
6	ENERGY ABSORBER REAR RH	85092-3ST0A	87.70		X
7	ENERGY ABSORBER REAR CENTRE	85090-3ST0A	35.00		X
8	CLIP REAR BUMPER @ \$1.20 EACH	01553-10501	7.20		OK
9	REAR BUMPER FASCIA	85022-3ST4H	625.80		OK
10	SUNDRIES	MPH			60.00 X
11	SENSOR-REVERSE	SENSOR			200.00 X
SUB TOTAL			784.20	0.00	0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			156.84	0.00	0.00
GRAND TOTAL			627.36	0.00	0.00
OVERALL TOTAL			627.36		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO S/MK9960H

NETT ITEM 784.20
LESS 20.00% -156.84
NETT AMOUNT 627.36

LIST ITEM 0.00
LESS 30.00% 0.00
LIST AMOUNT 0.00

SPECIAL NETT ITEM 0.00
LESS .00% 0.00
SPECIAL NETT AMOUNT 0.00

TOTAL LABOUR CHARGES 1140.00
TOTAL SPARE PARTS CHARGES 627.36

TOTAL CHARGES 1767.36
ADD 7 % GST 123.72

GRAND TOTAL 1891.08

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jul 2019		30 Jul 2019 13:02 Edit Adj Rpt	\$1,767.36 Edit Estimates	\$1,767.36 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: SIIX SINGAPORE PTE LTD , Co. Reg. No.: 197400730G									
Vehicle Reg. No.: SMK9960H		Date of Loss: 20/07/2019 12:00 - :59 [2 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D203418C02		Policy/Cover Note No.: DMCVSN3005871901							
Vehicle Reg. No. (Insured): GBE6275J		Policy No. (Claimant): 1900093793							
		Excess: \$500.00							
Repairer: Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4, 408623 Ubi - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 08/08/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMK9960H (SNM19D203418C02)
[GBE6275J]

TP

SIIX SINGAPORE PTE LTD

Jul 20 2019 12:00PM

[-]





























Autolution Industrial Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)		Thumbnail	Print
1	22/07/19 15:16	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)		Thumbnail	Print
1	22/07/19 15:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	22/07/19 15:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	22/07/19 15:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	22/07/19 15:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	22/07/19 15:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	22/07/19 15:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	22/07/19 15:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	22/07/19 15:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	22/07/19 15:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
10	22/07/19 15:12	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
11	22/07/19 15:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
12	22/07/19 15:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
13	22/07/19 15:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
14	22/07/19 15:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
15	22/07/19 15:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
16	22/07/19 15:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
17	22/07/19 15:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
18	22/07/19 15:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
19	22/07/19 15:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
20	22/07/19 15:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
21	22/07/19 15:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
22	22/07/19 15:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
23	22/07/19 15:13	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/09/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
2	16/09/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
3	16/09/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
4	16/09/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
5	16/09/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
6	16/09/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
7	16/09/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
8	16/09/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
9	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
10	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
11	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
12	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
13	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
14	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
15	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
16	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
17	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
18	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
19	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
20	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
21	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
22	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
23	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
24	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
25	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
26	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
27	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
28	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
29	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
30	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
31	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
32	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
33	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
34	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
35	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
36	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
37	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
38	16/09/19 11:53	General View		<input checked="" type="checkbox"/>
39	16/09/19 11:53	Reinspection Photo		<input checked="" type="checkbox"/>
40	16/09/19 11:53	Reinspection Photo		<input checked="" type="checkbox"/>
41	16/09/19 11:53	Reinspection Photo		<input checked="" type="checkbox"/>
42	16/09/19 11:53	Reinspection Photo		<input checked="" type="checkbox"/>
43	16/09/19 11:53	Reinspection Photo		<input checked="" type="checkbox"/>
44	16/09/19 11:53	Reinspection Photo		<input checked="" type="checkbox"/>
45	16/09/19 11:53	Reinspection Photo		<input checked="" type="checkbox"/>
46	16/09/19 11:53	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/07/19 13:02	PRS - SMK9960H		<input type="checkbox"/>
2	30/07/19 13:04	REPAIR ESTIMATE - SMK9960H		<input type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	22/07/19 15:09	Sketch Plan [Linked Accident Report Documents]		<input type="checkbox"/>
2	22/07/19 15:09	Sketch Plan #2 [Linked Accident Report Documents]		<input type="checkbox"/>
3	22/07/19 15:10	CI [Linked Accident Report Documents]		<input type="checkbox"/>
4	22/07/19 15:10	ICDL [Linked Accident Report Documents]		<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/10/19 09:36	Supplementary		<input type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	22/07/19 15:16	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	22/07/19 15:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	22/07/19 15:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	22/07/19 15:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	22/07/19 15:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	22/07/19 15:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	22/07/19 15:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	22/07/19 15:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	22/07/19 15:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	22/07/19 15:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	22/07/19 15:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	22/07/19 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	22/07/19 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	22/07/19 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	22/07/19 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	22/07/19 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	22/07/19 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	22/07/19 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
18	22/07/19 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	22/07/19 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
20	22/07/19 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
21	22/07/19 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
22	22/07/19 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
23	22/07/19 15:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Autolution Industrial Pte Ltd (Ubi)	Thumbnail	Print
1	22/07/19 15:09	Sketch Plan	 Load TIF	
2	22/07/19 15:09	Sketch Plan #2	 Load TIF	
3	22/07/19 15:10	CI	 Load TIF	
4	22/07/19 15:10	ICDL	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19013107/UTF3E2

Date: 04/10/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3005871901

Claimant
Vehicle No : SMK9960HInsured Vehicle
No : GBE6275J

Date of Loss: 20/07/2019

Nature of Claim: TP

Claim
No: SNM19D203418C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK9960H**

Make & Model: NISSAN SYLPHY, 1.6 (A)

Engine No: HR16941456C

Reg. Date: 30/04/2019 (Man. Year: 2019)

Chassis No: MNTBBAB17Z0035241

Colour: Silver

Odometer: 2147 km

Engine Capacity: 1598 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16

Rear Tyre Size: 195/60 R16

Front Left Side: Bridgestone 9 mm

Rear Left Side: Bridgestone 9 mm

Front Right Side: Bridgestone 9 mm

Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,161.20	627.36	533.84	45.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,255.00	1,140.00	115.00	9.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,416.20	1,767.36	648.84	26.85
+ GST 7.00/7.00% (S\$)	169.13	123.72	45.41	26.85
Nett Amount (S\$)	2,585.33	1,891.08	694.25	26.85

INSPECTION

Date of Assignment: 30/07/2019

Date Inspected: 30/07/2019 Inspected At:

Autolution Industrial Pte Ltd (Ubi)
19 Ubi Road 4
Singapore 408623

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2019)
Parts:	143	NISSAN SYLPHY 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK9960H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
2	1		*SENSOR-REVERSE	Serviceable	200.00 FS	*- FS
3	1		*REAR BUMPER STAY LH	Not Necessary	42.70 FN	*- FN
4	1		*REAR BUMPER STAY RH	Not Necessary	45.20 FN	*- FN
5	1		*ENERGY ABSORBER REAR LH	Not Necessary	131.70 FN	*- FN
6	1		*ENERGY ABSORBER REAR RH	Not Necessary	87.70 FN	*- FN
7	1		*ENERGY ABSORBER REAR CENTRE	Not Necessary	35.00 FN	*- FN
8	6		*CLIP REAR BUMPER	Necessary	7.20 FN	*7.20 FN
9	1		*REAR BUMPER FASCIA	Dented / Deformed	625.80 FN	*625.80 FN
10	1		*SYLPHY REAR EMBLEM	Necessary	98.90 FN	*98.90 FN
11	1		*NISSAN REAR EMBLEM	Necessary	52.30 FN	*52.30 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	1,386.50	784.20
- Nett Item Discount on N Items 20.00/20.00% (S\$)	225.30	156.84
Total Parts (S\$)	1,161.20	627.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REPAIR REAR PANEL AND RENEW REAR BUMPER	New	600.00	585.00
2	CHARGES TO SPRAY PAINTING SAME	New	600.00	500.00
3	REMOVE AND INSTALL REVERSE SENSOR AND RE-SETTING-RENEW IF NEC	New	55.00	55.00
Gross Labour Cost (\$\$)			1,255.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >