REF: CS/AWA19013125/AHPSpecial Inflitructions ASS. REC. BY: Surveyor: Adrian ASSIGNMENT (Office) From (Person): Stella Gok Date/Time: 25.7.19 11.769.m AWAL Estimated Cost Bill to: OD TIP WS/TP RES/OD RES/EVA/INV/MV/CS GB (9261P PBN 1587U To Inspect Vehicle No: Insured: at Workshop m/s Modern Automotive Tel: 67484422 of BIK 3023A Ubi road 1 #0161 Policy No: Claim No: NS V 1900306 1 56 Sum Insured: Excess: D.O.A. 19.6. 2019 Make of Veh-(Client's Record) rang. CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: mer Hu Date/Time 167.19 1.85 p.m Person Contacted: Vehicle IN OUT Date/Time Action/Instruction (V) Estimate NA/INC18012107/24 DOA = C FBN ISKTU (2/5/19 Q 4.30pm My Chan will chear Board us. lump Sum \$33001 cled: 231+ 75 14106

ASSIGNMENT

Fyrm Date	Veh No 6569261 Vr Regn: 2014 Feb.
Estimated Cost.	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
QD / TP / WS / TP RES / OQ RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toyota Hime co 2982
at Workshop m/s	Colour White A/G: Insured / Std / NI / NA
of.	Sp.Reading 192962 T/Radio: Insured / Std / NI / NA
insured	Eng/No:
Policy No.	C/No: TTFHT02PX00133165
Claims No.	Gen. Cond: Goold / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: (N) / S/Rim / STD A/Rim or
	Tyre Size F: 195 R15C
(Policy Condition)	R: 185 R15C
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO, I YOKO or
Bal. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal of mm R/Bal of mm
SIA / PR Seen: Consistent? Yes or No	UBal OC mm UBal OC mm
Est Repairs days Res.: Yes or No	D.O.A. D.O.L 08/10/19
Lum Sum: % 3 Val.: Yes or No	Survey held at Modern
	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OU	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
TP AWA	
MV : 33(C REC	EIVED 3 OUT 2019
PV: 16.8K	EIV LOCAL IN CO. Sec. Sec. Sec. Sec. Sec. Sec. Sec. Sec
Nett , 16-2 K	
1133	
	No.
Oute/Time, File Pass in/	Down Of Down of
The Transfer	Days Of Repair:
0 30 10 10 28 Final Report	Resurvey No. of Trip: Survey Fee
1119	99: Sife Insp. (\$) _ 3+88_ (#
add Fe	
TP ·	Interview (\$), Press
Papert Format (Tech line (1) y one.
1960 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	:Westeno III
	200

Nivitha (LKK Auto)

From:

Goh, Stella <stella.goh@awac.com> on behalf of Motorsurvey

<Motorsurvey@awac.com>

Sent:

Thursday, 25 July 2019 11:26 AM

To:

'assignments@lkkauto.com'

Cc: Subject: *Chin'; sur@lkkauto.com
TP Survey assignment for GBC9261P DOA: 19.06.2019 Our ref: NSV1900306/SG

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us <u>do have</u> consensus in the appointment of <u>Mr Adrian Ling</u> as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3rd Party Vehicle	:	GBC9261P
Insured Vehicle	:	FBN1587U
Policy Number		AVFMSB0000651800
Name of Workshop	1	MODERN AUTOMOTIVE PTE LTD
Contact Number		6748 4422
Person to Contact	:	MS GRACE CHIN
Estimated Cost of repairs	:	NA

Regards, Claims Division

Copy to Modern Automotive Pte Ltd (Your Ref: GBC9261P) via Email.

Note -

(x)

- This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
- Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.
- 3 Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
- Please do not construe this appointment of surveyor and our above request as an admission of liability.


Regards Motor Claims Claims Group Global Market The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

PREMIUM NO









Tigs: 2014 Toyria Hair, 2014 toyria York, Tryria Histo, Styria Host, Tryria, Histo, Hair, Mace, Hair, Shell, Tryria

Please Call To Arrange For Viewing, Thank You!

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	
Owner ID:	Company
Vehicle desuit	189G
Vehicle No.:	GBC9261P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	09 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	11 - 11 - 11 - 11 - 11 - 11 - 11 - 11
Primary Colour:	TOYOTA HIACE VAN TURBO 5 DR MANUAL White
Manufacturing Year:	2014
Engine No.:	1KD2369988
Chassis No.:	- Contraction Telephone
Maximum Power Output:	JTFHT02PX00133165
Open Market Value:	\$27,502.00
Original Registration Date:	\$27,502.00
First Registration Date:	25 Feb 2014
Transfer Count:	25 Feb 2014
Actual ARF Paid:	1
HITCHSORIZARE RELEASE DELISIO	\$1,376.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	\$0.00
103 Chigan East Reliable Definition	20.00
COE Expiry Date:	24 Feb 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$38,300.00
COE Rebate Amount:	\$16.761.00
Total Rebate Amount:	\$16,761.00
e information contained herein is correct as at 09 Oct 2019	7 5 7 1 7 4 1 W

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. information provided must be as truthful and accurate as possible. Any willul misnepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aloresaid.

A	T. III.	35	ы	All	301	30	

 Date Of Report
 19/06/2019 14:54

 Date Of Accident
 19/06/2019 09:40

 Exact Location Of Accident
 GEYLANG LOR 21

 Country/State of Loss
 SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBC9261P

Insured/Policyholder

Name Of Registered Owner CA M&E ENGINEERING PTE LTD

Co Reg No 200501189G

 Email Address
 SALES@CA-ME.COM.SG

 Mobile Phone No
 (LOCAL) +65-90028457

 Alternative Phone No
 OFFICE-67481155

Vehicle Particulars

Manufacturer TOYOTA

Model HIACE-3.0 D (M)

Exact Purpose for which vehicle was being used at

time of accident

WORK PURPOSE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 5070585102-04

Cover Note Number 25/02/2019 - 24/02/2020

Driver

 Name of Driver
 TAN HWEE MIN

 NRIC No
 \$1461310B

 Date Of Birth
 12/12/1961

 Occupation
 INDOOR

 Date Of Driving Pass
 24/05/2000

Driving Experience 19 YEARS AND 0 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91360361

Fax Number

Contact Number

EMail Address NOEMAIL

Adoresa

BLK 201E COMPASSVALE DRIVE #10-521

Postcode.

542201

Was driver an employee of the Insured's Company YES

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

NO

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver) 2

Passenger 1

ambulance?

NAME:

PASSENGER

GENDER:

MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes against whom?

Circumstances of Accident

MY VEHICLE WAS STOPPED STATIONARY ALONG GEYLANG LOR 21. WHILE WAITING FOR MAIN TRAFFIC CLEARANCE, I FELT AN IMPACT ON MY VEHICLE REAR PORTION AND MOTORBIKE B HAD HIT ONTO MY VEHICLE. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

NO

Remarks/ Reasons:

FRONTAL VIEW CAMERA ONLY

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBN1587U

Vehicle Make/Model/Colour MOTORBIKE

Details Of Properties FRONT PORTION
Vehicle Category MOTORCYCLE

Name of Driver ISKANDAR BIN OMAR

NRIC/Passport Number S8033911I

Contact Number

Address BLK 421 JURONG WEST ST 42 #08-1039

Postcode 640421

Insurance Company Name Nature Of Damage No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

Will I Bleamy Man Server Contr.

Report No. Mil.

Mary Model

Mayort thing two New Northead Toronto.

Reporting Page

this time

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the acorders to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any will a managementation or withholding of material facts. may allow incurance companies to regudiate policy liability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

understand, acknowledge, agree and consent that :

1) 1= 5

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this florm) and any other personal information provided by me or passessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any refevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations. relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages): and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, maylare permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GiA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed.
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators. aw enforcement and government agencies as reasonable required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, law or court orders.

19/6/2019 15:02

19/6/2019 15:02


Policyholder's Signature Date & Time

Driver's Signature (If driver is not the policyholder) Date & Time!

Name: Chen JunLiang

NRIC/ Fin No: S990765

Reporting Centre Personnel's Signature



MY VEHICLE WAS STOPPED STATIONARY ALONG GEYLANG LOR 21. WHILE WAITING FOR MAIN TRAFFIC CLEARANCE, I FELT AN IMPACT ON MY VEHICLE REAR PORTION AND MOTORBIKE B HAD HIT ONTO MY VEHICLE, NO ONE WAS INJURED

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature Date & Time:

19/6/2019 15:02

Driver's Signature (1 (diver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name: Chen JunLising NRICI Fin No: S990765

MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 # 01-61 SINGAPORE 408717

Tel: 6748 4422/ 6745 4422 Fax: 6747- 6720 REG NO 200501102H

			Quotation
Allied World Assurance Company	y Ltd	DATE	: 11.10.2019
60 Anson Road # 08-01	Derise.	VEH NO	: GBC9261P
Maple Tree Anson	Den ac.	MODEL	: Toyota Hiace
Singapore 079914	8	DOA	: 19.06.2019
Tel: 6220 - 1188		YR REF	FBN1587U

Fax: 6423 - 0864 (M / claim) Fax: 6423 - 0798

Attn Motor Claim Dept (Pis arrange vehicle survey & check liability)

RE: ESTIMATE FOR ACCIDENT REPAIR GBC9261P (TOYOTA HIACE)

<u>Item</u>	Description		_Qty	Amt
NO	LIST ILEMS			
1	Rear Bumper Deland		11	455.70
2	Rear Bumper Clips 144-		1 set	30.00
3	Rear Bumper Side Holder - LH & RH	w	2	110.80
4	Rear Bumper Lower Bracket - LH & RH		2	59.20
5	Rear End Panel Outer Pages	76.708.7	1	566.10 ₹
6	Taligate Suked		1	1,718.40
7	Tailgate Lock	3043.60	1	325.50
8	Taligate Weatherstripe Inf and	50.750	1	387.30 *
9	Tailgate Glass Moulding	2282.70	1	172 50 -
10	Toyota Logo 7		1	70.50
11	Toyola Sticker The		1	48.50
12	Hiace Sticker		1	52.50
				\$ 3,997.00
		Less 25%		(999.25)
				\$ 2,997.75
	S/NET ITEMS			
1	Reverse Sensor	1//0	1	280.00 2 57
2	Tailgate Glass Sealant	460	1	60.00
3	Company Logo Advertisement		1	400-80 200
	ii)			\$ 740.00
		Total Parts		\$ 3,737.75

LABOUR CHARGE

ESTIMATE FOR ACCIDENT REPAIR GBC9261P (TOYOTA HIACE) RE:

		Grand To	tal	\$ 5,617.75
				\$ 1,880.00
6	To remove tailgate glass			\$ 180,00 120
5	To transfer tailgate fittings		1380	\$ 150,00 80
4	To remove reverse sensor			\$ 100,00 50
3	To check wiring system			\$ 50,00 30
2	To putty & spray up paint works			\$ 600,e0 500
1	To knocking & pull out rear portion & renew	above parts		\$ 800,00 600
12				

GST Will be reflected in the final bills

NOTE: -

11.

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 4122.70 HS: 3.3K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey beforelatter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD Ref : CS/AWA19013125/Atf3n2

(SINGAPORE BRANCH)

60 ANSON ROAD #08-01 (8th FLOOR)

Date: 04-11-2019



17.50	PLETREE ANSON GAPORE 079914		Date: 04-11-2019	
			Code: AWA	
1.		Policy Particul	ars :- THIRD PARTY CLA	IM
	Insured Veh.	FBN 1587U	Veh. Inspected	GBC 9261P
	Policy No.	AVFMSB0000651800	Coverage (\$)	0.00
	Claim No.	NSV1900306/SG	Excess (\$)	0.00
	Assign From	STELLA GOH	Assign Date	25/07/2019
2.		Vehicle P	articulars & Condition	
	Make & Model	TOYOTA HIACE	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	JTFHT02PX00133165	Colour	WHITE
	Odometer	192962	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Cor	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195 R15C	TOYO	6 mm
	L/H Front Tyre	195 R15C	TOYO	6 mm
	R/H Rear Tyre	195 R15C	TOYO	6 mm
	L/H Rear Tyre	195 R15C	TOYO	6 mm
4.		1856/1810/	ription of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	E REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Ger	neral Information	
	Accident Date	19/06/2019	Inspection Date	08/10/2019
	Survey held at	MODERN AUTOMOTIVE P	TELTD	
		BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		
5a.			Remarks	
	A)THE INSPECTION	ON WAS CONDUCTED ON A	"WITHOUT PREJUDICE" BAS S, WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.
5b.	I I I I I I I I I I I I I I I I I I I		ate Days of Repair	1,101 ()(1)(0)
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	4 Working Day	vs



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 9261P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	455.70	455.70
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER SIDE HOLDER-LH & RH	NECESSARY	110.80	110.80
2	REAR BUMPER LOWER BRACKET-LH & RH	BENT	59.20	59.20
1	REAR END PANEL OUTER	TO REPAIR SEE LABOUR	566.10	
1	TAILGATE	DENTED	1,718.40	1,718.40
1	TAILGATE LOCK	DAMAGED	325.50	325.50
1	TAILGATE WEATHERSTRIPE	NOT NECESSARY	387.30	
1	TAILGATE GLASS MOULDING	NECESSARY	172.50	172.50
1	TOYOTA LOGO	NECESSARY	70.50	70.50
1	TOYOTA STICKER	NECESSARY	48.50	48.50
1	HIACE STICKER	NECESSARY	52.50	52.50
	LESS 25% DISCOUNT		-999.25	-760.90
			2,997.75	2,282.70
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	TAILGATE GLASS SEALANT (SN)	NECESSARY	60.00	60.00
1	COMPANY LOGO ADVERTISEMENT (SN)	NECESSARY	400.00	200.00
			740.00	460.00
	LABOUR			
	TO KNOCKING & PULL OUT REAR PORTION & RENE ABOVE PARTS, INCLUSIVE OF THE REPAIR OF REAR END PANEL OUTER.		800.00	600.00
	TO PUTTY & SPRAY UP PAINT WORKS.		600.00	500.00
	TO CHECK WIRING SYSTEM.		50.00	30.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
	TO TRANSFER TAILGATE FITTINGS.		150.00	80.00
	TO REMOVE TAILGATE GLASS.		180.00	120.00
			1,880.00	1,380.00
	GRAND TOTAL		5,617.75	4,122.70
	RECOMMENDED COST OF LUMP SUM REPAIR	s		5,617.75

RECOMMENDED COST OF LUMP SUM REPAIRS	3,300.00
(TO ITS PRE-ACCIDENT CONDITION)	Status
(TOTIS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/AWA19013125/Atf3n2





Report Ref No. CS/AWA19013125/Atf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report whally or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.