

ASS. REC. BY:

REF:

CS/INC19013186/R/1/3<sup>n2</sup>

Special Instruction:

Surveyor: Rasu

ASSIGNMENT (Office)

From (Person): Theresa Vimala of INC

Date/Time: 26/7/19 @ 9:52am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMH 3312J

Insured: FBN 9549C

at Workshop m/s Borneo Motor  
of 2 punden Crescent.

Tel: 98476171

Policy No: \_\_\_\_\_

Claim No: MT/1054490-002

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh:  
(Client's Record)

D.O.A. 21/7/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 10:11am @ 26/7/19 Person Contacted: Thomas

Vehicle IN / OUT

Date/Time	Action/Instruction
	Johny? ✓
	SMH 3312J X
	FBN 9549C X.
<u>25/9/19</u>	<u>Payment finalised final fig @ 4908.62, 5 days.</u> <u>(Red @ 1337.46, 21%)</u>

Form

REF: IVC

1201

ASSIGNMENT

From: \_\_\_\_\_ Date: 1-8-2019

Veh No: SMH 3312J Yr Regn: 2019 Jan

Estimated Cost: \_\_\_\_\_

Type:  M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or \_\_\_\_\_

To Inspect Vehicle No: SMH 3312J

Make: TOYOTA SIENNA ELEGANCE A.c.c 1496

at Workshop m/s Borneo Motor

Colour: Brown A/C: Insured / Std / NI / NA

of 2 Pandan Crescent

Sp. Reading: 12236 T/Radio: Insured / Std / NI / NA

Insured: \_\_\_\_\_

Eng/No: \_\_\_\_\_

Policy No. \_\_\_\_\_

C/No: MHF 228H 33 00061829

Claims No. \_\_\_\_\_

Gen. Cond: Good  Fair / Poor / Burnt

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Steering: Inorder  Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder  Jammed / Leaked / Burnt or


Make of Veh: After loop.m

Modi: Nil  S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 195/50R16

Remark: The veh had commenced its repair at the time of inspection.



R: \_\_\_\_\_

Bal. or Market Value: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

Front R/Bal. 6 mm Rear R/Bal. 6 mm

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

L/Bal. 6 mm L/Bal. 6 mm

Est. Repairs: 5 days Res.: Yes or No

D.O.A. 2/01/19 D.O.I. 01/08/19

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Survey held at Borneo Motor 2:44pm

CA / REV / REP. / 24 HRS

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or Rear o/s

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 26 SEP 2019

Date/Time, File Pass to?  : Preli. Report  : Final Report

Days Of Repair: 5 Resurvey No. of Trip: 1 Survey Fee: \_\_\_\_\_

Date/Time, File Return to? \_\_\_\_\_

Transportation: \_\_\_\_\_ \$ + RS \_\_\_\_\_ \$

Report Format: TP

Add Fee:  Site Insp (\$ )  Interview (\$ )  Tech. Invs (\$ )  Weekend (\$ )

Lump Sum / I.B.I: (\$ 4908.62 )

Photos \_\_\_\_\_ Others \_\_\_\_\_

TOTAL 250

## Nivitha (LKK Auto)

**From:** Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>  
**Sent:** Friday, 26 July 2019 9:52 AM  
**To:** Admin-D (LKKAuto); assignments; SUR  
**Cc:** Thio Tse Kiat; Hazalysa Binte Ibrahim  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 26/7/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	ALICE	MT/1054913-002	26/7/2019	SLX1880B	AUTO INSURE PTE LTD	6 MARSILING LANE	Sam Goh / 9743 6363		SLQ5534L	23/7	
2	MUHD AIRWA	MT/1054490-002	26/7/2019	SMH3312J	BORNEO MOTORS (S) PTE LTD	2 PANDAN CRESCENT SINGAPORE 128462	Thomas Pang / 9847 6171		FBN9549C	21/7	
3	HUEY HUEY	MT/1054768-001	26/7/2019	SMK3359J	BORNEO MOTORS (S) PTE LTD	2 PANDAN CRESCENT SINGAPORE 128462	WALLY / 9847 6178	10:00-12:00	FBF3981T	20/7	
4	CHARLOTTE	MT/1054229-002	26/7/2019	SMD3138S	BORNEO MOTORS (S) PTE LTD	2 PANDAN CRESCENT SINGAPORE 128462	WALLY / 9847 6178	10:00-12:00	SFB3770J	18/7	
5	AIRWAN	MT/1054924-001	26/7/2019	CB6055G	CONNECT 3	566 WOODLANDS ROAD (MANDAI ESTATE)	WINNIE CHAI / 98155098	10:00-12:00	SGY4843T	23/7	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

**Theresa Vimala**  
Senior Administrator  
Motor Insurance  
T +65 6430 7898  
[www.income.com.sg](http://www.income.com.sg)

 income  
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at [income.com.sg/careers](http://income.com.sg/careers)

 inwit  
yc

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

## Shiau Chan (LKKAuto)

---

**From:** Rasul (LKKAuto)  
**Sent:** Wednesday, 25 September 2019 10:17 AM  
**To:** Thomas Pang PTCBC; SUR  
**Subject:** RE: Finalize REport for SMH3312J

Hi Thomas,

Finalised amount confirmed as per attached


Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Thomas Pang PTCBC [mailto:[Thomas.Pang@borneomotors.com.sg](mailto:Thomas.Pang@borneomotors.com.sg)]  
**Sent:** Tuesday, 24 September, 2019 6:37 PM  
**To:** Rasul (LKKAuto); SUR; Admin A  
**Subject:** Finalize REport for SMH3312J

Dear Rasul,

Attach finalize report for your perusal.05 working days.

Thank you

Regards

thomas

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/07/2019 08:53
Date Of Accident	21/07/2019 17:00
Exact Location Of Accident	LEFT TURN TOWARDS HILLION MALL
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH3312J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	BONG KUI CHAI RAYMOND
NRIC No	S7976120F
Email Address	MAVISLLP@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-93397877
Alternative Phone No	OFFICE-93395866
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	SIENTA-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN030007
Cover Note Number	
<b>Driver</b>	
Name of Driver	LIM LAY PING
NRIC No	S7906057G
Date Of Birth	14/03/1979
Occupation	INDOOR
Date Of Driving Pass	03/10/2008
Driving Experience	10 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93391877
Fax Number	
Contact Number	
EMail Address	MAVISLLP@HOTMAIL.COM

Address BLK 409 SAUJANA RD #11-126  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured SPOUSE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 3  
 Passenger 1 NAME: : BONG JUN HAN GABRIEL  
 GENDER: : MALE  
 Passenger 2 NAME: : BONG JING MINRACHEL  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number FBN9549C  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category MOTORCYCLE  
 Name of Driver TAN AIK KEE  
 NRIC/Passport Number S9823301F  
 Contact Number 98505328  
 Address  
 Postcode

Insurance Company Name

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

No. Of Passenger (Including Driver)

1

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was making a left turn when suddenly a motorbike in front of me stopped, to make a turn up onto the pavement. In order not to hit the bike, I stepped on my brake but a bike behind me hit my car on the right-back.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



*Mr - Uk Nish*

Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

Online Service Booking :  
www.toyota.com.sg

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188

### ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ML account & more!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	
	Document No	
	0	Mr Bong Kui Chai 409 Saujana Road #11-126 Singapore 670409 Mobile: 93395866
	Document Date	
	22/07/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	MWYQKT	E3	NSP170R	18/01/2019	SMH3312J	0	47007 72/DS/SMH3312J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MHFZ28H3300061829	2NRX416994	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: TP VEH: FBN9549C DATE OF ACC: 21.07.2019			<i>acc</i>	<del>100.00</del> <i>50</i>
2	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR (NETT)				<del>180.00</del>
3	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST (NETT)				<del>122.40</del>
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME (NETT)				<del>180.00</del>
5	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				<del>2160.00</del> <i>1440</i>
6	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				<del>1770.00</del>
7	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION (REAR BUMPER, AND TAILGATE)				<del>183.18</del>
8	1	S52159-0U919 COVER, RR BUMPER, L <i>scr</i>	1.00	316.10		<del>316.10</del> <i>262.63</i>
9	2	S52575-0D280 RETAINER, RR BUMPER <i>scr</i>	1.00	70.50		<del>70.50</del> <i>59.92</i>
10	3	S52155-0D110 SUPPORT, RR BUMPER S <i>scr</i>	1.00	73.60		<del>73.60</del> <i>62.56</i>
11	4	S52576-0D270 RETAINER, RR BUMPER <i>scr</i>	1.00	70.50		<del>70.50</del> <i>X</i>
12	5	S52156-0D100 SUPPORT, RR BUMPER S <i>scr</i>	1.00	73.60		<del>73.60</del> <i>X</i>

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of <b>Borneo Motors</b>	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4044760

TO SECURITY GUARD

4044760

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE  
TIME 22/07/2019  
18:00

VEHICLE NO  
SMH3312J

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



# Borneo Motors

CUSTOMER

Co Reg.No : 196700086Z  
 GST Reg No : MR-8500000-9

**Toyota Bodycare Centre**  
 No. 2 Pandan Crescent  
 Singapore 128462  
 Tel no.: 6631 1188  
 Customer Detail

## ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota FIC account &amp; more!

Account Detail		Account No	Mr Bong Kui Chai 409 Saujana Road #11-126 Singapore 670409 Mobile: 93395866
THIRD PARTY CLAIM		S1000020 / TPCLAIM	
		Document No 0	
		Document Date	
		22/07/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	MWYQKT E3	NSP170R	18/01/2019	SMH3312J	0	47007	72/DS/SMH3312J
Chassis No		Engine No	Terms	Service Engineer	Vehicle In	Collected On	

MHF228H3300061829	2NRX416994	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	-----------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	6	S52151-0D010 EXTENSION, RR BUMPER <i>x 80</i>	1.00	190.00		190.00 X
14	7	S52161-0D070 EXTENSION, RR BUMPER <i>de-</i>	1.00	129.10		129.10
15	8	S81910-0D020 REFLECTOR ASSY, REFL <i>x 2</i>	1.00	59.80		59.80 X
16	9	T90975-02086 TOYOTA SYMBOL EMBLEM, <i>nee</i>	1.00	72.20		72.20
17	0	S75442-0D290 PLATE, BACK DOOR NAM <i>nee</i>	1.00	35.50		35.50
18	1	S75441-0D070 PLATE, BACK DOOR NAM <i>nee</i>	1.00	53.20		53.20
19	2	T81581-52330 LENS & BODY, RR <i>sc</i>	1.00	261.40		261.40
20	3	T52461-52020 CUSHION, RR BUMPER <i>nee</i>	4.00	26.00		104.00
21	4	S52161-0K040 PIECE, RR BUMPER <i>nee</i>	10.00	4.10		41.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*Handwritten notes:*  
 109.73  
 61.37  
 30.17  
 45.22  
 22.19  
 80.40  
 34.80

*Signature:* Rasul

*Handwritten notes:*  
 Hp 90010068  
 5-6 days  
 01/08/19 @ 1445  
 Resurvey before paint

For & on behalf of <b>Borneo Motors</b>	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	6,246.08
		Labour 1,550.50	GST 7.00%
		Materials 4,512.40	437.23
		Lubrication/Fluid 183.18	Less
		Others 0.00	0.00
		0.00	Amount Due
			6,683.31

PLEASE TEAR ALONG PERFORATED LINE

**4044761**
**4044761**

TO SECURITY GUARD

 PLEASE ALLOW THE UNDERMENTIONED  
 VEHICLE TO LEAVE THE COMPANY PREMISES.  
**SMH3312J**

 DATE 22/07/2019  
 TIME 18:00

VEHICLE NO

 SIGNATURE  
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD


# Borneo Motors

Inchcape

CUSTOMER

# INTERNAL INVOICE

Toyota Bodycare Centre  
No. 1 Pandan Crescent  
Singapore 110462  
Tel: 6631 1188

New vehicle preparation PDI  
\*\*\*\*\* For use by BMS PDI \*\*\*\*\*  
\*  
\*  
\*

10100001/NEWVEHIC

38033505

Mr KC Bong  
409 Saujana Road  
#11-126  
Singapore 670409

28/01/2019

18 MWYQKT E3      NSP170R 18/01/2019      SMH3312J      1      40759      69INT/SMH3312J

MHFZ28H3300061829      2NRX416994      00      Raymond Seah L M      --/--/---- 0.00      --/--/---- 0.00

- M D1068\*-PLATINUM SHINEPRO
- 1 \* PSPRO PDI      LABOUR FOR PLATINUM SHINE PDI  
    D1068D) Platinum Shine Glass Coating
- 1 \* PSPRO MAT PDI      PLATINUM SHINE SET

0.00    GST 0.00%      0.00  
0.00  
0.00      0.00  
0.00

28/01/2019  
14:06

SMH3312J



Co Reg No : 196700086Z  
 GST Reg No : MR-8500000-9

**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

**Borneo Motors (Singapore) Pte Ltd**

Online Service Booking :  
 www.toyota.com.sg  
 Toyota Bodycare Centre  
 No. 2 Pandan Crescent  
 Singapore 128462  
 Tel no.: 6631 1188

Account Detail		Account No	Customer Detail		
NTUC Income Ins Co-Operative Ltd 1 Maritime Square #10-01 Harbourfront Centre Singapore 099253 Attn: Motor Claims Dept.		S1000009/ICN11	Mr Bong Kui Chai 409 Saujana Road #11-126 Singapore 670409 Mobile: 93395866		
		Document No			0
		Document Date			06/08/2019

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	MWYQKT	E3	NSP170R	18/01/2019	SMH3312J	0	47007 72/DS/SMH3312J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MHFZ28H3300061829	2NRX416994	60	Thomas Pang W T	01/08/2019	8.00	06/08/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: NTUC INCOME TP VEH: FBN9549C DATE OF ACC: 21.07.2019				50.00
2	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR (NETT)	*			180.00
3	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST (NETT)	*			122.40
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME (NETT)	*			180.00
5	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	*			1440.00
6	B	BP-RES2 RESPRAY ACC AFFECTED AREAS	*			1770.00
7	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION (REAR BUMPER, AND TAILGATE)				183.18
8	1	S52159-0U919 COVER, RR BUMPER, L	1.00	316.10	15.00	268.68
9	2	S52575-0D280 RETAINER, RR BUMPER	1.00	70.50	15.00	59.92
10	3	S52155-0D110 SUPPORT, RR BUMPER S	1.00	73.60	15.00	62.56
11	4	S52161-0D070 EXTENSION, RR BUMPER	1.00	129.10	15.00	109.73
12	5	T90975-02086 EMBLEM, SYMBOL	1.00	72.20	15.00	61.37

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of <b>Borneo Motors</b>	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			<b>Amount Due</b>

4042686

PLEASE TEAR ALONG PERFORATED LINE

4042686

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 06/08/2019  
 TIME 14:59

VEHICLE NO SMH3312J

CUSTOMER

SIGNATURE  
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

**Borneo Motors**



Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z  
 GST Reg No : MR-8500000-9

**ESTIMATE**

Online Service Booking :  
 www.toyota.com.sg  
 Toyota Bodycare Centre  
 No. 2 Pandan Crescent  
 Singapore 128462  
 Tel no. : 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
NTUC Income Ins Co-Operative Ltd 1 Maritime Square #10-01 Harbourfront Centre Singapore 099253 Attn: Motor Claims Dept	S1000009 / ICNI1	Mr Bong Kui Chai 409 Saujana Road #11-126 Singapore 670409 Mobile: 93395866
	Document No	
	Document Date	
	0	
	06/08/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	MWYQKT	E3	NSP170R	18/01/2019	SMH3312J	0	47007 72/DS/SMH3312J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MHFZ28H3300061829	2NRX416994	60	Thomas Pang W T	01/08/2019	8.00	06/08/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	6	S75442-0D290 PLATE, BACK DOOR NAM	1.00	35.50	15.00	30.17
14	7	S75441-0D070 PLATE, BACK DOOR NAM	1.00	53.20	15.00	45.22
15	8	T81581-52330 LENS & BODY, RR	1.00	261.40	15.00	222.19
16	9	T52461-52020 CUSHION, RR BUMPER	4.00	26.00	15.00	88.40
17	0	S52161-0K040 PIECE, RR BUMPER	10.00	4.10	15.00	34.80

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of <b>Borneo Motors</b>	Customer's Signature	Charge Summary	Total	4,908.62
	Please acknowledge receipt of vehicle	Parts 983.04	GST 7.00%	343.60
		Labour 3,742.40	Less	0.00
		Materials 183.18		
		Lubrication/Fluid 0.00		
		Others 0.00		
			<b>Amount Due</b>	<b>5,252.22</b>

PLEASE TEAR ALONG PERFORATED LINE

4042687

TO SECURITY GUARD

4042687

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPOUND.

DATE 06/08/2019  
 TIME 14:59

VEHICLE NO

CUSTOMER

SIGNATURE  
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



**Borneo Motors**

Inchcape



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 3312J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	COVER,RR BUMPER,L (SN)	SCRATCHED	316.10	268.68
1	RETAINER,RR BUMPER (SN)	NECESSARY	70.50	59.92
1	SUPPORT,RR BUMPER S (SN)	NECESSARY	73.60	62.56
1	RETAINER,RR BUMPER (SN)	SERVICEABLE	70.50	-
1	SUPPORT,RR BUMPER S (SN)	SERVICEABLE	73.60	-
1	EXTENSION,RR BUMPER (SN)	SERVICEABLE	190.00	-
1	EXTENSION,RR BUMPER (SN)	DEFORMED	129.10	109.73
1	REFLECTOR ASSY,REFL (SN)	SERVICEABLE	59.80	-
1	TOYOTA SYMBOL EMBLEM (SN)	NECESSARY	72.20	61.37
1	PLATE,BACK DOOR NAM (SN)	NECESSARY	35.50	30.17
1	PLATE,BACK DOOR NAM (SN)	NECESSARY	53.20	45.22
1	LENS & BODY,RR (SN)	SCRATCHED	261.40	222.19
4	CUSHION,RR BUMPER (SN)	NECESSARY	104.00	88.40
10	PIECE,RR BUMPER (SN)	NECESSARY	41.00	34.80
1	SUNDRY (SN)	NECESSARY	100.00	50.00
			1,650.50	1,033.04
<b><u>LABOUR</u></b>				
DRILL HOLE AND INSTALL REVERSE SENSOR.			180.00	180.00
CHECK WIRING AND CONDUCT WATER TEST.			122.40	122.40
TO RESET ECU AND REPROGRAMME.			180.00	180.00
REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS.			2,160.00	1,440.00
RESPRAY ACC AFFECTED AREAS.			1,770.00	1,770.00
LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION (REAR BUMPER AND TAILGATE).			183.18	183.18
-			-	-
-			-	-
-			-	-
			4,595.58	3,875.58
<b>GRAND TOTAL</b>			<b>6,246.08</b>	<b>4,908.62</b>



<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>4,908.62</b>
--	--	--	-----------------

Report Ref No. CS/INC19013186/R1qf3n2

**MOHAMMED RASUL BIN MOHD YUNUS**

**Automotive Assessor**

**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**