

22/03/2002

ASS. REC. BY:

REF: CS/INC1901388/R1VAF32

Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Theresa Vimula of INC Date/Time: 26/7/19 @ 9.52am

Estimated Cost: Bill to:

CD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 3138S Insured: SFB 3770J

at Workshop m/s Borneo Motor Tel: 98476178

of 2 punden Crescent

Policy No: Claim No: MT/1054229-002

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 18/7/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:30am @ 26/7/19 Person Contacted: wally Vehicle: IN/OUT

Date/Time	Action/Instruction
	SMD 3138S X
	SFB 3770J X
5/8/19	Final fig \$14,954.85 (Red 911905, 3870) confirmed by email

Robau

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SMD 31385** Yr Regn: **2018 / July**

Type: **C** M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: **TOYOTA LEXUS NX300** c.c: **1998**

Colour: **GRN** A/C: Insured / Std / NI / NA

Sp. Reading: **22739** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JT JBARBZ 702176 079**

Gen. Cond: Good / **C** Poor / Burnt

Steering: In order / **C** Jammed / Leaked / Burnt or

Brake: In order / **C** Jammed / Leaked / Burnt or

Modi: Nil / **C** S/Rim / STD A/Rim or

Tyre Size: F: **225/60R18**

R: _____

C DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. **6** mm

L/Bal. **6** mm

D.O.A. **18/07/19**

Survey held at **BORNEO MOTOR**

Des. of Damages: Frt / **C** Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Table with 2 columns: Date / Time, Action / Instruction. The table is mostly empty.

RECEIVED 05 SEP 2019

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) **5/9 - typist**

Report Format : **TP**

Lump Sum / I.B.I. (\$) **14,954.85**

Days Of Repair: **6**

Resurvey No. of Trip: **1**

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

3 + RS, 31

Photos

Others

TOTAL

Table with 1 column and 5 rows. The first row contains the number **290**. The last row contains the number **290**.

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Friday, 26 July 2019 9:52 AM
To: Admin-D (LKKAuto); assignments; SUR
Cc: Thio Tse Kiat; Hazalya Binte Ibrahim
Subject: RE: TP CASES FARMED OUT TO LKK ON 26/7/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	ALICE	MT/1054913-002	26/7/2019	SLX1880B	AUTO INSURE PTE LTD	6 MARSILING LANE	Sam Goh / 9743 6363		SLQ5534L	23/7	
2	MUHD AIRWA	MT/1054490-002	26/7/2019	SMH3312J	BORNEO MOTORS (S) PTE LTD	2 PANDAN CRESCENT SINGAPORE 128462	Thomas Pang / 9847 6171		FBN9549C	21/7	
3	HUEY HUEY	MT/1054768-001	26/7/2019	SMK3359J	BORNEO MOTORS (S) PTE LTD	2 PANDAN CRESCENT SINGAPORE 128462	WALLY / 9847 6178	10:00-12:00	FBF3981T	20/7	
4	CHARLOTTE	MT/1054229-002	26/7/2019	SMD3138S	BORNEO MOTORS (S) PTE LTD	2 PANDAN CRESCENT SINGAPORE 128462	WALLY / 9847 6178	10:00-12:00	SFB3770J	18/7	
5	AIRWAN	MT/1054924-001	26/7/2019	CB6055G	CONNECT 3	566 WOODLANDS ROAD (MANDAI ESTATE)	WINNIE CHAI / 98155098	10:00-12:00	SGY4843T	23/7	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at Income.com.sg/careers



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	780E
Vehicle Details	
Vehicle No.:	SMD31385
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS NX300 LUXURY S/R
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	8ARW815814
Chassis No.:	JTJBARBZ702176079
Maximum Power Output:	175.0 kW (234 bhp)
Open Market Value:	\$46,099.00
Original Registration Date:	23 Jul 2018
First Registration Date:	23 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$56,539.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jul 2028
PARF Rebate Amount:	\$42,404.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jul 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,551.00
COE Rebate Amount:	\$29,226.00
Total Rebate Amount:	\$71,630.00

The information contained herein is correct as at 29 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/07/2019 17:19
Date Of Accident	18/07/2019 17:45
Exact Location Of Accident	ALONG SLE TOWARDS MANDAI AVE EXIT TOWARDS AMK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD3138S
Insured/Policyholder	
Name Of Registered Owner	LIM CHONG KOY
NRIC No	S0909780E
Email Address	CHONGKOYLIM@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97509758
Alternative Phone No	OFFICE-97509758
Vehicle Particulars	
Manufacturer	LEXUS
Model	NX300-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2153189
Cover Note Number	
Driver	
Name of Driver	LIM CHONG KOY
NRIC No	S0909780E
Date Of Birth	30/12/1945
Occupation	INDOOR
Date Of Driving Pass	06/08/1977
Driving Experience	41 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97509758
Fax Number	
Contact Number	OFFICE-97509758
EEmail Address	CHONGKOYLIM@GMAIL.COM

Address BLK 317 ANG MO KIO ST 31 #19-209
 Postcode 560317
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : OH LEE KIOK
 GENDER: : FEMALE
 Passenger 2 NAME: : TAN WAN JIE
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TECK GHEE NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 321 ANG MO KIO STREET 31 , POSTCODE: 560321 ,
 COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4599999 - FAX NO: 64574478
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFB3770J
 Vehicle Make/Model/Colour TOYOTA MPV
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver KOH ELSIE

NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GZ2597L
Vehicle Make/Model/Colour	VAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

A - SMD 31385
B - SFB 3770J
C - GZ 2597L



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

See Police report no :- T/20190719/2081 attached.

* See video footage attached.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Police Station Of Origin:
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321
Tel No: 1800-4599999

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMD3138S	AXA INSURANCE SINGAPORE PTE LTD	P2153189	23/07/2018	22/07/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	LIM CHONG KOY		ID No.	S0909780E
Related Vehicle	NIL		Contact No.	97509758
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	KOH ELSIE		ID No.	S7217013Z
Related Vehicle	NIL		Contact No.	98733770
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On the 18/07/2019 at about 1745hrs, I was driving my car SMD3138S at along SLE towards AMK near Mandai Ave Exit Lamppost 530. I was driving at the most right lane of the three lane road. The traffic was heavy and the weather was clear and dry. I had my wife seated at the front passenger seat and my daughter in-law was seated at the rear seat.

As I was moving straight, the vehicles in front of me braked and I too applied my brake. Suddenly I felt a vehicle collided with my car at the rear. I stopped my car and came out to check what happened. I checked with the rear car driver and she informed me that her car was hit by a van at the rear which caused her car to moved forward and hit my car. My wife and daughter-in law complained of back aching, thus ambulance was activated. Shortly Ambulance and Traffic Police came to scene and investigated. Paramedic checked my wife and daughter in law, however there were not conveyed as they were feeling alright. Due to accident my car's rear boot and bumper was damaged. We exchanged particulars and left the scene.



**SINGAPORE
POLICE FORCE**



T/20190719/2081

3 of 4

Police Station Of Origin:
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321
Tel No: 1800-4599999

Report No. T/20190719/2081

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20190719/2081

Police Station Of Origin:
Teck Ghee NPP
321 Ang Mo Kio Street 31 SINGAPORE
560321
Tel No: 1800-4599999

4 of 4


Report No. T/20190719/2081

CONTINUATION OF REPORT


Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474895 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / Staff Sgt RAHUMATHULLA AZIMAL ALI	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 19/07/2019 14:46
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt MOHAMMED FEROUZ BIN HUSSEIN Contact No.: 65476206	Classification Of Case: <div data-bbox="846 2016 956 2072" style="border: 1px solid black; padding: 2px;">SN 085</div>

Authentication Stamp
NP168


 Signature: 
 Singapore Police Force



TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z
GST Reg No : MB 8500000-9

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

ESTIMATE

*Attn: Achlyn & Sn,
liability check.*

Account Detail		Account No S1000020 / TPCLAIM	Customer Detail	
THIRD PARTY CLAIM		Document No 0	Mr Lim Chong Koy 317 Ang Mo Kio Street 31 #19-209 Singapore 560317 Mobile: 97509758	
		Document Date 22/07/2019	<i>6453 7309</i>	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AWTLTQ	L4	23/07/2018	SMD3138S	0	17441	4TP/SMD3138S/18071!

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
UTJBARBZ702176079	8ARW815814	60	Wally Tan G H	22/07/2019	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:			✓	50 / 80.00
2	B	BP-LAB3 TRANSFER BACK DOOR COMPONENT AND MECHANISM TO NEW DOOR SHELL. (NETT)			✓	866.00
3	B	BP-LAB3 REMOVE/REFIX REAR SPOILER. (NETT)			✓	216.50
4	B	BP-LAB3 REMOVE/REFIX REVERSE CAMERA. (NETT)			✓	216.50
5	B	BP-WS3 REMOVE/REFIX REAR WINDSHIELD TO ASSIST REPAIR. (NETT)			✓	866.00
6	S	BP-SUBLET INSTALLING SOLAR FILM FOR REAR WINDSHIELD. (NETT)			✓	480.00
7	B	BP-LAB3 REMOVE/REFIX REAR BUMPER LOWER EXTENSION. (NETT)			✓	216.50
8	B	BP-LAB3 CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE. (NETT)			✓	216.50
9	B	BP-LAB3 REMOVE/REFIX REVERSE SENSORS. (NETT)			✓	216.50

Amount
29/7/19
HP 9001068
6-9 days
26/07/19 @ 1115
Reay before paint

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Co.

Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD
PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 22/07/2019
TIME 08:45

Acknowledged by Repairer
Signature:
Date:

VEHICLE NO SMD3138S

CUSTOMER

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z
GST Reg No : MB-8500000-9

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

ESTIMATE

Account Detail	Account No S1000020 / TPCLAIM	Customer Detail
THIRD PARTY CLAIM	Document No 0	Mr Lim Chong Koy 317 Ang Mo Kio Street 31 #19-209 Singapore 560317 Mobile: 97509758
	Document Date 22/07/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AWTLTQ L4	AGZ15R	23/07/2018	SMD3138S	0	17441	4TP/SMD3138S/18071!

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTJBARBZ702176079	8ARW815814	60	Wally Tan G H	22/07/2019 0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB3 REMOVE/REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR. (NETT)				433.00
11	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN REAR PANEL, SPARE WHEEL PAN, R/R AND L/R BODY PANELS, CUT AND WELD PANEL AND FIT NEW PARTS.				4330.00
12	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				4081.00
13	Z	BP-SLANT SUPPLY SEALANT (NETT)				208.00
14	B	BP-ECU3 TO RESET ECU & REPROGRAMME. (NETT)				216.50
15	1	L67005-78050 PANEL SUB-ASSY, BACK	1.00	3067.00		3067.00
16	2	L61826-78010 PAD, NOISE SHUTTER,	2.00	5.20		10.40
17	3	L68105-78040 GLASS SUB-ASSY, BACK	1.00	1314.00		1314.00
18	4	T04562-12010 W/SCREEN DAM KIT, ne	1.00	104.60		104.60
19	5	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00
20	6	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
21	7	T69350-48063 LOCK ASSY, BACK DOOR	1.00	974.00		974.00
22	8	L69430-48030 STRIKER ASSY, BACK	1.00	41.00		41.00
23	9	L69321-78020 COVER, BACK DOOR	1.00	32.60		32.60

repair panel rear
2598
replace - 3464
new panel
2226
replace panel - 3710
100 208.00 208.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 22/07/2019
TIME 08:45

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SMD3138S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z
GST Reg No : 196700000-9

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

ESTIMATE

Account Detail	Account No S1000020 / TPCLAIM	Customer Detail
THIRD PARTY CLAIM	Document No 0	Mr Lim Chong Koy 317 Ang Mo Kio Street 31 #19-209 Singapore 560317 Mobile: 97509758
	Document Date 22/07/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AWTLTQ	L4	23/07/2018	SMD3138S	0	17441	4TP/SMD3138S/18071!

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTJBARBZ702176079	8ARW815814	60	Wally Tan G H	22/07/2019	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
24	0	L75444-78010 PLATE, BACK DOOR LEXUS <i>rec 57.97</i>	1.00	68.20		68.20
25	1	L75443-78070 PLATE, BACK DOOR <i>rec 57.97</i>	1.00	68.20		68.20
26	2	L52155-78010 SUPPORT, RR BUMPER ?	1.00	91.80		91.80
27	3	L52156-78010 SUPPORT, RR BUMPER ?	1.00	91.80		91.80
28	4	L52015-78010 ARM SUB-ASSY, RR ? } <i>X SVC</i>	1.00	147.70		147.70
29	5	L52016-78010 ARM SUB-ASSY, RR ?	1.00	147.70		147.70
30	6	L52171-78010 REINFORCEMENT, RR ?	1.00	820.10		820.10
31	7	L52591-78020 SEAL, RR BUMPER ?	1.00	89.50		89.50
32	8	L52592-78020 SEAL, RR BUMPER ?	1.00	89.50		89.50
33	9	L75895-78030 TAPE, MOULDING, NO.1 <i>rec 58.30</i>	2.00	34.30		68.60
34	0	L52462-78011 PAD, RR BUMPER, RH <i>rec 11.38</i>	2.00	6.70		13.40
35	1	L52159-78908 COVER, RR BUMPER <i>rec 902.53</i>	1.00	1061.80		1061.80
36	2	L52169-78030 COVER, RR BUMPER, <i>rec 683.57</i>	1.00	804.20		804.20
37	3	L52152-78010 EXTENSION, RR CTR ? } <i>X SVC</i>	1.00	226.70		226.70
38	4	L75392-35220 RETAINER OUTSIDE <i>rec 31.79</i>	11.00	3.40		37.40
39	5	T90467-07215 CLIP <i>rec 11.20</i>	6.00	2.20		13.20
40	6	L58302-78010 PANEL SUB-ASSY, LWR ? } <i>X SVC</i>	1.00	975.90		975.90
41	7	L58038-78010 CO PLATE SUB-ASSY, RR ? } <i>X SVC</i>	1.00	598.00		598.00
42	8	L89348-50130 RETAINER, ULTRASONIC <i>rec 28.22</i>	2.00	16.60		33.20
43	9	L89348-33130 RETAINER, ULTRASONIC <i>rec 27.54</i>	2.00	16.20		32.40

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	24,073.90
	Please acknowledge receipt of vehicle	Parts 11,438.90	GST 7.00%	1,685.17
		Labour 12,155.00		0.00
		Materials 480.00	Less	
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	25,759.07

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 22/07/2019
TIME 08:45

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SMD3138S

CUSTOMER

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 5 September 2019 10:13 AM
To: Wally Tan PTCBC; Rasul (LKKAuto); SUR
Cc: Dion Wang; Alvin Lee Yee Peng PTCBC
Subject: RE: Final bill for SMD3138S

Dear Wally,

WITHOUT PREJUDICE

Amount \$14,954.85 confirmed before GST @ 6 working days.

Kindly send Final invoice and all supporting documents directly to NTUC INCOME

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Wally Tan PTCBC <wally.tan@borneomotors.com.sg>
Sent: Wednesday, 4 September 2019 5:35 PM
To: rasul@lkkauto.com; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: Dion Wang <Dion.Wang@inchcape.com.sg>; Alvin Lee Yee Peng PTCBC <Alvin.LeeYP@inchcape.com.sg>
Subject: RE: Final bill for SMD3138S

Hi Rasul/Veron

Please find attached final bill of SMD3138S for your kind perusal.

Regards
Wally

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be



TAX INVOICE

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9
ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
 Lexus Bodycare Centre
 No.2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1388

Account Detail		Account No	Customer Detail	
NTUC Income Ins Co-Operative Ltd 1 Maritime Square #10-01 Harbourfront Centre Singapore 099253 Attn: Motor Claims Dept		S1000009 / ICN11	Mr Lim Chong Koy 317 Ang Mo Kio Street 31 #19-209 Singapore 560317 Mobile: 97509758	
		Document No		0
		Document Date		02/09/2019

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AWTLTQ	L4	AGZ15R	23/07/2018	SMD3138S	24465	17441 ADS/SMD3138S/18071!
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTJBARBZ702176079	8ARW815814	60	Wally Tan G H	22/07/2019	0.00	02/09/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS.:NTUC INCOME ACC DATE:18.07.19 T/P VEHICLE NO.:SFB3770J DATE-IN: DATE SURVEY:26.07.19 NO OF REPAIR DAYS:6 DAYS YOUR REF:MT/1054229-002/C CBY:RASUL (LKK) *DIRECT SETTLEMENT*				50.00
2	B	BP-LAB3 TRANSFER BACK DOOR COMPONENT AND MECHANISM TO NEW DOOR SHELL. (NETT)	*			866.00
3	B	BP-LAB3 REMOVE/REFIX REAR SPOILER. (NETT)	*			216.50
4	B	BP-LAB3 REMOVE/REFIX REVERSE CAMERA. (NETT)	*			216.50
5	B	BP-WS3 REMOVE/REFIX REAR WINDSHIELD TO ASSIST REPAIR. (NETT)	*			866.00
6	S	BP-SUBLET INSTALLING SOLAR FILM FOR REAR WINDSHIELD. (NETT) PO#4459	M30			480.00
7	B	BP-LAB3 REMOVE/REFIX REAR BUMPER LOWER EXTENSION. (NETT)	*			216.50
8	B	BP-LAB3 CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE. (NETT)	*			216.50
9	B	BP-LAB3 REMOVE/REFIX REVERSE SENSORS. (NETT)	*			216.50

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 02/09/2019
 TIME 09:08

VEHICLE NO SMD3138S

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



TAX INVOICE

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9
ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
 Lexus Bodycare Centre
 No.2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1388

Account Detail		Account No	Customer Detail		
NTUC Income Ins Co-Operative Ltd 1 Maritime Square #10-01 Harbourfront Centre Singapore 099253 Attn: Motor Claims Dept		S1000009 / ICN11	Mr Lim Chong Koy 317 Ang Mo Kio Street 31 #19-209 Singapore 560317 Mobile: 97509758		
		Document No			0
		Document Date			02/09/2019

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AWTLTQ	L4	AGZ15R	23/07/2018	SMD3138S	24465	17441 4DS/SMD3138S/18071!
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTJBARBZ702176079	8ARW815814	60	Wally Tan G H	22/07/2019	0.00	02/09/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB3 REMOVE/REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR. (NETT)	*			433.00
11	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN REAR PANEL, SPARE WHEEL PAN, R/R AND L/R BODY PANELS, CUT AND WELD PANEL AND FIT NEW PARTS.	*			2598.00
12	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	*			2226.00
13	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
14	B	BP-ECU3 TO RESET ECU & REPROGRAMME. (NETT)	18			216.50
15	1	L67005-78050 PANEL ASSY, BACK DR	1.00	3067.00	15.00	2606.95
16	2	L68105-78040 GLASS SUB-ASSY, BACK	1.00	1314.00	15.00	1116.90
17	3	T04562-12010 DAM KIT, WINDOW GLASS	1.00	104.60	15.00	88.91
18	4	T21000-20 SIKA 210002-0 TACK GO! (BLACK) SG	2.00	108.00	15.00	183.60
19	5	T21000-22 SIKA 210002-2 G+P 207 ADHESIVE PRIN	1.00	200.00	15.00	170.00
20	6	L75444-78010 PLATE, BACK DOOR	1.00	68.20	15.00	57.97
21	7	L75443-78070 PLATE, BACK DOOR	1.00	68.20	15.00	57.97
22	8	L75895-78030 TAPE, MOULDING, NO.1	2.00	34.30	15.00	58.30
23	9	L52462-78011 PAD, RR BUMPER, RH	2.00	6.70	15.00	11.38

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 02/09/2019
 TIME 09:08

VEHICLE NO SMD3138S

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



TAX INVOICE

Co Reg No : 196700086Z
 GST Reg No : NP 9500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
 Lexus Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1388

Account Detail		Account No S1000009 / ICN11	Customer Detail	
NTUC Income Ins Co-Operative Ltd 1 Maritime Square #10-01 Harbourfront Centre Singapore 099253 Attn: Motor Claims Dept		Document No 0	Mr Lim Chong Koy 317 Ang Mo Kio Street 31 #19-209 Singapore 560317 Mobile: 97509758	
		Document Date 02/09/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AWTLTQ L4	AGZ15R	23/07/2018	SMD3138S	24465	17441	4DS/SMD3138S/18071!

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTJBARB2702176079	8ARW815814	60	Wally Tan G H	22/07/2019 0.00	02/09/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc%	Amount
24	0	L52159-78908 COVER, RR BUMPER	1.00	1061.80	15.00	902.53
25	1	L52169-78030 COVER, RR BUMPER,	1.00	804.20	15.00	683.57
26	2	L75392-35220 RETAINER OUTSIDE	11.00	3.40	15.00	31.79
27	3	T90467-07215 CLIP	6.00	2.20	15.00	11.22
28	4	L89348-50130 RETAINER, ULTRASONIC	2.00	16.60	15.00	28.22
29	5	L89348-33130 RETAINER, ULTRASONIC	2.00	16.20	15.00	27.54

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	14,954.85
	Please acknowledge receipt of vehicle	Parts 6,036.85 Labour 8,438.00 Materials 480.00 Lubrication/Fluid 0.00 Others 0.00	GST 7.00%	1,046.84
			Less	0.00
			Amount Due	16,001.69

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 02/09/2019
TIME 09:08

VEHICLE NO SMD3138S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchape



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19013188/R1vf3e2
73 BRAS BASAH ROAD Date: 09-09-2019
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556
ATTN : CHARLOTTE Code: INC



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFB 3770J	Veh. Inspected	SMD 3138S
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1054229-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	26/07/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA LEXUS NX300	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTJBARBZ702176079	Colour	GREY
Odometer	22739 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/60 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/60 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/60 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/60 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/07/2019	Inspect Date / Time	26/07/2019 (10:56 AM)
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 3138S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	80.00	50.00
1	SEALANT (SN)	NECESSARY	200.00	100.00
1	PANEL SUB-ASSY, BACK (SN)	BENT	3,067.00	2,606.95
2	PAD, NOISE SHUTTER (SN)	SERVICEABLE	10.40	-
1	GLASS SUB-ASSY, BACK (SN)	NECESSARY	1,314.00	1,116.90
1	W/SCREEN DAM KIT (SN)	NECESSARY	104.60	88.91
2	SIKA 182010 SIKA TACK GO! (BLA (SN)	NECESSARY	216.00	183.60
1	SIKA 207. G+P ADHESIVE PRIMER (SN)	NECESSARY	200.00	170.00
1	LOCK ASSY, BACK DOOR (SN)	SERVICEABLE	974.00	-
1	STRIKER ASSY, BACK (SN)	SERVICEABLE	41.00	-
1	COVER, BACK DOOR (SN)	SERVICEABLE	32.60	-
1	PLATE, BACK DOOR LEXUS (SN)	NECESSARY	68.20	57.97
1	PLATE, BACK DOOR (SN)	NECESSARY	68.20	57.97
1	SUPPORT, RR BUMPER (SN)	SERVICEABLE	91.80	-
1	SUPPORT, RR BUMPER (SN)	SERVICEABLE	91.80	-
1	ARM SUB-ASSY, RR (SN)	SERVICEABLE	147.70	-
1	ARM SUB-ASSY, RR (SN)	SERVICEABLE	147.70	-
1	REINFORCEMENT, RR (SN)	SERVICEABLE	820.10	-
1	SEAL, RR BUMPER (SN)	SERVICEABLE	89.50	-
1	SEAL, RR BUMPER (SN)	SERVICEABLE	89.50	-
2	TAPE, MOULDING, NO.1 (SN)	NECESSARY	68.60	58.30
2	PAD, RR BUMPER, RH (SN)	NECESSARY	13.40	11.38
1	COVER, RR BUMPER (SN)	DEFORMED	1,061.80	902.53
1	COVER, RR BUMPER (SN)	SCRATCHED	804.20	683.57
1	EXTENSION, RR CTR (SN)	SERVICEABLE	226.70	-
11	RETAINER OUTSIDE (SN)	NECESSARY	37.40	31.79
6	CLIP (SN)	NECESSARY	13.20	11.22
1	PANEL SUB-ASSY, LWR (SN)	SERVICEABLE	975.90	-
1	PLATE SUB-ASSY, RR (SN)	SERVICEABLE	598.00	-
2	RETAINER, ULTRASONIC (SN)	NECESSARY	33.20	28.22

Report Ref No. CS/INC19013188/R1vf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	RETAINER, ULTRASONIC (SN)	NECESSARY	32.40	27.54
			11,718.90	6,186.85
	LABOUR			
	TRANSFER BACK DOOR COMPONENT AND MECHANISM TO NEW DOOR SHELL.		866.00	866.00
	REMOVE / REFIX REAR SPOILER.		216.50	216.50
	REMOVE / REFIX REVERSE CAMERA.		216.50	216.50
	REMOVE / REFIX REAR WINDSHIELD TO ASSIST REPAIR.		866.00	866.00
	INSTALLING SOLAR FILM FOR REAR WINDSHIELD.		480.00	480.00
	REMOVE / REFIX REAR BUMPER LOWER EXTENSION.		216.50	216.50
	CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE.		216.50	216.50
	REMOVE / REFIX REVERSE SENSORS.		216.50	216.50
	REMOVE / REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR.		433.00	433.00
	REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN REAR PANEL, SPARE WHEEL PAN, R/R AND L/R BODY PANELS, CUT AND WELD PANEL AND FIT NEW PARTS.		4,330.00	2,598.00
	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.		4,081.00	2,226.00
	TO RESET ECU & REPROGRAMME.		216.50	216.50
			12,355.00	8,768.00
	GRAND TOTAL		24,073.90	14,954.85
RECOMMENDED COST OF REPAIRS (CONFIRMED)				14,954.85

Report Ref No. CS/INC19013188/R1vf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.