

ASS. REC. BY:

REF:

CS | FCI19013207/Hvd3⁵²

Special Instruction:

Assigner: Hact Ann

ASSIGNMENT (Office)

CWS

From (Person): Serene Ter

of

FCI

Date/Time: 3:40pm @ 26/7/19

Estimated Cost:

Bill to:

OP/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SMA 719B

Insured:

SH 8259B

at Workshop m/s

N-51 Automotive

Tel:

G8420051

of

2kaki Bukit Ave 2 #01-18

Policy No:

Claim No:

D19004857MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24/07/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time:

3:55pm @ 26/7/19

Person Contacted:

Ziting

Vehicle IN

OUT

Date/Time

Action/Instruction Estimate (✓)

SMA 719B - NA/MSG/8017214/24

DOA: 20/9/2018

SH 8259B - CS/FCI19001182/T1/d3

DOA: 9/1/2019

19/8/19 @

4.33pm check with Ziting, she will arrange.

23/10/19

Email preli revised to FCI

31/10/19

Final fig \$ 983.42 confirmed by email (Ref 729.98, 432)

ASS. REC. BY:

H-ANN

REF:

FC1

ASSIGNMENT

From:

Date: 21.10.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMA 719B

at Workshop m/s

N-51 Automotiva

of

2 kaki Bukit Ave 2 #01-17

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

/

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMA 719B

Yr Regn:

28/05/2018

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

T. PRIUS PLUS

C.C.

1798

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

184952 km T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDZS3E450J027493

Gen. Cond:

Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60/R16

R:

205/60/R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

24/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

* SMA 719B Finalized Amount \$983.42 P/P

Agree by workshop MR KHENG

MV - 96900

PV - 54303

VV - 42500

SMA 719B Estimate case

So limit → (All given & held do process)

RECEIVED 1 NOV 2019

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

1/11 - typist

Pop. Formed:

CWS

Lump Sum / F.R. / C:

983.42

Days Of Repair:

1

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

100
50
50
31
231

- 1/11/19

MOTOR SURVEY ASSIGNMENT

Date	25-07-2019	Our Ref No. D19004857MFSH
Accident Date	24-07-2019	Claim Type. Third Party
Insured Vehicle	SH8259B	Third Party Vehicle. SMA719B
Survey Location	2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB	
Contact Person.	ZI TING	
Contact No.	68420051/ 0	Fax No. 67410510
Survey Type	WITHOUT PREJUDICE: NO EST.	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	N-51 AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 23 October 2019 5:16 PM
To: 'CWS Motor Claims'
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004857MFSH/1-SMA 719B
Attachments: SMA 719B PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SMA 719B
Date of survey: 21/10/2019
Number of days (estimated) : 1 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Friday, 26 July 2019 3:56 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004857MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 26 July 2019 3:40 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19004857MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004857MFSH

Our ref: CS/FCI19013207/Hvd3

Date: 23/10/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO. SMA 719B


We thank for your instruction on 26/7/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle
on 21/10/2019 at the premises of M/s N-51 AUTOMOTIVE PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$1,713.40
Revised Estimate Amount	: S\$1,197.55
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
o/s front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

LEE HOCK ANN

Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/07/2019 13:29
Date Of Accident	24/07/2019 09:10
Exact Location Of Accident	KEPPEL TOWER DROP OFF POINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA719B
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS PLUS (AUTO)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29114756MKF
Cover Note Number	

Driver

Name of Driver	NG KIAN SENG
NRIC No	S7023563C
Date Of Birth	10/07/1970
Occupation	OUTDOOR
Date Of Driving Pass	04/05/2004
Driving Experience	15 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97709969
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I drop off my passenger at the and drop off point of the building. Upon dropping off, I signal left and overtake the taxi that was stationary. Suddenly as I pass the taxi, the taxi left passenger door opened and hit my right side mirror. The Dover of my side mirror came off. I stop and exchange particulars. No injuries involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH8259B
Vehicle Make/Model/Colour	HYUNDAI / I40 1.7L CRDI AT ABS AIRBAG 4DR / BLUE
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	LOO HWEE HENG
NRIC/Passport Number	S0206437E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claim and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes and packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER


Mohammad Azaly Bin Abdullah

Witnessed by Reporting Centre
Personnel

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I drop off my passenger at the and drop off point of the building. Upon dropping off, I signal left and overtake the taxi that was stationary. Suddenly as I pass the taxi, the taxi left passenger door opened and hit my right side mirror. The Dover of my side mirror came off.

I stop and exchange particulars.
No injuries involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMMAD AZALY BIN ABDULLAH

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

25 July 2019 at 10:53 AM

Date/Time:

25 July 2019 at 10:54 AM

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	200G
Vehicle Details	
Vehicle No.:	SMA719B
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS PLUS (AUTO)
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	2ZR0B71637
Chassis No.:	JTDZS3EU50J027493
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$27,507.00
Original Registration Date:	28 May 2018
First Registration Date:	28 May 2018
Transfer Count:	0
Actual ARF Paid:	\$20,510.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 May 2028
PARF Rebate Amount:	\$15,382.00
Intended COE Rebate Details	
COE Expiry Date:	27 May 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,289.00
COE Rebate Amount:	\$38,921.00
Total Rebate Amount:	\$54,303.00

The information contained herein is correct as at 23 Oct 2019

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No:
SMA719B

Make / Model
TOYOTA / PRIUS PLUS (AUTO)

Vehicle Type:
Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover

Vehicle Scheme:
Normal

Propellant:
Petrol-Electric

Motor No.:
5JM0B71637

Power Rating:
60.0 kW

Maximum Laden Weight:
2115 kg

Year Of Manufacture:
2018

Lifespan Expiry Date:
-

Quota Premium:
\$45,289.00

Road Tax Expiry Date:
27 Nov 2019

Inspection Due Date:
27 May 2021

CO2 Emission:
105.00 (g/km)

CO Emission:
0.067150 (g/km)

NOx Emission:
0.004040 (g/km)

Vehicle Attachment 1:
No Attachment

Chassis No.:
JTDZS3EU50J027493

Engine No.:
2ZR0B71637

Engine Capacity:
1798 cc

Maximum Power Output:
100.0 kW (134 bhp)

Unladen Weight:
1500 kg

Original Registration Date:
28 May 2018

COE Category:
B - Car above 1600cc or 97kW (130bhp)

COE Expiry Date:
27 May 2028

PARF Eligibility Expiry Date:
27 May 2028

Intended Transfer Date:
23 Oct 2019

CEV/VES Rebate Utilised Amount:
\$10,000.00

HC Emission:
0.010640 (g/km)

PM Emission:
-

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
Road Tax Renewal - 6 months (28 Nov 2019 to 27 May 2020)	\$488.00
Road Tax Renewal - 12 months (28 Nov 2019 to 27 Nov 2020)	\$976.00

Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees. Any road tax that has been paid for the vehicle will be transferred to the next owner.

Print

Save as PDF

Copy as Text

DOA = 24/7/19

MV - 96900

PV - 54303

NV - 42500

Bulky → 8 year 8 month
Apex → 10000 year

OK →

10000 ÷ 12 = 833 month

80000 + 6664 + 10255
= 96919

GREENLIGHTING F&B DREAMS OF ALL SIZES
Grow with funding from GrabFinance.
GrabFinance

toyota prius

Price Range ▼

Depreciation ▼

2018 ▼

Vehicle Type ▼



Home » Used Cars » Prime Motor & Leasing » Toyota Prius Alpha Hybrid 1.8A S

Toyota Prius Alpha Hybrid 1.8A S

Overview

Financial

Accessories

Similar

Research

Photos

Map



PRIME MOTOR & LEASING



[CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES]

• PRIME CAR RENTAL & TAXI SERVICES PTE LTD • SECTION CREDIT & MOTOR LEASING PTE LTD • BEST PETROL AND DIESEL SUPPLY PTE LTD • BEST ELECTRICITY SUPPLY PTE LTD

Price	\$101,500	Fuel Type	Petrol-Electric
Depreciation ?	\$10,900 /yr View models with similar depre	Reg Date	09-Feb-2018 (8yrs 3mths 16days COE left)
Mileage	N.A.	Manufactured ?	2017
Road Tax ?	N.A.	Transmission	Auto
Dereg Value ?	\$54,165 as of today (change)	OMV ?	\$28,637
COE ?	\$45,289	ARF ?	\$22,092
Engine Cap	1,797 cc	No. of Owners ?	1
Curb Weight ?	1,460 kg		
Type of Vehicle	MPV		

Features

Airbags, ABS, Reliable And Fuel Efficient 1.8L 4 Cylinder DOHC 16V Hybrid Engine, Producing 134Bhp, 7 Seater MPV, Multi Function Steering. View specs of the Toyota Prius

Accessories

Leather Seats, Sports Rims, Audio System.

Description

Elegant Black, 7 Seater MPV, Almost New Condition, Low Fuel Consumption With Hybrid, Low Maintenance Cost, Very Well Maintained, With Warranty, Easy Financing, Flexible In-House Loan Packages Available.

Category

PARF Car, Hybrid Cars

Status

Available

Resources



Car Valuation - Free


Find out the market value of your existing car for free. Get started

Compare

tion



Price Chart



Click on the point to view the vehicle

Shortlist

Compare

Add nc

Report Error

More Actions

Seller Information

Company

Prime Motor & Leasing

» dealer's pricelist

» 80 vehs sold | 131 vehs i

Address

31 West Coast Highway #C

Search cars nearby this loc

Location

West Coast Car Mart

Office No

67782233

Contact Person(s)

Danny

8

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 97709969

ESTIMATE

Repair Code : CLM15420
Date in : 21/10/2019
Vehicle Num. : SMA719B
Model : TOYOTA PRIUS PLUS (AUTO)
Chassis/Eng# : JTDZS3EU50J027493/2ZR0B71637

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR SIDE MIRROR	1 ✓	1373.00	1373.00 ✓
FRONT RH DOOR SIDE MIRROR COVER	1 ✓	90.40	90.40 ✓
Subtotal before discount			1,463.40 ✓
Percentage discount 25%			365.85
Sub-total 1			1,097.55
Parts-total			1,463.40

LABOUR

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

Labour Total	250.00
Parts & Labour Total	1,713.40

LKK Auto Consultants hence notify the Repairs of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This is a computer-generated document which requires no signature.***
- Third party survey is on a "Without Prejudice" basis
- No legal action is allowed
- Supplemental parts must be resurveyed and approved by Insurance Company

Acknowledged by Rep: _____
Acknowledged by Repairer: _____
Signature: _____
Date: _____

page 1

24/10/19

Parts - 1177.90

Parts Dis 250/0

883.42

Labour 100

\$ 983.42

workshop required P/P repair
running life paint

1 Day

H. ANW

053/483

21/10/19

3.0pm
H. ANW@lkk Auto.com
without prejudice

Hock Ann (LKK Auto)

From: Hock Ann (LKK Auto)
Sent: Friday, 1 November, 2019 8:42 AM
To: 'Yeo Poh Kheng'
Cc: Veron Chen (LKKAuto)
Subject: RE: RE : SMA 719B FINALIZED CALCULATE ADJUSTMENT AMOUNT UPDATED 31.10.2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear ah kheng ,

Good day, o.k will be process base on finalized total amount COR \$ 983.42 and DOR 1 days close.

Thanks.

Best Regards,
Hock Ann | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yeo Poh Kheng [mailto:yeopk@n51.com.sg]
Sent: Thursday, 31 October, 2019 5:45 PM
To: Hock Ann (LKK Auto)
Subject: Re: RE : SMA 719B FINALIZED CALCULATE ADJUSTMENT AMOUNT UPDATED 31.10.2019

Dear Hock Ann

P/P \$983.42 1 day confirm

Thanks

On Thu, 31 Oct 2019 at 10:46 AM, Hock Ann (LKK Auto) <HockAnn@lkkauto.com> wrote:

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear mr ah ken,

Good day , Kindly attached refer SMA 719B TOYOTA PRIUS PLUS finalized updated calculate adjustment on 31.10.2019 .

COR - \$ 983.42

DOR – 1 DAYS

Please refer adjustment updated total part by part amount \$ 983.42 if agree total part by part amount and repair days, will be to close case.

Please to updated email back asap.

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, [Ubi Avenue 1, #02-25](#) | S(408933)

--

Regards,

Yeo Poh Kheng
N-51 Automotive Pte Ltd
Mobile : 8823 5151
Office : 6842 0051
www.n51.com.sg




*bizSAFE*₃

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19013207/Hvd3s2	
36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877		Date : 04-11-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 8259B	Veh. Inspected	SMA 719B
Policy No.		Coverage (\$)	0.00
Claim No.	D19004857MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	26/07/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS PLUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTDZS3EU50J027493	Colour	BLUE
Odometer	184952	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	COMFORT MAX	6 mm
L/H Front Tyre	205/60 R16	COMFORT MAX	6 mm
R/H Rear Tyre	205/60 R16	COMFORT MAX	6 mm
L/H Rear Tyre	205/60 R16	COMFORT MAX	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/07/2019	Inspection Date	21/10/2019
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 719B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT RH DOOR SIDE MIRROR	CRACKED	1,373.00	1,100.40
1	FRONT RH DOOR SIDE MIRROR COVER	CRUSHED	90.40	77.50
	LESS 25% DISCOUNT		-365.85	-294.48
			1,097.55	883.42
	LABOUR			
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		150.00	70.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		100.00	30.00
			250.00	100.00
	GRAND TOTAL		1,347.55	983.42
RECOMMENDED COST OF REPAIRS				983.42

Report Ref No. CS/FCI19013207/Hvd3s2

LEE HOCK ANN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.